October 19, 2022

HUD DEMOLITION/DISPOSITION PNA

Property Identification:

Hawk View Apartments 1548 Steelwood Lane Reno, Nevada 89512

AEI Project No. 459086

Site Inspection Date: May 18, 2022

Prepared For:

Housing Authority of the City of Reno 1525 East 9th Street Reno, Nevada 89512

Prepared By:

AEI Consultants 2500 Camino Diablo, Suite 100 Walnut Creek, CA 94597-3940 (804) 938-3935

AEI Main Contact: Staige Miller

Environmental Due Diligence

Building Assessments

Site Investigation & Remediation

Energy Performance & Benchmarking

Industrial Hygiene

Construction Risk Management

Zoning Analysis Reports & ALTA Surveys

National Presence Regional Focus Local Solutions



Housing Authority of the City of Reno 1525 East 9th Street, Reno, Nevada 89512

Subject: HUD DEMOLITION/DISPOSITION PNA

Hawk View Apartments 1548 Steelwood Lane, Reno, Nevada 89512 AEI Project No. 459086

Dear Heidi McKendree:

AEI's Physical Needs Assessment (PNA) (the Physical Inspection Report) has been prepared for the above-mentioned asset (the Property). During the property assessment and research, our needs assessor met with agents representing the Property, or agents of the owner, and reviewed the property and its history. This assessment and Physical Inspection Report have been prepared in accordance with ASTM-2018 "Standard Guide for Property Condition Assessments: Baseline Property Condition Assessment Process", and HUD's Special Application Center's (SAC) PIH Notice 2021-07.

This assessment included a site reconnaissance as well as research and interviews with on-site personnel and representatives of the regulatory agencies and property ownership. An assessment was made, preliminary cost estimates developed, and recommendations outlined.

The PNA was performed at the Client's request using the methods and procedures consistent with good commercial or customary practice designed to conform to acceptable industry standards. The Report may be relied upon by Housing Authority of the City of Reno, their respective successors and assigns, and by the United States Department of Housing and Urban Development (HUD).

In expressing the opinions stated in this report, AEI has exercised the degree of skill and care ordinarily exercised by a reasonably prudent capital needs assessor in the same community and in the same time frame given the same or similar facts and circumstances. Documentation and data provided by the Client, designated representatives of the Client or other interested third



parties, or from the public domain, and referred to in the preparation of this assessment, have been used and referenced with the understanding that AEI assumes no responsibility or liability for their accuracy.

The independent conclusions represent our professional judgment based on information and data available to us during the course of this assignment. AEI's evaluations, analyses and opinions are not representations regarding the design integrity, structural soundness, or actual value of the property. Factual information regarding operations, conditions and test data provided by the Client or their representative has been assumed to be correct and complete. The conclusions presented are based on the data provided, observations and conditions that existed on the date of the on-site visit.

Should you have any questions or require additional information, please contact Jeb Bonnett at 804-955-8373 or jbonnett@aeiconsultants.com.

Sincerely,

Staige Miller

Senior Vice President

AEI Consultants

Jeb Bonnett

Senior Vice President - HUD Building Assessments

AEI Consultants

TABLE OF CONTENTS

1.0	EXECUTIVE SUMMARY AND PROPERTY DESCRIPTION	5
1.1	Overall Condition Of The Property	7
1.2	Remaining Useful Life	. 11
1.3	List of Commonly Used Acronyms	. 11
2.0	PURPOSE AND SCOPE	. 13
2.1	Purpose	. 14
2.2	Scope of Work	. 14
2.3	Site Visit Information	. 16
2.4	Reliance	. 17
3.0	OVERALL GENERAL DESCRIPTION	. 18
3.1	Building and Unit Summary	. 18
3.2	Site	. 18
3.3	Structural Frame & Building Envelope	. 31
3.4	Mechanical & Electrical Systems	. 44
3.5	Life & Fire Safety	. 50
3.6		
4.0	ADDITIONAL CONSIDERATIONS	
4.1		
4.2	Pest Management	. 57
4.3	Seismic Zone	. 58
4.4	Wind Zone	. 59
4.5	Flood Plain	. 59
4.6	Known Problematic Building Materials	
	DOCUMENT REVIEW & INTERVIEWS	
5.1	Documents Reviewed	. 61
5.2	Interviews	. 61
5.3	Building Code Compliance	. 61
5.4		
5.5		
5.6	HUD Real Estate Assessment Center (REAC) Inspection	
	ACCESSIBILITY & INTRUSIVE EXAMINATIONS	
6.1	Accessibility	. 62
6.2	Intrusive Examinations	. 73
6.3	Owner Proposed Improvements	
	ASSESSOR QUALIFICATIONS	
	LIMITING CONDITIONS	
	TABLE OF ADDENDICES	
	TABLE OF APPENDICES	
APPE	NDIX A: Street Map and Aerial Photo	
	NDIX B: Dwelling Unit Photo Documentation	
	NDIX C: General Photo Documentation	
	NDIX D: HUD SAC/PIH Notice	
	NDIX E: HUD TDC Calculation and HUD Form 52860-B	
	NDIX F: Property Substantial Renovation Estimate	
	NDIX G: USGS Seismic Design Map	
	NDIX H: Pre-Site Visit Questionnaire	
	NDIX I: Record of all Documents Reviewed, Interviews, and Supporting Information	
	ENDIX J: Property Evaluator Qualifications	



1.0 EXECUTIVE SUMMARY AND PROPERTY DESCRIPTION

AEI was retained by Housing Authority of the City of Reno on March 16, 2022 to conduct a Physical Needs Assessment (PNA) at Hawk View Apartments located at 1548 Steelwood Lane in Reno, Nevada. The property features 100 dwelling units within Twenty-Eight (28) buildings, which were built in 1984 and are situated on two parcels totaling 6.733 acres. The property was observed in fair physical condition.

The subject property is a Public Housing Facility initially developed in 1984, featuring a Maintenance Garage, Leasing Office with Community Room and a Laundry Room Building. The apartment buildings are all two-story with individual MEP rooms adjacent to the entry of each apartment unit. All units are 2-bed/1-bath, with natural gas-fired water heater and heat pump split-system HVAC units. Units are individually metered for electric and natural gas. Buildings are individually metered for domestic water. Each apartment unit is accessed from an exterior entrance with lower units including a rear patio area. Upper floor units are accessed via covered open-air stairway. The buildings are individually addressed and are considered individual with four (4) units each by onsite management, despite some being connected at roofs and rear cladding, AEI maintained this consideration when composing this report.

Evidence of foundation settling was observed within the apartment buildings and Leasing Office, management provided a foundation analysis which provides analysis and commentary on the foundation system condition which is further discussed in the Foundation Section 3.3.1 below.

Please note that AEI's repair estimates for property needs over the next three years currently total \$14,955,811. HUD's 2022 Total Development Cost (TDC) thresholds, the new construction cost allowance to completely rebuild the site is valued at \$24,499,200. According to HUD's Special Application Center's (SAC) PIH Notice 2018-04, in order for the property to be considered an qualified candidate for demolition or disposition, the ratio of renovation costs to new construction costs needs to exceed 57.14%. Per this initial renovation model, the estimated costs for the required scope of work **DOES** qualify the property for a demolition/disposition application as the cost ratio is 61.05%.

Please note that it is AEI's understanding that only the resident buildings, and areas within 5-feet of the perimeter of the foundations can be considered towards the renovation costs. AEI has excluded general site conditions from the rehabilitation schedule per HUD PIH Notice instructions.

A summary of the Property improvements is provided in the following table.

Item	Description
Property Type	Multifamily
Number of Floors	2-/Res. Apt.; 1-/Community
Number of Apartment Units	100
Total Number of Buildings	Twenty-Eight (28)
Number of Apartment Buildings	Twenty-five (25)
Ancillary Buildings	Leasing Office, Maintenance Garage and Laundry
Parking	100 total spaces
	94 of Regular Spaces
	Seven (7) of Accessible Spaces with a single Van Accessible Spaces at



Item	Description
	the Leasing Office
	No covered parking is provided
	Source: Property Management
Gross Floor Area	98,600 per Property Management
Net Rentable Floor Area	86,500 per Rent Roll
Site Area	6.733 acres per Assessor
Year of Construction	1984 per Assessor



1.1 OVERALL CONDITION OF THE PROPERTY

Overall Condition of the Property

Based on AEI's observation of the Property and improvements, the Property appears to be in overall fair condition.

Accessibility Deficiencies:

ADAAG Concerns:

- Each of the UFAS qualifying dwelling units is equipped with an accessible parking space. The spaces were observed with a non-compliant access ramp to the adjacent flatwork site pathway to the dwelling unit. AEI recommends the installation of a compliant curb cut at each accessible space provided at each UFAS qualifying dwelling unit.
- The route to the common area Laundry, Leasing Office buildings and Leasing Office Playground from the onsite UFAS qualifying dwelling units was not accessible due, to the site slope requiring steps and lack of curb depressions needed to navigate them. AEI recommends further analysis by an architect to provide compliant site pathways to all onsite amenities from the five (5) UFAS qualifying dwelling units.
- The Leasing Office was observed with a van complaint parking space which was missing the van specific signage. AEI recommends the instillation of van specific signage at one of the two Leasing Office accessible parking spaces.
- The laundry building is equipped with an accessible parking space which was observed to have a curb cut but with a non-compliant pathway from the space to the curb cut. AEI recommends moving the accessible space and signage, so the pathway lines up with the provided curb cut.
- Three (3) site stairways between 1512 and 1504 Buildings were observed with a single hand railing. Complaint dual hand railings should be provided on both sides of onsite stairways.
- Both playground areas were observed with exposed bare ground and the absorptive surfacing was observed to be deficient requiring replacement. AEI recommends the replacement of the absorptive ground cover at both playgrounds.

UFAS/State Code Concerns:

- UFAS qualifying dwelling units: 1504/1, 1544/3, 1548/1, 2519/3 and 2541/1.
- Leasing office community kitchen was observed without compliant accessible modifications. The kitchen was not equipped with a lowered or roll-under counter at the sink, a complaint workspace or front controlled range. AEI recommends the facility remodel the community kitchen to comply with Uniform Federal Accessibility Standards (UFAS).



- The UFAS dedicated dwelling unit kitchens were observed without cabinet and drawer handles/pulls. In order to comply with Uniform Federal Accessibility Standards (UFAS), the instillation of compliant cabinet and drawer handles/pulls is required.
- The roll-under kitchen and bathroom sinks located in the UFAS were observed without or with partial scald and abrasion protection. The installation of full coverage scald and abrasion protection is required.
- The bathrooms in the UFAS dwelling units were observed with inadequate clear floor space at the toilet and sink. In order to comply with the UFAS, reconfiguring the restrooms in UFAS compliant dwelling units will be required.
- Kitchen and bathroom sinks were observed missing scald/abrasion protection. In order to comply with the UFAS, installation of piping protection will be required.
- The refuse enclosures were observed to be without a compliant accessible pathway from the UFAS dwelling units. To comply with UFAS AEI recommends the installation of a complaint pathway from the UFAS dwelling units to refuse enclosures.
- The property was originally constructed in 1984 and features project-based assistance.
 The apartments are therefore subject to the requirements of Section 504 of the
 Rehabilitation Act of 1973, which states that 2% or two (2) non-designated handicapped
 dwelling units are required to have audio/visual smoke alarms, currently there are no
 units that have this feature.
- The dwelling units are heated via a gas fired furnace and heated water is provided via a
 gas fired water heater. The MEP for each dwelling unit is positioned in an attached MEP
 room. These rooms are within the apartment buildings and share a wall with the dwelling
 units. While NV state law required CO detection in new construction single family and
 duplex residences. As a best management practice AEI recommends the instillation of
 CO detection be installed within the dwelling units.

FHA Design Concerns:

• The property was built before March 13, 1991 (actual 1984) and therefore FHA Design does not apply.

Building Envelope/Foundation:

- Property Management indicated the facility has been experiencing movement of the apartment buildings, which are developed with a crawl space including perimeter continuous footing and interior cripple wall over continuous footings. A structural analysis was performed by McElhaney Structural Engineers on the interior continuous footings at this site. The analysis revealed severe deficiencies in the concrete footings.
- The Leasing Office building which was not included in the provided analysis is moving
 with significant cracking and uplift just inside the main entrance to the building.
 Additional evidence of movement was also observable in the displaced ceiling drywall
 board. The prescribed repair of this building would likely be different, due to the slab



- type foundation. Based on the observed and reported evidence of movement, AEI recommends further analyses of the building foundation system at the Leasing Office by a qualified Structural Engineer.
- Each dwelling unit was observed with two (2) entry doors and one (1) door to the mechanical room. The doors were observed, due to settlement issues, age and condition, the doors have failing seals and becoming inoperable. Replacement of the doors is recommended.
- Vinyl windows were observed; however, due to foundational shifting (settlement) issues the windows have failing seals and becoming inoperable. Replacement of the windows is recommended.
- There are extensive areas of brick veneer at the units that feature missing mortar, cracking and displaced veneer from settling which appear to be original to 1984. Repair/ replacement of those areas of brick veneer is recommended.
- The textured T1-11 wood siding was observed to be mostly original to the date of construction (1984). Replacement of approximately 75% of the textured wood siding and exterior trim is recommended based on observed damage and settlement issues.
- Removal and replacement of building select framing, insulation and gypsum board is needed to gain access for plumbing piping replacement and correct settlement issues.

Unit Finishes:

- The unit gypsum board (drywall) was observed to be in fair to poor condition. The drywall as observed areas of cracking and separating due to foundation issues. Replacement of the plumbing pipes warranted removal of select areas (approximately 90% in total) of drywall is needed.
- With removal of approximately 90% of drywall, complete painting of the walls and ceilings in the dwelling units is needed.
- Removal and replacement of the unit kitchen cabinets and vanities based on gaining access to plumbing piping and age/condition (Fair/Poor).
- The dwelling unit interior doors was observed, due to settlement issues, age and condition, the doors are becoming inoperable and will not stay on track. Replacement of the doors is recommended.
- It was reported that the sealants around the tub surrounds were failing in many of the units. Replacement of sealants is recommended.
- The units ceramic tile will be removed to access plumbing piping replacement and to correct settlement issues. Installation of new underlayment and ceramic tile is required.
- The units VCT tile flooring was observed to be in poor condition with areas of missing and damaged tiles. Select areas of VCT tile will be removed to access plumbing piping replacement and to correct settlement issues. Installation of new VCT tile is required.

Plumbing Systems:



- The plumbing lines on-site were observed to be in poor condition with the site reporting
 multiple issues of leaks and backups. In a majority of the inspected units, water damage
 due to plumbing leaks were observed on the ceiling of kitchen directly below the unit
 bathrooms. In several of units, water was observed to be infiltrating the bathroom
 subfloors and damaging the floor joists. Replacement of the water and waste lines is
 recommended.
- The property features individual 40-gallon gas water heaters of various ages (approximately 75% are 2003 and 25% are 2013/14). With plumbing piping replacement being performed, replacement of water heaters is recommended.
- The bathroom fixtures were observed to be in poor condition. Due to plumbing piping replacement and potential leaks, replacement is recommended.

HVAC Systems:

- The units feature gas-fired furnaces for heat and outdoor condensing units with replacement on an as-needed basis. Select components were observed in various conditions (some appear to be in disrepair/not functioning properly. Replacement of the furnaces, condensers, thermostats and select ductwork is recommended.
- The dwelling units feature bathroom exhaust fans that were reported to be original to the date of construction (1984) and in various operating conditions. Replacement of the fans and ducting is recommended.

Unit Electrical Service:

- Apartment units' circuit breaker panels and electrical devices require 3-year modernization.
- Select electrical devices were observed to be original to the date of construction and therefore, replacement in conjunction with the panel replacement is recommended.
- Based on observations during the inspection, select fixtures were broken, non-operational, missing. Replacement of lighting fixtures is recommended.

Fire & Life Safety:

• Each dwelling unit equipped with a main area hard-wired smoke detectors with battery back-up, each bedroom was observed with a battery-operated (non-compliant) smoke detector. Per HUD MAP Guidelines; according to Life Safety Code (NFPA 101), paragraph 31.3.4.5.1, smoke alarms must be installed outside every sleeping area in the immediate vicinity of the bedrooms and on all levels of the dwelling unit, including basements. In addition to the NFPA requirements, the regulation in 24 CFR 200.76 requires that smoke detectors must also be installed inside each sleeping area; therefore, the installation of compliant smoke detectors within all the dwelling unit bedrooms is required. The smoke detectors must be hard wired.

Recommendations in this Report



The recommendations in this report are based upon ASTM guidelines and are limited to visual observations. Testing of systems was not performed and no invasive or destructive testing was undertaken. The condition of all items is to be described as good, fair, or poor based on the ASTM E2018-15 standards.

Good Condition: In working condition and does not require immediate or short-term repairs above an agreed threshold.

Fair Condition: In working condition but may require immediate or short-term repairs above an agreed threshold.

Poor Condition: Not in working condition or requires immediate or short-term repairs above an agreed threshold.

The agreed threshold is presumed to be the *de minimus* reporting threshold.

1.2 REMAINING USEFUL LIFE

Generally, wood framed buildings have a useful life of 50 years per industry standards. The buildings at the property are approximately 38 years old and are nearing the end of their useful life due to structural concerns.

1.3 LIST OF COMMONLY USED ACRONYMS

ADA The Americans with Disabilities Act AHU Air Handling Unit ASTM American Society for Testing and Materials	
5	
ASTM American Society for Testing and Materials	
7 5	
BOMA Building Owners & Managers Association	
BUR Built-up Roof System	
BTU British Thermal Unit (a measurement of heat)	
DWV Drainage, Waste, Ventilation	
EIFS Exterior Insulation and Finish System	
EMS Energy Management System	
EPDM Ethylene Propylene Diene Monomer (rubber membrane roof)	
EUL Expected Useful Life	
FCU Fan Coil Unit	
FEMA Federal Emergency Management Agency	
FFHA Federal Fair Housing Act	
FHA Forced Hot Air	
FHW Forced Hot Water	
FIRMS Flood Insurance Rate Maps	
FOIA U.S. Freedom of Information Act (5 USC 552 et seq.) and similar state statutes.	
FOIL Freedom of Information Letter	
GFI Ground Fault Interrupt (circuit)	
GPNA Green Physical Needs Assessment	
GWB Gypsum Wall Board	
HVAC Heating, Ventilating and Air Conditioning	
IAQ Indoor Air Quality	
IM / IR Critical or Non-Critical Repair	
MEP Mechanical, Electrical & Plumbing	



MDP	Main Distribution Panel
NA	Not Applicable
NFPA	National Fire Protection Association
PCA	Property Condition Assessment
PCR	Property Condition Report
PML	Probable Maximum Loss
PTAC	Packaged Through-wall Air Conditioning (Unit)
R&M	Repair and Maintain - Routine Maintenance
RR	Replacement Reserve
RTU	Rooftop Unit
SF	Square Feet
TPO	Thermoplastic Polyolefin Roof Membrane
VAV	Variable Air Volume Box
WDO	Wood Destroying Organisms



2.0 PURPOSE AND SCOPE

Cost Calculation Methodology

Estimates are based on construction costs developed by construction resources such as Marshall & Swift, RS Means, AEI's Commercial Inspectors' experience with past costs for similar projects, city cost indexes, consulting with local specialty contractors, client provided information, and assumptions regarding future economic conditions.

Actual costs may differ from AEI's cost estimates. Actual cost estimates are determined by many factors including but not limited to: choice and availability of materials, choice and availability of a qualified contractor, regional climate zone, quality of existing materials, site compatibility, and access to the subject property and buildings. Costs are solely based on material replacement and do not account for soft costs.

Effective Useful Life (EUL) is the average amount of time in years that a system, component or structure is estimated to function when installed new and assuming that routine maintenance is practiced. It is based upon site observations, research, and judgment, along with referencing EUL tables from the United States Department of Housing and Urban Development guidelines. Accurate historical replacement records, if provided, are typically the best source of information. Exposure to the elements, initial quality and installation, extent of use, the quality and amount of preventive maintenance exercised, etc., are all factors that impact the effective age of a system or component. As a result, a system or component may have an effective age that is greater or less than its actual chronological age. The Remaining Useful Life (RUL) of a component or system equals the EUL less its effective age.

The Remaining Useful Life (RUL) is a subjective estimate based upon observations, or average estimates of similar items, components, or systems, or a combination thereof, of the number of remaining years that it is estimated to be able to function in accordance with its intended purpose before requiring replacement. Such period of time is affected by the initial quality of the system or component, the quality of the initial installation, the quality and amount of preventive maintenance, climatic conditions, extent of use and other factors.

The RUL estimate is an expression of a professional opinion and is not a guarantee or warranty, expressed or implied. This estimate is based upon the observed physical condition of the property at the time of the visit and is subject to the possible effect of concealed conditions or the occurrence of extraordinary events such as natural disasters or other unforeseen events that may occur subsequent to the date of the site visit. The RUL estimate is made only with regard to the expected physical or structural integrity of the improvements on the Property. Based upon observations during our site visit and information received from our interviews with building management and service personnel, which for the purpose of the PNA was deemed reliable, AEI prepared general-scope, Opinions of Probable Cost based on appropriate remedies for the deficiencies noted. Such remedies and their associated costs were considered commensurate with the Property's position in the market and prudent expenditures. These opinions are for components of systems exhibiting significant deferred maintenance, and existing deficiencies requiring major repairs or replacement. Repairs or improvements that could be classified as (i)



cosmetic, (ii) decorative, (iii) part or parcel of a building's renovation program or to reposition the asset in the marketplace, (iv) routine or normal preventative maintenance, or (v) that are the responsibility of the tenants were not included.

2.1 PURPOSE

The purpose of this survey and related report is to assist Housing Authority of the City of Reno and HUD in the evaluation of the physical aspects of the subject property and how its condition may affect the soundness of their financial decisions over time. For this assessment, the Project Manager has performed a reconnaissance assessment of the subject property and its improvements, evaluated the apparent physical conditions, reviewed available documentation, assessed the expected useful life (EUL), and estimated the cost for repairs, replacements, and significant maintenance items. The Project Manager assessed a representative sample of the building/s; the assessment typically included roofs, operational components, parking structures, and all common areas and exteriors.

The PNA is not, and should not be construed as, a warranty or guarantee about the condition of the improvements. Neither is the Assessment intended to assure clear title to the property in question. This investigation was prepared for the sole use and benefit of Housing Authority of the City of Reno and HUD. Neither this report, nor any of the information contained herein shall be used or relied upon for any purpose by any person or entity other than Housing Authority of the City of Reno and HUD.

We have performed our services and prepared this Report in accordance with applicable, generally accepted engineering, environmental or appraisal consulting practices. We make no other warranties, either expressed or implied, as to the character and nature of such services and product.

2.2 SCOPE OF WORK

AEI's Physical Needs Assessment (PNA) (the Physical Inspection Report) has been prepared for the above-mentioned asset (the Property). During the property assessment and research, our needs assessor met with agents representing the Property, or agents of the owner, and reviewed the property and its history. This assessment and Physical Inspection Report have been prepared in accordance with ASTM-2018 "Standard Guide for Property Condition Assessments: Baseline Property Condition Assessment Process", and HUD's Special Application Center's (SAC) PIH Notice 2021-07. The PNA was performed at Hawk View Apartments property located at 1548 Steelwood Lane in Reno, Nevada. The scope of work included the following:

- The inspection of at least 25% of each unit type;
- The visual examination of the property's components, including MEP equipment, exterior walls, roofing, foundations, landscaping, utilities, and interior elements;
- The interviewing of property management and tenants;
- The information gathering from Freedom of Information request letters from the local Building, Zoning, and Fire departments;

Any exceptions to, or deletions from, this practice are described in Section 7 of this report.



2.2.1 ASSESSMENT METHODOLOGY

The PNA meets the specifications of the lender and has included the following:

Preliminary Due Diligence

Prior to the site visit by the Property Evaluator, the pre-survey questionnaire was provided to the managers of the Property with a request that the questionnaire be completed prior to the visit.

Site Reconnaissance

The PNA findings are based on the visual, non-intrusive and non-destructive evaluation of various external and internal site and building systems and components as noted during a site walk-through survey conducted by AEI representatives. The survey included access and observation of representative tenant spaces and common areas.

Interviews and Research

AEI representatives conducted limited research to identify and review available maintenance procedures, available drawings, and other readily available documentation concerning the property. AEI representatives also conducted interviews with available management and maintenance staff. As conditions warranted, contractors for the property were contacted for pertinent information. AEI requested readily available records with public agencies familiar with the property to gather historical property information. A summary of findings have been included in the narrative sections of this report.

Report

The evaluation covered readily apparent conditions at the property. Upon completion of the site reconnaissance, interviews, and research, AEI produced this summary report. This report includes a discussion of topics related to the property condition and outlines the costs to correct the deficiencies noted. Based upon observations during our site visit and information received from our interviews with building management and service personnel, which for the purpose of the PNA was deemed reliable, AEI prepared general-scope, Opinions of Probable Cost based on appropriate remedies for the deficiencies noted. Such remedies and their associated costs were considered commensurate with the Property's position in the market and prudent expenditures. These opinions are for components of systems exhibiting significant deferred maintenance, and existing deficiencies requiring major repairs or replacement. Repairs or improvements that could be classified as (i) cosmetic, (ii) decorative, (iii) part or parcel of a building's renovation program or to reposition the asset in the marketplace, (iv) routine or normal preventative maintenance, or (v) that are the responsibility of the tenants were not included.

It is the intent of the PNA to reflect material physical deficiencies and the corresponding opinion of probable costs that are (i) commensurate with the complexity of the Property and (ii) not minor or insignificant.

Standard Estimated Useful Life (EUL)

The EUL is the average amount of time in years that a system, component or structure is estimated to function when installed new and assuming that routine maintenance is practiced. HUD has hard coded an EUL associated with every component.



Assessed Remaining Useful Life (ARUL)

This is the Needs Assessor's best professional judgment of the actual RUL of the Component ID based on observed conditions that may not agree with the auto-populated value in the Standard Remaining Useful Life field.

Standard Remaining Useful Life (SRUL)

The SRUL Displays the RUL based on the Standard EUL less the current age of the component. This is an auto-populated field that is strictly math based.

2.3 SITE VISIT INFORMATION

Site Visit Facts

Date of Site Visit	May 18, 2022
Time of Site Visit	12:30 PM
Weather Conditions	Clear and approximately 83 degrees F
Site Assessor	Matt Youngblood
Site Escorts	Darrell L. Playford
Point of Contact	Darrell L. Playford
Total Units Inspected	Twenty-six (26)

Dwelling Units Inspected

Building Identification	Unit Type	Unit Identification	Unit Status
1500	2-bed/1-bath	715/2	Occupied
1508	2-bed/1-bath	719/1	Occupied
1516	2-bed/1-bath	726/4	Occupied
1524	2-bed/1-bath	729/3	Occupied
1504	2-bed/1-bath	703/1	Occupied
1512	2-bed/1-bath	709/3	Occupied
1512	2-bed/1-bath	710/4	Vacant
1520	2-bed/1-bath	714/4	Occupied
1528	2-bed/1-bath	691/1	Occupied
1536	2-bed/1-bath	698/4	Occupied
1544	2-bed/1-bath	701/3	Occupied
1532	2-bed/1-bath	681/3	Occupied
1540	2-bed/1-bath	685/3	Occupied
1548	2-bed/1-bath	687/1	Occupied
2531	2-bed/1-bath	668/2	Occupied
2539	2-bed/1-bath	672/2	Occupied
2545	2-bed/1-bath	677/3	Occupied
2527	2-bed/1-bath	655/1	Occupied
2535	2-bed/1-bath	659/2	Vacant
2541	2-bed/1-bath	663/1	Occupied
2505	2-bed/1-bath	643/3	Occupied
2509	2-bed/1-bath	649/3	Occupied
2519	2-bed/1-bath	653/3	Occupied
2501	2-bed/1-bath	631/1	Occupied
2515	2-bed/1-bath	636/2	Occupied
2523	2-bed/1-bath	641/3	Occupied



2.4 RELIANCE

The PNA is not, and should not be construed as, a warranty or guarantee about the condition of the improvements. Neither is the Assessment intended to assure clear title to the property in question. The investigation was conducted on behalf of and for the exclusive use of Housing Authority of the City of Reno (Client) and HUD solely for use in a property condition evaluation of the subject property. This report and findings contained herein shall not, in whole or in part, be disseminated or conveyed to any other party, nor used by any other party, in whole or in part without prior written consent of AEI. AEI acknowledges and agrees that the report may be conveyed to and relied upon by the Client, their successors and assigns, rating agencies and bond investors.

Reliance is provided in accordance with AEI's Proposal and Terms and Conditions executed by Housing Authority of the City of Reno on March 16, 2022. The limitation of liability defined in the Terms and Conditions is the aggregate limit of AEI's liability to the client and all relying parties.



3.0 OVERALL GENERAL DESCRIPTION

3.1 BUILDING AND UNIT SUMMARY

The Project Manager's findings are derived from a thorough review of all available resources, including but not limited to, construction drawings, rent rolls, interviews with property management, and field inspection observations.

Unit Mix Breakdown

Unit Type ID	Square Feet	# of This Floorplan	Total Unit Square Footage
2-bed/1-bath	865	100	Total NSF: 86,500

Building Breakdown

Building Identifier	Number of Stories	Gross Square Feet
Leasing Office	1	1,057
Maintenance	1	576
Laundry	1	675
1500	2	3,560
1508	2	3,560
1516	2	3,560
1524	2	3,560
1504	2	3,560
1512	2	3,560
1520	2	3,560
1528	2	3,560
1536	2	3,560
1544	2	3,560
1532	2	3,560
1540	2	3,560
1548	2	3,560
2531	2	3,560
2539	2	3,560
2545	2	3,560
2527	2	3,560
2535	2	3,560
2541	2	3,560
2505	2	3,560
2509	2	3,560
2519	2	3,560
2501	2	3,560
2515	2	3,560
2523	2	3,560
		Total GSF: 98,600

3.2 SITE



3.2.1 SITE TOPOGRAPHY

The Property slopes moderately from the elevated northern side downward to the southern side of the site. Rip rap back stabilization in present at areas of the site. Site grade is additionally maintained by onsite buildings. The western adjacent property is also above onsite grade and the property additionally slopes downward to the east.

3.2.2 STORMWATER DRAINAGE

Item	Description	Action	Condition
Topography	Moderate slopes throughout Property	R&M	Good
Retaining Walls	Masonry retaining walls, landscape timber retaining walls, concrete tapered slopes and rip rap stable sloping soils are present	R&M	Good/Fair
Adjoining Properties	The Property slopes moderately from the elevated northern side downward to the southern side of the site. The western adjacent property is also above onsite grade and the property additionally slopes downward to the east, with the eastern offsite property below grade.	R&M	Good
Storm Water Collection System	Underground municipal drainage system with drive lanes also conveying onsite stormwater	R&M	Good
Landscape Drainage System	Landscaped areas sloped towards area drains	R&M	Good
Pavement Drainage System	Hardscape directs storm water to adjacent municipal street	R&M	Good
Foundation Drainage System	Landscaping slopes away from the foundation.	R&M	Good

ASSESSMENT / RECOMMENDATION

No notable deficiencies or indications of deferred maintenance of topography, drainage or retaining wall features were observed or reported.



Eastern side of site at southern corner



Western side of site southern end





Typical asphalt paving



Partially retaining site wall at northern end of site



Partially retaining site wall at northern end of site



Wrip-wrap covered site slope



Landscaping timber retaining wall



Landscaping timber retaining wall

3.2.3 Access & Egress

Items	Description	Action	Condition
Site Access	Provided by a northern and southern positioned	R&M	Good
	entrances from the adjoining municipal roadways		



Items	Description	Action	Condition
Signalization at Site	No traffic lights are provided at the entrances to the	NA	Not applicable
Access	Property		
Easement or Alley	No Easement or alleyways were observed or reported.	NA	Not applicable
Way			

Photographs



Northern facility entrance and signage



Southern facility entrance and signage

3.2.4 PAVING, CURBING, & PARKING

The asphalt pavement was observed with worn seal coat. Installation of seal coat is recommended after the asphalt repairs are performed. (Non-Critical Repair)

Select areas of asphalt pavement were observed damaged. Repair of the damaged asphalt is recommended. Property Management reported that a phased replacement approach had been historically been taken. AEI observed approximately 25% of the asphalt paving was in need of repairs. (Non-Critical Repair)

Items	Description	Action	Condition
Asphalt Pavement	Asphalt pavement is provided for on-site parking and	IM	Fair
	drive lanes		
Concrete Pavement	Dumpster Pad and drainage swales in drivelanes	R&M	Good
Curbing	Concrete	R&M	Good
Seal Coating	Worn and considered at the end of its useful life	IM	Fair
Striping	Painted parking striping faded and worn	R&M	Fair
Total Number of	100 spaces in open lots	R&M	Good
Parking Spaces			
Number of ADA	Seven (7)	R&M	Good
Spaces			





Typical asphalt paving



Typical asphalt paving



Refuse container with no accessible pathway (Critical Repair)



Typical asphalt paving



Typical asphalt paving



3.2.5 FLATWORK (WALKS, PLAZAS, TERRACES, PATIOS)

An area of flatwork in the vicinity of the site stairways between 1512 and 1504 Buildings were observed with sectional uplift creating a trip hazard. AEI recommends the replacement of the flatwork at this area. (Critical Repair)

Three (3) site stairways between 1512 and 1504 Buildings were observed with a single hand railing. Complaint dual hand railings should be provided on both sides of onsite stairways. (Critical Repair)

Item	Description	Action	Condition
Sidewalks	Concrete	R&M	Good/Fair
Ramps	Not applicable	NA	Not applicable
Exterior Steps	Concrete steps located along pedestrian walkways due to	IM	Good/Fair
	changes in topography (Critical Repair)		
Handrails	Steel handrails protect exterior steps and ramps	R&M	Good/Fair
Loading Docks	Not applicable	NA	Not applicable



Site stairway and sectional uplift trip hazard between 1512 and 1504 Buildings, single hand railing at 3 site stairways (Critical Repair)



Site stairway north of 2539 and 2545 Buildings



Site stairway between 2539 and 2545 Buildings



Flatwork site access northern end of site



Typical flatwork in front of apartment building



Typical flatwork termination at drive intersection



Area of flatwork sectional repair

3.2.6 LANDSCAPING & APPURTENANCES

AEI observed an area of bare ground at rear of maintenance garage, AEI recommends the area of bare ground be covered by landscaping ground cover materials. (Non-Critical Repair)

Item	Description	Action	Condition
Landscaping	Trees, shrubbery, and lawn	IM	Good/Fair
Irrigation	Areas with automatic underground system	R&M	Good
Perimeter Fencing	Chain link fencing and masonry wall	R&M	Good/Fair
Entry Gates	Not applicable	NA	Not applicable
Patio Fencing	Chain link fencing with privacy slats	R&M	Good/Fair
Refuse Area	CMU (concrete masonry unit) three wall enclosures	R&M	Good/Fair
Fencing			
Site/Building	Exterior building mounted lights	R&M	Good/Fair
Lighting			
Parking Area	Lights mounted on building	R&M	Good/Fair
Lighting			
Signage	Wall mounted letter signage	R&M	Good
Water Features	Not applicable	NA	Not applicable



Eastern side of site at southern corner chain link fencing



Partially retaining site wall at northern end of site



Partially retaining site wall at northern end of site, area of recent sectional replacement



Partially retaining site wall at northern end of site



Chain link eastern perimeter fencing



Refuse container



Refuse container with no accessible pathway (Critical Repair)



Ground level rear deck enclosed with chain linked fencing





Ground level rear deck enclosed with chain linked fencing



Facade with soffit venting



Connected building area stairwell cladding

3.2.7 RECREATIONAL FACILITIES

Both playground areas were observed with exposed bare ground and the absorptive surfacing was observed to be deficient requiring replacement. AEI recommends the replacement of the absorptive ground cover at both playgrounds. (Critical Repair)

Item	Description	Action	Condition
Barbecue	Multiple charcoal BBQ units throughout site	R&M	Good/Fair
Picnic Areas	One picnic area at rear of Leasing Office	R&M	Good
Playground	One children's playground area at rear of Leasing Office and southern children's playground area positioned between buildings 2519 and 2541	IM	Fair







Rear of Leasing Office



Southern playground



Rear of Leasing Office



Southern playground



Other Structures

Item	Description	Action	Condition
Maintenance Garage Building	Wood framed Maintenance Garage with an overhead door and asphalt shingled roofing is located on the property. The maintenance and upkeep of this building is included in the costs associated with the general site.		Good
Laundry Building	Wood framed Laundry Room with nat gas fired tankless water heater and dryers is located on the property. The building is finished with a metal panel roof, with the remaining materials constructed of materials and finishes similar to the apartment buildings. The maintenance and upkeep of this building is included in the costs associated with the general site.	R&M	Good
Leasing Office	Wood framed slab-on-grade, single-story Leasing Office structure is located on the Property. With the exception of the slab foundation, the structure is constructed of materials and finishes similar to the apartment buildings. The maintenance and upkeep of this building is included in the costs associated with the general site. Additionally the slab foundation at this structure is additionally discussed in the Foundation Section 3.3.1 below.	IM	Fair



Leasing Office side



Leasing Office front





Leasing Office front with ADA parking space, non-van accessible (Critical Repair)



Maintenance garage



Laundry room with non-compliant access pathway from accessible space (Critical Repair)



Laundry room metal panel roofing

3.2.8 SITE UTILITIES

Utility Provider	Provider
Natural Gas	Nevada Energy
Electricity	Nevada Energy
Potable Water	Truckee Meadows Water Authority
Sanitary Sewerage	City of Reno
Storm Sewer	Municipal
Fuel Oil	Not Applicable



Photographs







Typical dwelling unit electric metering

Item	Description	Action	Condition
Domestic Water	Copper pipe	IM	Poor
Supply Lines			
Waste Service Lines	PVC and ABS waste piping	IM	Poor
Lift Stations	Not applicable	NA	Not applicable
Waste Water	Not applicable	NA	Not applicable
Treatment System			
Water Wells	Not applicable	NA	Not applicable
Emergency	Not applicable	NA	Not applicable
Generator			
Transformers	Utility-owned, pad-mounted electrical transformers	R&M	Good
Alternative Energy	Not applicable	NA	Not applicable
Systems			

3.3 STRUCTURAL FRAME & BUILDING ENVELOPE

3.3.1 FOUNDATION

Item	Description	Action	Condition
Foundation Type	Crawl Space with spread-footings	IM	Poor
Foundation Walls	Concrete stem walls and spread footings	IM	Poor
Building Slab	Raised wood floor	IM	Poor
Moisture Control	Landscaping sloped away from the foundation	R&M	Good
Uniformity	The foundation is considered to be generally uniform, but	IM	Poor
	this could not be confirmed		

ASSESSMENT / RECOMMENDATION

Property Management indicated the facility has been experiencing movement of the apartment buildings, which are developed with a crawl space including perimeter continuous footing and interior cripple wall over continuous footings. The property was originally developed over a large layer of highly expansive clay. The buildings continue to move due to the shrink/swell properties of the soils. A structural analysis was performed by McElhaney Structural Engineers on the interior continuous footings at this site. The analysis revealed severe deficiencies in the



concrete footings. the footings have deteriorated to the point that the rebar is exposed and oxidizing. There is substantial movement in the floor joists causing settling and severe cracking in the drywall. Management provided the proposed structural analysis and plan to stabilize the interior continuous footings at each building. The analysis does not address any of the exterior perimeter footings. Settling is evident in the slump stone veneer at the front lower area of the buildings. Also attached is a preliminary November 24, 2020 cost estimate based on the structural plans. The price for the repair of the interior continuous footing only is \$42,383.09 per building, and \$1,059,577.25 for all twenty-five (25) apartment buildings. This work does not address the perimeter foundation area which is also experiencing similar degradation. The analysis and letter format SOW are appended to this report.

The Leasing Office building which was not included in the provided analysis is moving with significant cracking and uplift just inside the main entrance to the building. Additional evidence of movement was also observable in the displaced ceiling drywall board. The prescribed repair of this building would likely be different, due to the slab type foundation. Based on the observed and reported evidence of movement, AEI recommends further analyses of the building foundation system at the Leasing Office by a qualified Structural Engineer. (Critical Repair)



Leasing Office side



Leasing Office front with ADA parking space, non-van accessible (Critical Repair)



Leasing Office Community Room evidence of movement



Leasing Office Community Room evidence of movement



Leasing Office entrance slab uplift and movement



Leasing Office entrance slab uplift and movement



Typical drywall damage from building settling



Typical drywall damage from building settling



Typical drywall damage from building settling

3.3.2 FRAMING

3.3.2.1 Framing System, Floors & Walls

Costs included are for correction of settlement cracking that was observed at walls and openings. Select areas of wood frame floors were observed with warping and buckling. Signs of water damage was observed several floor joists and roof framing.

Item	Description	Action	Condition
Wall Structure	Wood framing	IM	Poor
Secondary Framing Members	Not applicable	NA	Not applicable
Mezzanine	Not applicable	NA	Not applicable
Walls and Floors Plumb, Level and Stable	Signs of movement were apparent in the sloped areas at the floors of the buildings, identified issues with the building foundations are further discussed above in the Foundation Section 3.1.1	IM	Poor
Significant Signs of Deflection, Movement	Signs of movement were apparent in the sloped areas at the floors of the buildings, identified issues with the building foundations are further discussed above in the Foundation Section 3.1.1	IM	Poor

3.3.2.2 CRAWL SPACES, ENVELOPE PENETRATIONS

AEI made limited observations of the crawl spaces from the vent openings/basement access. From our limited viewpoint, no unusual or significant evidence of excessive moisture was observed. Ventilation of the crawl space is provided to allow air flow through exterior vents. Good ventilation helps to decrease moisture near wood framing helps to deter termite activity, mold, and degradation of insulation. No notable deficiencies or indications of deferred maintenance of foundations were observed or reported.



Photographs



Representative crawl space venting



Representative crawl space



Representative crawl space with perimeter stem wall insulation



Representative crawl space with wood floor joists and moisture barrier

3.3.2.3 ROOF FRAME & SHEATHING

Item	Description	Action	Condition
Roof Design	Pitched with attic space	R&M	Good
Roof Framing	Wood rafters	R&M	Good
Roof Deck or	Plywood decking	R&M	Good
Sheathing			
FRT Plywood	FRT plywood was not observed or reported to be present	R&M	Good
	in the attic areas		
Significant Signs of	No unusual problems were observed or reported at the	R&M	Good
Deflection,	building roof areas, foundation movement is discussed in		
Movement	Section 3.1.1 above.		



Photographs



Leasing Office rear



Typical roof condition

3.3.2.4 FLASHING & MOISTURE PROTECTION

Roof flashing appeared to be in overall good to fair condition.

Photographs



Leasing Office side



Typical roof condition with flashing

3.3.2.5 ATTICS & EAVES

The attics are ventilated by a combination of ridge vents and perforated eave vents. The ridge vent is aluminum and covered with shingles to match the rest of the roofing.



Photographs



Facade with soffit venting



Facade with soffit venting



Apartment building end facade

3.3.2.6 Insulation

The roofs are insulated with loose-fill fibers. The depth of the insulation was reported to be approximately 12-14-inches with a R value of approximately 30. Replacement of damaged and missing insulation and any insulation to be removed as a result of reconstruction work is included.

3.3.2.7 EXTERIOR STAIRS, RAILS, BALCONIES/PORCHES, CANOPIES

The upper floor unit access stairway at 1516 building was observed to be damaged with the vertical support at the bottom of the outer hand railing observed to be broken. Based on the observed condition AEI recommends the damaged hand railing be repaired. (Critical Repair)

The railing system at upper floor unit access stairways and landings were observed with excessive baluster opening widths. AEI recommends vertical slats or additional material be added to the existing railing and landing systems. (Critical Repair)

Item	Description	Action	Condition
Balcony Framing	Not applicable	NA	Not applicable



Item	Description	Action	Condition
Balcony Deck Material	Not applicable	NA	Not applicable
Balcony Railing	Not applicable	NA	Not applicable
Patio Construction	Wood framed patios with composite board decking and chain link enclosures at each ground level dwelling unit	RR	Good/Fair
Terraces	Not applicable	NA	Not applicable
Fire Escapes	Not Applicable	NA	Not applicable
Elevated Walkway	Not applicable	NA	Not applicable
Exterior Stairs	Steel frame stairs with pre-cast concrete treads and painted metal railing systems	IM/RR	Fair



Upper floor unit access stairway at building end



Upper floor unit access stairway at building end



Upper floor unit access stairway at building connection



Upper floor unit access stairway at 1516 building damaged hand railing (Critical Repair)





Typical stairway landing



Typical onsite railing system with excessive bollard opening widths (Critical Repair)



Ground level rear deck enclosed with chain linked fencing



Typical onsite railing system



Ground level rear deck enclosed with chain linked fencing



Ground level rear deck enclosed with chain linked fencing



3.3.2.8 EXTERIOR DOORS & ENTRY SYSTEMS

Each dwelling unit was observed with two (2) entry doors and one (1) door to the mechanical room. The doors were observed, due to settlement issues, age and condition, the doors have failing seals and becoming inoperable. The dwelling unit interior doors was observed, due to settlement issues, age and condition, the doors are becoming inoperable and will not stay on track.

Item	Description	Action	Condition
Unit Entry Doors	Residential grade solid core wood doors	IM	Fair/Poor
Service Doors	Residential grade solid core wood doors	IM	Fair/Poor
Sliding Glass Doors	Not applicable	NA	Not applicable
Overhead Doors	Maintenance garage with automatic overhead door	RR	Good
Common Entrance	Residential grade solid core metal clad doors	RR	Good/Fair
Doors			



Leasing Office main entrance



Dwelling unit and MEP room doors



Unit rear doors

3.3.3 SIDEWALL SYSTEM

The textured T1-11 wood siding was observed to be mostly original to the date of construction (1984). Replacement of approximately 75% of the textured wood siding and exterior trim is recommended based on observed damage and settlement issues.

Item	Description	Action	Condition
Primary Exterior	Painted wood (T1-11 siding) with lower unpainted	IM	Fair/Poor
Wall Finishes and	masonry veneer		
Cladding			
Trim Finishes	Painted wood	IM	Fair/Poor
Soffits/Eaves	Exposed	IM	Fair/Poor
Sealants	Sealants are used at window and doors	IM	Fair/Poor
Painting	Last painting not known but estimated to have greater	IM	Fair/Poor
	than ten (10) years ago		



Typical exterior area



Typical exterior area



Typical exterior area



Upper floor unit access stairway at building end





Apartment building end facade

3.3.3.1 **WINDOWS**

Vinyl windows were observed; however, due to foundational shifting (settlement) issues the windows have failing seals and becoming inoperable. Replacement of the windows is recommended.

Item	Description	Action	Condition
Window Type	Single hung windows	IM	Fair/Poor
Window Frame	Vinyl	IM	Fair
Window Panes	Double pane insulated	IM	Fair/Poor







Typical window unit





Typical window units

3.3.4 ROOFING FINISH

Roof ID	Construction Type	Approx. Area	Reported Age	RUL	Warranty	Action	Condition
All	Pitched with	58,869	19 years	6 years	No	RR	Good /
	asphalt shingles	SF					Fair

Roof ID	Drainage	Coping (parapet)	Skylights	Action	Condition
All		Not applicable	Custom, domed skylights at select conjoined upper floor entries	RR	Good



Typical roof condition



Typical roof condition





Typical roof condition



Typical roof condition



Typical roof condition



Typical roof condition



Typical roof skylight



Conjoined covered entry gutter and downspout

3.4 MECHANICAL & ELECTRICAL SYSTEMS

3.4.1 PLUMBING

The plumbing lines on-site were observed to be in poor condition with the site reporting multiple issues of leaks and backups. In a majority of the inspected units, water damage due to plumbing leaks were observed on the ceiling of kitchen directly below the unit bathrooms. In several of units, water was observed to be infiltrating the bathroom subfloors and damaging the floor joists. Replacement of the water and waste lines is recommended. The property features individual 40-gallon gas water heaters of various ages (approximately 75% are 2003 and 25% are 2013/14). With plumbing piping replacement being performed, replacement of water heaters is recommended. The bathroom fixtures were observed to be in poor condition. Due to plumbing piping replacement and potential leaks, replacement is recommended.

Item	Description	Action	Condition
Hot and Cold Water Distribution	Copper pipe	IM	Fair
Polybutylene Water Piping	No polybutylene piping was observed or reported.	NA	Not applicable
Sanitary Waste and Vent	PVC and ABS piping	IM	Fair
Domestic Water Circulation Pumps	Not applicable	NA	Not applicable
Domestic Water Heaters	Individual, gas-fired, 40-gallon tank-type water heaters	IM	Fair
Domestic Water Boilers	Not applicable	NA	Not applicable
Boiler Peripherals	Not applicable	NA	Not applicable
Water Softening / Treatment	Not applicable	NA	Not applicable



Bld 1512-Unit 3-2x1 -MEP



Typical nat gas fired water heater and furnace





Water heater tagging



Water heater tagging



Water heater tagging



Typical nat gas fired water heater and furnace



Typical nat gas fired water heater and furnace

3.4.2 HVAC SYSTEMS

The units feature gas-fired furnaces for heat and outdoor condensing units with replacement on an as-needed basis. Select components were observed in various conditions (some appear to be in disrepair/not functioning properly. Replacement of the furnaces, condensers, thermostats and



select ductwork is recommended. The dwelling units feature bathroom exhaust fans that were reported to be original to the date of construction (1984) and in various operating conditions. Replacement of the fans and ducting is recommended.

Item	Description	Action	Condition
Cooling Equipment	Individual Split Systems with air-cooled condensing units	IM	Fair/Poor
Heating Equipment	Individual Gas Furnace (integral with Split system)	IM	Fair/Poor
Cooling Tower	Not applicable	NA	Not applicable
Terminal Units	Not applicable	NA	Not applicable
Refrigerant	R-22	IM	Fair
Tonnage of Cooling	(100) condenser units, each with a rated capacity of	IM	Fair/Poor
Equipment	around 2-tons		
Distribution System	Ducted forced-air system	IM	Fair/Poor
Controls	Local Thermostat	IM	Fair/Poor
Supplemental	Not applicable	NA	Not applicable
Systems			
Corridor and Stair-	Not applicable	NA	Not applicable
tower Ventilation			
Toilet Room	Direct vent bathroom fans	IM	Fair/Poor
Ventilation			



Exterior condensing unit



Exterior condensing units



Typical nat gas fired water heater and furnace



Exterior condensing units



Exterior condensing units

3.4.3 ELECTRICAL SYSTEM

Apartment units' circuit breaker panels and electrical devices require 3-year modernization. Select electrical devices were observed to be original to the date of construction and therefore, replacement in conjunction with the panel replacement is recommended. Based on observations during the inspection, select fixtures were broken, non-operational, missing. Replacement of lighting fixtures is recommended.

Item	Description	Action	Condition
Service Type	Underground lines to pad-mounted transformers	R&M	Good/Fair
Building Service	400-Amp, 120/240-Volt, three-phase, four- wire, alternating current (AC)	IM	Poor
Typical	125 Amp, 16-space breaker panel	IM	Poor
Tenant Service			
Amperage			
Panel Manufacturer	ITE electric panel	IM	Poor
Overload Protection	Circuit breaker switches	IM	Poor
Service Wire	Aluminum wiring observed	IM	Fair/Poor
Branch Wiring	Copper wiring observed	IM	Poor
Ground Fault Circuit Interrupter	Observed in kitchen, bathrooms, and wet areas	IM	Poor



Photographs



Typical dwelling unit meter bank



Typical dwelling unit meter bank



Typical dwelling unit metered service 100-amp main breaker

ASSESSMENT / RECOMMENDATION

There are no elevators at the subject property.



Typical dwelling unit ITE breaker panel



Bld 1512-Unit 3-2x1 -Breaker panel



3.5 LIFE & FIRE SAFETY

The dwelling units are heated via a gas fired furnace and heated water is provided via a gas fired water heater. The MEP for each dwelling unit is positioned in a common MEP room housing the equipment for two dwelling units in each. These rooms are within the apartment buildings and share a wall with the dwelling units. While NV state law required CO detection in new construction single family and duplex residences. As a best management practice AEI recommends the instillation of CO detection be installed within the dwelling units. (Critical Repair)

Item	Description	Action	Condition
Fire Suppression Systems	Not applicable	NA	Not applicable
Fire Suppression System Inspection Date	Not Applicable	NA	Not applicable
Other Equipment and Devices	Illuminated exit signs and battery back up light fixtures at leasing office.	IM	Poor
	Each dwelling unit equipped with a main area hard-wired smoke detectors with battery back-up, each bedroom was observed with a battery operated smoke detector.		
	CO detection was not identified (Critical Repair)		
Fire Extinguishers	Mounted on exterior wall of apartment buildings and interior of Leasing Office Last inspection completed in (5/22)	R&M	Good
Fire Alarms	Not applicable	NA	Not applicable
Fire Alarm Inspection Date	Not applicable	NA	Not applicable
Fire Hydrants	There are fire hydrants located along the drive lanes	R&M	Good
Fire Egress Stairs	The buildings feature breezeway staircases	R&M	Good



Bld 2541-Unit 1-2x1-UFAS -Bedroom



Bld 2541-Unit 1-2x1-UFAS -Bedroom





Typical dwelling unit hardwired smoke detection



Typical dwelling unit battery operated smoke detection



Typical fire extinguisher



Typical fire extinguisher

3.6 INTERIOR ELEMENTS

3.6.1 COMMON AREA INTERIOR ELEMENTS

Item	Description	Action	Condition
Common Area Kitchen	The Leasing Office is developed with a common area Kitchen with vinyl flooring, a stove and refrigerator. Finishes include vinyl floor tile and painted drywall walls and ceilings.	RR	Fair
Common Area Laundry	A stand alone laundry building is provided with leased laundry equipment, the room is with vinyl flooring and painted drywall walls and ceiling. The room is heated via a wall mounted gas fired heater and is not cooled. Heated water is provided via a nat gas tank-less water heated.	RR	Fair



Photographs



Leasing Office Community Room





Leasing Office Community Room



Leasing Office Community Room Kitchen



Laundry Room dryers



Laundry Room washers

3.6.2 DWELLING UNIT INTERIOR ELEMENTS

The units VCT tile flooring was observed to be in poor condition with areas of missing and damaged tiles. Select areas of VCT tile will be removed to access plumbing piping replacement and to correct settlement issues. Installation of new VCT tile is required.



The unit's ceramic tile will be removed to access plumbing piping replacement and to correct settlement issues. Installation of new underlayment and ceramic tile is required.

The unit gypsum board (drywall) was observed to be in fair to poor condition. The drywall as observed areas of cracking and separating due to foundation issues. Replacement of the plumbing pipes warranted removal of select areas (approximately 90% in total) of drywall is needed.

With removal of approximately 90% of drywall, complete painting of the walls and ceilings in the dwelling units is needed as well as window and door trim.

Unit Finishes

Item	Description	Action	Condition
Carpet	Not applicable	NA	Not applicable
Resilient Flooring (vinyl)	Vinyl tile	IM	Fair/Poor
Other	Ceramic tile in bathrooms	IM	Fair/Poor
Walls	Gypsum board with painted finish	IM	Fair/Poor
Ceilings	Gypsum board with painted finish	IM	Fair/Poor
Window Coverings	Window blinds are provided	R&M	Good



Bld 1512-Unit 3-2x1 -Kitchen



Bld 1512-Unit 3-2x1 -Kitchen



Bld 1512-Unit 3-2x1 -Living room



Bld 1512-Unit 3-2x1 -Bathroom

Appliances

Item	Description	Action	Condition
Refrigerators	Units vary in age and condition but are reaching the end of their EUL	IM	Fair
Ranges	Units vary in age and condition but are reaching the end of their EUL	IM	Fair
Range hoods	Recent replacment	IM	Fair
Dishwashers	Not provided		
Microwaves	Tenant responsibility		
Garbage Disposals	Garbage disposals are provided	IM	Fair
Dryers	Tenant responsibility		
Washers	Tenant responsibility		
Washer/Dryer Connection	Units are equipped with washer and dryer connections, with a small laundry room at the eastern end of 2535 Building served with leased equipment	IM	Fair



Photographs



Bld 2541-Unit 1-2x1-UFAS -Kitchen



Bld 2541-Unit 1-2x1-UFAS -Kitchen

Cabinets & Fixtures

Item	Description	Action	Condition
Kitchen Sink &	Plastic laminated particle board with double-basin ceramic	IM	Fair/Poor
Countertop	sink, original units in use		
Bathroom Sink and	Vanity unit with resilient surfaced counter and integrated	IM	Fair/Poor
Countertop	sink, original units in use		
Kitchen Cabinetry	Plywood frame and doors, original units in use	IM	Fair/Poor
Bathroom Cabinetry	Plywood frame and doors, original units in use	IM	Fair/Poor
Bathtub/Shower	Enamel over steel bathtub with ceramic tile tub surround,	IM	Fair/Poor
and Enclosure	original units in use		
Toilet	Water saver toilet	IM	Fair
Accessories	Towel bars and wall mounted mirror	IM	Fair



Bld 1512-Unit 3-2x1 -Kitchen



Bld 1512-Unit 3-2x1 -Kitchen





Bld 1512-Unit 3-2x1 -Bathroom



Bld 1512-Unit 3-2x1 -Bathroom

4.0 ADDITIONAL CONSIDERATIONS

4.1 MOISTURE AND MICROBIAL GROWTH

Microbial growth (e.g., mold or fungus) may occur when excess moisture is present. Porous building materials such as gypsum board, insulation in walls and ceilings, and carpeting retain moisture and become microbial growth sites if moisture sources are not controlled or mitigated. Potential sources of moisture include rainwater intrusion, groundwater intrusion, condensation on cold surfaces, and water leaks from building systems (e.g., plumbing leaks, HVAC system leaks, overflowing drains, etc.). Inadequate ventilation of clothes dryers and shower stalls may also result in excess moisture conditions. Microbial growth may be clearly visible (e.g., ceramic tile mortar in shower stalls) or may be concealed with no visible evidence of its existence (e.g., inside wall cavities). However, without proper tests, the existence of mold cannot be verified. Testing for mold is outside the scope of a baseline PNA.

AEI conducted a limited visual survey for the presence of microbial growth at the Property. Sampling or testing was not included in the scope of work for this survey. The assessment consisted of gaining entry to interior spaces, and visually evaluating the accessible areas.

Darrell L. Playford reported that he was not aware of suspected mold or microbial growth at the Property and that tenant occupants have not had complaints concerning suspected mold or microbial growth. Darrell L. Playford indicated that no formal indoor air quality management plan currently exists at the Property.

AEI identified no documents regarding indoor air quality or microbial concerns.

Darrell L. Playford was not aware of any roof leaks, water leaks or infiltration and associated damage from pipes, fixtures, or HVAC systems at the Property. No flood drains or ground water problems were reported.

ASSESSMENT / RECOMMENDATION

No repair or reserve funding is recommended at this time.

4.2 PEST MANAGEMENT

As part of the site and property assessment, AEI conducted limited, visual, non-intrusive observations to ascertain if there was evidence of wood destroying organism (WDO) activity on the physical structures at the Property during our site visit. Our WDO assessment process included visual observation of select interior and exterior building systems for noticeable signs of WDO activity, such as damaged or deteriorated wood, noticeable remnants of deceased WDO's (termites, beetles, ants, bees, etc.), and applying hand pressure (with a hard object tool) to reachable areas where these types of organisms generally attack to determine if there is any hidden damage to such surfaces (surfaces generally limited to trim work along baseboards and around windows).



Our WDO assessment process also included a limited visual and physical assessment of easily accessible and observable site conditions. The visual assessment included looking for noticeable signs of WDO activity on the Property, such as mud tubes on walls, round or oval holes, mounded soil around building perimeters, trace insect residue, and damaged wood. Our observations of exterior materials also include the application of hand pressure to reachable areas where these types of organisms generally attack, to determine if there is any hidden damage to such surfaces. This information is provided incidental to our standard PNA assessment. WDO observations, conducted by AEI, are not intended, and may not be interpreted as a professional pest inspection, and AEI makes no representation or warranty as to these activities or observations.

Our WDO assessment did not identify any unusual problems or concerns related to WDO activity on the property.

ASSESSMENT / RECOMMENDATION

No unusual problems or concerns with termites or wood destroying organisms were reported or observed.

No repair or reserve funding is recommended at this time.

4.3 SEISMIC ZONE

AEI reviewed the property location in order to determine whether or not the site is located in an area that may constitute a seismic hazard as determined by the ASCE/SEI Standard ASCE 41-13 "Seismic Evaluation and Retrofit of Existing Buildings. The determination employs output from design mapping with data provided from the US Geological Survey.

Per HUD MAP Guide (revised March 19, 2021), any detached or semi-detached structure where the calculated Design Earthquake Spectral Response Acceleration Parameter ($S_{\chi S}$) is less than .400g and any building where both Design Earthquake Spectral Response Acceleration Parameters ($S_{\chi S}$ and $S_{\chi 1}$) are less than .330g and .133g respectively, a detailed seismic hazard and building performance analysis is not required.

The values for S_{XS} and S_{X1} have been provided as output from a Design Maps Summary Report as derived from current USGS data.

A copy of the USGS data is included in the USGS Design Maps Appendix.

The value for S_{XS} was calculated at MORE than 0.330g.

The value for S_{X1} was calculated at MORE than 0.133g.

ASSESSMENT / RECOMMENDATION

A detailed seismic hazard and building performance analysis is required as defined in HUD MAP Guide.



4.4 WIND ZONE

AEI reviewed the property location in order to determine the wind zone in which the property is located. The Design Wind Speed measuring criteria are consistent with ASCE 7-05. Our judgement is that the property is located in Wind Zone IV. This map also indicates that the Property is also located in a Special Wind Region.

Wind Zones are defined as follows:

Zone I (130 MPH)

Zone II (160 MPH)

Zone III (200 MPH)

Zone IV (250 MPH)

Special Wind Zone

Hurricane Susceptible Zone

4.5 FLOOD PLAIN

AEI reviewed FEMA flood zone maps to identify the flood zone in which the property is located. According to Panel No. 32031C3045G, dated 03/16/2009, this property is located within Flood Zone X (Non-shaded).

Flood Zones are described as follows:

Flood Zone A, defined as an area of 100-year flood; base flood elevations and flood hazard factors not determined.

Flood Zone AE, defined as an area of 100-year flood; base flood elevation determined.

Flood Zone B, defined as an area between limits of the 100-year flood and 500-year flood; an area subject to 100-year flooding with average depths less than one foot or where the contributing drainage area is less than one square mile; or an area protected by levees from the base flood.

Flood Zone C, defined as an area of minimal flooding.

Flood Zone D, defined as an area of undetermined, but possible flood hazards.

Flood Zone V, defined as an area of 100-year flood with velocity (wave action); base flood elevations and flood hazard factors not determined.

Flood Zone X (shaded area), defined as an area of 500-year flood; an area of 100- year flood with average depths of less than one foot or with drainage areas less than one square mile; or an area protected by levees from 100-year flood.



Flood Zone X (non-shaded area), defined as an area outside the 500-year flood plain.

This information is provided for reference purposes only. Further Study may be undertaken at the discretion of our client.

4.6 Known Problematic Building Materials

The following list of Known Problematic Building Materials has been developed by Fannie Mae and is typically referenced in CNA reports as a general summary of systems or organisms that have been part of a manufacturer recalled or have been specifically identified as problematic. If these items are identified through reports or observation, the topic will be further discussed in the report sections listed in the following table:

Red Flag Material or System	Identified	Action Recommended
Fire Retardant Treated Plywood (FRTP)	No	Not applicable
Compressed Wood or Composite Board Siding	No	Not applicable
Exterior Insulation and Finishing (EIFS)	No	Not applicable
Problem Drywall (aka "Chinese Drywall")	No	Not applicable
Unit electrical capacity less than 60 amps	No	Not applicable
Electrical Overload Protection - Fused Subpanels	No	Not applicable
Federal Pacific Electric Stab-Lok panels	No	Not applicable
Polybutylene Water Distribution Lines	No	Not applicable
Galvanized Steel Water Distribution Lines	No	Not applicable
Recalled fire sprinkler heads (Central, Omega, Gem, Star)	No	Not applicable
Recalled Cadet Brand Electric in-Wall Heaters	No	Not applicable
Recalled General Electric / Hotpoint dishwashers	No	Not applicable
Microbial Growth	No	Not applicable
Wood Destroying Organisms	No	Not applicable



5.0 DOCUMENT REVIEW & INTERVIEWS

5.1 DOCUMENTS REVIEWED

Document	Source / Author	Date
Pre-Survey Questionnaire	Client / Property Management	May 2022
Construction Drawings	Not Provided	
ALTA Survey	Not Provided	
Historical Capital Schedule	Client / Property Management	May 2022
Rent Roll	Client / Property Management	May 2022

5.2 Interviews

Contact Name	Contact Title	Contact Phone	Information Source Provided
Darrell L. Playford	Property Management	, ,	Provided interview and
	Representative	ext. 212	conducted the site visit

5.3 BUILDING CODE COMPLIANCE

AEI requested a record of open violations on file for the Property from the City of Reno Building Department. No open violations were reported for the Property at the time of the assessment.

5.4 FIRE CODE COMPLIANCE

AEI requested a record of open violations on file for the Property from the City of Reno Fire Department. No open violations were reported for the Property at the time of the assessment.

5.5 ZONING COMPLIANCE

The property is zoned (MF30) MULTI-FAMILY (30 UNITS PER ACRE) and based on online research the property is a legal conforming use.

5.6 HUD REAL ESTATE ASSESSMENT CENTER (REAC) INSPECTION

AEI was not provided with an appended incomplete REAC inspection was provided dating from May 2017 which indicated an overall Final Score of 99b.



6.0 ACCESSIBILITY & INTRUSIVE EXAMINATIONS

6.1 ACCESSIBILITY

Determination of ADA, UFAS, FHA Applicability

Determination of ADA, UFAS, FHA App	Yes/No	Definition
Application Age: Was this property constructed	No	Under Title III of the ADA, all "new construction"
after July 1992? (ADAAG Question)		(construction, modification, or alterations) after the effective date of the ADA (approx. July 1992) must be fully compliant with the ADAAG.
Use: Does the property feature areas of public accommodation? (ADAAG Question)	Yes, leasing office	A public accommodation is a private entity that owns, operates, leases, or leases to a place of public accommodation. Places of public accommodation include restaurants, hotels, theaters, doctor's offices, pharmacies, retail stores, museums, libraries, parks, private schools, and day care centers, and entities that offer certain examinations and courses related to educational or occupational certification.
Use : Is the property classified as a historic structure? (ADAAG Question)	No	Properties listed or are eligible for listing in the National Register of Historic Places or properties designated as historic under state or local law should comply to the "maximum extent feasible" unless the changes would destroy the historic significance of a feature of the building.
Use: Is the property classified as a private club or religious structure? (ADAAG Question)	No	Properties classified as such are exempt from complying with the ADAAG.
Use: Does the property plan a significant renovation that is at least 20% of the value of the building? (If so, the renovation budget should include upgrades to correct all ADA issues). (ADAAG Question)	No	Alterations include, but are not limited to, remodeling, renovation, rehabilitation, reconstruction, historic restoration, changes or rearrangement in structural parts or elements, and changes or rearrangement in the plan configuration of walls and full-height partitions. Normal maintenance, reroofing, painting or wallpapering, asbestos removal, or changes to mechanical and electrical systems are not alterations unless they affect the usability of the building or facility.
Use: Does the property feature federal financial assistance? (UFAS Question)	Yes	Section 504 of the Rehabilitation Act of 1973 states: No otherwise qualified individual with a disability in the United Statesshall, solely by reason of her or his disability, be excluded from participation in, be denied the benefits of, or be subjected to discrimination under any program, service or activity receiving federal financial assistance or under any program or activity conducted by any Executive agency or by the United States Postal Service. (29 U.S.C. 794). This



Application	Yes/No	Definition
		means that Section 504 prohibits discrimination on the basis of disability in any program or activity that receives financial assistance from any federal agency, including the U.S. Department of Housing and Urban Development (HUD) as well as in programs conducted by federal agencies including HUD.
Age: Was this property constructed prior to July 11, 1988? (UFAS Question)	Yes	While UFAS is still applicable for all project based properties; HUD has allowed for load bearing wall, financial, and administrative burden exceptions to retroactively achieving UFAS compliance.
Age: Was this property constructed after March 13, 1991? (FHA Question)	No	Multi-family properties constructed after March 13, 1991 should be in compliance with the Fair Housing Act Accessibility Guidelines. There are select exceptions.
Age: Was this property provided original building permits after June 15, 1990? (FHA Question)	No	Buildings where the last building permit was issued on or before June 15, 1990 are not covered by the design and construction requirements. Even if the last building permit was issued after June 15, 1990, if the property was occupied before March 13, 1991, it is not covered. HUD adopted these dates to allow time for the requirements to be considered during the design and construction phase of new properties.

Abbreviated Screening Checklist for ADAAG Compliance

	Building History	Yes	No	N/A	Comments
1.	Has an ADA survey previously been completed on the property?		>	_	No previous ADA Survey for the property was provided or reported.
2.	Have any ADA improvements been made to the property?		>		
3.	Does a Transition Plan / Barrier Removal Plan exist for the property?		>		
4.	Has building ownership or management received any ADA-related complaints that have not been resolved?		>		
5.	Is any litigation pending related to ADA issues?		>		
Pai	king				
1.	Are there sufficient accessible parking spaces with respect to the total number of reported spaces?	•			100 total spaces Seven (7) designated accessible spaces
2.	Are there sufficient van-accessible parking spaces available (96" wide aisle for van)?	~			Leasing Office Van accessible space provided
3.	Are accessible spaces marked with the International Symbol of Accessibility? Are there signs reading "Van Accessible" at van spaces?		~		Leasing Office Van accessible space not provided with van specific signage (Critical Repair)



	Building History	Yes	No	N/A	Comments
4.	Is there at least one accessible route			, ^	Johnnend
l	provided within the boundary of the site				
	from public transportation stops,				
	accessible parking spaces, passenger	~			
	loading zones, if provided, and public				
	streets and sidewalks?				
5.	Do curbs on the accessible route have				
	depressed, ramped curb cuts at drives,	~			
	paths, and drop-offs?				
6.	If required does signage exist directing				
	you to accessible parking and an			~	
	accessible building entrance?				
	nps				
1.	Do all ramps along accessible path of				
	travel appear to meet slope				
	requirements? (1:12 or less) Please note			/	
	shorter ramps can be more steep than				
	1:12 if rise is less than 6-inches.				
2.	Are ramps that appear longer than 6 ft			~	
_	complete with railings on both sides?				
3.	Does the width between railings appear to be at least 36 inches?			~	
1					
4.	Are the cross slopes less steep than 1:48?			~	
5.	Do the ramp runs rise no more than				
٦.	30-inches?			~	
6.	Are there level landings at the bottom				
0.	and top of the ramp runs?			~	
Ent	rances/Exits				
1.	Do all required accessible entrance				
	doorways appear at least 32 inches wide	~			
	and not a revolving door?				
2.	If the main entrance is inaccessible, are				
	there alternate accessible entrances?	<u></u>	<u> </u>	~	
3.	Is the door hardware easy to operate				
	(lever/push type hardware, no twisting				
1	required and not higher than	~			
	approximately 48 inches above the				
	floor)?				
Pat	hs of Travel				
1.	Are all paths of travel free of obstruction				
	and wide enough for a wheelchair	~			
	(appear at least 36 inches wide)?				
2.	Are wheelchair-accessible facilities (toilet	l			
	rooms, exits, etc.) identified with	~			
	signage?				
3.	Is there a path of travel that does not	•			
	require the use of stairs?	<u> </u>			



	Building History	Yes	No	N/A	Comments
Ele	vators	1.03		111/7	Comments
1.	Do the call buttons have visual and audible signals to indicate when a call is registered and answered when car arrives?			•	
2.	Are there visual and audible signals inside cars indicating floor change?			~	
3.	Are there standard raised and Braille marking on both jambs of each hoist way entrance as well as all cab/call buttons?			•	
4.	Do elevator doors have a reopening device that will stop and reopen a car door if an object or a person obstructs the door?			•	
5.	Are elevator controls low enough to be reached from a wheelchair (appears to be between 15 and 48 inches)?			•	
6.	If a two-way emergency communication system is provided within the elevator cab, is it usable without voice communication?			•	
Toi	let Rooms				
1.	Are common area public restrooms	_			
	located on an accessible route?	<u> </u>			
3.	Are pull handles push/pull or lever type? Are toilet room access doors wheelchairaccessible (appear to be at least 32 inches wide)?	*			Lever
4.	Are public restrooms large enough to accommodate a wheelchair turnaround (appear to have 60"• turning diameter)?	~			
5.	Are toilet stall doors wheelchair accessible (appear to be at least 32"• wide)?	•			
6.	Are grab bars provided in toilet stalls?	~			
7.	Are sinks provided with clearance for a wheelchair to roll under?	~			
8.	Are sink handles operable with one hand without grasping, pinching or twisting?	~			
9.	Are exposed pipes under sink sufficiently insulated against contact?	~			Under counter pipes are insulated
Pod					
1.	Are public access pools provided? If the answer is no, please disregard this section.			•	
2.	How many accessible access points are provided to each pool/spa? Provide number in comment field.			•	



Abbreviated Screening Checklist for UFAS Compliance

Abb	reviated Screening Checklist for UFAS Com				
	Building History	Yes	No	N/A	Comments
Coı	mmon Area Paths of Travel				
1.	Are all paths of travel free of obstruction and wide enough for a wheelchair?	~			
2.	Do the common laundry rooms have a front controlled washing machine?	~			
3.	Is there a path of travel that does not require the use of stairs to get to all common areas?		*		The route to the common area Laundry, Leasing Office buildings and Leasing Office Playground from the onsite UFAS qualifying dwelling units was not accessible due, to the site slope requiring steps and lack of curb depressions needed to navigate them. (Critical Repair) The refuse enclosures were observed to be without a compliant accessible pathway from the UFAS dwelling units. (Critical Repair) Each of the UFAS qualifying dwelling units is equipped with an accessible parking space. The spaces were observed with a non-compliant access ramp to the adjacent flatwork site pathway to the dwelling unit. (Critical Repair) The laundry building is equipped with an accessible parking space which was observed to have a curb cut but with a non-compliant pathway from the space to the curb cut. (Critical Repair)
Pla	y Area				
1.	Are the common area playgrounds accessible by wheelchair?	•			
	Designated Ha	ndic	anne	d Dw	elling Units
1.	Do the unit entrance doors as well as the bathroom and bedroom doors feature 32" clear openings and low entrance thresholds for wheelchair access?	✓	иррс	J. DW	UFAS qualifying dwelling units: 1504/1, 1544/3, 1548/1, 2519/3 and 2541/1 Dwelling Units with audio/visual smoke alarms were not identified. (Critical Repair)
2.	Do all accessible doors have adequate space provided at latch side of door (see UFAS Figure 25)?	~			repair)
3.	Are exterior balconies/decks <1/2" below interior floor level?			~	
4.	Are all switches, controls and outlets located at between 15" and 54" above floor	~			



	Building History	Yes	No	N/A	Comments
5.	Accessible Kitchens: Is a 30x48 clear space provided at range/cooktop as well as front controls?	•			
6.	Accessible Kitchens: Is 40" clearance provided between counters, cabinets, walls, or appliances and opposing item.Is a 60" turning radius available in U-shaped kitchens if sink or range/ cooktop is located at base of U? Are the sinks roll-under for a 30"x48" forward approach?	•			
7.	Accessible Kitchens: Are the countertops and sinks lowered from 36" to approximately 34"?	~	~		UFAS qualifying dwelling units: 1504/1, 1544/3, 1548/1, 2519/3 and 2541/1 were observed with lowered kitchen counters. Leasing office community kitchen non-accessible kitchen. (Critical Repair)
8.	Accessible Bathrooms: Do the bathrooms feature adequate clear floor space to each of the fixtures?		*		The bathrooms in the UFAS dwelling units were observed with inadequate clear floor space at the toilet and sink.
9.	Accessible Bathrooms: Do the bathrooms feature accessible accessories (levered hardware, shower hoses, shower chairs or benches, lowered mirrors etc)?	•	•		The bathrooms in the UFAS dwelling units were observed with inadequate clear floor space at the toilet and sink. (Critical Repair) The roll-under kitchen and bathroom sinks located in the UFAS were observed without or with partial scald and abrasion protection. (Critical Repair)

Abbreviated Screening Checklist for FHA Compliance

	Building History	Yes	No	N/A	Comments		
	Fair Housing Act Accessibility Review						
1.	Requirement 1. Are there accessible						
	building entrances on an accessible						
	route? All covered multifamily dwellings						
	must have at least one accessible			,			
	building entrance on an accessible route			•			
	unless it is impractical to do so because						
	of the terrain or unusual characteristics						
	of the site.						
2.	Requirement 2. Are the public and						
	common use areas						
	accessible? Covered housing must						
	have accessible and usable public and						
	common-use areas. Public and common-			~			
	use areas cover all parts of the housing						
	outside individual units. They include						
	for example building-wide fire alarms,						
	parking lots, storage areas, indoor and						



	Building History	Yes	No	N/A	Comments
	outdoor recreational areas, lobbies,				
	mailrooms and mailboxes, and laundry areas.				
3.	Requirement 3. Are the doors				
J.	"Usable" (usable by a person in a				
	wheelchair)? All doors that allow passage into and within all premises				
	must be wide enough to allow passage				
	by persons using wheelchairs (32-inch				
	nominal clearance).				
4.	Requirement 4. Is there an accessible route into and through				
	the dwelling unit? There must be an			•	
	accessible route into and through each				
	covered unit.				
5.	Requirement 5. Are the light				
	switches, electrical outlets, thermostats and other				
	environmental controls in				
	accessible locations? Light switches,			•	
	electrical outlets, thermostats and other				
	environmental controls must be in accessible locations.				
6.	Requirement 6. Are there				
	reinforced walls in bathrooms for				
	later installation of grab				
	bars? Reinforcements in bathroom walls must be installed, so that grab bars can			~	
	be added when needed. The law does				
	not require installation of grab bars in				
	bathrooms.				
7.	Requirement 7. Are the kitchens and bathrooms "Usable"?. Kitchens				
	and bathrooms must be usable - that is,				
	designed and constructed so an			~	
	individual in a wheelchair can maneuver				
	in the space provided.				

RECOMMENDATIONS

ADAAG Concerns:

- The Leasing Office was observed with a van complaint parking space which was missing the van specific signage. AEI recommends the instillation of van specific signage at one of the two Leasing Office accessible parking spaces. (Critical Repair)
- The designated handicapped parking space near the Leasing Office was missing van specific signage. The instillation of van specific signage at van accessible spaces is required. (Critical Repair)



- The Leasing Office accessible uni-sex restroom was observed with an elevated mirror, the lowering of the mirror to a compliant 40-inches at bottom is required. (Critical Repair)
- Two ramps on the northern side of the facility at the entrance pathways were observed with a single hand railing. Complaint hand railings should be provided on both sides of the ramps. (Critical Repair)

UFAS/State Code Concerns:

UFAS applies, the property is developed with UFAS qualifying dwelling units: 1504/1, 1544/3, 1548/1, 2519/3 and 2541/1 and the following concerns were noted:

- The property was originally constructed in 1962 and 1963 and features project-based assistance. The apartments are therefore subject to the requirements of Section 504 of the Rehabilitation Act of 1973, which states that 2% or two (2) non-designated handicapped dwelling units are required to have audio/visual smoke alarms. In order to comply with UFAS, the installation of audio/visual smoke alarms in two (2) non-designated handicapped dwelling units is required. (Critical Repair)
- The bathrooms in the UFAS dwelling units were observed with inadequate clear floor space at the toilet and sink. In order to comply with the UFAS, reconfiguring the restrooms in UFAS compliant dwelling units will be required. (Critical Repair)
- The route to the common area Laundry, Leasing Office buildings and Leasing Office Playground from the onsite UFAS qualifying dwelling units was not accessible due, to the site slope requiring steps and lack of curb depressions needed to navigate them. AEI recommends further analysis by an architect to provide compliant site pathways to all onsite amenities from the five (5) UFAS qualifying dwelling units. (Critical Repair)
- The UFAS dedicated dwelling unit kitchens were observed without cabinet and drawer handles/pulls. In order to comply with Uniform Federal Accessibility Standards (UFAS), the installation of compliant cabinet and drawer handles/pulls is required. (Critical Repair)
- The refuse enclosures were observed to be without a compliant accessible pathway from the UFAS dwelling units. To comply with UFAS AEI recommends the instillation of a complaint pathway from the UFAS dwelling units to refuse enclosures. (Critical Repair)
- Leasing office community kitchen was observed without compliant accessible modifications. The entrance door was measured with 28-inches of clear space, the kitchen was not equipped with a lowered or roll-under counter at the sink, a complaint workspace or front controlled range. AEI recommends the facility remodel the community kitchen to comply with Uniform Federal Accessibility Standards (UFAS). (Critical Repair)
- Each of the UFAS qualifying dwelling units is equipped with an accessible parking space. The spaces were observed with a non-compliant access ramp to the adjacent flatwork site pathway to the dwelling unit. AEI recommends the instillation of a compliant curb cut at each accessible space provided at each UFAS qualifying dwelling unit. (Critical Repair)



• The laundry building is equipped with an accessible parking space which was observed to have a curb cut but with a non-compliant pathway from the space to the curb cut. AEI recommends moving the accessible space and signage, so the pathway lines up with the provided curb cut. (Critical Repair)



Bld 2541-Unit 1-2x1-UFAS -Bathroom



Bld 2541-Unit 1-2x1-UFAS -Bathroom



Bld 2541-Unit 1-2x1-UFAS -Bathroom



Bld 2541-Unit 1-2x1-UFAS -Bathroom inadequate clear space at sink (Critical Repair)



Bld 2541-Unit 1-2x1-UFAS -Bathroom inadequate clear space at toilet (Critical Repair)



Bld 2541-Unit 1-2x1-UFAS -Bathroom inadequate clear space at toilet (Critical Repair)



Leasing Office front with ADA parking space, non-van accessible (Critical Repair)



Leasing Office Community Room Kitchen



Leasing Office Community Room Kitchen non accessible kitchen sink



Leasing Office Community Room Kitchen non accessible kitchen range





Playground at rear of Leasing Office



Southern playground



Typical ADA parking space at UFAS dwelling unit excessive slope and cross slope at access ramp (Critical Repair)



Rear of Leasing Office accessible access



Typical ADA parking space at UFAS dwelling unit excessive slope and cross slope at access ramp (Critical Repair)



Typical ADA parking space at UFAS dwelling unit excessive slope and cross slope at access ramp (Critical Repair)





Typical flatwork termination at drive intersection



Typical flatwork termination at drive intersection



Laundry room with non-compliant access pathway from accessible space (Critical Repair)



Laundry Room washers

6.2 Intrusive Examinations

6.2.1 SEWER INSPECTION

No sewer inspections were performed as part of this investigation.

6.2.2 ELECTRICAL INSPECTION

No electrical inspections were performed as part of this investigation.

6.3 OWNER PROPOSED IMPROVEMENTS

There are no additional owner proposed improvements.



7.0 ASSESSOR QUALIFICATIONS

I understand that my Physical Needs Assessment will be used by Housing Authority of the City of Reno to document to the U.S. Department of Housing and Urban Development the condition of the property. I certify that my review was in accordance with the HUD requirements applicable on the date of my review and that I have no financial interest or family relationship with the officers, directors, stockholders, or partners of the Borrower, the general contractor, any subcontractors, the buyer or seller of the proposed property or engage in any business that might present a conflict of interest.

I have no other side deals, agreements, or financial considerations with the PHA or others in connection with this transaction.

I hereby certify under penalty of perjury that all of the information I have provided on this form and in any accompanying documentation is true and accurate. I acknowledge that if I knowingly have made any false, fictitious, or fraudulent statement, representation, or certification on this form or on any accompanying documents, I may be subject to criminal, civil, and/or administrative sanctions, including fines, penalties, and/or imprisonment under applicable federal law, including but not limited to 12 U.S.C. § 1833a; 18 U.S.C. §§1001, 1006, 1010, 1012, and 1014; 12 U.S.C. §1708 and 1735f-14; and 31 U.S.C. §§3729 and 3802.

The site inspection was completed on May 18, 2022

A resume of the property evaluator and the senior reviewers are included in the appendix of this report.

Scott Moyer, Assessment Project Manager

cett Moyn

Jeb Bonnett, Vice President - HUD Building Assessments

David Taylor, Accessibility Manager



Warning: Title 18 U.S.C. 1001, provides in part that whoever knowingly and willfully makes or uses a document containing any false, fictitious, or fraudulent statement or entry, in any manner in the jurisdiction of any department or agency of the United States, shall be fined not more than \$10,000 or imprisoned for not more than five years or both.

8.0 LIMITING CONDITIONS

Physical Needs Assessments performed by AEI Consultants are based upon, but not limited to, the scope of work outlined by ASTM Standard E2018-15. Our review of the subject property consisted of a visual inspection of the site, the structure(s) and the interior spaces. Technical Assessments were made based on the appearance of the improvements at the time of this Assessment. No destructive or invasive testing was included in the scope of this review.

The recommendations and conclusions presented as a result of this Assessment apply strictly to the time the Assessment was performed. Available documentation has been analyzed using currently accepted Assessment techniques and AEI believes that the inferences made are reasonably representative of the property.

No warranty is expressed or implied, except that the services rendered have been performed in accordance with generally accepted Assessment practices applicable at the time and location of the study.

This report should not be construed as technically exhaustive. This report does not warranty or guarantee compliance with any Federal, state or local stature, ordinance or regulation including but not limited to, building codes, safety codes, environmental regulations, health codes or zoning ordinances or compliance with trade/design standards or the standards developed by the insurance industry. Local, state and federal regulations, and codes change significantly over time from when the subject property was developed and the subject building was constructed. The subject property and subject building may not meet all current regulations, and code requirements put forth on a local, state, or federal level.

AEI Consultants has made reasonable efforts to properly assess the property conditions within the contracted scope of services; however, limitations during the assessment may be encountered.

AEI Consultants' findings and conclusions were based primarily on the visual assessment of the property at the time the site visit. In addition, the assessment value is based upon comparative judgments with similar properties in the property observer's experience. The Client is herewith advised that the conditions observed by AEI are subject to change. AEI's property observations included areas that were readily accessible without opening or dismantling secure areas or components. AEI's conclusions did not include any destructive or invasive testing, laboratory analysis, exploratory probing or engineering evaluations of structural, mechanical, electrical, or other systems with related calculations.

No assessment can wholly eliminate the uncertainty regarding the presence of physical deficiencies and performances of the building system. According to the ASTM guidelines, a property condition assessment is intended to reduce the risk regarding potential building system and component failure. The ASTM standard recognizes the inherent subjective nature of the assessment regarding such issues as workmanship, quality of care during installation, maintenance of building systems and remaining useful of the building system or components.




Assessments, analysis and opinions expressed within this report are not representations regarding either the design integrity or the structural soundness of the project.

No destructive or invasive testing was included in the scope of this Assessment. Significant limitations to AEI's standard site assessment protocol were not encountered.



APPENDIX A Street Map and Aerial Photo









1548 Steelwood Lane, Reno, Nevada 89512 AEI Project Number: 459086





APPENDIX B Dwelling Unit Photo Documentation





1. Bld 1512-Unit 3-2x1 -Kitchen



2. Bld 1512-Unit 3-2x1 -Kitchen



3. Bld 1512-Unit 3-2x1 -Living room



4. Bld 1512-Unit 3-2x1 -Living room





5. Bld 1512-Unit 3-2x1 -Bedroom



6. Bld 1512-Unit 3-2x1 -Bedroom



7. Bld 1512-Unit 3-2x1 -Bedroom hardwired smoke detection



8. Bld 1512-Unit 3-2x1 -Bedroom





9. Bld 1512-Unit 3-2x1 -Bedroom



10. Bld 1512-Unit 3-2x1 -Hall with breaker panel and thermostat



11. Bld 1512-Unit 3-2x1 -Bathroom GFCI



12. Bld 1512-Unit 3-2x1 -Bathroom





13. Bld 1512-Unit 3-2x1 -Bathroom



14. Bld 1512-Unit 3-2x1 -MEP



15. Bld 1512-Unit 3-2x1 -Breaker panel



16. Bld 2541-Unit 1-2x1-UFAS -Entry at storm door





17. Bld 2541-Unit 1-2x1-UFAS -Entry at main door



18. Bld 2541-Unit 1-2x1-UFAS -Typical wall switch and thermostat height



19. Bld 2541-Unit 1-2x1-UFAS -Typical wall switch height



20. Bld 2541-Unit 1-2x1-UFAS -Bathroom





21. Bld 2541-Unit 1-2x1-UFAS -Bathroom



22. Bld 2541-Unit 1-2x1-UFAS -Bathroom



23. Bld 2541-Unit 1-2x1-UFAS -Bathroom



24. Bld 2541-Unit 1-2x1-UFAS -Bathroom



25. Bld 2541-Unit 1-2x1-UFAS -Bathroom inadequate clear space at sink (Critical Repair)



26. Bld 2541-Unit 1-2x1-UFAS -Bathroom inadequate clear space at toilet (Critical Repair)



27. Bld 2541-Unit 1-2x1-UFAS -Bathroom inadequate clear space at toilet (Critical Repair)



28. Bld 2541-Unit 1-2x1-UFAS -Bathroom





29. Bld 2541-Unit 1-2x1-UFAS -Bathroom



30. Bld 2541-Unit 1-2x1-UFAS -Bathroom



31. Bld 2541-Unit 1-2x1-UFAS -Bathroom



32. Bld 2541-Unit 1-2x1-UFAS -Bathroom





33. Bld 2541-Unit 1-2x1-UFAS -Bedroom



34. Bld 2541-Unit 1-2x1-UFAS -Bedroom



35. Bld 2541-Unit 1-2x1-UFAS -Bedroom



36. Bld 2541-Unit 1-2x1-UFAS -Bedroom





37. Bld 2541-Unit 1-2x1-UFAS -Bedroom



38. Bld 2541-Unit 1-2x1-UFAS -Bedroom



39. Bld 2541-Unit 1-2x1-UFAS -Bedroom




40. Bld 2541-Unit 1-2x1-UFAS -Bedroom





41. Bld 2541-Unit 1-2x1-UFAS -Bedroom



42. Bld 2541-Unit 1-2x1-UFAS -Bedroom



43. Bld 2541-Unit 1-2x1-UFAS -Bedroom




44. Bld 2541-Unit 1-2x1-UFAS -Kitchen entrance





45. Bld 2541-Unit 1-2x1-UFAS -Kitchen



46. Bld 2541-Unit 1-2x1-UFAS -Kitchen



47. Bld 2541-Unit 1-2x1-UFAS -Kitchen



48. Bld 2541-Unit 1-2x1-UFAS -Kitchen





49. Bld 2541-Unit 1-2x1-UFAS -Kitchen



50. Bld 2541-Unit 1-2x1-UFAS -Kitchen



51. Bld 2541-Unit 1-2x1-UFAS -Kitchen



52. Bld 2541-Unit 1-2x1-UFAS -Kitchen





53. Bld 2541-Unit 1-2x1-UFAS -Kitchen missing cabinet and drawer handles/pulls (Critical Repair)



54. Bld 2541-Unit 1-2x1-UFAS -Kitchen partial scald and abrasion protection (Critical Repair)

APPENDIX C General Photo Documentation





1. Southern facility entrance and signage



2. Northern facility entrance and signage



3. Northern end of site



4. Northern end of site





5. Eastern side of site



6. Eastern side of site at southern corner



7. Southern side of site



8. Western side of site northern end





9. Western side of site southern end



10. Typical exterior area



11. Typical exterior area



12. Typical exterior area at laundry building





13. Typical exterior area



14. Typical exterior area



15. Typical exterior area



16. Typical exterior area





17. Typical exterior area



18. Typical exterior area



19. Typical exterior area



20. Typical exterior area





21. Leasing Office rear



22. Leasing Office side



23. Leasing Office front



24. Leasing Office front with ADA parking space, non-van accessible (Critical Repair)





25. Leasing Office main entrance



26. Leasing Office main entrance



27. Leasing Office main entrance



28. Leasing Office main entrance





29. Leasing Office Community Room lighting controls



30. Leasing Office Community Room



31. Leasing Office Community Room



32. Leasing Office Community Room





33. Leasing Office Community Room Kitchen



34. Leasing Office Community Room Kitchen non accessible kitchen sink



35. Leasing Office Community Room Kitchen non accessible kitchen sink



36. Leasing Office Community Room Kitchen kitchen sink





37. Leasing Office Community Room Kitchen non accessible kitchen range



38. Leasing Office Community Room Kitchen upper cabinets



39. Leasing Office Community Room office entrance



40. Leasing Office Community Room office





41. Leasing Office Community Room bathroom entrance



42. Leasing Office Community Room bathroom entrance



43. Leasing Office Community Room bathroom



44. Leasing Office Community Room bathroom





45. Leasing Office Community Room bathroom



46. Leasing Office Community Room bathroom



47. Leasing Office Community Room bathroom



48. Leasing Office Community Room bathroom





49. Leasing Office Community Room bathroom



50. Leasing Office Community Room bathroom



51. Leasing Office Community Room bathroom



52. Leasing Office Community Room bathroom light switch





53. Leasing Office Community Room bathroom GFIC



54. Leasing Office Community Room evidence of movement




55. Leasing Office Community Room evidence of movement



56. Leasing Office entrance slab uplift and movement






57. Leasing Office entrance slab uplift and movement



58. Typical flatwork pathway



59. Playground at rear of Leasing Office



60. Rear of Leasing Office accessible access





61. Rear of Leasing Office



62. Rear of Leasing Office



63. Southern playground



64. Southern playground





65. Western drive lane



66. Typical asphalt paving



67. Typical asphalt paving



68. Typical asphalt paving





69. Typical asphalt paving



70. Typical asphalt paving



71. Typical asphalt paving



72. Typical asphalt paving





73. Typical asphalt paving



74. Typical ADA parking space at UFAS dwelling unit excessive slope and cross slope at access ramp (Critical Repair)



75. Typical ADA parking space at UFAS dwelling unit 76. Typical ADA parking space at UFAS dwelling unit excessive slope and cross slope at access ramp (Critical Repair)



excessive slope and cross slope at access ramp (Critical Repair)





77. Typical ADA parking space at UFAS dwelling unit excessive slope and cross slope at access ramp (Critical Repair)



78. Area of bare ground at rear of maintenance garage (Non-Critical Repair)



79. Flatwork site access northern end of site



80. Typical flatwork termination at drive intersection





81. Typical flatwork termination at drive intersection



82. Site stairway and sectional uplift trip hazard between 1512 and 1504 Buildings, single hand railing at 3 site stairways (Critical Repair)



83. Typical flatwork in front of apartment building



84. Typical flatwork termination at drive intersection





85. Area of flatwork sectional repair



86. Maintenance garage



87. Laundry room with non-compliant access pathway from accessible space (Critical Repair)



88. Laundry room metal panel roofing





89. Laundry Room washers



90. Laundry Room tankless water heater



91. Laundry Room nat gas wall heater



92. Laundry Room entrance





93. Laundry Room dryers



94. Laundry room



95. Typical dwelling unit Nat Gas metering



96. Typical dwelling unit electric metering






97. Upper floor unit access stairway at building end



98. Upper floor unit access stairway at building end



99. Upper floor unit access stairway at building connection



100. Upper floor unit access stairway at 1516 building damaged hand railing (Critical Repair)





101. Typical stairway landing



102. Site stairway north of 2539 and 2545 Buildings



103. Site stairway between 2539 and 2545 Buildings



104. Typical onsite railing system





105. Typical onsite railing system with excessive bollard opening widths (Critical Repair)



106. Partially retaining site wall at northern end of site



107. Partially retaining site wall at northern end of site



108. Partially retaining site wall at northern end of site





109. Partially retaining site wall at northern end of site



110. Partially retaining site wall at northern end of site



111. Partially retaining site wall at northern end of site



112. Partially retaining site wall at northern end of site





113. Site wall at southern end of site



114. Chain link eastern perimeter fencing



115. Chain link eastern perimeter fencing



116. Area of bare ground between 2539 and 1540 buildings (Non-Critical Repair)





117. Wrip-wrap covered site slope



118. Landscaping timber retaining wall



119. Landscaping timber retaining wall



120. Site stormwater drainage





121. Refuse container



122. Refuse container with no accessible pathway (Critical Repair)



123. Ground level rear deck enclosed with chain linked fencing



124. Ground level rear deck enclosed with chain linked fencing





125. Ground level rear deck enclosed with chain linked fencing



126. Typical mailbox



127. Typical mailbox



128. Typical mailbox





129. Typical mailbox



130. Typical mailbox



131. Typical mailbox



132. Typical mailbox





133. Typical mailbox



134. Typical mailbox



135. Typical mailbox



136. Representative crawl space with perimeter stem wall insulation





137. Representative crawl space with wood floor joists and moisture barrier



138. Representative crawl space



139. Representative crawl space venting



140. Masonry veneer CMU footing





141. Typical drywall damage from building settling



142. Typical drywall damage from building settling



143. Typical drywall damage from building settling



144. Facade






145. Facade with soffit venting



146. Facade with soffit venting



147. Connected building area stairwell cladding



148. Connected building area stairwell cladding





149. Connected building area stairwell cladding and roof skylight



150. Apartment building end facade



151. Typical window unit



152. Typical window units





153. Typical roof condition



154. Typical roof condition



155. Typical roof condition



156. Typical roof condition





157. Typical roof condition



158. Typical roof condition



159. Typical roof skylight



160. Conjoined covered entry gutter and downspout





161. Typical nat gas fired water heater and furnace



162. Water heater tagging



163. Exterior condensing unit



164. Exterior condensing units






165. Typical nat gas fired water heater and furnace



166. Water heater tagging



167. Typical nat gas fired water heater and furnace



168. Water heater tagging





169. Typical nat gas fired water heater and furnace



170. Exterior condensing units



171. Exterior condensing units



172. Exterior condensing unit tagging





173. Exterior condensing unit tagging



174. Typical dwelling unit meter bank



175. Typical dwelling unit ITE breaker panel



176. Typical dwelling unit meter bank





177. Typical dwelling unit metered service 100-amp main breaker



178. Typical dwelling unit hardwired smoke detection



179. Typical dwelling unit battery operated smoke detection



180. Typical fire extinguisher





181. Typical fire extinguisher

APPENDIX D HUD SAC/PIH Notice



ASSISTANT SECRETARY FOR PUBLIC AND DESIGN MOUSENG

U.S. DEPARTMENT OF HOUSING AND URBAN DEVELOPMENT WASHINGTON, DC 20410-5000

Special Attention of:

Public Housing Agencies (PHAs)
Public Housing Directors
Resident Management Corporations

Notice PIH 2021-07 (HA)

Issued: January 19, 2021

This notice supersedes and replaces Notice PIH 2018-04. This notice remains in effect until amended, superseded or rescinded.

Cross-References: Notices: PIH 2011-7; 2016-13; 2016-20; 2016-22; 2016-23; 2017-10; 2017-22; 2017-24; 2020-04; RAD Final Implementation Notice Revision 4 (H-2019-09 PIH-2019-23 (HA)

Subject: Demolition and/or disposition of public housing property, eligibility for tenant-protection vouchers, and associated requirements.

1) **Purpose.** This notice explains application requirements to request HUD approval to demolish and/or dispose of public housing property under Section 18 of the United States Housing Act of 1937 (42 U.S.C. 1437p) (1937 Act) and related Tenant Protection Voucher (TPV) eligibility for such actions. This notice is used in conjunction with HUD's implementing regulations at 24 CFR part 970 and related rules and applies to all SAC applications, including those under review or already approved by HUD if the PHA is requesting an amendment of HUD's approval.

For purposes of this notice, public housing or public housing property means low-income housing, and all necessary appurtenances thereto, assisted under the 1937 Act, other than assistance under 42 U.S.C. 1437f of the 1937 Act (section 8), and includes public housing units developed pursuant to the mixed-finance development method. The term "project" is defined by section 3(b)(1) of the 1937 Act and means housing developed, acquired, or assisted by a PHA under the 1937 Act, and the improvements of any such housing. Public housing includes non-dwelling property (e.g., vacant land, administrative buildings and community buildings) acquired, developed, modernized, operated, or maintained with 1937 Act funds.

The contents of this notice, except when based on statutory or regulatory authority or law, do not have the force and effect of law and are not meant to bind the public in any way. This document is intended only to provide clarity to the public regarding existing requirements under the law or agency policies.

2) SAC Application Requirements.¹

- **A. Processing.** HUD's Special Applications Center (SAC) reviews applications for demolition and disposition (SAC applications) in accordance with the requirements of 24 CFR part 970. SAC only reviews complete SAC applications. Pursuant to 24 CFR 970.29, HUD disapproves a SAC application if HUD determines: (1) a certification made by the PHA under 24 CFR part 970 is clearly inconsistent with the PHA Plan or any information and data available to or requested by HUD; or (2) the application was not developed in consultation with residents, resident groups, and local government officials.
- **B. PHA Plan.** Proposed demolition or disposition must be included in a PHA Annual Plan, Significant Amendment, or MTW Annual Plan. All PHAs, including qualified PHAs, must discuss the demolition or disposition at a public hearing, as required by 24 CFR 903.17.²
- **C. Environmental Requirements.** Proposed demolitions and disposition must comply with 24 CFR 970.13 and have environmental clearance, which means final approval from a HUD Approving Official or the Responsible Entity of an environmental review conducted under 24 CFR part 50 or 58. See Notice PIH 2016-22. PHAs are responsible for providing the Responsible Entity or local Office of Public Housing (Field Office) with a full description of the activities in connection with the demolition and/or disposition (including relocation, known future use of the site, use of disposition proceeds) to comply with aggregation requirements.³ The site re-use is not limited to future actions by the PHA, but includes any future known re-use. See 24 CFR 970.13(b) for factors in determining what constitutes a known future use.
- **D. Resident Consultation.** In addition to resident consultation for PHA Plans, PHAs must comply with resident consultation requirements under 24 CFR 970.9, including consultation with: (i) residents who may be affected by the demolition or disposition action; (ii) resident organizations for the affected project, if any; (iii) PHA-wide resident organizations, if any; and (iv) the Resident Advisory Board or equivalent body. PHAs must ensure communications and materials are accessible to individuals with disabilities and take reasonable steps to provide meaningful access to persons with Limited English Proficiency (LEP). See section 6)F.5.
- **E.** Offer of Sale to Resident Organizations (Disposition Only). PHAs must, in appropriate circumstances as determined by the Assistant Secretary, provide resident entities the opportunity to purchase the project, subject to certain exceptions. See 24 CFR 970.9(b)(3). A PHA requesting consideration of exceptions to 24 CFR 970.9(b)(1) must follow the process stated at 24 CFR 970.9(b)(4).
- **F. Board Resolution.** A PHA must obtain a signed and dated resolution from its Board of Commissioners authorizing the PHA to submit the SAC application. The Board must be consulted and approve all material parts of the SAC application including the justification;

¹ Note that these items are not a substitute for the SAC application requirements described in 24 CFR part 970 or HUD-52860. Rather, the below provide additional guidance and clarification on certain requirements.

³ See 24 CFR 58.32 and 24 CFR 50.21.

method of disposition (if applicable); use of proceeds; and relocation plan. The authorizing resolution must be dated after all local government and resident consultations are conducted.

- **G. Phased Applications.** PHAs may submit SAC applications through a "phased" method with staggered timelines, so that buildings in later phases remain eligible for Operating Funds. A PHA submits a SAC application in IMS/PIC for each phase, with different relocation start timelines. The same supporting documentation (e.g., board resolution, resident consultation, government consultation) may be used for its all phases. See 24 CFR 970.7(a).
- **H. Amendments.** PHAs must comply with all material terms of the SAC application. If after receiving HUD approval a PHA's plan changes on material terms, SAC approval of the change is required. Material terms include (i) method of disposition; (ii) public bid sale where offer is less than 80% of fair market value (FMV) appraisal submitted in the SAC application (the PHA must describes its due diligence in offering the public housing property for sale on the open and competitive market and its rationale for accepting an offer that is less than 80% of appraised FMV; alternatively, the PHA may submit an updated appraisal); and (iii) terms of commensurate public benefit disposition (the PHA must describe the revised future use of the property so HUD can confirm the commensurate public benefit). PHAs request amendments by sending an email to SACTA@hud.gov with the information noted above and a board resolution approving the change. On a case-by-case basis, SAC may require additional supporting documentation to support an amendment (e.g., evidence of local government and/or resident consultation; confirmation of environmental clearance).

3) Disposition.

A. Justification Criteria for Dwelling Units. HUD reviews PHA certifications and narratives, along with other information available to or requested by HUD, on a case-by-case basis. HUD approves SAC applications for dispositions based on at least one of the following two reasons:

- 1. Retention of the property is not in the best interests of the residents or the PHA. HUD will approve a request for disposition by sale or other transfer of a public housing project or other real property if the PHA certifies that the retention of the property is not in the best interests of the residents, relative to:
 - **a.** Surrounding Area (24 CFR 970.17(a)): The conditions in the area surrounding the project (e.g., density, industrial or commercial development) adversely affect the health or safety of the residents or the feasible operation of the project by the PHA. The PHA supports its application with at least one of the following:
 - (1) Health or safety. PHAs demonstrate conditions that present serious obstacles in maintaining the units as healthy or safe housing and why the PHA cannot cure or mitigate those conditions in a cost-effective manner. HUD encourages PHAs to submit supporting third-party documentation, which include environmental reviews conducted under 24 CFR part 58. HUD may consider other available information, including analyses of land development, socioeconomic, community

- facilities and services, and natural features. In accordance with Notice PIH 2016-22, HUD may elect to perform an environmental review under 24 CFR part 50; or
- (2) Infeasible operation. PHAs demonstrate a lack of demand for the units. Supporting documentation includes evidence the units have long-term vacancy issues, notwithstanding due diligence in marketing (e.g., census tract data on declining population in the jurisdiction; units located in an isolated area with limited access to transportation and infrastructure; high turnover rates). On a case-by-case basis, HUD may require a PHA to submit a market analysis or HUD may perform one.
- b. Improved Efficiency/Effectiveness Through Off-Site Development of Lowincome Housing (24 CFR 970.17(b)). The disposition allows for the development of other properties that will be more efficiently or effectively operated as low-income housing projects. For purposes of this notice, "low-income housing" is limited to public housing units, project-based voucher (PBV) units, or Section 8 PBRA units and does not include housing where tenants are using tenant-based Section 8 Housing Choice Vouchers (HCV). Development may include acquisition (with or without rehabilitation) or new construction. PHAs must demonstrate why the replacement low-income housing units are preferable (e.g., more energy efficient; better unit configuration; better location in terms of transportation, jobs, or schools; furthers minority or economic de-concentration where units are relocated from an area of minority concentration to one that is not concentrated). The units being acquired, developed, or rehabilitated must be off-site. In providing the statement justifying the proposed disposition pursuant to 24 CFR 970.7(a)(5), PHAs explain their intention to acquire, develop, or rehabilitate low-income housing projects. For public housing units, the PHA submits the development proposal to HUD under 24 CFR part 905. For PBV units, the PHA submits an "intent to project-base" notification to the Field Office.
- 2. PHA certifies that it has determined the disposition to be appropriate (24 CFR 970.17(c)). A PHA has determined the disposition to be appropriate for reasons that are in the best interests of the residents and the PHA; consistent with the PHA goals and plans; and otherwise consistent with the 1937 Act. In making such a certification, a PHA considers its need for public housing units, the purpose and mandate of the 1937 Act, the mission and obligations of the PHA to maintain and operate projects as decent and safe housing in accordance with its ACC, and other tools available to the PHA to preserve and reposition its public housing stock. SAC applications are reviewed on a case-by-case basis. Below are examples:
 - **a.** Unit obsolescence. The units are obsolete as to physical condition in accordance with applicable demolition criteria described at section 4)A.1 of this notice.
 - **b.** Very Small PHAs. The PHA owns and operates 50 or fewer public housing units under its ACC and has determined that it is in the best interests of the residents and

PHA to close out its Section 9 public housing program in accordance with Notice PIH 2016-23.

- c. Improved Efficiency/Effectiveness Through On-Site Development of Low-income Housing (24 CFR 970.17(c)). The requirements of Section 3)A.1.b of this notice apply except that the replacement low-income housing units are located on-site. The replacement low-income housing units may be newly constructed or the same public housing units after modernization (rehabilitation).⁴
- **d. Scattered Site Units.** Due to distance between units and lack of uniformity of systems (e.g. HVAC, utilities), the PHA demonstrates an unsustainability to operate and/or maintain the units as public housing. For purposes of this notice, scattered site units generally mean units in non-contiguous buildings with four or fewer total units.
- e. Blending Section 18 Disposition Approvals with Rental Assistance
 Demonstration (RAD) Conversion. The PHA is converting a portion of the public housing units within a Converting Project and is replacing the units proposed for disposition with project-based Section 8 assistance within the Covered Project, as the terms "Converting Project" and "Covered Project" are defined in the RAD Final Implementation Notice Revision 4 (H-2019-09 PIH-2019-23 (HA)), as amended from time to time (the "RAD Notice"). The aggregate number of replacement units (RAD and project-based Section 8) must meet the RAD "substantial conversion of assistance" requirements.
 - (1) RAD/Section 18 Construction Blend. The percentage of units eligible for disposition within the Converting Project is based on the hard construction costs, including general requirements, overhead and profit, and payment and performance bonds, proposed for the new construction or rehabilitation of the Covered Project. To be eligible, the proposed transaction may not use 9% Low Income Housing Tax Credits. The following sets forth the percentage of units eligible for disposition within the Converting Project based on the level of construction activity:
 - (a) If the hard construction costs are equal to or exceed ninety percent (90%) of the Housing Construction Costs as published by HUD for the given market area, at the PHA's discretion up to sixty percent (60%) of the units in the Converting Project may be disposed of under Section 18. For high-cost areas, defined as those where HCC exceeds 120% of the national average,⁵ at the PHA's discretion up to eighty percent (80%) of the units in the Converting Project may be disposed of under Section 18.

5

⁴ If the PHA is proposing to dispose of public housing units to allow the same units to be modernized (rehabilitated) under mixed-finance public housing development rules of 24 CFR part 905, the PHA submits the SAC application under the "MF-MOD" disposition application type in IMS/PIC. This ensures Capital Fund and Operating Fund subsidy are accurate.

⁵ To calculate the national average HCC and the HCC for each jurisdiction, HUD used the average of the 2-BR HCC for Elevator and Walk-up structures.

- (b) If the hard construction costs are equal to or exceed sixty percent (60%) but are less than ninety percent (90%) of the Housing Construction Costs as published by HUD for the given market area, at the PHA's discretion up to forty percent (40%) of the units in the Converting Project may be disposed of under Section 18.
- (c) If the hard construction costs are equal to or exceed thirty percent (30%) but are less than sixty percent (60%) of the Housing Construction Costs as published by HUD for the given market area, at the PHA's discretion up to twenty percent (20%) of the units in the Converting Project may be disposed of Section 18.
- (2) RAD/Section 18 Small PHA Blend. For any PHA with 250 or fewer public housing units under its ACC, at the PHA's discretion up to eighty percent (80%) of the units in a Converting Project may be disposed of under Section 18. The PHA is not required to remove all of its remaining public housing units through a Small PHA Blend transaction. However, to be eligible for the Small PHA blend, the PHA must submit to HUD a feasible repositioning plan approved by the PHA's board of commissioners and acceptable to HUD that removes all of a PHA's public housing ACC units, reflects that the PHA will not develop additional public housing units under otherwise available Faircloth authority, and will not transfer that Faircloth authority to another PHA and will result in the closeout of the PHA's Section 9 public housing program and termination of its Section 9 ACC. Any PBV contract created under this subparagraph must be administered by an HCV contract administrator with at least 250 HCV units under its HCV ACC prior to creation of such PBV contract.

Please see Section 1.5.B of the RAD Notice relating to the applicability of RAD relocation requirements to residents of the Section 18 units and Section 1.6 of the RAD Notice relating to the applicability of RAD requirements to non-RAD units to facilitate the uniform treatment of residents where specified in the RAD Notice.

RAD/Section 18 blends are primarily processed by the Office of Recapitalization and are subject to RAD requirements and processes related to Financing Plan submission requirements, underwriting, DOT releases, terms of the disposition (e.g., treatment of proceeds), and placement of a long-term use agreement at the Covered Project. Notwithstanding processing by the Office of Recapitalization, in addition to RAD requirements, the PHA must also comply with Section 18 submission requirements.

B. Justification Criteria of Non-Dwelling Buildings and Vacant Land. The PHA certifies, by narrative statement and supporting documentation, that disposition of non-dwelling buildings or vacant land meets the criteria of 24 CFR 970.17(d) because the property exceeds the needs of the project after the date of full availability (DOFA); or the disposition of the property is incidental to, or does not interfere with, continued operation of the remaining portion of the project.

C. Commensurate Public Benefit. In accordance with 24 CFR 970.19, dispositions proposed below FMV require a finding of commensurate public benefit, which HUD determines on a caseby-case basis. Generally, the disposed property is developed for affordable housing purposes serving low-income families (incomes at or below 80% of area median). Such affordable housing may include, but is not limited to, public housing, project-based Section 8 housing, and housing developed with low-income housing tax credits (LIHTCs). HUD encourages PHAs to maximize economic opportunities available to residents (as described in section 6)F.5 of this notice) when requesting HUD approval of a below FMV disposition based on commensurate public benefit. PHAs should specifically describe these economic opportunity benefits in their SAC applications as part of the commensurate public benefit description. To ensure compliance with a HUD-approved commensurate public benefit, a use restriction may be required (such that it survives foreclosure of mortgages and other liens) and publicly recorded in the land records. As part of the SAC application, a PHA may propose a preferred form of use restriction (e.g., LIHTC extended use agreement, HOME agreement, reversion clause in transfer documents, provision in ground lease, separate use agreement). The use restriction must be in a form acceptable to HUD. Field Offices will not release the Declaration of Trust/Declaration of Restricted Covenants (DOT/DORC) (HUD-52190) (4/2018) (or previous versions) until the PHA evidences compliance.

4) Demolition.

A. Justification Criteria. HUD reviews demolition requests in accordance with the following criteria: (1) the project or portion of a project is obsolete as to physical condition, location, or other factors, making it unsuitable for housing purposes; and no reasonable program of modifications is cost-effective to return the public housing project or portion of the project to useful life; and (2) in the case of an application for demolition of a portion of a project, the demolition will help to ensure the viability of the remaining portion of the project.

1. Physical Condition (24 CFR 970.15(b)(1)(i) and (b)(2)). PHAs must demonstrate substantial physical issues of the buildings/units (e.g., critical structural issues, deficiencies in major systems, deterioration due to prolonged deferred maintenance) that cannot be corrected in a cost-effective manner. PHAs may submit Physical Needs Assessments (PNAs), government inspections (including condemnation orders), and/or independent architect or engineer's reports as supporting documentation. HUD may consider other available information, including REAC scores; Capital Fund Program Five Year Action Plans, Energy Performance Contracting (EPC) information; and/or on-site inspections by HUD staff. To support a certification of physical obsolescence and cost-ineffectiveness, the PHA submits

_

⁶ In accordance with 24 CFR 905.314(g), PHAs are permitted to rehabilitate and address the capital needs of projects provided the rehabilitation costs do not exceed 90% of total development cost TDC. Accordingly, per 24 CFR 970.15(b)(2), if a project's rehabilitation costs are between 57.14% (or 62.5% if elevator) and 90% of TDC, the PHA may either voluntarily pursue a demolition or disposition action for the project or may rehabilitate the project with Capital Funds. However, if rehabilitation costs for a project exceed 90% of TDC, the PHA's only choice is to pursue a demolition or disposition or use funds other than Capital Funds to address the project's capital needs.

form HUD-52860-A (4/2018) and HUD-52860-B (4/2018), along with a list of specific and detailed work items that require rehabilitation or repair, preferably prepared by an outside engineer or architect, in two components: scope of work and cost-estimates. The following generally applies to the scope of work:

- **a.** Estimates based on the standards outlined in the most recent International Building Code (IBC) and National Fire Protection Association (NFPA) 5000 standards. PHAs may include local code requirements (e.g., fire codes; requirements for natural disasters such as flooding or wildfires);
- b. Building systems (e.g., HVAC, plumbing, electric), external amenities (e.g., roofs, doors, windows), and internal amenities (e.g., kitchens, bathrooms, flooring) limited to those that address immediate capital needs for a maximum of three years. Replacement costs are restricted to the remaining useful life of an item for three years or less. Actual service life may depend on initial quality of the item, local environmental factors, use/abuse, and levels of routine maintenance. Age of an item alone is not evidence of need to repair or replace. Each item is individually estimated and may reference life cycle values per the R.S. Means Facilities Maintenance and Repair Cost Data book;
- **c.** Underground utilities (e.g., sewer, water, gas, electric), regardless of distances, provided the PHA owns the utility and evidences the need for replacement;
- **d.** Mitigation costs of asbestos, lead-based paint, or other environmental issues supported by reports submitted with the SAC application;
- **e.** Structural defects when supported by reports from a licensed professional engineer;
- f. Accessibility improvements for persons with mobility, vision, hearing or other impairments, provided improvements are consistent with standards, regulations, and other requirements under Section 504 of the Rehabilitation Act of 1973 (including the Uniform Federal Accessibility Standards (UFAS)), Fair Housing Act, Americans with Disabilities Act, other applicable federal authorities, state or local requirements that exceed federal baseline requirements, and accessibility requirements in remedial agreements or orders;
- **g.** Imminent health and/or safety issues even if such costs are otherwise not eligible provided the PHA provides supporting documentation from an independent party evidencing the occurrence and resulting health and/or safety risks.

HUD reserves the right to disallow items in a scope of work if HUD determines there are more cost-effective alternatives to address the rehabilitation or replacement needs. If PHAs complete major capital work after the scope of work is prepared, the PHA must include a description of that work in the SAC application. HUD generally does not allow the following costs to be included in a rehabilitation scope of work:

- **a.** Work associated with enhancements or improvements of working systems or fixtures at the project (including energy efficiency "green" improvements);
- **b.** Amenities not currently existing at the project (e.g., solar panels; tankless water heaters; trash enclosures, washer/dryer hook-ups; garbage disposals; central airconditioning; addition of new porches);
- **c.** Work items that address a project's needs beyond three years;
- **d.** Local code compliance if the building code requirements are otherwise not triggered by the rehabilitation/repair;
- **e.** Landscaping or other site work beyond five feet of the exterior walls of a building;
- **f.** Upgrading utility lines that are otherwise in working condition;
- **g.** Work items associated with site improvements and appurtenances (e.g., parking lots, security cameras, playgrounds, community centers), even if those site improvements or appurtenances exist and in need of repairs; and
- **h.** Replacing PHA personal property (e.g., replacing appliances or other removable fixtures such as refrigerators, ovens, and window treatments).

The following generally applies to cost estimates of the eligible scope of work items:

- **a.** Total development costs (TDC) comparisons per HUD-posted costs for the year the rehabilitation estimate is made. See 24 CFR 905.314.
- **b.** R.S. Means cost index, Marshall and Swift cost index, or other accurate and reliable cost estimates (e.g., actual and competitive bids).
- **c.** Hard construction costs (HCC) as defined in 24 CFR part 905 (including existing items inside a building or within five feet of the exterior walls; and costs to repair landscaping damaged due to rehabilitation).

PHAs may not include additional costs attributable to inflation or "cost escalation." For example, if a PNA completed in 2017 indicates a roof replacement is necessary in 2019, the PHA must use current estimated costs without any escalation, cost adjustments or other means of adjusting for inflation for work projected to be undertaken/completed in 2019. Instead, the PHA uses 2017 cost index information.

The following fees are maximum amounts for soft costs associated with public housing rehabilitation.⁷ PHAs may flexibly determine costs for each item provided the total cost does not exceed the maximum. Percentages are based on hard construction and will vary based on the project size:

- a. Construction contingency: 7.5 percent
- **b.** Architectural/engineer's design and construction monitoring fees: 5.5 percent
- **c.** Profit and overhead fees for specialty subcontractor (e.g. HVAC, electric, plumbing, elevator): 10 percent
- **d.** General condition fees (e.g., permit, insurance, bonds): 5 percent
- e. PHA administrative costs: 2 percent
- 2. Location (24 CFR 970.15(b)(1)(ii) and (b)(2)). PHA demonstrates the location of the units causes obsolescence, including physical deterioration of the neighborhood; change in neighborhood from residential to industrial or commercial; or environmental conditions which jeopardize the suitability of the site or a portion of the site and its housing structures for residential use. The cost test for obsolescence based on location includes the PHA's cost to cure the obsolescence (e.g., buffering nearby industrial or commercial development; mitigating environmental conditions) and whether these costs exceed applicable TDC percentages. In some cases, there may be no way to cure the obsolescence, regardless of cost (e.g., project is in a Federal Emergency Management Agency (FEMA) designated floodway). In other cases, the obsolescence may be curable with a mitigation cost (e.g., flood-proofing and flood insurance for designated floodplains).
- 3. Other Factors (24 CFR 970.15(b)(1)(iii) and (b)(2)). PHA demonstrates factors impacting the marketability, usefulness, or management of the units that seriously impede operations for residential use supported by third party documentation. The cost test for obsolescence based on other factors includes the PHA's cost to cure the cause and whether these costs exceed applicable TDC percentages. In some cases, curing the obsolescence is not possible regardless of costs. In cases where the obsolescence may be curable, include the PHA's cost of due diligence in marketing and to cure obsolete factors (e.g., cost to add a second bathroom to units with a high number of bedrooms).
- **B.** *De Minimis* **Demolition.** In any 5-year period, a PHA may demolish the lesser of 5 dwelling units or 5 percent of the total public housing dwelling units without the need to obtain HUD approval under 24 CFR part 970, provided the resulting space is used to meet the service or other needs of the residents or the PHA determines the unit(s) are beyond repair. Demolition criteria of 970.15 do not apply to *de minimis* demolitions. Prior to

_

⁷ HUD may consider higher percentages for soft costs for compelling reasons on a case-by-case basis.

demolishing units under this authority, the PHA must submit information to HUD via IMS/PIC, including a description of the proposed units and other items required by 24 CFR 970.7(a)(1), (2), (12), (13), and (14).

5) Eligibility and Application Process for Tenant-Protection Vouchers (TPVs).

A. TPV Eligibility. As part of HUD's approval of a SAC application, a PHA may be eligible to receive Section 8 HCV assistance from HUD in the form of TPVs. The issuance of TPVs to a PHA does not occur with SAC approval of an application. Instead, the PHA must apply separately for TPVs in accordance with the current PIH funding notice for the HCV program.

HUD determines a PHA's TPV award based on the relevant appropriations and other HUD-issued guidance (including the applicable year's HCV funding notice). HUD's approval of the SAC application indicates the maximum number of both relocation and replacement TPVs that a PHA may be eligible to receive.

Based on limited availability of TPV funding, HUD is limiting the maximum TPV awards for dispositions based on improved efficiency or effectiveness under Section 3)A.1.b or 3)A.2.c of this notice to 25 percent of the occupied units at the project. However, even if a PHA is not eligible to receive TPVs in a SAC-approved disposition, the PHA must still comply with relocation requirements of 24 CFR 970.21.

B. TPV Application Process. A PHA must submit the following to the Field Office:

- 1. Name and IMS/PIC number for the units approved in the SAC application. Number of TPVs (both relocation and replacement) requested which must equal or be less than the maximum number of TPVs identified in the SAC approval and address relevant appropriation limits including HUD TPV guidance. See Notice PIH 2017-10 (or the current replacement PIH funding notice for the HCV program) concerning the differences between replacement and relocation TPVs.
- **2.** Form HUD-52515 (Voucher Funding Application). If lease-up covers more than one calendar year, the PHA must submit a separate Form HUD-52515 for each calendar year.
- **3.** Leasing schedule identifying the number of TPVs leased on a month-to-month basis. If lease-up covers more than one calendar year, the PHA must submit separate leasing schedules for each calendar year. If the PHA is approved for both replacement and relocation TPVs as part of the same SAC approval, the PHA must submit separate leasing schedule(s) for each type of TPV.
- **4.** SAC application approval as a PDF copy, signed and dated.
- **5.** If the PHA is a Public Housing-only PHA (and therefore cannot receive or administer TPVs), the name and PHA code of the PHA that has agreed to administer the TPVs, along with an agreement letter from that PHA. HUD does not allow Public Housing-only PHAs to create Section 8 HCV programs based solely on TPV eligibility.

The Field Office conducts a threshold review of the TPV request prior to sending the request to HUD's Financial Management Division (FMD) for processing. HUD's Financial Management Center (FMC) notifies PHAs of final TPV awards.

6) Other Requirements.

- **A. Existing Financial Transactions.** PHAs with an approved transaction through the Capital Fund Financing Program (CFFP), Section 30 (including PHA Mortgaged Transaction (PMT)), Energy Performance Contracting (EPC), or Operating Fund Financing Program (OFFP) must comply with additional instructions provided by HUD regarding such financing and may not take any steps to implement a SAC-approved application without receiving confirmation from HUD that all applicable requirements of the financing are satisfied. PHAs must certify an existing financial agreement is not at risk because of the proposed demolition or disposition action.
- **B. Operating Fund Accuracy. Updating Days to Relocation.** As part of the SAC application, PHAs include an estimated number of days from a SAC-approved application that it plans to start relocation. HUD recognizes relocation plans sometimes change. However, because HUD relies on relocation information to determine Operating Funds, PHAs are responsible to ensure the relocation information remain reasonably accurate. If days to relocation in a SAC application is not reasonably accurate, Asset Repositioning Fee (ARF) payments under 24 CFR 990.190 will be affected. See Notice PIH 2017-22 on how to update relocation dates.
- C. Re-occupying Units Proposed for Demolition or Disposition. 24 CFR 970.25(a) states a PHA should not re-rent units at turnover while HUD is considering a SAC application. However, due to community needs or for other reasons consistent with its PHA Plan, a PHA may decide it is in the best interests of the PHA, its residents, and the community to re-occupy vacated units that are under SAC review. If the PHA proposes demolition or disposition because units are structurally unsound, located in a floodway, or otherwise uninhabitable, the PHA cannot reoccupy the units. PHAs cannot re-occupy units after issuance of the 90-day relocation notice.
- **D. Reporting Requirements.** Within seven days of completion of the demolition or disposition (e.g., execution of the sale or lease contract for disposition), PHAs must report the action in IMS/PIC. On a case-by-case basis, HUD may require other reporting information.
- **E**. **False Certifications and HUD Enforcement.** Any person knowingly presenting a false, fictitious or fraudulent statement or claim in a HUD matter, including certifications and supporting documentation submitted with SAC applications, is subject to criminal penalties, civil liability, or administrative actions which HUD may prosecute. HUD may pursue debarment/suspensions of principals and PHAs, and any enforcement actions available including, but not limited to, injunctive relief and other equitable remedies.
- **F. Civil Rights Requirements.** This notice does not modify a PHA's fair housing, civil rights, or accessible housing obligations. It does clarify those obligations with respect to public housing demolition/disposition under Section 18.

- 1. PHA Certification. As part of the SAC application, PHAs certify they will carry out the removal action in compliance with all applicable civil rights requirements, including Title VI of the Civil Rights Act of 1964, the Fair Housing Act, Section 504 of the Rehabilitation Act of 1973, Title II of the Americans with Disabilities Act of 1990, all regulations implementing these authorities, other applicable Federal, State, and local civil rights laws, and the duty to affirmatively further fair housing. A PHA's certification means that it will fulfill the requirements set out in HUD regulations found at Title 24 of the Code of Federal Regulations, including regulations in place at the time of this certification, and any subsequently promulgated regulations governing the obligation to affirmatively further fair housing. The PHA is always responsible for understanding and implementing the requirements of HUD regulations and policies, and has a continuing obligation to affirmatively further fair housing in compliance with the 1968 Fair Housing Act, the Housing and Community Development Act of 1974, The Cranston-Gonzalez National Affordable Housing Act, and the Quality Housing and Work Responsibility Act of 1998. (See 42 U.S.C. 3608, 5304(b)(2), 5306(d)(7)(B), 12705(b)(15), and 1437C-1(d)(16)). PHAs also certify that, if HUD approves the SAC application, subsequent implementation complies with all applicable civil rights requirements, including environmental determinations for environmental justice.
- 2. HUD Civil Rights Review. HUD's Office of Fair Housing and Equal Opportunity (FHEO) conducts a civil rights review of SAC applications, which may include applications for non-dwelling property. Pursuant to 24 CFR 970.7(a)(17), HUD may request additional information, including information about the PHA's compliance with nondiscrimination requirements in relocations under 24 CFR 970.21(a) and the PHA's affirmatively furthering fair housing certification under 24 CFR 903.7(o).
- 3. Disclosure of Remedial Orders and Compliance Agreements. In its SAC application, the PHA provides a certification that the demolition or disposition does not violate any remedial civil rights order or agreement, voluntary compliance agreement, final judgment, consent decree, settlement agreement, or other court order or agreement (per 24 CFR § 970.9(a)(16)). In addition, the PHA states whether it is operating under any federal, state, or local remedial order, compliance agreement, final judgment, consent decree, settlement agreement or other court order or agreement, including but not limited to those related to a fair housing or other civil rights finding of noncompliance. If the PHA is operating under such a document, it must provide a citation to the document and attach a narrative description explaining how the proposed demolition or disposition is consistent with such document.
- **4. Federal Labor Standards and Economic Opportunity.** PHAs using HUD funds for demolition or disposition must comply with all applicable federal labor standards of Section 12 of the 1937 Act (42 U.S.C. 1437j) (Davis-Bacon) and requirements of Section 3 of the Housing and Urban Development Act of 1968 (12 U.S.C 1701u), as amended. Activities include but are not limited to demolition and resident relocation. Under Section 3 and 24 CFR part 75, recipients of certain HUD financial assistance must provide employment, training, and economic opportunities to the greatest extent feasible

to Section 3 residents or business concerns. Recipients of HUD funds have Section 3 obligations regardless of the amount of funds (see 24 CFR 75.3).

- 5. Resident Consultation for Persons with Disabilities and Persons with Limited **English Proficiency.** To ensure individuals with disabilities have reasonable opportunities to consult on the SAC application, PHAs must ensure communications and materials are accessible and in compliance with Section 504 of the Rehabilitation Act of 1973, 24 CFR 8.6, and the Americans with Disabilities Act of 1990, 28 CFR parts 35.160-35.163. This includes ensuring written and oral communications, including resident meetings, are provided in appropriate alternative formats as needed, e.g., Braille, audio, large type, accessible electronic communications, assistive listening devices, sign language interpreters, computer-assisted real time transcription of meetings, Brailled materials, large print documents, accessible web-based and email communications, and when providing materials via the Web. In selecting locations for consultation with residents, the PHA must provide equal access for persons with disabilities, conducting sessions at locations that are physically accessible to persons with disabilities, including individuals who use wheelchairs. Individuals with disabilities must receive services in the most integrated setting appropriate to their needs, meeting the needs of qualified individuals with disabilities that enables interactions to the fullest extent possible. The PHA is guided by the goal of maximizing participation in an integrated setting so that residents with disabilities and residents without disabilities may hear and consider each other's views. Priority shall be given to on-site accessible locations (e.g., TV rooms or informal gathering places) even if to do so requires multiple sessions with smaller groups of residents. Title VI of the Civil Rights Act of 1964 and regulations at 24 CFR part 1, require PHAs to take reasonable steps to ensure meaningful access to their programs and activities for persons who have limited ability to read, speak, or understand English (i.e., individuals who have limited English proficiency or LEP persons). Written materials provided in English are to be provided in regularly encountered languages among the residents. PHAs may need to provide interpreters to communicate between different languages to ensure LEP persons have meaningful access. PHAs hold meetings in languages other than English to provide direct communication and participation.
- 7) Relocation of Residents. If residents are relocated due to a demolition and/or disposition, the PHA must follow relocation requirements at 24 CFR 970.21, and not the relocation requirements at 49 CFR part 24, which implements the Uniform Relocation Assistance and Real Property Acquisition Policies Act of 1970 (URA), as amended. However, if subsequent acquisition, rehabilitation or demolition carried out with HUD funds or carried out with other HUD-funded activities causes residents to relocate, the URA may apply to those relocations. Additionally, if CDBG or HOME funds are used in the demolition or with conversion of lower-income dwelling units to a use other than lower-income dwelling units, the project may be subject to section 104(d) of the Housing and Community Development Act of 1974, including relocation assistance and one-for-one replacement provisions under 24 CFR part 42 subpart C.
- 8) Technical Assistance. Contact SACTA@hud.gov.

9) Paperwork Reduction Act. Information collection requirements contained in this notice are
approved by the Office of Management and Budget (OMB) under the Paperwork Reduction Act
of 1995 (44 U.S.C. 3501-3520). The OMB control numbers are 2577-0029, 2502-0612 and
2577-0075.

APPENDIX E HUD TDC Calculation and HUD Form 52860-B



2022 UNIT TOTAL DEVELOPMENT COST (TDC) LIMITS

Number of Bedrooms

	U		1		2		3		4		3		0
HCC	TDC	HCC	TDC	HCC	TDC	HCC	TDC	HCC	TDC	HCC	TDC	HCC	TDC
500) sqft	700	sqft	900	sqft	1200	sqft	1500	sqft	1700) sqft	1900	sqft
117,759	206,078	152,626	267,096	182,284	318,997	217,104	379,932	255,420	446,985	280,005	490,009	303,725	531,519
93,266	163,215	121,980	213,465	147,567	258,243	180,183	315,321	213,567	373,742	235,231	411,654	255,443	447,026
89,699	156,973	122,458	214,302	155,172	271,550	204,635	358,111	253,674	443,930	285,897	500,319	317,742	556,049
95,285	152,456	133,399	213,439	171,513	274,421	228,684	365,895	285,855	457,369	323,970	518,351	362,084	579,334
108,100	189,175	140,223	245,390	167,568	293,244	199,717	349,505	235,054	411,345	257,730	451,027	279,656	489,399
84,884	148,548	111,176	194,557	134,663	235,660	164,723	288,265	195,384	341,922	215,292	376,760	233,893	409,313
81,086	141,900	110,562	193,484	139,996	244,992	184,518	322,907	228,639	400,119	257,607	450,812	286,217	500,880
87,086	139,338	121,920	195,073	156,755	250,808	209,007	334,410	261,258	418,013	296,093	473,748	330,927	529,483
	117,759 93,266 89,699 95,285 108,100 84,884 81,086	117,759 206,078 93,266 163,215 89,699 156,973 95,285 152,456 108,100 189,175 84,884 148,548 81,086 141,900	HCC TDC HCC 500 sqft 700 117,759 206,078 152,626 93,266 163,215 121,980 89,699 156,973 122,458 95,285 152,456 133,399 108,100 189,175 140,223 84,884 148,548 111,176 81,086 141,900 110,562	HCC TDC HCC TDC 500 sqft 700 sqft 117,759 206,078 152,626 267,096 93,266 163,215 121,980 213,465 89,699 156,973 122,458 214,302 95,285 152,456 133,399 213,439 108,100 189,175 140,223 245,390 84,884 148,548 111,176 194,557 81,086 141,900 110,562 193,484	HCC TDC HCC TDC HCC 500 sqft 700 sqft 900 117,759 206,078 152,626 267,096 182,284 93,266 163,215 121,980 213,465 147,567 89,699 156,973 122,458 214,302 155,172 95,285 152,456 133,399 213,439 171,513 108,100 189,175 140,223 245,390 167,568 84,884 148,548 111,176 194,557 134,663 81,086 141,900 110,562 193,484 139,996	HCC TDC HCC TDC HCC TDC 500 sqft 700 sqft 900 sqft 117,759 206,078 152,626 267,096 182,284 318,997 93,266 163,215 121,980 213,465 147,567 258,243 89,699 156,973 122,458 214,302 155,172 271,550 95,285 152,456 133,399 213,439 171,513 274,421 108,100 189,175 140,223 245,390 167,568 293,244 84,884 148,548 111,176 194,557 134,663 235,660 81,086 141,900 110,562 193,484 139,996 244,992	HCC TDC HCC TDC HCC TDC HCC HCA HCA <td>HCC TDC HCC TDC HCC TDC HCC TDC HCC TDC J200 sqft TDC J200 sqft J200 sqft</td> <td>HCC TDC HCC TDC HCC TDC HCC TDC HCC $I200$ $I200$</td> <td>HCC TDC HCC HCC TDC HCC HCA HCA HCA HCA HCA HCA<td>HCC TDC HCC TDC HCC TDC HCC TDC HCC TDC HCC $I200$ sqft I</td><td>HCC TDC HCC ISO ISO III <t< td=""><td>HCC TDC HCC TDC TDC HCC TDC <t< td=""></t<></td></t<></td></td>	HCC TDC HCC TDC HCC TDC HCC TDC HCC TDC J200 sqft TDC J200 sqft J200 sqft	HCC TDC HCC TDC HCC TDC HCC TDC HCC $I200$	HCC TDC HCC HCC TDC HCC HCA HCA HCA HCA HCA HCA <td>HCC TDC HCC TDC HCC TDC HCC TDC HCC TDC HCC $I200$ sqft I</td> <td>HCC TDC HCC ISO ISO III <t< td=""><td>HCC TDC HCC TDC TDC HCC TDC <t< td=""></t<></td></t<></td>	HCC TDC HCC TDC HCC TDC HCC TDC HCC TDC HCC $I200$ sqft I	HCC TDC HCC ISO ISO III <t< td=""><td>HCC TDC HCC TDC TDC HCC TDC <t< td=""></t<></td></t<>	HCC TDC HCC TDC TDC HCC TDC <t< td=""></t<>

Report Title: TDC for all building types-5/10/2022 8:15:20 AM

Printed on: 5/24/2022

Total Development Cost (TDC) and Rehab Cost Estimate Addendum HUD-52860-B

U.S. Department of Housing and Urban Development Office of Public and Indian Housing

OMB Approval No. 2577-0075 (exp. 08/31/2023)

The information collection requirements contained in this document have been approved by the Office of Management and Budget (OMB) under the Paperwork Reduction Act of 1995 (44 U.S.C. 3501-3520) and assigned OMB control number 2577-0075. There is no personal information contained in this application. Information on activities and expenditures of grant funds is public information and is generally available for disclosure. Recipients are responsible for ensuring confidentiality when disclosure is not required. In accordance with the Paperwork Reduction Act, HUD may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the collection displays a currently valid OMB control number.

This information is required as a supplement to the HUD-52860 for all SAC applications that propose a demolition under 24 CFR 970.15 or a disposition under 24 CFR 970.17 based on physical obsolsence. HUD will use this information to determine whether, and under what circumstances, to approve SAC applications as well as to track removals for other record keeping requirements. Responses to this collection of information are statutory and regulatory to obtain a benefit. All terms not defined in this form have the meanings as 24 CFR part 970 and PIH notice 2018-04 (or any replacement notice). The information requested does not lend itself to confidentiality.

1. SAC Application Number in IMS	/PIC	DDA	
Project (AMP) Name & Number in	i IMS/PIC	Hawk View Apartments	
2. Housing Construction Cost (HCC) Calculation		
Based on HUD Notice	PIH-2021-07	Year: <u>2022</u>	For Locality: Reno, Nevada

Complete the calculations below for the unit proposed for demolition and/or disposition based on physical obsolescence:

Size - Type	Number of units	Times	TDC Per Unit	= TDC
0 - Bdr Detached and Semi detached		X		\$0.00
0 - Bdr Row Dwelling		X		\$0.00
0 - Bdr Walk-Up		X		\$0.00
0 - Bdr elevator		X		\$0.00
1 - Bdr Detached and Semi detached		X		\$0.00
1 - Bdr Row Dwelling		X		\$0.00
1 - Bdr Walk-Up		X		\$0.00
1 - Bdr elevator		X		\$0.00
2 - Bdr Detached and Semi detached		X		\$0.00
2 - Bdr Row Dwelling		X		\$0.00
2 - Bdr Walk-Up	100	X	\$ 244,992.00	\$24,499,200.00
2 - Bdr elevator		X		\$0.00
3 - Bdr Detached and Semi detached		X		\$0.00
3 - Bdr Row Dwelling		X		\$0.00
3 - Bdr Walk-Up		X		\$0.00
3 - Bdr Elevator		X		\$0.00
4 - Bdr Detached and Semi detached		X		\$0.00
4 - Bdr Row Dwelling		X		\$0.00
4 - Bdr Walk-Up		X		\$0.00
4 - Bdr Elevator		X		\$0.00
5 - Bdr Detached and Semi detached		X		\$0.00
5 - Bdr Row Dwelling		X		\$0.00
5 - Bdr Walk-Up		X		\$0.00
5 - Bdr Elevator		X		\$0.00
6 - Bdr Detached and Semi detached		X		\$0.00
6 - Bdr Row Dwelling		X		\$0.00
6 - Bdr Walk-Up		X		\$0.00
6 - Bdr Elevator		X		\$0.00
Total Units	100			\$24,499,200.00

3. Estimated Cost of Rehabilitation	\$15,002,999
Attach a document showing rehabalition needs by line item and dollar amount	
4. Rehabilitation Cost % (estimated cost of Rehabilitation/Total HCC) x 100 =	61.24%

Instructions Form HUD-52860-B

Refer to SAC website at www.hud.gov/sac for more information

PHAs proposing to demolish or dispose of public housing developments based on physical obsolosecence under 24 CFR part 970 must complete this HUD-52860-B in order to demonstrate to HUD that no reasonable program of modification is cost-effective to return the development to their useful life.

Item 1: Insert the number of the PIH Notice from which the PHA extracted the Total Development Cost (TDC) data. The year of the PIH Notice should coincide with the year the rehabilitation estimate was generated, which should not be more than two years prior to the SAC application submission date. Insert the name of the nearest locality to the proposed developments.

Item 2: TDC Calculation: Complete the TDC calculation for the proposed developments.

Item 3: Rehabilitation Calculation: Attach a document showing rehabilitation needs by line item and dollar amount for the proposed developments in accordance with 24 CFR 970.15 and PIH notice 2018-04 (or any replacement notice). Soft costs associated with the rehabilitation (e.g. construction contingency, architectural/engineer's design and construction monitoring fees; profit & overhead fees for specialty sub-contractor; general condition fees; and PHA administrative costs) should all be listed as separate line items. Certain costs may require additional third-party documentation. See PIH notice 2018-04 (or any replacement notice).

APPENDIX F Property Substantial Renovation Estimate



Date:	04/21/2023			Gross Square Feet:	98,600
Project:	Hawk View	Substantial Rehabiltation Estimate	Net Le	easable Square Feet:	86,500
Address:	1548 Steelwood Lane	2-story Wood-frame Multifamily Walk-up Apartment Buildings		Number of Units:	100
City, State:	Reno, NV		R.S.	Means City Source:	Reno, NV (894-895)
		R.S. Means Year 2022 Quarter 2	Labor Type (Standard or Union):	Residential/DBWR

Quantity	Line Item No.	R.S. Means Line Item Description	Unit	Unit Cost		Total
		Costs included are for demolition/construction debris containment and removal, demolition work need for foundation and building				
	Existing Conditions	repairs.			\$	851,629.20
500	024119166100	Selective demolition, cutout, drywall, to 5/8" thick, openings to 5 S.F., excludes re-framing, loading and disposal	Ea.	\$ 14.57	\$	7,285.00
		Selective demolition, cutout, wood frame, roofs, sheathing, to 1" thick, openings to 5 S.F., excludes re-framing, roofing, loading and				
200	024119167310	disposal	Ea.	\$ 58.38	\$	11,676.00
400	024119167410	Selective demolition, cutout, wood frame, walls, sheathing, to 1" thick, openings to 5 S.F., excludes re-framing, siding, loading and disposal	Ea.	\$ 49.97	\$	19,988.00
		Selective demolition, rubbish handling, dumpster, 40 C.Y., 10 ton capacity, weekly rental, includes one dump per week, cost to be added to				
10	024119190840	demolition cost	Week	\$ 850.00	\$	8,500.00
40	024119192000	Selective demolition, rubbish handling, 0'-50' haul, load, haul, dump and return, hand carried, cost to be added to demolition cost	C.Y.	\$ 28.95	\$	3,474.00
40	024119192005	Selective demolition, rubbish handling, 0'-50' haul, load, haul, dump and return, wheeled, cost to be added to demolition cost	C.Y.	\$ 18.68	\$	747.20
420	024440200400		-	\$ 81.00		0.720.00
120	024119200100	Selective demolition, dump charges, typical urban city, building construction materials, includes tipping fees only	Ton	\$ 81.00	\$	9,720.00
3,100	060505106140	Selective demolition, wood framing, wood framing, sheathing from walls, 5/8", from walls	S.F.	\$ 0.57	\$	1,767.00
1300	060505201000	Selective demolition, millwork and trim, wood base cabinets	L.F.	\$ 7.88	\$	10,244.00
1300	060505201020	Selective demolition, millwork and trim, wood wall cabinets	L.F.	\$ 7.88	\$	10,244.00
1300	060505201500	Selective demolition, millwork and trim, counter top, straight runs	L.F.	\$ 3.15	\$	4,095.00
32300	090505200850	Selective demolition, millwork and trim, vinyl or rubber cove base	L.F.	\$ 0.43	\$	13,889.00
100	028200000000	Hazardous Material Remediation: Allowance Per Unit; VCT mastic, insulation, drywall	Ea.	\$ 7,500.00	\$	750,000.00
					\$	-
	Concrete	Costs included are for concrete replacement of footings and slabs as a result of foundation repairs and plumbing piping repair/replacement.			\$	1,589,362.50
25	Contractor Quote	Push-pile support of Interior continuous footing	Bldg.	\$ 42,383.00	\$	1,059,575.00
25	AEI Estimate	Allowance for Exterior continuous footing repair (1/2 interior cost)	Bldg.	\$ 21,191.50	\$	529,787.50
					ć	
					\$	-

Date:	04/21/2023			Gross Square Feet:	98,600
Project:	Hawk View	Substantial Rehabiltation Estimate	Net Le	easable Square Feet:	86,500
Address:	1548 Steelwood Lane	2-story Wood-frame Multifamily Walk-up Apartment Buildings		Number of Units:	100
City, State:	Reno, NV		R.S.	Means City Source:	Reno, NV (894-895)
		R.S. Means Year 2022 Quarter 2	Labor Type (Standard or Union):	Residential/DBWR

Quantity	Line Item No.	R.S. Means Line Item Description	Unit	Unit Cost		Total
		Costs included are for replacement of damaged masonry as well as technical pointing of brick veneer (approximately 30%) and final				
30%	Masonry	clean-up.			\$	187,518.94
		Brick veneer masonry, buff or grey brick, running bond, truckload lots, 6.75/SF, 4" x 2-2/3" x 8", includes 3% brick and 25% mortar waste,				
5967	042113132600	excludes scaffolding, grout and reinforcing	S.F.	\$ 18.47	\$	110,210.49
5967	040505105020	Selective demolition, masonry, veneers, brick, hard mortar, remove	S.F.	\$ 3.34	\$	19,929.78
5967	040120200300	Pointing masonry, tuck, cut and re-point, hard mortar, running bond	S.F.	\$ 6.86	\$	40,933.62
2386.8	040120520300	Cleaning masonry, heavy restoration, light soil, by chemical, high pressure wash, brush and rinse, excludes scaffolding	S.F.	\$ 1.49	\$	3,556.33
		Cleaning masonry, heavy restoration, average soil, biological staining, by chemical, high pressure wash, brush and rinse, excludes				
2386.8	040120520310	scaffolding	S.F.	\$ 2.22	\$	5,298.70
		Cleaning masonry, heavy restoration, heavy soil, biological and mineral staining, paint, by chemical, high pressure wash, brush and rinse,				
1193.4	040120520320	excludes scaffolding	S.F.	\$ 3.51	\$	4,188.83
5967	040120524000	Cleaning masonry, add for masking doors and windows	S.F.	\$ 0.57	\$	3,401.19
					\$	-
	Metals	Costs included are for missing metal railings needed as noted, accessibility deficiency.			\$	25,203.00
200	057323500550	Railing, ornamental, steel, 3'-6" high, posts @ 6' OC, panelized, plain	L.F.	\$ 103.15	¢	20,630.00
200	03/323300330	naming, arramental, steer, 5 o mgm, posts ee o oe, panenzea, piani	L.I.	ψ 103.15	٠	20,030.00
100	055213500940	Railing, pipe, steel, wall rail, primed, 1-1/2" diameter, shop fabricated	L.F.	\$ 45.73	\$	4,573.00
					١.	
					\$	-

Date:	04/21/2023			Gross Square Feet:	98,600	
Project:	Hawk View	Substantial Rehabiltation Estimate	Substantial Rehabiltation Estimate Net Leasable Square Fr			
Address:	1548 Steelwood Lane	2-story Wood-frame Multifamily Walk-up Apartment Buildings		Number of Units:	100	
City, State:	Reno, NV		R.S.	Means City Source:	Reno, NV (894-895)	
		R.S. Means Year 2022 Quarter 2	Labor Type (Standard or Union):	Residential/DBWR	

Quantity	Line Item No.	R.S. Means Line Item Description	Unit	Unit Cost	Total
	Rough Carpentry	Costs included are for correction of settlement issues that was observed at walls and openings. Select areas of wood frame floors were observed with warping and buckling. Signs of water damage was observed at several floor joists and roof framing.			\$ 345,182.27
5,000	0302028	Floor framing systems, 2" x 8", 16" OC	S.F.	\$ 9.53	\$ 47,650.00
10,000	0302038	Floor framing systems, 2" x 10", 16" OC	S.F.	\$ 10.59	\$ 105,900.00
1,000	0308026	Exterior wall framing systems, 2" x 4", 16" OC	S.F.	\$ 6.07	\$ 6,070.00
500	0308042	Exterior wall framing systems, 2" x 6", 16" OC	S.F.	\$ 6.94	\$ 3,470.00
800	0312034	Gable end roof framing systems, 2" x 6" rafters, 16" OC, 4/12 pitch	S.F.	\$ 9.26	\$ 7,408.00
800	0312046	Gable end roof framing systems, 2" x 8" rafters, 16" OC, 4/12 pitch	S.F.	\$ 10.64	\$ 8,512.00
1,000	0348026	Interior partition framing systems, 2" x 4", 16" OC	S.F.	\$ 2.60	\$ 2,600.00
500	0348042	Interior partition framing systems, 2" x 6", 16" OC	S.F.	\$ 3.31	\$ 1,655.00
5,000	061110022620	2" x 4" miscellaneous wood blocking, to wood construction	B.F.	\$ 4.74	\$ 23,690.50
2,600	061110022660	2" x 8" miscellaneous wood blocking, to wood construction	B.F.	\$ 3.63	\$ 9,426.77
9,600	0660038	Plywood, 1/2" thick	S.F.	\$ 4.36	\$ 41,856.00
16,000	0660039	Plywood, 5/8" thick	S.F.	\$ 4.46	\$ 71,360.00
3,200	0660040	Plywood, 3/4" thick	S.F.	\$ 4.87	\$ 15,584.00
					\$ -

Date:	04/21/2023			Gross Square Feet:	98,600
Project:	Hawk View	Substantial Rehabiltation Estimate	Net Le	easable Square Feet:	86,500
Address:	1548 Steelwood Lane	2-story Wood-frame Multifamily Walk-up Apartment Buildings		Number of Units:	100
City, State:	Reno, NV		R.S.	Means City Source:	Reno, NV (894-895)
		R.S. Means Year 2022 Quarter 2	Labor Type (Standard or Union):	Residential/DBWR

Quantity	Line Item No.	R.S. Means Line Item Description	Unit	Unit Cost	Total
75%	Finish Carpentry	Costs included are for replacement of kitchen and bath cabinets due to condition and access to replace the plumbing piping. Interior trim due to settlement issues, plumbing replacement, window and door replacement.			\$ 283,608.95
1,100	060505201000	Selective demolition, millwork and trim, wood base cabinets	L.F.	\$ 7.71	\$ 8,481.00
1,100	060505201020	Selective demolition, millwork and trim, wood wall cabinets	L.F.	\$ 7.71	\$ 8,481.00
1,100	060505201500	Selective demolition, millwork and trim, counter top, straight runs	L.F.	\$ 3.10	\$ 3,410.00
13600	062213300110	Moldings, casings, apron, 5/8" x 3-1/2", pine	L.F.	\$ 4.39	\$ 59,704.00
8287.5	062213400330	Exterior trim and moldings, band board, pine, #2, 1" x 4"	L.F.	\$ 2.95	\$ 24,448.13
8287.5	062213400350	Exterior trim and moldings, band board, pine, #2, 1" x 8"	L.F.	\$ 3.92	\$ 32,487.00
4143.75	062213400370	Exterior trim and moldings, band board, pine, #2, 1" x 12"	L.F.	\$ 5.51	\$ 22,832.06
8287.5	060505202100	Selective demolition, millwork and trim, paneling, boards, 1" x 4", remove	S.F.	\$ 1.31	\$ 10,856.63
12431.25	060505202140	Selective demolition, millwork and trim, paneling, boards, 1" x 8"	S.F.	\$ 1.15	\$ 14,295.94
5860	062213155100	Moldings, base, classic profile, 5/8" x 5-1/2", finger jointed and primed	L.F.	\$ 3.37	\$ 19,748.20
500	062213502800	Moldings, window & door, for doors, stock, decorative, plain, 1-1/8" wide	Set	\$ 69.89	\$ 34,945.00
500	062213505950	Moldings, window & door, window trim sets, 2-1/2" wide, includes casings, header, stops, stool & apron, pine	Opng.	\$ 87.84	\$ 43,920.00
					\$ -

Date:	04/21/2023			Gross Square Feet:	98,600
Project:	Hawk View	Substantial Rehabiltation Estimate	Net Le	asable Square Feet:	86,500
Address:	1548 Steelwood Lane	2-story Wood-frame Multifamily Walk-up Apartment Buildings		Number of Units:	100
City, State:	Reno, NV		R.S.	Means City Source:	Reno, NV (894-895)
		R.S. Means Year 2022 Quarter 2	Labor Type (Standard or Union):		Residential/DBWR

Quantity	Line Item No.	R.S. Means Line Item Description	Unit	Unit Cost	Total
		75% of the textured wood siding and exterior trim is recommended based on observed damage, observed condition and settlement			
75%	Thermal & Moisture	issues.			\$ 513,775.28
59670	072510103000	Weather barriers, building paper, spun bonded polyethylene	S.F.	\$ 0.33	\$ 19,691.10
59670	074629102050	Wood product siding, plywood, Texture 1-11, southern yellow pine, natural, 5/8" thick	S.F.	\$ 4.40	\$ 262,548.00
8287.5	074673100100	Soffit, baked enamel on steel, 16 or 18 gauge	S.F.	\$ 13.50	\$ 111,881.25
8287.5	070505102775	Selective demolition, thermal and moisture protection, roof ventilation, soffit vent strip, aluminum, 3" to 4" wide	L.F.	\$ 1.85	\$ 15,331.88
59670	070505105670	Selective demolition, thermal and moisture protection, siding, textured plywood	S.F.	\$ 0.59	\$ 35,205.30
33150	070505100020	Selective demolition, thermal and moisture protection, caulking/sealant, to 1" x 1" joint	L.F.	\$ 0.49	\$ 16,243.50
16575	079213200055	Joint sealants, caulking and sealants, bulk acrylic latex, 1/4" x 1/4", in place	L.F.	\$ 1.40	\$ 23,205.00
11050	079213200075	Joint sealants, caulking and sealants, bulk acrylic latex, 3/8" x 3/8", in place	L.F.	\$ 1.69	\$ 18,674.50
5525	079213200100	Joint sealants, caulking and sealants, bulk acrylic latex, 1/2" x 1/2", in place	L.F.	\$ 1.99	\$ 10,994.75
					\$ -
	Insulation	Costs included are for replacement of damaged and missing insulation and any insulation to be removed as a result of reconstruction work.			\$ 31,845.00
11,000	0420043	Non-rigid insul, batts, fbgls, kraft faced, 3-1/2" thick, R13, 15" W	S.F.	\$ 1.19	\$ 13,090.00
12,100	0420045	Non-rigid insul, batts, fbgls, kraft faced, 6" thick, R19, 11" wide	S.F.	\$ 1.55	\$ 18,755.00
					\$ -
	Roofing				\$
	_	NONE INCLUDED			\$ -
	Sheet Metal				\$
		NONE INCLUDED			\$ _

Date:	04/21/2023			Gross Square Feet:	98,600
Project:	Hawk View	Substantial Rehabiltation Estimate	Net Le	easable Square Feet:	86,500
Address:	1548 Steelwood Lane	2-story Wood-frame Multifamily Walk-up Apartment Buildings		Number of Units:	100
City, State:	Reno, NV		R.S. Means City Source:		Reno, NV (894-895)
		R.S. Means Year 2022 Quarter 2	Labor Type (Standard or Union):	Residential/DBWR

Quantity	Line Item No.	R.S. Means Line Item Description	Unit	Unit Cost	Total
100%	Doors	Each dwelling unit was observed with two (2) entry doors and one (1) door to the mechanical room. Due to settlement issues (failing seals and becoming inoperable), age and condition, replacement is warranted. The dwelling unit interior doors was observed, due to settlement issues (becoming inoperable and will not stay on track), age and condition, replacement is warranted.			\$ 780,869.60
100%	Doors	settlement issues (becoming inoperable and will not stay on track), age and condition, replacement is warranted.			\$ 780,869.60
300	080505100200	Door demolition, exterior door, single, 3' x 7' high, 1-3/4" thick, remove	Ea.	\$ 20.05	\$ 6,015.00
300	080505100700	Door demolition, interior bi-fold door, 3' x 6' - 8" high, remove	Ea.	\$ 15.95	\$ 4,785.00
200	080505101520	Door demolition, interior door,Solid, 1-3/8" thick, remove and reset, minimum	Ea.	\$ 68.67	\$ 13,734.00
300	080505104010	Door demolition, residential lockset, exterior, with deadbolt, remove	Ea.	\$ 15.87	\$ 4,761.00
200	080505104020	Door demolition, residential lockset, interior, remove	Ea.	\$ 13.78	\$ 2,756.00
300	080505104200	Door demolition, residential lockset, deadbolt lock, remove and reset	Ea.	\$ 12.92	\$ 3,876.00
100	081433200280	Doors, wood, residential, exterior, combination storm and screen, pine, crossbuck, 6'-9" x 3'-0" wide	Ea.	\$ 571.52	\$ 57,152.00
300	081433201320	Doors, wood, residential, entrance, flush, birch, solid core, 1-3/4" x 6'-8" x 3'-0" wide	Ea.	\$ 719.54	\$ 215,862.00
200	081416090210	Door, wood, architectural, flush, interior, hollow core, 7 ply, birch face, 3'-0" x 7'-0" x 1-3/4" thick	Ea.	\$ 332.00	\$ 66,400.00
200	081433202740	Doors, wood, residential, interior, closet, bi-fold, flush, birch, 6'-6" or 6'-8" x 3'-0" wide, incl. hardware, excl. frame and trim	Ea.	\$ 337.76	\$ 67,552.00
100	081433202800	Doors, wood, residential, interior, closet, bi-fold, flush, birch, 6'-6" or 6'-8" x 6'-0" wide, incl. hardware, excl. frame and trim	Ea.	\$ 585.58	\$ 58,558.00
100	087120151000	Door hardware, apartment, interior	Apt.	\$ 748.67	\$ 74,867.00
300	087120154200	Door hardware, for peep hole, add to price of door	Ea.	\$ 11.65	\$ 3,495.00
300	087120400400	Door hardware, lockset, standard duty, cylindrical, with sectional trim, keyed, single cylinder function	Ea.	\$ 255.79	\$ 76,737.00
300	087120400500	Door hardware, lockset, standard duty, cylindrical, with sectional trim, lever handled, keyed, single cylinder function	Ea.	\$ 253.61	\$ 76,083.00
300	087120411420	Door hardware, deadbolt lock, single cylinder	Ea.	\$ 159.52	\$ 47,856.00
5	087120652010	Threshold, wood oak, ADA, 3-1/2" wide x 36" long	Ea.	\$ 76.12	\$ 380.60
					\$ -

Date:	04/21/2023			Gross Square Feet:	98,600
Project:	Hawk View	Substantial Rehabiltation Estimate	Net Le	asable Square Feet:	86,500
Address:	1548 Steelwood Lane	2-story Wood-frame Multifamily Walk-up Apartment Buildings		Number of Units:	100
City, State:	Reno, NV		R.S.	Means City Source:	Reno, NV (894-895)
		R.S. Means Year 2022 Quarter 2	Labor Type (Standard or Union):		Residential/DBWR

Quantity	Line Item No.	R.S. Means Line Item Description	Unit	Unit Cost		Total
100%	Windows	Vinyl windows were observed; however, due to foundational shifting (settlement) issues the windows have failing seals and becoming inoperable. Replacement of the windows is recommended.			Ś	1,091,134.00
100	080505205020	Window demolition, window, up to a 2'x2' widow, remove and reset	Ea.	\$ 68.67	\$	6,867.00
				7 55.51	ş	0,807.00
200	080505205040	Window demolition, window, up to a 3'x3' window, remove and reset	Ea.	\$ 103.21	\$	20,642.00
200	080505205080	Window demolition, window, up to a 4'x5' window, remove and reset	Ea.	\$ 206.43	\$	41,286.00
100	085113204100	Windows, aluminum, commercial grade, stock units, sliding, insulating glass, 3'-0" x 2'-0" opening, incl. frame and glazing	Ea.	\$ 1,544.23	\$	154,423.00
200	085113204400	Windows, aluminum, commercial grade, stock units, sliding, insulating glass, 5'-0" x 3'-0" opening, incl. frame and glazing	Ea.	\$ 1,746.77	\$	349,354.00
200	085113204700	Windows, aluminum, commercial grade, stock units, sliding, insulating glass, 8'-0" x 4'-0" opening, incl. frame and glazing	Ea.	\$ 2,592.81	\$	518,562.00
					\$	-
	Glass				\$	_
		NONE INCLUDED			\$	_
		Note: Metable				
	Lath and Plaster				\$	-
		NONE INCLUDED			\$	-
		The unit gypsum board (drywall) was observed to be in fair to poor condition. The drywall as observed areas of cracking and separating due to foundational issues (settlement). Replacement of the plumbing pipes warranted removal of select areas				
	Drywall	(approximately 90% in total) of drywall is needed.			\$	329,125.50
10,000	090170100100	Gypsum wallboard, repairs, fill and sand, pin / nail holes	Ea.	\$ 0.40	\$	4,000.00
7,500	090170100110	Gypsum wallboard, repairs, fill and sand, screw head pops	Ea.	\$ 0.80	\$	6,000.00
5,000	090170100120	Gypsum wallboard, repairs, fill and sand, dents, up to 2" square	Ea.	\$ 8.00	\$	40,000.00
2,500	090170100130	Gypsum wallboard, repairs, fill and sand, dents, 2" to 4" square	Ea.	\$ 15.87	\$	39,675.00
1,500	090170100140	Gypsum wallboard, repairs, cut square, patch, sand and finish, holes, up to 2" square	Ea.	\$ 32.07	\$	48,105.00
500	090170100150	Gypsum wallboard, repairs, cut square, patch, sand and finish, holes, 2" to 4" square	Ea.	\$ 34.89	Ś	17,445.00
300			Ea.			•
300	090170100160	Gypsum wallboard, repairs, cut square, patch, sand and finish, holes, 4" to 8" square		\$ 38.60	\$	11,580.00
100	090170100170	Gypsum wallboard, repairs, cut square, patch, sand and finish, holes, 8" to 12" square	Ea.	\$ 48.33	\$	4,833.00

Date:	04/21/2023			Gross Square Feet:	98,600
Project:	Hawk View	Substantial Rehabiltation Estimate	Net Le	easable Square Feet:	86,500
Address:	1548 Steelwood Lane	2-story Wood-frame Multifamily Walk-up Apartment Buildings		Number of Units:	100
City, State:	Reno, NV		R.S. Means City Source:		Reno, NV (894-895)
		R.S. Means Year 2022 Quarter 2	Labor Type	(Standard or Union):	Residential/DBWR
Quantity	Line Item No.	R.S. Means Line Item Description	Unit	Unit Cost	Total
100	090170100180	Gypsum wallboard, repairs, cut square, patch, sand and finish, holes, 12" to 32" square	Ea.	\$ 65.41	\$ 6,541.00
50	090170100210	Gypsum wallboard, repairs, cut square, patch, sand and finish, holes, 16" by 48"	Ea.	\$ 79.59	\$ 3,979.50
50	090170100220	Gypsum wallboard, repairs, cut square, patch, sand and finish, holes, 32" by 48"	Ea.	\$ 100.25	\$ 5,012.50
25	090170100230	Gypsum wallboard, repairs, cut square, patch, sand and finish, holes, 48" square	Ea.	\$ 115.47	\$ 2,886.75
25	090170100240	Gypsum wallboard, repairs, cut square, patch, sand and finish, holes, 60" square	Ea.	\$ 129.11	\$ 3,227.75
64,000	090170100500	Gypsum wallboard, repairs, skim coat surface with joint compound	S.F.	\$ 0.29	\$ 18,560.00
16,000	090170100510	Gypsum wallboard, repairs, prepare, retape and refinish joints	L.F.	\$ 7.33	\$ 117,280.00
100%	Ceramic Tile	The units ceramic tile will be removed to access plumbing piping replacement and to correct settlement issues. Installation of new underlayment and ceramic tile is required.			\$ 47,703.53
425	092813100110	Cementitious backerboard, on floor, 3' x 5' x 5/8" sheet	S.F.	\$ 2.77	\$ 1,177.25
938	092813100190	Cementitious backerboard, on wall, 3' x 5' x 5/8" sheet	S.F.	\$ 3.55	\$ 3,328.13
1,703	093095100200	Membrane, elastomeric, moisture resistant, anti-fracture, 1/16" thick	S.F.	\$ 4.85	\$ 8,260.16
210	093213101200	Ceramic tile, sanitary cove base, mud set, 6" x 4-1/4" h	L.F.	\$ 9.39	\$ 1,971.90
25	093113101800	Ceramic bathroom accessories, average, (soap dish, toothbrush holder)	Ea.	\$ 17.20	\$ 430.00
210	093213102700	Ceramic tile, bullnose trim, mud set, 2" x 6"	S.F.	\$ 5.86	\$ 1,230.60
1,594	093213106250	Ceramic tile, walls, mud set, 6" x 6"	S.F.	\$ 16.64	\$ 26,520.00
425	093113103300	Ceramic tile, floors, glazed, porcelain type, 1 color, color group 2, 1" x 1"	S.F.	\$ 11.26	\$ 4,785.50
					\$ -
	Acoustical				\$ -
		NONE INCLUDED		\$ -	\$ -
					\$ -

Date:	04/21/2023			Gross Square Feet:	98,600
Project:	Hawk View	Substantial Rehabiltation Estimate	Net Le	easable Square Feet:	86,500
Address:	1548 Steelwood Lane	2-story Wood-frame Multifamily Walk-up Apartment Buildings		Number of Units:	100
City, State:	Reno, NV		R.S. Means City Source:		Reno, NV (894-895)
		R.S. Means Year 2022 Quarter 2	Labor Type (Standard or Union):		Residential/DBWR

Quantity	Line Item No.	R.S. Means Line Item Description	Unit	Unit Cost		Total
	Wood Flooring				\$	_
		NONE INCLUDED		\$ -	\$	-
					\$	-
	Resilient Flooring	The units VCT tile flooring was observed to be in poor condition with areas of missing and damaged tiles. Select areas of VCT tile will be removed to access plumbing piping replacement and to correct settlement issues. Installation of new VCT tile is required.			\$	667,646.10
42,550	096510103600	Latex underlayment, cementitious for resilient flooring, 1/8" thick	S.F.	\$ 2.61	\$	111,055.50
3500	096513370240	Vinyl wheeled transition strip, various materials to resilient, 1/8" to 1/8" x 2-1/2"	L.F.	\$ 8.18	\$	28,630.00
51,060	096519237600	Flooring, vinyl tile, premium colors/patterns, 12" x 12"x 1/8"	S.F.	\$ 8.36	\$	426,861.60
32,300	096513131100	Wall base, rubber, straight or cove, standard colors, 4" high, 1/8" thick	L.F.	\$ 3.13	\$	101,099.00
					\$	-
	Painting	With removal of approximately 90% of drywall, complete painting of the walls and ceilings in the dwelling units is needed as well as window and door trim.			\$	844,149.33
79,560	090190930790	Surface preparation, exterior, siding, stucco, pressure wash, based on 2500 lb operating pressure	S.F.	\$ 0.12	\$	9,547.20
1,250	099113420310	Paints & coatings, misc. exterior, stair stringers, exterior, metal, roll & brush, zinc chromate, each coat, to 14"	L.F.	\$ 2.33	\$	2,912.50
200	099113420190	Paints & coatings, misc. exterior, wrought iron railings, brushwork, zinc chromate, primer, 60" high, 1" rail, 1/2" sq. verticals, 6" OC	L.F.	\$ 5.35	\$	1,070.00
200	099113420200	Paints & coatings, misc. exterior, wrought iron railings, brushwork, zinc chromate, 1 finish coat, 60" high, 1" rail, 1/2" sq. verticals, 6" OC	L.F.	\$ 6.21	. \$	1,242.00
300	099113700190	Paints & coatings, exterior doors, flush, both sides, roll & brush, primer + 2 coats, exterior latex, incl. frame & trim	Ea.	\$ 100.30	\$	30,090.00
22,100	099113800120	Paints & coatings, trim, exterior, fascia, latex paint, 1 coat coverage, brushwork, 1" x 4"	L.F.	\$ 0.57	\$	12,597.00
11,050	099113800150	Paints & coatings, trim, exterior, fascia, latex paint, 1 coat coverage, brushwork, 1" x 6" to 1" x 10"	L.F.	\$ 0.68	\$	7,514.00
5,525	099113800180	Paints & coatings, trim, exterior, fascia, latex paint, 1 coat coverage, brushwork, 1" x 12"	L.F.	\$ 0.68	\$	3,757.00
20,719	099113800410	Paints & coatings, trim, exterior, molding, primer + 2 coats exterior latex, brushwork, up to 14" wide	L.F.	\$ 1.42	\$	29,420.63
500	099123350400	Paints & coatings, interior latex, doors, panel, both sides, roll & brush, primer + 2 coats, incl. frame & trim	Ea.	\$ 145.45	\$	72,725.00

Date:	04/21/2023			Gross Square Feet:	98,600
Project:	Hawk View	Substantial Rehabiltation Estimate	Net L	easable Square Feet:	86,500
Address:	1548 Steelwood Lane	2-story Wood-frame Multifamily Walk-up Apartment Buildings		Number of Units:	100
City, State:	Reno, NV			. Means City Source:	Reno, NV (894-895)
		R.S. Means Year 2022 Quarter 2	Labor Type	(Standard or Union):	Residential/DBWR
Quantity	Line Item No.	R.S. Means Line Item Description	Unit	Unit Cost	Total
13,600	099123527400	Paints & coatings, miscellaneous interior, trim, wood, paint 2 coats, oil base, brushwork, under 6" wide	L.F.	\$ 1.04	\$ 14,144.00
76,200	099123721190	Paints & coatings, walls & ceilings, interior, concrete, drywall or plaster, latex paint, 3 coats, smooth finish, cut-in by brushwork	L.F.	\$ 0.81	\$ 61,722.00
304,800	099123721670	Painting walls, complete, on drywall or plaster, primer and 2 finish coats, with roller, including surface preparation	S.F.	\$ 1.96	\$ 597,408.00
					\$ -
	Specialties				\$ -
		NONE INLCLUDED			
	Special Equipment				\$ -
		NONE INCLUDED			\$ -
	Appliances	Built-in and PHA-owned only are eligible			\$ 45,607.00
100	113013194150	Range hood, residential appliances, vented, min, 2 speed, 30" wide, minimum	Ea.	\$ 456.07	\$ 45,607.00
					\$ -
	Cabinets	Removal and replacement of the unit kitchen cabinets and vanities based on gaining access to plumbing piping and age/condition (Fair/Poor).			\$ 1,050,112.95
1300	123223109600	Custom cabinets, rule of thumb: kitchen cabinets, excl. counters & appliances, maximum	L.F.	\$ 637.80	\$ 829,140.00
95	123223308100	Wood casework vanities, base, 2 door, 30" h x 21" d x 36" w	Ea.	\$ 597.01	\$ 56,715.95
1300	123623131000	Countertops, custom, plastic laminate, square edge, plastic face, 7/8" thick, includes backsplash	L.F.	\$ 90.65	\$ 117,845.00
600	123623131700	Countertops, for end splash, add	Ea.	\$ 35.75	\$ 21,450.00
300	123623132000	Countertops, for standard cutouts, add, maximum	Ea.	\$ 74.88	\$ 22,464.00
100	123623132020	Countertops, cut out for sink	Ea.	\$ 24.98	\$ 2,498.00
					\$ -
	Blinds, Shades & Art	NOT ELIGIBLE PER PIH 2018-04			\$ -
		NONE INCLUDED		\$ -	\$ -

Date:	04/21/2023			Gross Square Feet:	98,600
Project:	Hawk View	Substantial Rehabiltation Estimate	Net Le	asable Square Feet:	86,500
Address:	1548 Steelwood Lane	2-story Wood-frame Multifamily Walk-up Apartment Buildings		Number of Units:	100
City, State:	Reno, NV		R.S.	Means City Source:	Reno, NV (894-895)
		R.S. Means Year 2022 Quarter 2	Labor Type (Standard or Union):	Residential/DBWR

Quantity	Line Item No.	R.S. Means Line Item Description	Unit	Unit Cost		Total
	Carpets				\$	-
		NONE INCLUDED			\$	-
	Special Construction	Work noted below is needed after completion of the scope of work and work need for Section 504 and accessibility code compliance.			\$	332,500.00
100	Final Cleaning	Apartment punch-out, cleaning, prelease procedures, historical costs	Ea.	\$ 2,500.00	\$	250,000.00
2	Special Construction	ADA 2% Audio/Visual Upgrades for Hearing Impaired, historical costs	Ea.	\$ 3,750.00	\$	7,500.00
5	Special Construction	Section 504 of Rehabilitation Act of 1973 complaince- 5% UFAS units.	Ea.	\$ 15,000.00	\$	75,000.00
					\$	-
	Elevators				\$	-
		NONE INCLUDED			\$	-
					\$	-
100%	Plumbing & Hot Water	The plumbing lines on-site were observed to be in poor condition with the site reporting multiple issues of leaks and backups. In a majority of the inspected units, water damage due to plumbing leaks were observed on the ceiling of kitchen directly below the unit bathrooms. In several of units, water was observed to be infiltrating the bathroom subfloors and damaging the floor joists. Replacement of the water and waste lines is recommended. The property features individual 40-gallon gas water heaters of various ages (approximately 75% are 2003 and 25% are 2013/14). With plumbing piping replacement being performed, replacement of water heaters is recommended. The bathroom fixtures were observed to be in poor condition. Due to plumbing piping replacement and potential leaks, replacement is recommended.			Ś	1,798,456.45
100	220505101141	Fixture, steel tub/shower, selective demolition	Ea.	\$ 60.08		6,008.00
100	220505101221	Fixture, counter top lavatory, disconnect and remove	Ea.	\$ 18.82	\$	1,882.00
100	220505101321	Fixture, sink, double compartment, selective demolition	Ea.	\$ 30.04	\$	3,004.00
100	220505101400	Fixture, water closet, floor mounted, selective demolition, includes 10' piping	Ea.	\$ 54.87	\$	5,487.00
100	220505102001	Pipe, metal pipe, to 1-1/2" diam., selective demolition	L.F.	\$ 1.50	\$	150.00
100	220505102051	Pipe, metal pipe, 2" to 3-1/2" diam., selective demolition	L.F.	\$ 1.99	\$	199.00
100	220505102101	Pipe, metal pipe, 4" to 6" diam., selective demolition	L.F.	\$ 3.00	\$	300.00
100	220505102160	Pipe, plastic, with fittings, up thru 1-1/2" diameter, selective demolition	L.F.	\$ 1.75	\$	175.00
100	220505102162	Pipe, plastic, with fittings, 2" thru 3" diameter, selective demolition	L.F.	\$ 2.19	\$	219.00

Date:	04/21/2023		Gross Square Feet:		98,600
Project:	Hawk View	Substantial Rehabiltation Estimate	Net Leasable Square Feet:		86,500
Address:	1548 Steelwood Lane	2-story Wood-frame Multifamily Walk-up Apartment Buildings		Number of Units:	100
City, State:	Reno, NV	R.S. Means Year 2022 Quarter 2		Means City Source: (Standard or Union):	Reno, NV (894-895) Residential/DBWR
		N.S. Medits real 2022 Quarter 2	Labor Type	Residential/DBWN	
Quantity	Line Item No.	R.S. Means Line Item Description	Unit	Unit Cost	Total
100	220505102164	Pipe, plastic, with fittings, 4" thru 6" diameter, selective demolition	L.F.	\$ 3.94	\$ 394.00
100	220505106100	Fixture, plumbing, remove and reset fixtures, difficult access	Ea.	\$ 109.74	\$ 10,974.00
5	220576100100	Cleanout, floor type, round or square, scoriated nickel bronze top, 2" pipe size	Ea.	\$ 616.32	\$ 3,081.60
5	220576200220	Cleanout tee, cast iron, B. & S., 3" pipe size, includes countersunk plug	Ea.	\$ 407.52	\$ 2,037.60
5	220576200240	Cleanout tee, cast iron, B. & S., 4" pipe size, includes countersunk plug	Ea.	\$ 563.89	\$ 2,819.45
5	220576204020	Cleanout tee, plastic tee, ABS, 1-1/2" pipe size, type DWV, excludes plug	Ea.	\$ 63.26	\$ 316.30
100	221113741860	Pipe, plastic, PVC, 1/2" diameter, schedule 40, includes couplings 10' OC, and hangers 3 per 10'	L.F.	\$ 16.36	\$ 1,636.00
100	221113741870	Pipe, plastic, PVC, 3/4" diameter, schedule 40, includes couplings 10' OC, and hangers 3 per 10'	L.F.	\$ 17.45	\$ 1,745.00
100	221113741880	Pipe, plastic, PVC, 1" diameter, schedule 40, includes couplings 10' OC, and hangers 3 per 10'	L.F.	\$ 17.58	\$ 1,758.00
100	221113741890	Pipe, plastic, PVC, 1-1/4" diameter, schedule 40, includes couplings 10' OC, and hangers 3 per 10'	L.F.	\$ 20.17	\$ 2,017.00
100	221113741900	Pipe, plastic, PVC, 1-1/2" diameter, schedule 40, includes couplings 10' OC, and hangers 3 per 10'	L.F.	\$ 23.75	\$ 2,375.00
100	221113741910	Pipe, plastic, PVC, 2" diameter, schedule 40, includes couplings 10' OC, and hangers 3 per 10'	L.F.	\$ 27.78	\$ 2,778.00
100	221113741920	Pipe, plastic, PVC, 2-1/2" diameter, schedule 40, includes couplings 10' OC, and hangers 3 per 10'	L.F.	\$ 35.70	\$ 3,570.00
100	221113741930	Pipe, plastic, PVC, 3" diameter, schedule 40, includes couplings 10' OC, and hangers 3 per 10'	L.F.	\$ 41.91	\$ 4,191.00
100	221113741940	Pipe, plastic, PVC, 4" diameter, schedule 40, includes couplings 10' OC, and hangers 3 per 10'	L.F.	\$ 35.29	\$ 3,529.00
100	221113744214	Pipe, plastic, ABS, foam core, 1-1/2" diameter, DWV, schedule 40, includes couplings 10' OC, and hangers 3 per 10'	L.F.	\$ 15.59	\$ 1,559.00
100	221113744216	Pipe, plastic, ABS, foam core, 2" diameter, DWV, schedule 40, includes couplings 10' OC, and hangers 3 per 10'	L.F.	\$ 17.89	\$ 1,789.00
100	221113744218	Pipe, plastic, ABS, foam core, 3" diameter, DWV, schedule 40, includes couplings 10' OC, and hangers 3 per 10'	L.F.	\$ 23.34	\$ 2,334.00
100	221113744220	Pipe, plastic, ABS, foam core, 4" diameter, DWV, schedule 40, includes couplings 10' OC, and hangers 3 per 10'	L.F.	\$ 28.92	\$ 2,892.00
100	221113744222	Pipe, plastic, ABS, foam core, 6" diameter, DWV, schedule 40, includes couplings 10' OC, and hangers 3 per 10'	L.F.	\$ 54.11	\$ 5,411.00
100	221113744410	Pipe, plastic, PVC, 1-1/4" diameter, DWV, schedule 40, includes couplings 10' OC, and hangers 3 per 10'	L.F.	\$ 18.11	\$ 1,811.00
100	221113744420	Pipe, plastic, PVC, 1-1/2" diameter, DWV, schedule 40, includes couplings 10' OC, and hangers 3 per 10'	L.F.	\$ 18.63	\$ 1,863.00

Date:	04/21/2023			Gross Square Feet:	98,600
Project:	Hawk View	Substantial Rehabiltation Estimate	Net Le	easable Square Feet:	86,500
Address:	1548 Steelwood Lane	2-story Wood-frame Multifamily Walk-up Apartment Buildings		Number of Units:	100
City, State:	Reno, NV			. Means City Source:	Reno, NV (894-895)
		R.S. Means Year 2022 Quarter 2	Labor Type (Standard or Union):	Residential/DBWR
Quantity	Line Item No.	R.S. Means Line Item Description	Unit	Unit Cost	Total
100	221113744460	Pipe, plastic, PVC, 2" diameter, DWV, schedule 40, includes couplings 10' OC, and hangers 3 per 10'	L.F.	\$ 21.42	\$ 2,142.00
100	221113744470	Pipe, plastic, PVC, 3" diameter, DWV, schedule 40, includes couplings 10' OC, and hangers 3 per 10'	L.F.	\$ 25.61	\$ 2,561.00
100	221113744480	Pipe, plastic, PVC, 4" diameter, DWV, schedule 40, includes couplings 10' OC, and hangers 3 per 10'	L.F.	\$ 31.35	\$ 3,135.00
100	221316204100	Pipe, cast iron soil, no hub, 1-1/2" diameter, includes couplings 10' OC, clevis hanger assemblies 5' OC	L.F.	\$ 22.26	\$ 2,226.00
100	221316204120	Pipe, cast iron soil, no hub, 2" diameter, includes couplings 10' OC, clevis hanger assemblies 5' OC	L.F.	\$ 23.53	\$ 2,353.00
100	221316204140	Pipe, cast iron soil, no hub, 3" diameter, includes couplings 10' OC, clevis hanger assemblies 5' OC	L.F.	\$ 27.50	\$ 2,750.00
100	221316204160	Pipe, cast iron soil, no hub, 4" diameter, includes couplings 10' OC, clevis hanger assemblies 5' OC	L.F.	\$ 33.57	\$ 3,357.00
100	220719100245	Insulation, insulated protectors (ADA), for exposed piping under sinks or lavatories, vinyl coated foam, velcro tabs, p trap, 1-1/4" or 1-1/2"	Ea.	\$ 35.02	\$ 3,502.00
100	220719100265	Insulation, insulated protectors (ADA), for exposed piping under sinks or lavatories, vinyl coated foam, velcro tabs, valve and supply cover, 1/2", 3/8", and 7/16" pipe size	Ea.	\$ 34.68	\$ 3,468.00
100	220719100285	Insulation, insulated protectors (ADA), for exposed piping under sinks or lavatories, vinyl coated foam, velcro tabs, tailpiece offset (wheelchair), 1-1/4" pipe size	Ea.	\$ 31.11	\$ 3,111.00
100	220719106840	Insulation, pipe covering (price copper tube one size less than I.P.S.), fiberglass with all service jacket, 1" wall, 1/2" iron pipe size	L.F.	\$ 6.84	\$ 684.00
100	220719106860	Insulation, pipe covering (price copper tube one size less than I.P.S.), fiberglass with all service jacket, 1" wall, 3/4" iron pipe size	L.F.	\$ 4.64	\$ 464.00
100	220719106870	Insulation, pipe covering (price copper tube one size less than I.P.S.), fiberglass with all service jacket, 1" wall, 1" iron pipe size	L.F.	\$ 6.31	\$ 631.00
100	220719106900	Insulation, pipe covering (price copper tube one size less than I.P.S.), fiberglass with all service jacket, 1" wall, 2" iron pipe size	L.F.	\$ 7.40	\$ 740.00
100	221119382080	Water supply meter, domestic/commercial, bronze, threaded, to 30 GPM, 3/4" diameter	Ea.	\$ 507.89	\$ 50,789.00
100	221119424120	Backflow preventer, reduced pressure principle, corrosion resistant, automatic, ball valves, threaded, 3/4" pipe size, includes valves and test cocks	Ea.	\$ 751.06	\$ 75,106.00
50	223430132900	Water heater, safety-drain pan, 26" diameter	Ea.	\$ 57.92	\$ 2,896.00
50	223430132100	Water heater, residential, gas fired, foam lined tank, 10 year, 75 gallon, excludes vent	Ea.	\$ 2,091.80	\$ 104,590.00
50	223413109440	Water heaters, tankless, on-demand, natural gas/propane, 9.5 GPM, excludes vent	Ea.	\$ 1,622.43	\$ 81,121.50
100	0824032	Three fixture bathroom with lavatory installed in vanity	Ea.	\$ 8,314.96	\$ 831,496.00
100	224116131160	Lavatory, vanity top, cultured marble, white, single bowl, 37" x 22", includes trim	Ea.	\$ 450.41	\$ 45,041.00

1,109.05 \$

110,905.00

100

224116133580

Lavatory, vanity top, rough-in, supply, waste and vent

Date:	04/21/2023			Gross Square Feet:	98,600			
Project:	Hawk View	Substantial Rehabiltation Estimate	Net Le	easable Square Feet:	86,500			
Address:	1548 Steelwood Lane	2-story Wood-frame Multifamily Walk-up Apartment Buildings		Number of Units:	100			
City, State:	Reno, NV		R.S.	. Means City Source:	Reno, NV (894-895)			
		R.S. Means Year 2022 Quarter 2	Labor Type (Standard or Union):	Residential/DBWR			
Quantity	Line Item No.	R.S. Means Line Item Description	Unit	Unit Cost	Total			
100	224116164980	Sink, kitchen, counter top style, rough-in, supply, waste and vent	Ea.	\$ 1,038.89	\$ 103,889.00			
100	224139100420	Faucets/fittings, bath, pressure balance mix valve with diverter, spout, shower head, arm and flange	Ea.	\$ 323.16	\$ 32,316.00			
100	224139100500	Faucets/fittings, bath, drain, central lift, 1-1/2" I.P.S. male	Ea.	\$ 93.21	\$ 9,321.00			
100	224139101000	Faucets/fittings, kitchen sink faucets, top mount, cast spout	Ea.	\$ 151.30	\$ 15,130.00			
100	224139101100	Faucets/fittings, kitchen sink faucets, top mount, cast spout, for spray, add	Ea.	\$ 41.47	\$ 4,147.00			
100	224139102120	Faucets/fittings, lavatory faucet, center set with pop-up drain	Ea.	\$ 177.42	\$ 17,742.00			
100	224139104250	Faucets/fittings, shower pressure balancing mixing valve, satin nickel, with shower head, arm, flange and diverter tub spout	Ea.	\$ 806.83	\$ 80,683.00			
100	224139701030	Washer dryer accessories, valves ball type single lever, I.P.S., 1/2" diam.	Ea.	\$ 90.83	\$ 9,083.00			
100	224139701350	Washer dryer accessories, recessed box, two hose valves and drain (economy type), 20 gauge, 1/2" size, 2" ABS/PVC drain	Ea.	\$ 209.19	\$ 20,919.00			
100	224139701980	Washer dryer accessories, rough-in, supply, waste and vent for washer boxes	Ea.	\$ 938.53	\$ 93,853.00			
1					\$ -			

Date:	04/21/2023			Gross Square Feet:	98,600
Project:	Hawk View	Substantial Rehabiltation Estimate	Net Leasable Square Feet:		86,500
Address:	1548 Steelwood Lane	2-story Wood-frame Multifamily Walk-up Apartment Buildings		Number of Units:	100
City, State:	Reno, NV		'		Reno, NV (894-895)
		R.S. Means Year 2022 Quarter 2			Residential/DBWR

Quantity	Line Item No.	R.S. Means Line Item Description	Unit	Unit Cost	Total
100%	Heat & Ventilation	The units feature gas-fired furnaces for heat and outdoor condensing units with replacement on an as-needed basis. Select components were observed in various conditions (some appear to be in disrepair/not functioning properly. Replacement of the furnaces, condensers, thermostats and select ductwork is recommended. The dwelling units feature bathroom exhaust fans that were reported to be original to the date of construction (1984) and in various operating conditions. Replacement of the fans and ducting is recommended.			\$ 551,516.50
50	230505100100	Air conditioner, split unit air conditioner, 3 ton, selective demolition	Ea.	\$ 604.76	\$ 30,238.00
250	230505105090	Handling & disposal, remove refrigerant from system	Lb.	\$ 16.82	\$ 4,205.00
50	237313100900	Air-handling unit, built-up, horizontal/vertical, constant volume, single zone, 1,600 CFM, with cooling/heating coil section, filters, mixing box	Ea.	\$ 7,051.10	\$ 352,555.00
50	238143101020	Heat pump, air to air split system, 2 ton cooling, 8.5 MBH heat @ 0Deg.F, includes outside condensing unit only, excludes interconnecting tubing, curbs, pads and ductwork	Ea.	\$ 2,356.85	\$ 117,842.50
50	260590109530	Thermostat, residential, hook-up, using low voltage wire, heating/cooling, 25' of #18-4	Ea.	\$ 49.76	\$ 2,488.00
100	233423106670	Fans, residential, bath exhaust, grille, back draft damper, 110 CFM	Ea.	\$ 246.35	\$ 24,635.00
100	233423106948	Fans, residential roof jacks and wall caps, wall cap with back draft damper, 6" diam. round duct	Ea.	\$ 195.53	\$ 19,553.00
					\$
50%	Air Conditioning	INCLUDED WITH HEAT & VENTILATION ABOVE			\$ -
		NO STAND ALONE A/C INCLUDED			\$ -
					\$ _

Date:	04/21/2023			Gross Square Feet:	98,600
Project:	Hawk View	Substantial Rehabiltation Estimate	Net Le	easable Square Feet:	86,500
Address:	1548 Steelwood Lane	2-story Wood-frame Multifamily Walk-up Apartment Buildings		Number of Units:	100
City, State:	Reno, NV		R.S. Means City Source:		Reno, NV (894-895)
		R.S. Means Year 2022 Quarter 2	Labor Type (Standard or Union):	Residential/DBWR

Quantity	Line Item No.	R.S. Means Line Item Description	Unit	Unit Cost		Total
100%	Electrical	Apartment units' circuit breaker panels and electrical devices require 3-year modernization. Select electrical devices were observed to be original to the date of construction and therefore, replacement in conjunction with the panel replacement is recommended. Based on observations during the inspection, select fixtures were broken, non-operational, missing. Replacement of lighting fixtures is recommended.			Ś	1,015,746.50
10070	Liectrical	recommended.			٦	1,013,740.30
4,325	260505102600	Electrical make-safe mechanical demolition	S.F.	\$ 0.50	\$	2,162.50
200	260505102620	Incandescent fixtures, exterior, 100 Watt, electrical demolition, remove, wall mount	Ea.	\$ 20.21	\$	4,042.00
200	260505103000	Ceiling fan, electrical demolition, tear out and remove	Ea.	\$ 21.10	\$	4,220.00
800	260505102480	Incandescent fixtures, interior, metal cylinder type, 75 Watt, electrical demolition, remove, surface, ceiling, or wall mount, to 10' high	Ea.	\$ 16.48	\$	13,184.00
100	260505101230	Panelboards, 3 wire, 120/240 V, 100 amp, 20 circuits, electrical demolition, remove, including removal of all breakers, conduit terminations & wire connections	Ea.	\$ 196.66	\$	19,666.00
100	260590101230	Service & panel, residential, w/18 branch breakers, w/RGS conduit & wire, 200 amp, incl 24' SE-AL cable, service eye, meter socket	Ea.	\$ 3,285.67	\$	328,567.00
1,200	260590102120	Switch devices, residential, single pole, ivory, type MC cable, 20', 15 amp, incl box & cover plate	Ea.	\$ 65.49	\$	78,588.00
100	260590102170	Switch devices, residential, 3-way, #14/3, type MC cable, 20', incl box & cover plate	Ea.	\$ 80.73	\$	8,073.00
100	260590102220	Switch devices, residential, 4-way, #14/3, type MC cable, 20', incl box & cover plate	Ea.	\$ 90.59	\$	9,059.00
300	260590102270	Switch devices, residential, single pole, #12/2, type MC cable, 20', 20 amp, incl box & cover plate	Ea.	\$ 79.56	\$	23,868.00
1,000	260590104070	Receptacle devices, residential, duplex outlet, ivory, w/#12/2, type MC cable, 20', 15 amp, incl box & cover plate	Ea.	\$ 79.46	\$	79,460.00
800	260590104120	Receptacle devices, residential, duplex outlet, ivory, w/#12/2, type MC cable, 20', 20 amp, incl box & cover plate	Ea.	\$ 95.47	\$	76,376.00
100	260590104580	Air conditioner outlet, residential, 30' of #12/2, 2 pole circuit breaker, type MC cable, 20 amp, 240 V, incl box & exterior cover plate	Ea.	\$ 169.91	\$	16,991.00
100	260590104680	Dryer outlet, residential, 30' of #10/3, 2 pole circuit breaker, type MC cable, 30 amp, 240 V, incl box & exterior cover plate	Ea.	\$ 176.82	\$	17,682.00
100	260590104980	Door bell chime, residential, transformer, 2 buttons, custom model, 60' bellwire	Ea.	\$ 182.43	\$	18,243.00
100	260590106120	Lighting outlets, residential, box 4" & wire (for fixture), type MC cable, 20'	Ea.	\$ 54.54	\$	5,454.00
100	260590106220	Light fixtures, residential, canopy style, custom grade	Ea.	\$ 89.75	\$	8,975.00
100	260590106320	Light fixtures, residential, kitchen fixture (fluorescent), custom grade	Ea.	\$ 318.35	\$	31,835.00
200	260590106360	Light fixtures, residential, outdoor, wall mounted, custom grade	Ea.	\$ 185.80	\$	37,160.00

Date:	04/21/2023			Gross Square Feet:	98,600	
Project:	Hawk View	Substantial Rehabiltation Estimate	Net Le	easable Square Feet:	86,500	
Address:	1548 Steelwood Lane	2-story Wood-frame Multifamily Walk-up Apartment Buildings		Number of Units:	100	
City, State:	Reno, NV		R.S.	Means City Source:	Reno, NV (894-895)	
		R.S. Means Year 2022 Quarter 2	Labor Type (Labor Type (Standard or Union):		
Quantity	Line Item No.	R.S. Means Line Item Description	Unit	Unit Cost	Total	
100	260590106610	Light fixtures, residential, downlight, w/shower light trim, recessed	Ea.	\$ 118.04	\$ 11,804.00	
300	260590107070	Smoke detectors, residential, box, #14/3, type MC cable, 20'	Ea.	\$ 97.98	\$ 29,394.00	
100	260590108280	Bathroom vent fan, residential, hook-up, (use w/above hook-up), custom model, 50 CFM	Ea.	\$ 199.12	\$ 19,912.00	
100	260590108320	Bathroom or kitchen vent fan, residential, low noise model, 110 CFM	Ea.	\$ 180.73	\$ 18,073.00	
100	260590108670	Hot water heater, residential, hook-up, #10/2, MC cable, 20', incl 1-2 pole circuit breaker, box, 3' of flexible	Ea.	\$ 180.98	\$ 18,098.00	
100	265113550100	Interior LED fixtures, downlight, recess mounted, 25 watt, 7.5" diameter, incl lamps, mounting hardware and connections	Ea.	\$ 538.08	\$ 53,808.00	
100	265113550180	Interior LED fixtures, downlight, cylinder, 20 watts, incl lamps, mounting hardware and connections	Ea.	\$ 184.50	\$ 18,450.00	
100	265113552010	Interior LED fixtures, strip, surface mounted, 5,000 K, one light bar 4' long, incl lamps, mounting hardware and connections	Ea.	\$ 432.13	\$ 43,213.00	
100	265113555000	Interior LED fixtures, track, lighthead, 6 watt	Ea.	\$ 91.71	\$ 9,171.00	
100	265113555010	Interior LED fixtures, track, lighthead, 9 watt	Ea.	\$ 102.18	\$ 10,218.00	
					\$ -	
	Subtotal (Structures)				\$ 11,956,877.99	
				\$ -	\$ -	

Date:	04/21/2023			Gross Square Feet:	98,600
Project:	Hawk View	Substantial Rehabiltation Estimate	Net Leasable Square Feet:		86,500
Address:	1548 Steelwood Lane	2-story Wood-frame Multifamily Walk-up Apartment Buildings		Number of Units:	100
City, State:	Reno, NV		R.S. Means City Source:		Reno, NV (894-895)
		R.S. Means Year 2022 Quarter 2	Labor Type (Standard or Union):		Residential/DBWR

Quantity	Line Item No.	R.S. Means Line Item Description	Unit	Unit Cost	Total
	Accessory Structures				\$ -
		NOT ALLOWED PER PIH 2018-04		\$ -	\$ -
	Total (Lines 33 and 34)				\$ 11,956,877.99
	Earthwork	Work outlined below is needed for access to perform corrections to settlement issues and plumbing piping replacement and occurs within the five foot (5') perimeter outside the edge of the foundation. Other work noted is to restore disturbed areas.			\$ 67,825.25
100	310516100100	Aggregate for earthwork, bank run gravel, spread with 200 HP dozer, includes load at pit and haul, 2 miles round trip, excludes compaction	L.C.Y.	\$ 34.50	\$ 3,450.00
2200	311413231510	Topsoil stripping and stockpiling, loam or topsoil, remove and stockpile on site, by hand, less than 100 S.Y., 6" deep, 50' haul	S.Y.	\$ 10.74	\$ 23,628.00
7000	312216101200	Fine grading, fine grade granular base for sidewalks and bikeways	S.Y.	\$ 1.20	\$ 8,400.00
9200	312216103300	Fine grading, slopes, gentle, finish grading	S.Y.	\$ 0.19	\$ 1,748.00
125	312316131400	Excavating, trench or continuous footing, common earth, by hand with pick and shovel, 2' to 6' deep, light soil, excludes sheeting or dewatering	B.C.Y.	\$ 43.85	\$ 5,481.25
125	312316131500	Excavating, trench or continuous footing, common earth, by hand with pick and shovel, 2' to 6' deep, heavy soil, excludes sheeting or dewatering	B.C.Y.	\$ 87.24	\$ 10,905.00
2500	312514161000	Synthetic erosion control, silt fence, install and remove, 3' high	L.F.	\$ 2.45	\$ 6,125.00
100	312514161625	Erosion control, silt Sac for Catch Basin, Single, 2ft x 2ft	L.F.	\$ 80.88	\$ 8,088.00

Date:	04/21/2023			Gross Square Feet:	98,600
Project:	Hawk View	Substantial Rehabiltation Estimate	Substantial Rehabiltation Estimate Net Leasable Square Feet:		86,500
Address:	1548 Steelwood Lane	2-story Wood-frame Multifamily Walk-up Apartment Buildings		Number of Units:	100
City, State:	Reno, NV		R.S. Means City Source:		Reno, NV (894-895)
		R.S. Means Year 2022 Quarter 2	Labor Type (Standard or Union):		Residential/DBWR

Quantity	Line Item No.	R.S. Means Line Item Description	Unit	Unit Cost	Total
		Work outlined below is needed for access to perform corrections to settlement issues and plumbing piping replacement and occurs			
	Exterior Improvements	within the five foot (5') perimeter outside the edge of the foundation. Other work noted is to restore disturbed areas.			\$ 193,182.25
5000	024113175700	Demolish, remove pavement & curb, patio/carport, concrete, no reinforcing, to 6" thick, with hand held air equipment, excludes hauling	S.F.	\$ 1.56	\$ 7,800.00
2000	024113175900	Demolish, remove pavement & curb, sidewalk, concrete, rod reinforced, 6" thick, with hand held air equipment, excludes hauling	S.F.	\$ 3.24	\$ 6,480.00
2000	320610100310	Sidewalks, driveways, and patios, sidewalk, concrete, cast-in-place with 6 x 6 - W1.4 x W1.4 mesh, broomed finish, 3,000 psi, 4" thick, excludes base	S.F.	\$ 4.90	\$ 9,800.00
5000	320610100400	Sidewalks, driveways, and patios, sidewalk, concrete, cast-in-place with 6 x 6 - W1.4 x W1.4 mesh, broomed finish, 3,000 psi, 6" thick, excludes base	S.F.	\$ 6.51	\$ 32,550.00
7000	320610100450	Sidewalks, driveways, and patios, sidewalks, concrete, excludes base, for 4" thick bank run gravel base, add	S.F.	\$ 1.11	\$ 7,770.00
625	323113250100	Fence, chain link, residential, galvanized steel, 11 ga. wire, 1-5/8" post, 10' OC, 1-3/8" top rail, 2" corner post, 6' high, schedule 20, includes excavation, excludes concrete	L.F.	\$ 28.71	\$ 17,943.75
25	323113800110	Chain link fence, gates, residential, single, 4', includes concrete, hinges, latch and post hardware	Ea.	\$ 521.72	\$ 13,043.00
82800	329119130801	Topsoil placement and grading, loam or topsoil unscreened, 6" deep, furnish and place, truck dumped	S.F.	\$ 0.62	\$ 51,336.00
375	329313100900	Ground cover, pea gravel, truckload lots	Ton	\$ 51.34	\$ 19,252.50
50	329313100012	Ground cover, plants, pachysandra, excludes preparation of beds	С	\$ 167.57	\$ 8,378.50
50	329313100200	Ground cover, plants, Vinca minor, 1 year, bare root, excludes preparation of beds	С	\$ 176.58	\$ 8,829.00
50	329333100600	Shrubs and trees, evergreen, in prepared beds, juniper, andorra, B&B, 18" - 24", in prepared beds	Ea.	\$ 62.16	\$ 3,108.00
50	329333100700	Shrubs and trees, evergreen, in prepared beds, pine, black, B&B, 2-1/2' - 3', in prepared beds	Ea.	\$ 66.64	\$ 3,332.00
50	329450101100	Tree guying, guy wire and wrap, less than 3" caliper, 3" anchors, includes arrowhead anchor, cable, turnbuckles and wrap	Ea.	\$ 71.19	\$ 3,559.50
					\$ -

Date:	04/21/2023			Gross Square Feet:	98,600
Project:	Hawk View	Substantial Rehabiltation Estimate Net Leasable Square Feet:			
Address:	1548 Steelwood Lane	2-story Wood-frame Multifamily Walk-up Apartment Buildings		Number of Units:	100
City, State:	Reno, NV		R.S. Means City Source:		Reno, NV (894-895)
		R.S. Means Year 2022 Quarter 2	Labor Type (Standard or Union):		Residential/DBWR

Quantity	Line Item No.	R.S. Means Line Item Description	Unit	Unit Cost	Total
	Utilties				\$ -
		NONE INCLUDED			\$ -
		Land Improvements Hard Cost Subtotal:			\$ 261,007.50
		Structure(s) and Land Improvements Hard Cost Subtotal			\$ 12,217,885.49
		Soft Costs and Fees			
		Contingency	7.50%		\$ 916,341.41
		General Conditions	5.00%		\$ 610,894.27
		Builder's Profit & Overhead	10.00%		\$ 294,348.05
		Architectural Design Fees	5.50%		\$ 671,983.70
		Payment/Performance Bond Fee	0.00%		\$ -
		PHA Administration Fee	2.00%		\$ 244,357.71
		Subtotal Soft Costs and Fees	30.00%		\$ 2,737,925.14
		TOTAL REHABILITATION / RETROFIT CONSTRUCTION COST BUDGET:			\$ 14,955,810.63
		HUD TOTAL DEVELOPMENT COST (TDC):			\$ 24,499,200.00
	•	TOTAL REHABILITATION ESTIMATE / TDC COST:			61.05%

APPENDIX G USGS Seismic Design Map



U.S. Seismic Design Maps






Hawk View Apartments

1548 Steelwood Ln, Reno, NV 89512, USA

Latitude, Longitude: 39.5542233, -119.7934475



Туре	Description	Value
Hazard Level		BSE-2N
S _S	spectral response (0.2 s)	1.5
S ₁	spectral response (1.0 s)	0.515
S _{XS}	site-modified spectral response (0.2 s)	1.2
S _{X1}	site-modified spectral response (1.0 s)	0.412
Fa	site amplification factor (0.2 s)	0.8
F _v	site amplification factor (1.0 s)	0.8
ssuh	max direction uniform hazard (0.2 s)	1.61
crs	coefficient of risk (0.2 s)	0.951
ssrt	risk-targeted hazard (0.2 s)	1.531
ssd	deterministic hazard (0.2 s)	1.5
s1uh	max direction uniform hazard (1.0 s)	0.544
cr1	coefficient of risk (1.0 s)	0.945
s1rt	risk-targeted hazard (1.0 s)	0.515
s1d	deterministic hazard (1.0 s)	0.6

Type Description	n	Value
Hazard Level		BSE-1N
S _{XS} site-modifi	ed spectral response (0.2 s)	0.8
S _{X1} site-modifi	ed spectral response (1.0 s)	0.275

1 of 2 6/1/2022, 9:34 AM

Description	Value
	BSE-2E
spectral response (0.2 s)	1.133
spectral response (1.0 s)	0.375
site-modified spectral response (0.2 s)	0.907
site-modified spectral response (1.0 s)	0.3
site amplification factor (0.2 s)	0.8
site amplification factor (1.0 s)	0.8
	spectral response (0.2 s) spectral response (1.0 s) site-modified spectral response (0.2 s) site-modified spectral response (1.0 s) site amplification factor (0.2 s)

Туре	Description	Value
Hazard Level		BSE-1E
S _S	spectral response (0.2 s)	0.553
S ₁	spectral response (1.0 s)	0.179
S _{XS}	site-modified spectral response (0.2 s)	0.442
S _{X1}	site-modified spectral response (1.0 s)	0.143
Fa	site amplification factor (0.2 s)	0.8
F _v	site amplification factor (1.0 s)	0.8

Туре	Description	Value
Hazard Level		TL Data
T-Sub-L	Long-period transition period in seconds	6

DISCLAIMER

While the information presented on this website is believed to be correct, SEAOC /OSHPD and its sponsors and contributors assume no responsibility or liability for its accuracy. The material presented in this web application should not be used or relied upon for any specific application without competent examination and verification of its accuracy, suitability and applicability by engineers or other licensed professionals. SEAOC / OSHPD do not intend that the use of this information replace the sound judgment of such competent professionals, having experience and knowledge in the field of practice, nor to substitute for the standard of care required of such professionals in interpreting and applying the results of the seismic data provided by this website. Users of the information from this website assume all liability arising from such use. Use of the output of this website does not imply approval by the governing building code bodies responsible for building code approval and interpretation for the building site described by latitude/longitude location in the search results of this website.

2 of 2 6/1/2022, 9:34 AM

APPENDIX H Pre-Site Visit Questionnaire





HUD CNA PRE-SURVEY QUESTIONNAIRE (MF)

GENERAL INSPECTION INFORMATION

PER HUD GUIDANCE, AEI MUST BE ALLOWED ACCESS INTO 25% OF EACH DWELLING UNIT FLOORPLAN, AS WELL AS ALL COMMON AREAS, AND EXTERIORS AT THE SITE.

GENERAL PROPERTY INFORMATION

PROPERTY NAME:		Hawk View Apartments								
SITE ADDRESS:	1548 Steelwood L	n	CITY	Reno		STATE	NV			
Number of Apt Buildings:	25	Date of Construction:	1984		Number of Units:	100				
Number of Common Buildings:	3	Renovation Date(s):		9, 2001-12, 5, 2017-20	Number of Vacant Units:	3				
Number of Stories:	2	Gross Building Area:	14.3		Number of Down Units:	0				
Site Area in Acres:	acres	Total Number of Parking Spaces:	100		Number of HC Parking Spaces:	5				

GENERAL PROPERTY INFORMATION

Please describe all pertinent building maintenance, renovation, seismic, and upgrade work within the last 3 years. If available, please attached supporting documentation, i.e. work orders, receipts, etc.:

Concrete Replacement, Retaining Wall Repair, Asphalt Replacement, Appliance Replacement

Please describe any ongoing/current major building maintenance, renovation, seismic, and upgrade work: $N\!/\!A$

Please describe any future building maintenance, renovation, seismic, and upgrade work being planned: (CF2020) Multi-Site Water Heater Replacement

Please list the designated handicapped dwelling units:

2519 Tripp#3, 2541 Tripp#1, 1548 Steelwood#1, 1544 Steelwood#3, 1504 Steelwood#1

Please list all major vendors servicing the Property (If addition provided, please attach separate sheet):

	Vendor Name	Phone No.		Vendor Name	Phone No.
Roofing	<mark>?</mark>	?	Painting	JF Painting	775-690-3209
Elevator	TK Elevator	888-952-9647	HVAC	Gardner Mech	775-329-4133
Fire Protection	Summit Fire	775-900-9209	Plumbing	Michael's Plumbing	775-355-1611
Electrician	Merit Electric	775-853-3444	Trash Disposal	Waste Management	775-329-8822
Landscaping	T&T Lawns	775-424-4168	Security System	All Pro Security	775-284-3644

Please list all utility	provider	s for the Pro	perty:							
Domestic Water	TMWA	TMWA			Gas/ Oil/ Other	NV Ener	NV Energy			
Sanitary Sewer	City of	f Reno			Electricity	NV Ener	gy			
Storm Drainage	City of	f Reno			Steam	N/A				
Please provide info	rmation r	egarding cui	rrent unit r	nix:						
Unit Type:		Occupied	Vacant	Down	Unit Type:		Occupied	Vacant	Down	
Studio					3 Bedroom/ 1.5 B	athroom				
1 Bedroom/ 1 Bath	room				3 Bedroom/ 2 Bat	hroom				



1 Bedroom/ 1 1/2 Bath			4 Bedroom/ 1 Bathroom		
2 Bedroom/ 1 Bath	97	3	Model Unit/Manager Unit		
2 Bedroom/ 1 1/2 Bath					

			_
QUESTIONNAIRE Note to Field Observer: Answers should be verified during site interview and field observations.	YES	No	Unknown
A YES answer should be followed up thoroughly and documented if issues are present.	1		
Are you aware of any violations the property has been cited for? (If Yes, attach citation)		X	
Does the property feature Section 8 project based assistance?		X	
Does the property accept Section 8 vouchers?		X	
Was an "Accessibility Survey" ever conducted on the property? (If Yes, please attach a copy)			
Have any accessibility improvements been made to the Property or does a Barrier Removal Plan exist for the Property?			
Are there any unresolved accessibility related complaints or pending litigation?			
Is a tenant monthly fee charged for common area maintenance (CAM)?			
Does the Property experience any site drainage, ground water or flooding problems?			
Is the amount of on-site parking provided inadequate?			
Is there damaged or nonoperational site lighting?			
Are the utilities (water, sewer, gas, electric) inadequate to meet needs of the tenants?			
Does the Property have any structural issue such as settlement, cracking or deflection?			
Has the Property experienced any fire related or seismic damage?			
Does the Property exhibit any water/ moisture infiltration?			
Does the Property exhibit any sewer backups?			
Does the Property have any leakage or failures at the roof, walls or cellar?			
Is fire retardant plywood (FRT) installed anywhere in the structure(s)?			
Are any portions of the facades covered with EIFS (synthetic stucco or Dryvit)?			
Any problems regarding synthetic stucco or EIFS?			
Roof is inaccessible with no on-site OSHA approved ladder or roof hatch?			
Are the HVAC systems inadequate and/or non-functioning?			
Are there any plumbing leaks or prevalent past leaks?			
Are there any water pressure issues at any time?			
Is galvanized or polybutylene "gray" piping present anywhere in the Property?			
Has any active or historical leaks related to galvanized or polybutylene piping occurred?			
Has retrofitting or replacement of galvanized or polybutylene piping taken place?			
Are there any electrical problems or inadequate electrical service?			
Electrical amperage to each unit is less than 60-amps?			
Is aluminum branch wiring present anywhere in the Property?			
If aluminum branch wiring is present, has retrofitting been performed?			
Are there any screw-in fuses present in the Property?			
Are there kitchens and bathrooms that are not equipped with GFI's/GFCI's?			
Are there any elevator or escalator shutdowns or deemed out of service?			
Are there any elevator or escalator strutdowns or deemed out or service: Are there elevators present not regularly serviced under a full-service maintenance contract?			
Are there elevators present not regularly serviced drider a full-service maintenance contract: Are there fire sprinkler systems present and not regularly serviced and tested?			
Are there fire alarm and detection devices not regularly serviced and tested?			
Is common area interior painting performed as part of routine maintenance?			
Is there any mold or microbial growth at the Property?			
Have any tenants or occupants complained about mold or microbial growth at the Property?			
Is there a current formal indoor air quality management plan at the Property?			
Are there any water leaks or damage at the Property?			
Please indicate when the following systems have been last inspected:			
Fire Sprinkler Elevators/ Escalators			

Facades _____

Fire Alarm






REPLACEMENT/ REPA	REPLACEMENT/ REPAIR HISTORY							
Please list the approxin				ı consti	ruction If a	applicable give a	n estimated range	
(Indicate "NA" if tenant-owned or not applicable; indicate "ORIG", if from original building construction. If applicable, give an estimated range, i.e. approx. 50% are 3 yrs. in age, 25% are 10 yrs. in age, etc. – please attach additional pages for comments/ clarifications.								
Paving:	Yrs.	Sealant/Striping:		Yrs.	Ext	erior Lighting:	Yrs.	
Landscaping:	Yrs.	Irrigation System:		Yrs.	Buil	ding Signage:	Yrs.	
Pool Deck:	Yrs.	Pool Surfaces:		Yrs.	Other_	:	Yrs.	
Masonry Pointing:	Yrs.	Exterior Paint:		Yrs.		EIFS:	Yrs.	
Windows:	Yrs.	Doors:		Yrs.	Build	ding Sealants:	Yrs.	
Roofing:	Yrs.	Other Roofing:		Yrs.		Skylights:	Yrs.	
HVAC ():	Yrs.	HVAC (): Emergency		Yrs.	HVAC ():	Yrs.	
Electric Service:	Yrs.	Generator:		Yrs.		Water Lines:	Yrs.	
Water Pumps:	Yrs.	Water Heaters:		∕rs.		Sewer Lines	Yrs.	
Elevator Finishes:	Yrs.	Elevator Controller:		Yrs.		or Machinery: ral Fire Alarm	Yrs.	
Escalators:	Yrs.	Fire Pump:	/	∕rs.		Panel:		
Common Areas:	Yrs.	Unit Finishes:		Yrs.	Un	it Appliances:	Yrs.	
DOCUMENT REVIEW								
Please provide us with documentation may be						oility of each.	This	
					ailable n-site	Available Attached	Not Available	
Site Plan and ALTA Su								
Certificate of Occupano	•							
Copy of Open Building								
Copy of Zoning Variand			2224 0/)					
Rent Roll (with unit nun Reduced Floor Plans	nber, teriant nam	e, uniit area and occup	Dancy 76)					
Original construction do	ocuments (core a	nd shell)						
List of Mechanical Equi	•							
List of Capital expenditures for last 5 years								
List of Planned Capital expenditures								
Local Law #11 Façade Inspection Reports (NYC)								
Roof survey and warrar	•							
Service reports and ins			ator, HVAC,					
electrical generator, fire ADA Survey or Barrier		NICI)						
Previously prepared Pre		Report or engineering	studies					
Interviewee / Title:			,	1		Date:		

APPENDIX I

Record of all Documents Reviewed, Interviews, and Supporting Information



HAWK VIEW APARTMENTS FOUNDATION STABILIZATION



GENERAL NOTES

1. THE CONTRACT DOCUMENTS ARE COMPLEMENTARY AND WHAT IS REQUIRED BY ANY ONE SHALL BE AS BINDING AS IF REQUIRED BY ALL. THE INTENTIONS OF THE DOCUMENTS IS TO INCLUDE ALL LABOR, MATERIALS, EQUIPMENT AND OTHER ITEMS AS NECESSARY FOR THE PROPER EXECUTION AND COMPLETION OF THE WORK. CONTRACTOR IS TO VERIFY ALL EXISTING CONDITIONS AND DIMENSIONS AND IS TO CONTACT ENGINEER PRIOR TO PROCEEDING WITH WORK IF DISCREPANCIES OR UNANTICIPATED CONDITIONS ARE FOUN 2. DO NOT SCALE DRAWINGS. ANY QUESTIONS REGARDING DIMENSIONS SHOULD BE DIRECTED TO THE ENGINEER PRIOR TO PROCEEDING WITH THE WORK.

3. NOTES REPRESENT ITEMS OF WORK TO BE ACCOMPLISHED AT EACH LOCATION OF THE ITEM THROUGHOUT THE SITE, BUILDING OR PROJECT LIMITS.

4. BEFORE SUBMITTING A BID: EACH BIDDER SHALL CAREFULLY EXAMINE THE DRAWINGS, READ THE SPECIFICATIONS AND ALL OTHER PROPOSED CONTRACT DOCUMENTS AND VISIT THE SITE OF THE WORK. EACH BIDDER SHALL FULLY INFORM HIM/HERSELF PRIOR TO BIDDING AS TO ALL EXISTING CONDITIONS AND LIMITATIONS UNDER WHICH THE WORK IS TO BE PERFORMED AND HE SHALL INCLUDE IN HIS BID A SUM TO COVER ALL COSTS OF ALL ITEMS NECESSARY TO PERFORM THE WORK AS SET FORTH IN THE PROPOSED CONTRACT DOCUMENTS. NO ALLOWANCE WILL BE MADE TO ANY BIDDER BECAUSE OF LACK OF SUCH EXAMINATION OR KNOWLEDGE. THE SUBMISSION OF A BID WILL BE CONSTRUED AS CONCLUSIVE EVIDENCE.

5. THE CONTRACTOR SHALL CAREFULLY STUDY AND COMPARE THE CONTRACT DOCUMENTS WITH EACH OTHER, WITH INFORMATION FURNISHED BY THE OWNER, WITH EXISTING CONDITIONS AND SHALL AT ONCE REPORT TO THE ENGINEER ERRORS, INCONSISTENCIES, OR OMISSIONS DISCOVERED.

6. ALL WORK PERFORMED UNDER THIS CONTRACT SHALL COMPLY WITH THE CURRENT EDITION OF THE CALIFORNIA BUILDING CODE, UNIFORM PLUMBING CODE, CALIFORNIA ELECTRICAL CODE AND OTHER RELATED LOCAL CODES, ORDINANCES AND STATE STATUTES.

7. COORDINATION: COORDINATE VARIOUS CONSTRUCTION ACTIVITIES TO ASSURE EFFICIENT AND ORDERLY INSTALLATION OF EACH PART OF THE WORK. COORDINATE CONSTRUCTION OPERATIONS THAT ARE DEPENDENT UPON EACH OTHER FOR PROPER INSTALLATION, CONNECTION AND OPERATION.

8. INSPECTION OF CONDITIONS: THE INSTALLER OF EACH COMPONENT SHALL INSPECT THE SUBSTRATE AND

CONDITIONS UNDER WHICH WORK IS TO BE PERFORMED. DO NOT PROCEED UNTIL UNSATISFACTORY CONDITIONS HAVE BEEN CORRECTED.

9. MANUFACTURER'S INSTRUCTIONS: COMPLY WITH MANUFACTURER'S INSTALLATION INSTRUCTIONS AND RECOMMENDATIONS, TO THE EXTENT THAT THEY ARE MORE STRINGENT THAN REQUIREMENTS CONTAINED IN

THE CONTRACT DOCUMENTS.

10. INSPECT MATERIAL AND EQUIPMENT IMMEDIATELY UPON DELIVERY AND AGAIN PRIOR TO INSTALLATION.

REJECT DAMAGED AND DEFECTIVE ITEMS.

11. PROVIDE ATTACHMENT AND CONNECTION DEVICES AND METHODS NECESSARY FOR SECURING WORK. SECURE

EACH WORK TRUE TO LINE AND LEVEL.

12. INSTALL EACH COMPONENT DURING WEATHER CONDITIONS AND PROJECT STATUS THAT WILL ENSURE THE BEST RESULTS. ISOLATE EACH PART FROM INCOMPATIBLE MATERIAL AS NECESSARY TO PREVENT

13. CLEANING AND PROTECTION DURING HANDLING AND INSTALLATION: CLEAN AND PROTECT CONSTRUCTION IN PROGRESS AND ADJOINING MATERIALS IN PLACE. APPLY PROTECTIVE COVERING WHERE REQUIRED TO INSURE PROTECTION FROM DAMAGE OR DETERIORATION. CLEAN AND MAINTAIN COMPLETED CONSTRUCTION

AS OFTEN AS NECESSARY THROUGH THE CONSTRUCTION PERIOD.

14. LIMITING EXPOSURES: SUPERVISE CONSTRUCTION ACTIVITIES TO ENSURE THAT NO PART OF CONSTRUCTION, EXISTING, COMPLETED OR IN PROGRESS, IS SUBJECT TO HARMFUL OR DELETERIOUS EXPOSURE. SUCH EXPOSURES INCLUDE:

EXCESSIVE STATIC OR DYNAMIC LOADINGEXCESSIVE WEATHERING

- EXCESSIVE HIGH OR LOW TEMPERATURES OR HUMIDITY AIR CONTAMINATION OR POLLUTION
- WATER OR ICE
 CHEMICALS OR SOLVENTS
- HEAVY TRAFFIC, SOILING, STAINING OR CORROSION
 UNUSUAL WEAR OR OTHER MISUSE
- CONTACT BETWEEN INCOMPATIBLE MATERIALS

THEFT OR VANDALISM

15. APPLICABILITY OF STANDARDS: EXCEPT WHERE CONTRACT DOCUMENTS INCLUDE MORE STRINGENT REQUIREMENTS, APPLICABLE INDUSTRY STANDARDS HAVE THE SAME FORCE AND EFFECT AS IF BOUND OR COPIED INTO CONTRACT DOCUMENTS. SUCH STANDARDS ARE PART OF THE CONTRACT DOCUMENTS BY REFERENCE. WHERE COMPLIANCE WITH A STANDARD IS REQUIRED, COMPLY WITH STANDARD IN EFFECT AS

OF DATE OF CONTRACT DOCUMENTS.

16. CONFLICTING REQUIREMENTS: WHERE COMPLIANCE WITH TWO OR MORE STANDARDS THAT ESTABLISH DIFFERENT OR CONFLICTING REQUIREMENTS FOR MINIMUM QUANTITIES OR QUALITY LEVELS IS SPECIFIED, THE MOST STRINGENT REQUIREMENT WILL BE ENFORCED. REFER UNCERTAINTIES AS TO WHICH QUALITY LEVEL IS

MOST STRINGENT REQUIREMENT WILL BE ENFORCED. REFER UNCERTAINTIES AS TO WHICH QUALITY LEVEL IS MORE STRINGENT TO THE ARCHITECT FOR A DECISION BEFORE PROCEEDING.

17. CONTRACTOR RESPONSIBILITIES: PROVIDE INSPECTIONS AND TESTS SPECIFIED OR REQUIRED BY GOVERNING

AUTHORITIES, FOR YOUR PART OF THE WORK.

18. SOURCE LIMITATIONS: TO THE FULLEST EXTENT POSSIBLE, PROVIDE PRODUCTS OF THE SAME KIND, FROM A SINGLE SOURCE

PROJECT TEAM

GENERAL

MATTHEW ROBINSON CITY OF RENO HOUSING AUTHORITY 1525 EAST 9TH STREET RENO, NV 89512

P: (775) 329-3630 EXT: 213 E: mrobinson@renoha.org

ARCHITECTURAL / STRUCTURAL

290 BRINKBY AVE. #205

F: (775) 297-0739 E: Brett@mcelhaneystructural.com

G000

SHEET INDEX

S000 S001 S002 S101 TITLE SHEET
GENERAL NOTES
GENERAL NOTES

PROJECT INFORMATION

SCOPE OF WORK

PROVIDE DESIGN AND COST ESTIMATE TO STABILIZE INTERIOR BEARING WALL FOUNDATIONS IN CRAWL SPACE.


DESIGN INFORMATION

OCCUPANCY CLASSIFICATION:
LIVE LOAD: SEE STRUCTURAL
GROUND SNOW LOAD: SEE STRUCTURAL
ROOF SNOW LOAD: SEE STRUCTURAL
SOIL BEARING: SEE STRUCTURAL
WIND SPEED: SEE STRUCTURAL
WIND EXPOSURE: SEE STRUCTURAL
SEISMIC INFORMATION: SEE STRUCTURAL

SEE STRUCTURAL

SITE CLASS:

PROJECT LOCATION Hawk View Apartments Tripp Dr VICINITY MAP





HAWK VIEW APARTMENTS FOUNDATION STABILIZATION City of Reno Housing Authority 1524 Steelwood Ln,

DRAWING DESCRIPTION

TITLE SHEET

DRAWN BY:

SZ
CHECKED BY:

BAM
DATE:

11/24/2020
SCALE:

JOB NUMBER:
PROJECT NUMBER
SHEET:

DIVISION 01

GENERAL REQUIREMENTS

- THE CONTRACTOR SHALL VERIFY ALL DIMENSIONS AND CONDITIONS PRIOR TO STARTING CONSTRUCTION. THE ENGINEER SHALL BE NOTIFIED OF ANY DISCREPANCIES OR INCONSISTENCIES.
- DO NOT SCALE THE DRAWINGS FOR WORKING DIMENSIONS. NOTES AND DETAILS ON DRAWINGS SHALL TAKE PRECEDENCE OVER GENERAL NOTES AND TYPICAL DETAILS. TYPICAL DETAILS SHALL APPLY TO THE PROJECT DRAWINGS EXCEPT WHEN SPECIFIC DETAILS
- ARE SHOWN WHICH SHALL TAKE PRECEDENCE. ALL WORK SHALL CONFORM TO THE MINIMUM STANDARDS OF THE FOLLOWING CODE: THE 2018 INTERNATIONAL BUILDING CODE (IBC), ANY OTHER REGULATING AGENCIES WHICH HAVE AUTHORITY OVER ANY PORTION OF THE WORK, AND THE CODES AND STANDARDS LISTED IN THESE NOTES AND
- SEE ARCHITECTURAL DRAWINGS FOR THE FOLLOWING:
 - a. SIZE AND LOCATION OF WINDOW AND DOOR OPENINGS. b. SIZE AND LOCATION OF CONCRETE CURBS, FLOOR DRAINS, AND DEPRESSED AREAS.
 - c. SIZE AND LOCATION OF FLOOR AND ROOF OPENINGS. EXCEPT AS SHOWN.
- d. SIZE AND LOCATION OF INTERIOR AND EXTERIOR NON-BEARING PARTITIONS. SEE MECHANICAL, PLUMBING, AND ELECTRICAL DRAWINGS FOR THE FOLLOWING:
- a. ELECTRICAL CONDUIT RUNS, BOXES, OUTLETS IN WALLS, AND SIZE AND LOCATION OF
- EQUIPMENT BASES. b. PIPE RUNS, SLEEVES, HANGERS, TRENCHES, AND OPENINGS.
- c. CONCRETE INSERTS OR FIXTURES.
- CONTRACTOR SHALL INVESTIGATE SITE DURING CLEARING AND EARTH WORK OPERATIONS FOR FILLED EXCAVATIONS OR BURIED STRUCTURES SUCH AS CESSPOOLS, CISTERNS, FOUNDATIONS, ETC. IF ANY SUCH STRUCTURES ARE FOUND, NOTIFY STRUCTURAL ENGINEER IMMEDIATELY.
- THE CONTRACT STRUCTURAL DRAWINGS AND SPECIFICATIONS REPRESENT THE FINISHED STRUCTURE. THEY DO NOT INDICATE THE METHOD OF CONSTRUCTION. THE CONTRACTOR SHALL PROVIDE ALL MEASURES NECESSARY TO PROTECT THE STRUCTURE DURING CONSTRUCTION. SUCH MEASURES SHALL INCLUDE, BUT NOT BE LIMITED TO, BRACING, SHORING FOR LOADS DUE TO CONSTRUCTION EQUIPMENT, ETC. OBSERVATION VISITS TO THE SITE BY THE STRUCTURAL ENGINEER SHALL NOT INCLUDE INSPECTION OF THE ABOVE ITEMS.
- OPENINGS, POCKETS, ETC. LARGER THAN 6 INCHES SHALL NOT BE PLACED IN SLABS, DECKS, BEAMS, JOISTS, COLUMNS, WALLS, ETC, UNLESS SPECIFICALLY DETAILED ON THE STRUCTURAL DRAWINGS. NOTIFY THE STRUCTURAL ENGINEER WHEN DRAWINGS BY OTHERS SHOW OPENINGS, POCKETS, ETC. NOT SHOWN ON THE STRUCTURAL DRAWINGS, BUT WHICH ARE LOCATED IN STRUCTURAL MEMBERS.
- 10. CONSTRUCTION MATERIALS SHALL BE SPREAD OUT IF PLACED ON FRAMED FLOORS OR ROOF. LOAD SHALL NOT EXCEED THE DESIGN LIVE LOAD PER SQUARE FOOT. PROVIDE ADEQUATE SHORING AND/OR BRACING WHERE STRUCTURE HAS NOT ATTAINED DESIGN STRENGTH.
- 11. SHOP DRAWINGS SUBMITTED TO THE STRUCTURAL ENGINEER FOR REVIEW SHALL CONSIST OF THE NUMBER OF SETS TO BE RETURNED PLUS ONE. SHOP DRAWING SUBMITTALS SHALL BE BOUND 12. ADHESIVE ANCHORS SHALL BE SIMPSON SET-XP EPOXY PER ICC ESR-2508 WITH ASTM A-36 THREADED
- ROD OR APPROVED EQUAL, U.N.O. EXPANSION ANCHORS SHALL BE SIMPSON STRONG-BOLT CARBON STEEL PER ICC ESR-1771, U.N.O. ADHESIVE OR EXPANSION ANCHORS SHALL NOT BE INSTALLED UNTIL MASONRY OR CONCRETE HAS CURED TO DESIGN STRENGTH. 13 DESIGN LOADS:

. DESIGN LUADS.	
ROOF DEAD LOAD:	12 psf
ROOF LIVE LOAD:	20 psf
FLOOR DEAD LOAD:	12 psf
FLOOR LIVE LOAD:	40 psf
GROUND SNOW LOAD:	30 psf
ROOF SNOW LOAD DATA:	
 ROOF SNOW LOAD: 	21 psf
2. Ce = 0.9	
3. ls = 1.00	

- 4. Ct = 1.1 WIND DESIGN DATA:
- 1. ULTIMATE DESIGN WIND SPEED = 120 mph (3-SECOND GUST) 2. RISK CATEGORY II
- WIND EXPOSURE C 4. INTERNAL PRESSURE COEFFICIENT = 0.18
- EARTHQUAKE DESIGN DATA
- RISK CATEGORY II 2. le = 1.00
- 3. Ss = 1.456g, S1 = 0.511g
- 4. SITE CLASS: D 5. Sds = 1.165g, Sd1 = 0.511g
- 6. SEISMIC DESIGN CATEGORY: D
- 7. BASIC SEISMIC-FORCE-RESISTING SYSTEM(S): = LIGHT FRAMED WALL SHEATHED WITH STRUCTURAL PANELS RATED FOR SHEAR RESISTANCE.
- 8. RESPONSE MODIFICATION COEFFICIENT(S), R = 6.5
- 9. ANALYSIS PROCEDURE USED: EQUIVALENT LATERAL FORCE

DIVISION 01

SUMMARY OF WORK

- 1. IT SHALL BE THE CONTRACTOR'S DIRECT RESPONSIBILITY TO COMPLY WITH TYPICAL DETAILS AND GENERAL NOTES AS DELINEATED OR DEFINED ON THE TYPICAL DETAIL DRAWINGS OF THESE CONTRACT DOCUMENTS REGARDLESS OF SPECIFIC FLAGGING OR REFERENCE TO APPLICABLE NOTE OR DETAIL. IT SHALL BE THE CONTRACTOR'S RESPONSIBILITY TO COORDINATE WITH ALL TRADES REGARDING
- UTILITIES PASSING THROUGH AND UNDER FOOTINGS. STRUCTURAL REQUIREMENTS FOR THESE CONDITIONS ARE DELINEATED IN TYPICAL DETAILS. TOP OF FOOTING ELEVATIONS NOTED ARE MINIMUM. SEE NOTE 2 FOR ADDITIONAL REQUIREMENTS. . CONTRACTOR SHALL VERIFY AND COORDINATE ALL LOCATIONS AND SIZES OF OPENINGS IN SLABS, SLAB
- DEPRESSIONS, AND CURBS FOR ALL RELATED CONSTRUCTION PRIOR TO FLOOR LAYOUT OR CONSTRUCTION. CONTRACTOR SHALL THEN USE APPROPRIATE DETAIL(S) OR WALL SECTION FOR EACH CONTRACTOR SHALL VERIFY WITH APPROPRIATE SUB-CONTRACTORS THE EXACT LOCATION, WEIGHT, AND INTENDED METHOD OF ATTACHMENT OF ALL ITEMS TO BE SUSPENDED FROM OR IN ANY WAY ATTACHED TO ANY ROOF FRAMING OR OTHER STRUCTURAL MEMBER UNLESS SUCH ITEM(S) ARE CLEARLY
- ADDRESSED BY THE STRUCTURAL CONSTRUCTION DOCUMENTS. THIS INFORMATION SHALL BE TRANSMITTED IN WRITING TO THE APPROPRIATE FRAMING MANUFACTURER VIA THE STRUCTURAL ENGINEER PRIOR TO FINAL DESIGN OR FABRICATION OF STRUCTURAL FRAMING MEMBERS.
- CONTRACTOR SHALL VERIFY ALL DIMENSIONS WITH ENGINEER PRIOR TO CONSTRUCTION. CONTRACTOR SHALL VERIFY ALL EXISTING CONDITIONS AND DIMENSIONS AND NOTIFY THE STRUCTURAL ENGINEER IN WRITING OF ANY DISCREPANCIES.
- THE CONTRACTOR AND ALL SUB-CONTRACTORS HE/SHE INTENDS TO USE (INCLUDING AGENTS AND SUPPLIERS) ARE AWARE OF AND ACKNOWLEDGE THAT CLOSE COORDINATION AMONG ARCHITECTURAL, MECHANICAL, PLUMBING, ELECTRICAL, AND STRUCTURAL DRAWINGS IS REQUIRED FOR THE FOLLOWING: a. DETERMINATION OF ALL COLUMN LOCATIONS AND SIZES.
- b. DETERMINATION OF TOP OF FLOOR, TOP OF STEEL, WALL PLATES, AND TOP OF BEAM ELEVATIONS. c. VERIFICATION OF ALL DIMENSIONS. d. VERIFICATION OF ALL TOP OF FOOTINGS.
- THE CONTRACTOR AND ALL SUB-CONTRACTORS HE/SHE INTENDS TO USE (INCLUDING AGENTS AND SUPPLIERS) SHALL MAKE CONSIDERATION FOR AND INCLUDE MONIES FOR THE ABOVE, IN PREPARATION OF THEIR BIDS. THIS REQUIREMENT SHALL SUPERSEDE ANY CONTAINED IN THE AISC "MANUAL OF STEEL CONSTRUCTION"

DIVISION 01

FOUNDATION PERFORMANCE REQUIREMENTS

- . FOUNDATION DESIGN BASED ON 2018 IBC TABLE 1806.2, SOIL CLASS 5. FOOTING DESIGN BASED ON ALLOWABLE SOIL BEARING PRESSURE OF 1500 psf DEAD PLUS LIVE LOADS AND 1995 psf TOTAL LOAD (INCLUDING WIND OR SEISMIC).
- 2. THE CONTRACTOR SHALL PROVIDE FOR PROPER DE-WATERING OF EXCAVATIONS FROM SURFACE WATER, GROUND WATER, SEEPAGE, ETC.
- THE CONTRACTOR SHALL PROVIDE FOR DESIGN AND INSTALLATION OF ALL CRIBBING, SHEATHING, AND
- SHORING REQUIRED TO SAFELY AND ADEQUATELY RETAIN THE EARTH BANKS. EXCAVATIONS FOR FOOTINGS SHALL BE APPROVED BY THE SOILS ENGINEER PRIOR TO PLACING THE CONCRETE AND REINFORCING. THE CONTRACTOR SHALL NOTIFY THE SOILS ENGINEER WHEN INSPECTION OF EXCAVATIONS ARE READY. THE SOILS ENGINEER SHALL SUBMIT A LETTER OF COMPLIANCE TO THE
- ALL EXCAVATIONS SHALL BE PROPERLY BACKFILLED. DO NOT PLACE BACKFILL BEHIND RETAINING WALLS BEFORE CONCRETE HAS ATTAINED FULL DESIGN STRENGTH. THE CONTRACTOR SHALL BRACE OR PROTECT ALL BUILDING PIT WALLS BELOW GRADE FROM LATERAL LOADS UNTIL ATTACHING FLOORS ARE COMPLETELY IN PLACE AND HAVE ATTAINED FULL STRENGTH. THE CONTRACTOR SHALL PROVIDE FRO DESIGN, PERMITS, AND INSTALLATION OF SUCH BRACING.
- FOOTINGS SHALL BE PLACED AND ESTIMATED ACCORDING TO DEPTHS SHOWN ON DRAWINGS. SHOULD SOIL ENCOUNTERED AT THESE DEPTHS NOT BE APPROVED BY THE SOILS ENGINEER, FOOTING ELEVATIONS OR FOOTING DESIGN WILL BE ALTERED BY CHANGE ORDER.
- FOOTING BACKFILL AND UTILITY TRENCH BACKFILL WITHIN BUILDING AREA SHALL BE MECHANICALLY COMPACTED IN LAYERS, TO THE APPROVAL OF THE SOILS ENGINEER. FLOODING WILL NOT BE PERMITTED. ALL ABANDONED FOOTINGS, UTILITIES, ETC. THAT INTERFERE WITH NEW CONSTRUCTION SHALL BE

DIVISION 01 SPECIAL INSPECTION AND DEFERRED SUBMITTALS

- SPECIAL INSPECTIONS SHALL BE IN COMPLIANCE WITH IBC SECTION 1704. 2. THE OWNER SHALL EMPLOY A QUALIFIED TESTING AGENCY TO PROVIDE A QUALITY ASSURANCE AND
- TESTING PROGRAM AS NOTED IN SECTIONS 1705, 1706, 1707, AND 1708 OF THE IBC. THE TESTING AGENCY SHALL WORK WITH THE ENGINEER OF RECORD IN DEVELOPING A QUALITY ASSURANCE PLAN. 3. STATEMENT OF SPECIAL INSPECTION PER IBC SECTION 1705.

		CONTINUOUS	PERIOD
DRI	/EN DEEP FOUNDATION ELEMENTS		
1.	VERIFY ELEMENT MATERIALS, SIZES AND LENGTHS COMPLY WITH THE REQUIREMENTS.	Х	-
2.	DETERMINE CAPACITIES OF TEST ELEMENTS AND CONDUCT ADDITIONAL LOAD TEST, AS REQUIRED.	Х	-
3.	OBSERVE DRIVING OPERATIONS AND MAINTAIN COMPLETE AND ACCURATE RECORDS FOR EACH ELEMENT.	Х	-
4.	VERIFY PLACEMENT LOCATIONS AND PLUMBNESS, CONFORM TYPE AND SIZE OF HAMMER, RECORD NUMBER OF BLOWS PER FOOT OF PENETRATION, DETERMINE REQUIRED PENETRATIONS TO ACHIEVE DESIGN CAPACITY, RECORD TIP AND BUTT ELEVATIONS AND DOCUMENT ANY DAMAGE TO FOUNDATION ELEMENT.	х	-
5.	FOR STEEL ELEMENTS, PERFORM ADDITIONAL INSPECTIONS IN ACCORDANCE WITH SECTION 1705.2.		
6.	FOR CONCRETE ELEMENTS AND CONCRETE FILLED ELEMENTS, PERFORM ADDITIONAL INSPECTIONS IN ACCORDANCE WITH SECTION 1705.3.		
7.	FOR SPECIALTY ELEMENTS, PERFORM ADDITIONAL INSPECTIONS AS DETERMINED BY THE REGISTERED DESIGN PROFESSIONAL IN RESPONSIBLE CHARGE.		

4. STRUCTURAL OBSERVATIONS. THE OWNER SHALL EMPLOY THE ENGINEER OR ARCHITECT RESPONSIBLE FOR THIS STRUCTURAL DESIGN, OR ANOTHER ENGINEER OR ARCHITECT DESIGNATED BY THE ENGINEER OR ARCHITECT RESPONSIBLE FOR THE STRUCTURAL DESIGN, TO PERFORM STRUCTURAL OBSERVATION AS DEFINED IN SECTION 202. OBSERVED DEFICIENCIES SHALL BE REPORTED IN WRITING TO THE OWNER'S REPRESENTATIVE, SPECIAL INSPECTOR, CONTRACTOR & THE BUILDING OFFICIAL, THE STRUCTURAL OBSERVER SHALL SUBMIT TO THE BUILDING OFFICIAL A WRITTEN STATEMENT THAT THE SITE VISITS HAVE BEEN MADE & IDENTIFYING ANY REPORTED DEFICIENCIES THAT, TO THE BEST OF THE STRUCTURAL OBSERVER'S KNOWLEDGE. HAVE NOT BEEN RESOLVED. STRUCTURAL OBSERVATIONS SHALL BE PERFORMED AT THE FOLLOWING STAGES OF CONSTRUCTION PRIOR TO PLACEMENT OF CONCRETE:

STRUCTURAL OBSERVATION DOES NOT WAIVE NOR REPLACE RESPONSIBILITY FOR THE INSPECTIONS REQUIRED OF THE BUILDING INSPECTOR OR THE DEPUTY INSPECTOR. STRUCTURAL OBSERVATION IS NOT INSPECTION. IT IS FAMILIARIZATION WITH THE PROGRESS AND QUALITY OF THE WORK AND CLARIFICATION OF THE DOCUMENTS AND GENERAL CONFORMANCE TO DESIGN INTENT. SEE "INSPECTION NOTES" FOR INSPECTION CRITERIA AND NOTE THAT CONTINUOUS SPECIAL INSPECTION PERFORMED BY A QUALIFIED DEPUTY IS REQUIRED FOR ALL PRIMARY STRUCTURAL ELEMENTS, ETC. THE CONTRACTOR AND INSPECTOR WILL ASSURE THAT CERTIFIED RECORD OF CONTINUOUS SPECIAL INSPECTION OF THE WORK TO BE OBSERVED IS MADE AVAILABLE TO THE OBSERVER BEFORE REQUESTING OBSERVATION. THE STRUCTURAL OBSERVER SHALL PERFORM SITE VISITS AT THOSE STEPS IN THE PROGRESS OF THE WORK THAT ALLOW FOR CORRECTION OF DEFICIENCIES WITHOUT SUBSTANTIAL EFFORT OR UNCOVERING OF THE WORK INVOLVED. 5. DEFERRED SUBMITTALS. THE FOLLOWING DEFERRED SUBMITTALS SHALL FIRST BE SUBMITTED TO THE PROJECT ENGINEER OF RECORD/ARCHITECT FOR REVIEW AND COORDINATION. FOLLOWING THE COMPLETION OF THE REVIEW AND COORDINATION BY THE ENGINEER OF RECORD/ARCHITECT, A SUBMITTAL WOULD THEN BE MADE TO THE CITY BUILDING DEPARTMENT FOR REVIEW AND APPROVAL. THE SUBMITTAL WILL INCLUDE A LETTER STATING THAT THIS REVIEW AND COORDINATION IS COMPLETED AND PLANS AND CALCULATIONS FOR THE DEFERRED ITEMS ARE FOUND TO BE ACCEPTABLE WITH NO EXCEPTIONS.

DIVISION 03 REINFORCING STEEL

a. INSTALLATION OF PUSH PIERS

- ALL REINFORCING STEEL SHALL BE DETAILED AND PLACED IN CONFORMANCE WITH THE "BUILDING CODE REQUIREMENTS FOR REINFORCED CONCRETE" (ACI 318, LATEST APPROVED EDITION), AND THE "MANUAL OF STANDARD PRACTICE FOR REINFORCED CONCRETE CONSTRUCTION" (LATEST EDITION), BY THE C.R.S.I.
- AND THE W.C.R.S.I., AS MODIFIED BY THE PROJECT DRAWINGS AND SPECIFICATIONS. . DEFORMED REINFORCING BARS SHALL BE ASTM A-615 GRADE 60, EXCEPT TIES, STIRRUPS, SLAB DOWELS, AND REINFORCING BARS IN NON-STRUCTURAL CONCRETE SUCH AS, SLABS ON GRADE, WHICH MAY BE GRADE 40, UNLESS NOTED OTHERWISE. USE ASTM A-706 REINFORCING BARS THAT ARE REQUIRED TO BE
- 3. DEFORMED REINFORCING BARS FOR MOMENT FRAMES SHALL CONFORM TO THE 2018 INTERNATIONAL BUILDING CODE (IBC), CHAPTER 19.
- 4. WELDING OF REINFORCING BARS SHALL BE WITH LOW HYDROGEN ELECTRODES IN CONFORMANCE WITH "RECOMMENDED PRACTICES FOR WELDING REINFORCING STEEL", AMERICAN WELDING SOCIETY, AWS-D1.4 (SEE SPECIFICATIONS).
- 5. ALL REINFORCING BARS BENDS SHALL BE MADE COLD. 6. WELDED WIRE FABRIC (WWF) SHALL CONFORM TO ASTM A-185.
- MINIMUM LAP OF WELDED WIRE FABRIC SHALL BE 6" OR 1-1/2 FULL MESH, WHICH EVER IS GREATER. REINFORCING SPLICES SHALL BE MADE ONLY WHERE INDICATED ON THE DRAWINGS.
- 9. DOWELS BETWEEN FOOTINGS AND WALLS OR COLUMNS SHALL BE THE SAME GRADE, SIZE, AND SPACING OR NUMBER AS THE VERTICAL REINFORCING, RESPECTIVELY.
- 10. ALL BARS SHALL BE MARKED SO THEIR IDENTIFICATION CAN BE VERIFIED WHEN THE FINAL IN-PLACE INSPECTION IS PERFORMED. 11. THE CONTRACTOR SHALL PROVIDE FOR AN ALLOWANCE OF TWO TONS OF REINFORCING BARS TO BE FURNISHED, FABRICATED, AND PLACED DURING PROGRESS OF WORK AS MAY BE DIRECTED BY THE
- STRUCTURAL ENGINEER, IN ADDITION TO ALL STEEL INDICATED ON THE DRAWINGS. 12. SEE TYPICAL DETAILS FOR REINFORCEMENT SPLICES IN CONCRETE. SPLICE ALL REINFORCING BARS 2'-6"
- MINIMUM, U.N.O. 13. ALL REINFORCING BARS SHALL BE TIED IN PLACE BEFORE CONCRETE OR GROUT.
- 14. DO NOT SPLICE REINFORCING STEEL IN THE MIDDLE THIRD OF WALLS

DIVISION 03 **CONCRETE**

- 1. ALL PHASES OF WORK PERTAINING TO THE CONCRETE CONSTRUCTION SHALL CONFORM TO THE "BUILDING CODE REQUIREMENTS FOR REINFORCED CONCRETE", AMERICAN CONCRETE INSTITUTE 318 (ACI 318) AND THE "SPECIFICATIONS FOR STRUCTURAL CONCRETE FOR BUILDINGS" (ACI 301), LATEST APPROVED ADDITIONS, WITH MODIFICATIONS AS NOTED IN THE DRAWINGS OR SPECIFICATIONS.
- REINFORCED CONCRETE DESIGN IS BY THE "ULTIMATE STRENGTH DESIGN METHOD." CONCRETE MIXES SHALL BE DESIGNED BY A QUALIFIED TESTING LABORATORY AND APPROVED BY THE
- STRUCTURAL ENGINEER. CALCIUM CHLORIDE SHALL NOT BE USED. a. PROPOSED MIX DESIGNS SHALL BE NO MORE THAN ONE (1) YEAR OLD, AND HAVE AFFIXED
- ON EACH SUBMITTED COPY THE ORIGINAL SEAL OF THE REVIEWING ENGINEER. THE REVIEWING ENGINEER SHALL BE REGISTERED IN THE STATE OF NEVADA.
- b. EACH DESIGN MIX SHALL INDICATE THE PROJECT NAME AND ADDRESS. THE CONTRACTOR
- SHALL DESIGNATE THE LOCATION OF USE FOR EACH PROPOSED MIX DESIGN. c. EACH MIX DESIGN SHALL INCLUDE THE SLUMP, BEFORE AND AFTER ADDING PLASTICIZER, AIR ENTRAINMENT, TYPE OF AGGREGATE, TYPE OF CEMENT, AND ADMIXTURES TO BE USED.
- 4. SCHEDULE OF STRUCTURAL CONCRETE 28 DAY STRENGTHS: LOCATION IN STRUCTURE STRENGTH NORMAL WT. 1) FOOTINGS 145 ± 5 pcf (DESIGN BASED ON 2,500) 4,000* 2) SLABS NORMAL WT. 145 ± 5 pcf 3) GRADE BEAMS 3,000* NORMAL WT. 145 ± 5 pcf
- 3,000* NORMAL WT. 145 ± 5 pcf 4) OTHER PROVIDE 6%±1% AIR ENTRAINMENT IN EXTERIOR CONCRETE AND ANY CONCRETE EXPOSED TO FREEZING
- * SEE NOTE 5 BELOW, FOR CONCRETE IN CONTACT WITH SOIL.
- 5. PORTLAND CEMENT SHALL CONFORM TO ASTM C-150, TYPE II. VERIFY w/ SOILS ENGINEER; USE TYPE V CEMENT w/ MAX. WATER TO CEMENT RATIO 0.45 AND F'c = 4,500 psi FOR CONCRETE IN CONTACT w/ SOIL IF
- DIRECTED BY THE SOILS ENGINEER. a. PANELS: MIN. 5-1/2 SACK CEMENT CONTENT, PLACED AT 3" MAX. SLUMP.
- b. SLABS ON GRADE: MIN. 5-1/2 SACK CEMENT CONTENT, PLACED AT 3" MAX. SLUMP.
- c. FOOTINGS: MIN. 5-1/4 SACK PER CUBIC YARD CEMENT CONTENT, 4" MAX. SLUMP. . MAXIMUM WATER TO CEMENT RATIO SHALL BE AS FOLLOWS:
- a. EXTERIOR SLABS AND ALL EXTERIOR CONCRETE: 0.45 b. INTERIOR SLABS: 0.54 AGGREGATE FOR NORMAL WEIGHT CONCRETE SHALL CONFORM TO ALL REQUIREMENTS AND TEST OF ASTM C-33 AND PROJECT SPECIFICATIONS. EXCEPTIONS MAY BE USED ONLY WITH PERMISSION FROM THE
- STRUCTURAL ENGINEER. MAXIMUM AGGREGATE SIZE SHALL CONFORM WITH THE FOLLOWING: 1/5 DISTANCE BETWEEN FORMS, 3/4 DISTANCE BETWEEN REINFORCING BARS, AND 1/3 THICKNESS OF SLAB. CONCRETE MIXING OPERATIONS, ETC. SHALL CONFORM TO ASTM C-94.
- 9. PLACEMENT OF CONCRETE SHALL CONFORM TO ACI 318 REQUIREMENTS AND PROJECT SPECIFICATIONS. SANDBLAST ALL CONCRETE SURFACES AGAINST WHICH CONCRETE IS TO BE PLACED.
- 10. IF COLUMNS AND WALLS ARE PLACED WITH FLOOR, TWO HOURS MUST ELAPSE BETWEEN THE END OF COLUMN OR WALL POUR AND THE BEGINNING OF THE FLOOR POUR.
- 11. CLEAR COVERAGE OF CONCRETE OVER OUTER REINFORCING BARS SHALL BE AS FOLLOWS
- a. CONCRETE CAST AGAINST AND PERMANENTLY EXPOSED TO EARTH b. CONCRETE EXPOSED TO WEATHER: No. 6 THROUGH No. 18 BARS
- No. 5 BAR, W31 OD D31 WIRE, AND SMALLER c. CONCRETE NOT EXPOSED TO WEATHER OR IN CONTACT WITH GROUND: No. 14 AND No. 18 BARS 1 1/2"
- No. 11 BARS AND SMALLER 12. ALL REINFORCING BARS, ANCHOR BOLTS, AND OTHER CONCRETE INSERTS SHALL BE SECURED IN THEIR FINAL POSITION PRIOR TO PLACING CONCRETE. 13. PROVIDE SLEEVES FOR PLUMBING AND ELECTRICAL OPENINGS IN CONCRETE BEFORE PLACEMENT. DO
- NOT CUT ANY REINFORCING WHICH MAY CONFLICT. CORING CONCRETE IS NOT PERMITTED, EXCEPT AS SHOWN. NOTIFY THE STRUCTURAL ENGINEER IN ADVANCE OF CONDITIONS NOT SHOWN ON THE DRAWINGS
- 14. CONDUITS SHALL NOT BE RUN IN SLABS OR PLACED IN BASE MATERIAL. CONCENTRATED RUNS OF CONDUITS OR PIPES SHALL BE AVOIDED, EXCEPT WHERE DETAILED OPENINGS ARE PROVIDED.
- 15. PROJECTING CORNERS OF BEAMS, WALLS, COLUMNS, ETC. SHALL BE FORMED WITH A 1/2" CHAMFER, UNLESS NOTED OTHERWISE ON ARCHITECTURAL DRAWINGS.
- 16. CURING COMPOUNDS USED ON CONCRETE THAT IS TO RECEIVE A RESILIENT TILE FINISH SHALL BE
- APPROVED BY THE TILE MANUFACTURER BEFORE USE. 17. SHRINKAGE OF CONCRETE, WHEN TESTED IN ACCORDANCE WITH ASTM C-157, SHALL NOT EXCEED 0.00065 INCHES/INCH FOR HARD ROCK CONCRETE AND 0.00055 INCHES/INCH FOR LIGHT WEIGHT CONCRETE.
- 18. PLACE AND PROTECT CONCRETE IN COMPLIANCE WITH ACI 305 AND 306, RESPECTIVELY, DURING HOT AND COLD EXPOSURE CONDITIONS.

DIVISION 06 WOOD

1" BOLT

- 1. FRAMING LUMBER SHALL BE DOUGLAS FIR NO. 2 GRADE OR BETTER, WITH MOISTURE CONTENT < 19% UNLESS OTHERWISE NOTED. LOAD BEARING STUDS SHALL BE DOUGLAS FIR NO. 2 GRADE OR BETTER, UNLESS OTHERWISE NOTED. POSTS AND BEAMS 6x AND LARGER SHALL BE DOUGLAS FIR NO. 1 GRADE.
- UNLESS OTHERWISE NOTED. 2. ALL PLYWOOD SHALL BE CC OR CD CONFORMING TO PRODUCT STANDARD PS 1-95.
- LISE COMMON WIRE NAILS 3. ALL BOLTS SHALL CONFORM TO ASTM A-307 Gr. A, UNLESS NOTED OTHERWISE ON PLANS. BOLT HOLES SHALL BE 1/16" MAXIMUM LARGER THAN THE BOLT SIZE. RETIGHTEN ALL NUTS PRIOR TO CLOSING IN. ALL BOLTS SHALL HAVE A MINIMUM OF 3 THREADS PROJECTING BEYOND THE NUT, ROLLED THREADS (UPSET)
- ARE NOT PERMITTED. USE ASTM A563 NUTS AND ASTM F436 WASHERS U.N.O. STANDARD CUT WASHERS SHALL BE USED UNDER BOLT HEADS AND NUTS AGAINST WOOD. USE HEAVY PLATE OR MALLEABLE IRON WASHERS FOR ALL BOLTS DESIGNED TO ACT IN TENSION. SEE DRAWINGS FOR LOCATION.
- HEAVY PLATE WASHER SIZES SHALL BE AS FOLLOWS: 1/2" BOLT 2 x 2 x 1/4 5/8" BOLT 21/2 x 21/2 x 1/4 3/4" BOLT 3 x 3 x 1/4 7/8" BOLT 31/2 x 31/2 x 5/16
- 11/8" BOLT 4 x 4 x 7/16 5. ALL SILLS OR PLATES RESTING ON CONCRETE OR MASONRY SHALL BE PRESSURE TREATED DOUGLAS FIR. BOLTS SHALL BE PLACED 12" OR LESS THAN 4" FROM THE END OF A PLATE, OR FROM A NOTCH GREATER THAN 1/2 THE WIDTH OF A PLATE, AND SPACED AT INTERVALS NOTED. ANCHOR BOLTS SHALL HAVE
- 6. ALL STUD PARTITIONS OR WALLS OVER 10 FEET HIGH SHALL HAVE 2x BRIDGING, SAME WIDTH AS THE STUD, PREFERABLY AT MID-HEIGHT BUT NOT TO EXCEED INTERVALS OF 8 FEET.
- DO NOT NOTCH JOISTS, RAFTERS OR BEAMS, EXCEPT WHERE SHOWN IN DETAILS. OBTAIN ENGINEER'S APPROVAL FOR ANY HOLES OR NOTCHES NOT DETAILED. HOLES THROUGH SILLS, PLATES, STUDS AND DOUBLE PLATES IN INTERIOR, BEARING AND SHEAR WALLS SHALL NOT EXCEED 1/3 THE PLATE WIDTH. USE
- BORED HOLES LOCATED IN THE CENTER OF THE STUD OR PLATE. 8. APPROVED CROSS-BRIDGING OR SOLID BLOCKING SHALL BE SPACED AS FOLLOWS:

4 x 4 x 3/8

FOR RAFTERS MORE THAN 8" IN DEPTH, AT 10 FT, O.C. MAXIMUM. FOR FLOOR JOISTS MORE THAN 4" IN DEPTH, AT 8 FT. O.C. MAX.

3"x3"x0.229 SQUARE WASHERS AT DESIGNATED SHEAR WALLS.

- 9. NAILED CONNECTIONS SHALL CONFORM TO THE MINIMUM NAILING SCHEDULE OF TABLE 2304.9.1 OF THE INTERNATIONAL BUILDING CODE, EXCEPT AS OTHERWISE NOTED. ALL NAILS SHALL BE COMMON WIRE NAILS. WHERE DRIVING OF NAILS CAUSES SPLITTING, HOLES FOR THE NAILS SHALL BE PRE-DRILLED.
- 10. UNLESS NOTED OTHERWISE, PRE-MANUFACTURED FRAMING CONNECTORS CALLED FOR ON THE DRAWINGS SHALL BE SIMPSON STRONG-TIE CONNECTORS, OR APPROVED EQUAL. 11. ALL LAMINATED VENEER LUMBER (LVL) ALL PARALLEL STRAND LUMBER (PSL) SPECIFIED SHALL HAVE THE
- FOLLOWING MINIMUM DESIGN STRENGTHS: Fb=2600 psi, Fv=285 psi, E=1,900,000 psi. Fb=2600 psi, Fv=285 psi, E=2,000,000 psi. (2.OE BEAMS)

Fb=1700 psi, Fv=425 psi, E=1,300,000 psi (1 1/4" THICKNESS)

12. ALL FLOOR OPENINGS SHALL BE BETWEEN JOISTS, (U.N.O.) 13. DO NOT NOTCH BEAMS, JOISTS, AND STUDS, (U.N.O.) 14. NAIL ALL MULTIPLE PLY FRAMING (2)16d AT 12" O.C. EACH PLY U.N.O.




DRAWING DESCRIPTION **GENERAL NOTES**


DRAWN BY CHECKED BY DATE: 11/24/2020 SCALE: 12" = 1'-0" JOB NUMBER: PROJECT NUMBER

S00²

ABBREVIATIONS

ADD	REVIATIONS		
ADDL.	ADDITIONAL	LBS.	POUNDS
AGGR.	AGGREGATE	LT.	LIGHT
	ALTERNATE	L.L.	LIVE LOAD
A.B. ANC.	ANCHOR BOLT ANCHOR	LG. L.L.H.	LONG LONG LEG HORIZONTAL
	APPROXIMATE	I I V	LONG LEG VERTICAL
ARCH.	ARCHITECTURAL	L.V.L.	LAMINATED VENEER LUMBER
	ASSEMBLY	M.B.	MACHINE BOLT
	AVERAGE	M.I.W.	
BM. BRG.	BEAM BEARING	MFR. MK	MANUFACTURER MARK
BEL.	BELOW	MAX.	MAXIMUM
BETW.	BETWEEN	M.D.	
BLK.		MECH.	
BLKG.		MTL.	METAL
BOTT.	BOTTOM BOTTOM OF	MIN. MISC.	MINIMUM MISCELLANEOUS
B.O.D.	BOTTOM BOTTOM OF BOTTOM OF DECK BOUNDARY NAILING	N.F.	NEAR FACE
B.N.	BOUNDARY NAILING	N.S.	NEAR SIDE
B.S., B/S		(N)	NEW
BLDG.	BUILDING	NOM.	NOMINAL
C.B.C.	CALIFORNIA BUILDING CODE CANTILEVER	N.I.C. NTS	NOT IN CONTRACT NOT TO SCALE
CLG.	CEILING	#	NUMBER OR POUNDS
CEN.	CENTER	 О.С.	ON CENTER
C.L.	CENTERLINE	OPNG.	OPENING
c.c.	CENTER TO CENTER CENTER OF GRAVITY	OPP.	OPPOSITE HAND
C.G. CHNL.	CENTER OF GRAVITY CHANNEL	O.H. O.D.	OPPOSITE HAND OUTSIDE DIAMETER
CLR.	CLEAR	PR.	PAIR
COL.	COLUMN	PTN.	PARTITION
C.P.	COMPLETE PENETRATION	PSL	PARALLEL STRAND LUNBER
CONC.	CONCRETE	PARL.	PARALLEL
CONN. C.J.	CONNECTION CONSTRUCTION JOINT	PEN. PERP.	PENETRATION DEPRENDICULAR
C.J.	CONTROL JOINT	PERP. PL.	PERPENDICULAR PLATE
CONT.		pcf	POUNDS PER CUBIC FOOT
CONTR	CONTRACTOR	nef	POLINDS PER SOLIARE FOOT
CONST.	CONSTRUCTION	psi	POUNDS PER SQUARE INCH
C/S	COUNTERSINK	P.A.F.	POWDERED ACTUATED FASTENER
D&E	CONSTRUCTION COUNTERSINK DRILL AND EPOXY DEAD LOAD DEFORMED BAR ANCHOR DETAIL DIAGONAL	P.D.F. DREEAR	POWDER DRIVER FASTENER
D.B.A.	DEFORMED BAR ANCHOR	P.J.F.	PREMOLDED JOINT FILLER
DET.	DETAIL	PROJ.	PROJECT
DIAG.	DIAGONAL	P.T.	PRESSURE TREATED
DIA.	DIAMETER	RAD.	RADIUS
DIM.	DIMENSION	REF.	REFERENCE REINEORCEMENT
D.O. DBI	DITTO DOUBLE DRAWING	REINE.	REINFORCEMENT REINFORCED CONCRETE REQUIRED
DWG.	DRAWING	REQ'D	REQUIRED
D.J.	DOWEL JOINT	REV.	REVISION
D.1.	DRAG TRUSS	SCHED.	SCHEDULE
EA. E E	EACH EACH FACE EDGE NAILING	SECT. STS	SECTION SELF TAPPNG SCREW SHEAR WALL
E.N.	EDGE NAILING	SW	SHEAR WALL
E.S.	EACH SIDE	SHT.	SHEET
	EACH WAY		SHEATHING
ELEC.	ELECTRICAL	SIM.	SIMILAR
EL. EMBED	ELEVATION EMBEDMENT	S.J. S.O.G	SLAB JOINT SLAB ON GRADE SOLID BLOCK
ENGR.	ENGINEER	S.B.	SOLID BLOCK
EQ.	EQUAL	SPECS.	SPECIFICATIONS
EQUIP.	EQUIPMENT	SQ.	SQUARE
EXCAV.	EXCAVATION	s.f.	SQUARE FEET
(⊑) FXP	EXCAVATION EXISTING EXPANSION	STAGG. STD	SQUARE FEET STAGGERED STANDARD
E.J.	EXPANSION JOINT EXTERIOR	STFNR.	STIFFENER
EXT.	EXTERIOR	STRUCT.	STRUCTURAL
FAB.	FABRICATION	SYM.	SYMMETRICAL
F.O. F.O.C	FACE OF CONCRETE	THRU.	SYMMETRICAL THREADED THROUGH
F.O.S.	FACE OF STUD	T.N.	TOE NAIL
FT.	EXPANSION EXPANSION JOINT EXTERIOR FABRICATION FACE OF FACE OF CONCRETE FACE OF STUD FEET FIGURE FINISH	TOL.	TOLERANCE
FIG.	FIGURE	T&B	TOP AND BOTTOM
FIN. F.F.	FINISH FINISHED FLOOR	T.O.	TOP OF TOP OF BEAM
r.r. FLR.	FINISHED FLOOR	T.O.B. T.O.C.	TOP OF BEAM TOP OF CONCRETE
F.D.	FLOOR DRAIN	T.O.F.	TOP OF FOOTING
FTG.	FOOTING	T.O.P.	TOP OF PLATE
FDN.	FOUNDATION FRAMING	T.O.S.	TOP OF PLATE TOP OF STEEL TOP OF WALL
GA.	GAUGE	T.O.W. TS	TUBE STEEL
GALV.	GALVANIZED	TYP.	TYPICAL
GR.	GRADE	U.N.O.	UNLESS NOTED OTHERWISE
GB	GRADE BEAM	V.I.F.	VERIFY IN FIELD
GRND. HGR.	GROUND HANGER	VERT. WT.	VERTICAL WEIGHT
HGR. H.S.A.	HANGER HEADED STUD ANCHOR	WT. W.S.	WEIGHT WELDED STUD OR WOOD SCREW
HDR.	HEADER	WWF	WELDED GIOD OR WOOD SCREW WELDED WIRE FABRIC
HT.	HEIGHT	WWM	WELDED WIRE MESH
H.S.B.	HIGH STRENGTH BOLT	WF	WIDE FLANGE
HSS HORIZ.	HOLLOW STRUCTURAL SECTION HORIZONTAL	w/ w/O	WITH WITHOUT
HONIZ.	HORIZONTAL HORIZONTAL REINF.	W/O WP	WORK POINT
I.B.C.	INTERNATIONAL BUILDING CODE		
IN.	INCHES		
INCL'D	INCLUDED		
INFO. I.D.	INFORMATION INSIDE DIAMETER		
INT.	INTERIOR		
I.J.	ISOLATION JOINT		
JT.	JOINT		
JST.	JOIST		







FOUNDATION STABILIZATION
City of Reno Housing Authority
1524 Steelwood Ln,

DRAWING DESCRIPTION

GENERAL NOTES

DRAWN BY:

SZ

CHECKED BY:

BAM

DATE:

11/24/2020

SCALE:


12" = 1'-0"

JOB NUMBER:

PROJECT NUMBER

SHEET:

S002





DRAWING DESCRIPTION

FOUNDATION PLAN/DETAILS

CHECKED BY: DATE: 11/24/2020 SCALE:

> As indicated JOB NUMBER:

PROJECT NUMBER

S101

Rent Roll Report

For Monthly Rent Run: 05/01/2022

Development: Hawk View Apartments
Development ID: NV001000107P-107

Unit ID	Resident Name	Excl from Late Fee	Suite	Address	Bdr.	Security Deposit	Current Rent	Next Month Rent Lease Exp.
107631	Tankersley, Kimberlyann M	No	1	2501 Tripp Dr 1, Reno, 89512	2	\$300.00	\$582.00	63.00
107632	Sanchez-Vasquez, Llane	No	2	2501 Tripp Dr 2, Reno, 89512	2	\$200.00	\$711.00	711.00
107633	Byrd, Breyena A	No	3	2501 Tripp Dr 3, Reno, 89512	2	\$500.00	\$570.00	570.00 05/31/2019
107634	Holt, Charity R	No	4	2501 Tripp Dr 4, Reno, 89512	2	\$300.00	\$593.00	593.00 03/06/2017
107635	Guzman, Blasa	No	1	2515 Tripp Dr 1, Reno, 89512	2	\$300.00	\$180.00	180.00 09/30/2021
107636	Vivian, Heavenly A	No	2	2515 Tripp Dr 2, Reno, 89512	2	\$300.00	\$58.00	58.00 02/28/2022
107637	Yingag, Sarah	No	3	2515 Tripp Dr 3, Reno, 89512	2	\$300.00	\$833.00	833.00
107638	Hamilton, Juliza D	No	4	2515 Tripp Dr 4, Reno, 89512	2	\$300.00	\$27.00	27.00 09/30/2019
107639	Garcia, Alicia	No	1	2523 Tripp Dr 1, Reno, 89512	2	\$200.00	\$833.00	833.00
107640	Tucker, Terra R	No	2	2523 Tripp Dr 2, Reno, 89512	2	\$300.00	\$27.00	27.00 04/30/2022
107641	Art, Joseph J	No	3	2523 Tripp Dr 3, Reno, 89512	2	\$500.00	\$438.00	438.00 03/03/2017
107642	Dia, Kadidia Oumar	No	4	2523 Tripp Dr 4, Reno, 89512	2	\$300.00	\$659.00	659.00 01/01/2016
107643	Hitchcock, Amber J	No	1	2505 Tripp Dr 1, Reno, 89512	2	\$300.00	\$27.00	27.00 12/31/2020
107644	Redington, Nancy L	No	2	2505 Tripp Dr 2, Reno, 89512	2	\$400.00	\$833.00	833.00
107645	Johnson, Latoya R	No	3	2505 Tripp Dr 3, Reno, 89512	2	\$300.00	\$833.00	833.00 12/31/2019
107646	Boyd, Yuko	No	4	2505 Tripp Dr 4, Reno, 89512	2	\$200.00	\$833.00	833.00
107647	Hurt, Stella J	No	1	2509 Tripp Dr 1, Reno, 89512	2	\$300.00	\$632.00	632.00 03/03/2017
107648	Douglas, Felicia L	No	2	2509 Tripp Dr 2, Reno, 89512	2	\$300.00	\$77.00	77.00 04/30/2019
107649	Weinberg, Tammila M	No	3	2509 Tripp Dr 3, Reno, 89512	2	\$700.00	\$563.00	563.00 01/15/2018
107650	Rodriguez, Ana C	No	4	2509 Tripp Dr 4, Reno, 89512	2	\$200.00	\$380.00	380.00
107651	Stephens, Dallas L	No	1	2519 Tripp Dr 1, Reno, 89512	2	\$400.00	\$833.00	833.00
107652	Curry, Alisa A	No	2	2519 Tripp Dr 2, Reno, 89512	2	\$0.00	\$833.00	833.00 08/01/2015
107653	Ernsberger, Valerie A	No	3	2519 Tripp Dr 3, Reno, 89512	2	\$200.00	\$177.00	177.00 03/31/2019
107654	Vitola, Jacklyn A	No	4	2519 Tripp Dr 4, Reno, 89512	2	\$300.00	\$27.00	27.00 02/29/2020
107655	Bailey, Destiney J	No	1	2527 Tripp Dr 1, Reno, 89512	2	\$300.00	\$369.00	369.00 06/30/2021
107656	Chestine, Diana D	No	2	2527 Tripp Dr 2, Reno, 89512	2	\$500.00	\$27.00	27.00 09/05/2016
107657	Clay, Oryanna L	No	3	2527 Tripp Dr 3, Reno, 89512	2	\$300.00	\$27.00	27.00 11/30/2019
107658	Reyna, Kimie M	No	4	2527 Tripp Dr 4, Reno, 89512	2	\$300.00	\$27.00	27.00 11/10/2017
107659	Byrd, Corey E	No	1	2535 Tripp Dr 1, Reno, 89512	2	\$300.00	\$72.00	72.00 05/31/2022
107660	Vacant as of 05/01/2022		2	2535 Tripp Dr 2, Reno, 89512	2	\$0.00	\$0.00	0.00
107661	Landeros, Alicia S	No	3	2535 Tripp Dr 3, Reno, 89512	2	\$300.00	\$27.00	800.00 12/31/2021
107662	Castillo, Monica I	No	4	2535 Tripp Dr 4, Reno, 89512	2	\$300.00	\$91.00	49.00 03/05/2018

5/9/2022 7:52:34AM By: Shanika Bumphurs

Rent Roll Report

107663	Harding, Michelle R	No	1	2541 Tripp Dr 1, Reno, 89512	2	\$400.00	\$165.00	165.00
107664	McGee, Terri L	No	2	2541 Tripp Dr 2, Reno, 89512	2	\$300.00	\$27.00	27.00 09/30/2019
107665	Gilmore, Aaliyah M	No	3	2541 Tripp Dr 3, Reno, 89512	2	\$300.00	\$27.00	27.00 02/29/2020
107666	Williams, Judith J	No	4	2541 Tripp Dr 4, Reno, 89512	2	\$300.00	\$289.00	289.00 10/31/2016
107667	Garcia Roman, Sharon A	No	1	2531 Tripp Dr 1, Reno, 89512	2	\$300.00	\$27.00	27.00 05/04/2018
107668	Harnett, Alison K	No	2	2531 Tripp Dr 2, Reno, 89512	2	\$600.00	\$833.00	833.00
107669	Ripley, Amanda L	No	3	2531 Tripp Dr 3, Reno, 89512	2	\$500.00	\$251.00	36.00 03/31/2019
107670	Lee, Ronesha	No	4	2531 Tripp Dr 4, Reno, 89512	2	\$300.00	\$33.00	33.00
107671	Cunha, Britney N	No	1	2539 Tripp Dr 1, Reno, 89512	2	\$300.00	\$79.00	79.00 01/23/2017
107672	Eagen, Nicole M	No	2	2539 Tripp Dr 2, Reno, 89512	2	\$200.00	\$796.00	796.00
107673	Haro Vazquez, Jessika M	No	3	2539 Tripp Dr 3, Reno, 89512	2	\$300.00	\$833.00	833.00 04/30/2021
107674	Kennedy, Hannah L	No	4	2539 Tripp Dr 4, Reno, 89512	2	\$300.00	\$27.00	27.00 03/31/2022
107675	Martin, Brittany A	No	1	2545 Tripp Dr 1, Reno, 89512	2	\$300.00	\$27.00	27.00 06/30/2021
107676	Aarbane, Amira N	No	2	2545 Tripp Dr 2, Reno, 89512	2	\$300.00	\$27.00	27.00 04/30/2020
107677	Tscheekar, David M	No	3	2545 Tripp Dr 3, Reno, 89512	2	\$200.00	\$190.00	190.00
107678	Emmerson, Marc S	No	4	2545 Tripp Dr 4, Reno, 89512	2	\$300.00	\$192.00	192.00 03/15/2017
107679	Lezama Rojas, Montzerrat	No	1	1532 Steelwood Ln 1, Reno, 89512	2	\$300.00	\$832.00	832.00
107680	Noneo, Natasha	No	2	1532 Steelwood Ln 2, Reno, 89512	2	\$300.00	\$833.00	833.00 02/28/2019
107681	Stirgus, Laquetta D	No	3	1532 Steelwood Ln 3, Reno, 89512	2	\$300.00	\$27.00	27.00 04/30/2020
107682	Figueroa, Miguel A	No	4	1532 Steelwood Ln 4, Reno, 89512	2	\$200.00	\$405.00	405.00
107683	Freeman, Lindsay M	No	1	1540 Steelwood Ln 1, Reno, 89512	2	\$300.00	\$833.00	833.00 01/31/2019
107684	Clark, Wesley M	No	2	1540 Steelwood Ln 2, Reno, 89512	2	\$300.00	\$138.00	138.00
107685	Baker, Brandy M	No	3	1540 Steelwood Ln 3, Reno, 89512	2	\$300.00	\$27.00	27.00 11/30/2018
107686	Gutierrez, William J	No	4	1540 Steelwood Ln 4, Reno, 89512	2	\$300.00	\$27.00	27.00 03/31/2020
107687	Conser, Cynthia C	No	1	1548 Steelwood Ln 1, Reno, 89512	2	\$300.00	\$435.00	435.00 05/31/2020
107688	Seguin, Ashley J	No	2	1548 Steelwood Ln 2, Reno, 89512	2	\$300.00	\$27.00	27.00
107689	Pinon, Ashley R	No	3	1548 Steelwood Ln 3, Reno, 89512	2	\$300.00	\$455.00	455.00 10/31/2020
107690	Nunez, Maria A	No	4	1548 Steelwood Ln 4, Reno, 89512	2	\$200.00	\$265.00	265.00
107691	Coprich, Andre	No	1	1528 Steelwood Ln 1, Reno, 89512	2	\$300.00	\$227.00	227.00 09/30/2019
107692	Brown, Dejanae J	No	2	1528 Steelwood Ln 2, Reno, 89512	2	\$300.00	\$802.00	802.00 01/22/2018
107693	Kinney, Darla J	No	3	1528 Steelwood Ln 3, Reno, 89512	2	\$200.00	\$27.00	27.00
107694	Tate, Arlo Lamont	No	4	1528 Steelwood Ln 4, Reno, 89512	2	\$300.00	\$166.00	166.00 09/26/2016
107695	Sloan, Trista M	No	1	1536 Steelwood Ln 1, Reno, 89512	2	\$500.00	\$27.00	27.00 12/31/2018
107696	Fine, Ladonia S	No	2	1536 Steelwood Ln 2, Reno, 89512	2	\$300.00	\$27.00	27.00 07/31/2021
107697	Labrador-Berdon, Noreen	No	3	1536 Steelwood Ln 3, Reno, 89512	2	\$300.00	\$221.00	221.00 02/15/2018
107698	Ramirez, Anna C	No	4	1536 Steelwood Ln 4, Reno, 89512	2	\$300.00	\$833.00	833.00 11/25/2016
107699	Delgado, Mayra A	No	1	1544 Steelwood Ln 1, Reno, 89512	2	\$300.00	\$764.00	764.00 12/31/2020
107700	Adkins, Catherine A	No	2	1544 Steelwood Ln 2, Reno, 89512	2	\$300.00	\$296.00	296.00 04/30/2019
107701	Berdon, Stephanie C	No	3	1544 Steelwood Ln 3, Reno, 89512	2	\$200.00	\$215.00	215.00
107702	Lynch, Timothy L	No	4	1544 Steelwood Ln 4, Reno, 89512	2	\$300.00	\$659.00	659.00 08/31/2016
	• •			, ,				-

Rent Roll Report

			Total For All Developments:		\$30,800.00	\$35,061.00	\$35,058.00
			Total By Development: Hawk View Apartments		\$30,800.00	\$35,061.00	\$35,058.00
Lanini, Briella M	No	4	1524 Steelwood Ln 4, Reno, 89512	2	\$700.00	\$692.00	692.00 03/31/2022
Kang, Rachel M	No	3	1524 Steelwood Ln 3, Reno, 89512	2	\$200.00	\$27.00	27.00
Lopez Barajas, Flor M	No	2	1524 Steelwood Ln 2, Reno, 89512	2	\$300.00	\$833.00	833.00 06/30/2020
Wirowek, Jennifer B	No	1	1524 Steelwood Ln 1, Reno, 89512	2	\$300.00	\$772.00	772.00 03/31/2022
Johnson, Teresa D	No	4	1516 Steelwood Ln 4, Reno, 89512	2	\$200.00	\$579.00	579.00
Aldrich, Walter B	No	3	1516 Steelwood Ln 3, Reno, 89512	2	\$300.00	\$659.00	659.00 11/30/2018
Cowdin, Joyce Kay	No	2	1516 Steelwood Ln 2, Reno, 89512	2	\$300.00	\$183.00	183.00 05/31/2019
Preciado, Maria S	No	1	1516 Steelwood Ln 1, Reno, 89512	2	\$300.00	\$101.00	101.00 10/01/2017
Dailey, Mi G	No	4	1508 Steelwood Ln 4, Reno, 89512	2	\$300.00	\$308.00	308.00 10/31/2018
Fields, Latauna N	No	3	1508 Steelwood Ln 3, Reno, 89512	2	\$700.00	\$296.00	296.00
Gilbert, Dana N	No	2	1508 Steelwood Ln 2, Reno, 89512	2	\$300.00	\$432.00	432.00 08/31/2019
Fong, Jenny K	No	1	1508 Steelwood Ln 1, Reno, 89512	2	\$200.00	\$232.00	232.00
Sears, Alicia M	No	4	1500 Steelwood Ln 4, Reno, 89512	2	\$600.00	\$833.00	833.00
Grey, Louis H	No	3	1500 Steelwood Ln 3, Reno, 89512	2	\$200.00	\$256.00	256.00
Garcia, Justina A	No	2	1500 Steelwood Ln 2, Reno, 89512	2	\$500.00	\$597.00	597.00 06/20/2017
Delguidice, Gary M	No	1	1500 Steelwood Ln 1, Reno, 89512	2	\$400.00	\$177.00	177.00 10/18/2016
Orosco, Moriah A	No	4	1520 Steelwood Ln 4, Reno, 89512	2	\$300.00	\$310.00	310.00 02/28/2022
Benites Mora, Clodualda	No	3	1520 Steelwood Ln 3, Reno, 89512	2	\$400.00	\$424.00	424.00
Arthur, Joline A	No	2	1520 Steelwood Ln 2, Reno, 89512	2	\$300.00	\$27.00	27.00 01/31/2022
Dannenbring, James S	No	1	1520 Steelwood Ln 1, Reno, 89512	2	\$400.00	\$484.00	484.00
Vacant as of 05/01/2022		4	1512 Steelwood Ln 4, Reno, 89512	2	\$0.00	\$0.00	0.00
Vacant as of 05/01/2022		3	1512 Steelwood Ln 3, Reno, 89512	2	\$0.00	\$0.00	0.00
Moreno, Alyssa A	No	2	1512 Steelwood Ln 2, Reno, 89512	2	\$300.00	\$833.00	833.00 11/30/2018
Calderon-Diaz, Victoria	No	1	1512 Steelwood Ln 1, Reno, 89512	2	\$200.00	\$186.00	186.00
Cruz Franco, Juana M	No	4	1504 Steelwood Ln 4, Reno, 89512	2	\$300.00	\$409.00	409.00 04/30/2022
Saunders, Megan R	No	3	1504 Steelwood Ln 3, Reno, 89512	2	\$300.00	\$585.00	585.00 05/31/2021
Tolliver, Diana	No	2	1504 Steelwood Ln 2, Reno, 89512	2	\$300.00	\$27.00	27.00
Roa, Steven T	No	1	1504 Steelwood Ln 1, Reno, 89512	2	\$300.00	\$209.00	209.00 04/30/2021
	Tolliver, Diana Saunders, Megan R Cruz Franco, Juana M Calderon-Diaz, Victoria Moreno, Alyssa A Vacant as of 05/01/2022 Vacant as of 05/01/2022 Dannenbring, James S Arthur, Joline A Benites Mora, Clodualda Orosco, Moriah A Delguidice, Gary M Garcia, Justina A Grey, Louis H Sears, Alicia M Fong, Jenny K Gilbert, Dana N Fields, Latauna N Dailey, Mi G Preciado, Maria S Cowdin, Joyce Kay Aldrich, Walter B Johnson, Teresa D Wirowek, Jennifer B Lopez Barajas, Flor M Kang, Rachel M	Tolliver, Diana Saunders, Megan R No Cruz Franco, Juana M Calderon-Diaz, Victoria Moreno, Alyssa A Vacant as of 05/01/2022 Vacant as of 05/01/2022 Dannenbring, James S Arthur, Joline A Benites Mora, Clodualda Orosco, Moriah A No Delguidice, Gary M No Garcia, Justina A No Grey, Louis H No Sears, Alicia M Fong, Jenny K Gilbert, Dana N Fields, Latauna N No Dailey, Mi G Preciado, Maria S No Cowdin, Joyce Kay Aldrich, Walter B No Wirowek, Jennifer B No Lopez Barajas, Flor M No Cardena N No Caudin, No N	Tolliver, Diana Saunders, Megan R No Saunders, Megan R No Cruz Franco, Juana M Calderon-Diaz, Victoria Moreno, Alyssa A Vacant as of 05/01/2022 Vacant as of 05/01/2022 Dannenbring, James S No Arthur, Joline A Benites Mora, Clodualda No Orosco, Moriah A Delguidice, Gary M No Garcia, Justina A No Sears, Alicia M Fong, Jenny K No Gilbert, Dana N No Seirleds, Latauna N No Dailey, Mi G Preciado, Maria S No Aldrich, Walter B No Johnson, Teresa D No Kang, Rachel M No Calderon-Diaz, Victoria No No A Ro Covdin, Joyce Kay No Aldrich, Walter B No Sang, Rachel M No Sang, Rachel M No A Calderon-Diaz, Victoria No A No A Calderon-Diaz, Calderon-Diace A No A	Tolliver, Diana No 2 1504 Steelwood Ln 2, Reno, 89512 Saunders, Megan R No 3 1504 Steelwood Ln 3, Reno, 89512 Cruz Franco, Juana M No 4 1504 Steelwood Ln 4, Reno, 89512 Moreno, Alyssa A No 2 1512 Steelwood Ln 1, Reno, 89512 Wacant as of 05/01/2022 Vacant as of 05/01/2022 Vacant as of 05/01/2022 Dannenbring, James S No 1 1520 Steelwood Ln 1, Reno, 89512 Dannenbring, James S No 1 1520 Steelwood Ln 1, Reno, 89512 Dannenbring, James S No 1 1520 Steelwood Ln 1, Reno, 89512 Denites Mora, Clodualda No 3 1520 Steelwood Ln 3, Reno, 89512 Delguidice, Gary M No 1 1500 Steelwood Ln 1, Reno, 89512 Grey, Louis H No 3 1500 Steelwood Ln 2, Reno, 89512 Sears, Alicia M No 4 1500 Steelwood Ln 3, Reno, 89512 Sears, Alicia M No 4 1500 Steelwood Ln 1, Reno, 89512 Fields, Latauna N No 2 1508 Steelwood Ln 1, Reno, 89512 Fields, Latauna N No 3 1508 Steelwood Ln 1, Reno, 89512 Fields, Latauna N No 4 1508 Steelwood Ln 1, Reno, 89512 Fields, Latauna N No 5 1508 Steelwood Ln 1, Reno, 89512 Fields, Latauna N No 6 1508 Steelwood Ln 1, Reno, 89512 Fields, Latauna N No 7 1508 Steelwood Ln 1, Reno, 89512 Fields, Latauna N No 8 1508 Steelwood Ln 1, Reno, 89512 Fields, Latauna N No 9 1508 Steelwood Ln 1, Reno, 89512 Fields, Latauna N No 9 1508 Steelwood Ln 1, Reno, 89512 Fields, Latauna N No 9 1508 Steelwood Ln 1, Reno, 89512 Fields, Latauna N No 9 1508 Steelwood Ln 1, Reno, 89512 Fields, Latauna N No 9 1508 Steelwood Ln 1, Reno, 89512 Fields, Latauna N No 9 1508 Steelwood Ln 1, Reno, 89512 Fields, Latauna N No 9 1508 Steelwood Ln 1, Reno, 89512 Fields, Latauna N No 9 1508 Steelwood Ln 1, Reno, 89512 Fields, Latauna N No 9 1508 Steelwood Ln 2, Reno, 89512 Fields, Latauna N No 9 1524 Steelwood Ln 3, Reno, 89512 Fields, Latauna N No 9 1524 Steelwood Ln 3, Reno, 89512 Fields, Latauna N No 9 1524 Steelwood Ln 3, Reno, 89512 Fields, Latauna N No 9 1524 Steelwood Ln 3, Reno, 89512 Fields, Latauna N No 9 1524 Steelwood Ln 4, Reno, 89512 Fields, Latauna N No 9 1524 Steelwood Ln 3, Reno, 89512 Fields, Latauna N No 9 1524 Steelwood Ln 3, Reno, 89512 Fields	Tolliver, Diana No 2 1504 Steelwood Ln 2, Reno, 89512 2 Saunders, Megan R No 3 1504 Steelwood Ln 3, Reno, 89512 2 Cruz Franco, Juana M No 4 1504 Steelwood Ln 1, Reno, 89512 2 Calderon-Diaz, Victoria No 1 1512 Steelwood Ln 1, Reno, 89512 2 Moreno, Alyssa A No 2 1512 Steelwood Ln 1, Reno, 89512 2 Vacant as of 05/01/2022 3 1512 Steelwood Ln 3, Reno, 89512 2 Vacant as of 05/01/2022 4 1512 Steelwood Ln 4, Reno, 89512 2 Dannenbring, James S No 1 1520 Steelwood Ln 1, Reno, 89512 2 Dannenbring, James S No 1 1520 Steelwood Ln 1, Reno, 89512 2 Dantes Mora, Clodualda No 3 1520 Steelwood Ln 2, Reno, 89512 2 Orosco, Moriah A No 4 1520 Steelwood Ln 3, Reno, 89512 2 Delguidice, Gary M No 1 1500 Steelwood Ln 1, Reno, 89512 2 Delguidice, Gary M No 1 1500 Steelwood Ln 1, Reno, 89512 2 Garcia, Justina A No 2 1500 Steelwood Ln 1, Reno, 89512 2 Grey, Louis H No 3 1500 Steelwood Ln 2, Reno, 89512 2 Sears, Alicia M No 4 1500 Steelwood Ln 3, Reno, 89512 2 Sears, Alicia M No 4 1500 Steelwood Ln 1, Reno, 89512 2 Gilbert, Dana N No 2 1508 Steelwood Ln 1, Reno, 89512 2 Gilbert, Dana N No 3 1508 Steelwood Ln 1, Reno, 89512 2 Fields, Latauna N No 3 1508 Steelwood Ln 1, Reno, 89512 2 Fields, Latauna N No 4 1508 Steelwood Ln 1, Reno, 89512 2 Dailey, Mi G No 4 1508 Steelwood Ln 1, Reno, 89512 2 Dailey, Mi G No 4 1508 Steelwood Ln 1, Reno, 89512 2 Dailey, Mi G No 4 1508 Steelwood Ln 1, Reno, 89512 2 Dailey, Mi G No 4 1508 Steelwood Ln 1, Reno, 89512 2 Dailey, Mi G No 4 1508 Steelwood Ln 1, Reno, 89512 2 Dailey, Mi G No 4 1508 Steelwood Ln 1, Reno, 89512 2 Dailey, Mi G No 4 1508 Steelwood Ln 1, Reno, 89512 2 Dailey, Mi G No 4 1508 Steelwood Ln 1, Reno, 89512 2 Dailey, Mi G No 4 1508 Steelwood Ln 1, Reno, 89512 2 Dailey, Mi G No 4 1508 Steelwood Ln 1, Reno, 89512 2 Dailey, Mi G No 4 1508 Steelwood Ln 1, Reno, 89512 2 Dailey, Mi G No 4 1508 Steelwood Ln 1, Reno, 89512 2 Dailey, Mi G No 4 1508 Steelwood Ln 1, Reno, 89512 2 Dailey, Mi G No 4 1508 Steelwood Ln 1, Reno, 89512 2 Dailey, Mi G No 4 1508 Steelwood Ln 1, Reno, 89512 2 Dailey, Mi G No 4 150	Tolliver, Diana	Tolliver, Diana

^{**}End of Report**

Development Name: Hawk View Apartments

HUD Code: NV39-P001-007

Location: 1548 Steelwood Lane, Reno NV 89512

Parcel Number: 004-292-17, -18

Program Type: Conventional Public Housing, Family

Constructed: 1984

End of Initial Operating Period: 4th Quarter, 1984

Physical Data:

Community Facilities: Community Room, Laundry Room, 2 Playgrounds, Shop

Fully Accessible Units: 5

Gross Site Area: 7 Acres
Units Per Acre: 14.3

Public Asphalt Pavement Area: 21,091 Square Feet RHA Asphalt Pavement Area: 98,492 Square Feet Public Concrete Area: 2,860 Square Feet RHA Concrete Area: 33,088 Square Feet

Accessible Units:	5		
Unit No.	<u>Address</u>	Bedrooms	Accommodation
653	2519#3 Tripp Dr	Two	Roll in Shower
663	2541 #1 Tripp Dr	Two	Roll in Shower
687	1548 #1 Steelwood	Two	Roll in Shower
701	1544 #3 Steelwood	Two	Roll in Shower
703	1504 #1 Steelwood	Two	Roll in Shower


Barrier Free Units: None


Bedroom Size:	<u>0/Studio</u>	<u>1</u>	<u>2</u>	<u>3</u>	<u>4</u>	Total
Number of Units			100			100
Square Footage of Units			865			86,500


Updated: 12/21/20


Recent Modernization:	Year:	Recent Modernization:	Year:
			
Bathroom, Kitchen Renovation	1996	Appliance Replacement of 24 Ranges	2008
Exterior Light Upgrade	1997	Cable TV Outlet Installation	2009
Fog Seal Parking Lots	1998	Energy Efficient Kitchen Lighting	2009
Sidewalk Replacement	1998	Community Room Floor Repairs	2009
Maintenance Shop Replacement	1998	Patio Installation	2010
Community Center Expansion	1998	Stair Landing Adjustment	2010
Security Screen Doors	1998	Tree Pruning	2010
Bicycle Racks	1998	Stair Step Replacement Phase 2	2010
Closet Door Replacement	1998	Stair Landing	2010
Upgrade Exterior Door Locks	1999	Kitchen Cabinets	2011
Community Building Remodel	1999	Kitchen Countertops	2011
Exterior Trim and Paint	1999	Security Lighting	2011
Playground Improvements	1999	Concrete Repair and Replace	2011
Replace Community Room Roof	2001	Under Floor Insulation	2011
Ceiling Fans	2001	Additional Rain Gutters	2011
Downspout Installation	2001	Post and Chain Fence West Bank	2011
Appliance Replacement	2002	Water Conservation	2011
Window and Trim Replacement	2003	Accessible Kitchens	2011
Roof Replacement	2003	Appliance Replacement	2012
Carpet Upstairs/Vinyl Entry	2003	Turf Removal	2014
Additional Attic Insulation	2003	Laundry Room Remodel	2014
Security Cameras	2004	Asphalt Replacement	2014
Landscape/Xeriscape Improvements	2004	Concrete Replacement	2014
Unit Patios	2005	Landscape Improvements	2014
Concrete Repairs	2005	Turf Reduction	2015
Landscape and Irrigation Improvements	2005	Security Camera Improvements	2015
Furnace Replacement	2005	Appliance Replacement	2015
Air Conditioning Installation in Upstairs	2006	Westbank Landscape	2017
Units		•	
Heating Duct Repairs	2006	Irrigation Sleeve Installation	2018
Security Improvements with DV Recorders	2006	Retaining Wall Repair	2019
Concrete Replacement	2006	Appliance Replacement	2019
Air Conditioning Installation in Downstairs	2007	Concrete Replacement	2019
Units		•	
Landscape and Irrigation Improvements	2007	Asphalt Replacement	2020
Asphalt Repairs of Parking Lots and	2008	Retaining Wall Repair	2020
Driveways			
Exterior Vent Replacement	2008		
•			


Updated: 12/21/20











COMMUNITY BUILDING/OFFICE 1,057 SF

RENO HOUSING AUTHORITY 1525 E 9TH ST., RENO NV, 89512 (775) 329-3630 PH (775) 786-1712 FAX



PROJECT NAME:

HAWK VIEW APARTMENTS

1548 STEELWOOD LANE


COMMUNITY BUILDING/OFFICE MAINTENANCE SHOP

DATE: MAY 2011

UPDATE: -

SCALE: 3/32"=1"-0"





RENO HOUSING AUTHORITY 1525 E 9TH ST., RENO NV, 89512 (775) 329-3630 PH (775) 786-1712 FAX




PROJECT NAME: HAWK VIEW APARTMENTS 1548 STEELWOOD LANE

LAUNDRY ROOM

DATE: MAY 2011

UPDATE: -SCALE: 1/4"=1'-0" RHA 11



Washoe County GIS Source: Esri, Maxar, Earthstar Geographics, and the GIS User Community Home » Assessor » Real Property Assessment Data

WASHOE COUNTY ASSESSOR PROPERTY DATA

5/31/2022

Owner Information			Building Ir	nformation	XFOB	SUBAREA	
APN	004-292-17	Card 1 of 14		Bld #1 Situs		Property	
Situs 1	1500 STEELWOOD	Bld # 1			STEELWOOD	Name	
	LN RENO NV			Quality	Commercial		Multiple Res (Low Rise)
Owner 1	HOUSING			Stories	1.0 (Low)	2nd	
	AUTHORITY CITY OF RENO			Year Built	1984	Occupancy	1984
Mail Address	1525 E 9TH ST			Bedrooms		Square Feet	3560
Parcel Information				Full Baths	4	Finished Bsmt	
Keyline Desc	PJ KELLY'S FRA	C LOTS 10 & 11		Half Baths	0	Unfin Bsmt	0
Subdivision	Subdivision P J KELLY`S SUBDIVISION			Fixtures	0	Basement Type	
	Section 36 Township 20 Range 19		Fireplaces	0	Gar Conv Sq Feet		
Record of Sur		rcel Map# 0 : Property Code		Heat Type	WARM/COOL	Total Garage	
2022 Tax		Prior APN	023	2nd Heat	AIR	Area Garage Type	
District 2021 Tax District	1000		Use does not qualify for Low		STUD WALLS	Detached	
			Cap, High Cap Applied	waiis	- TEXTURED PLYWOOD	Garage	
	PERMITS	wjackins 11/16	6/2020		STUD WALLS - BRICK VENEER	Basement Gar Door	0
				Roof Cover		Sub Floor	
				% Complete	100	Frame	WD/STL FRAME
				Obso/Bldg Adj	0	Units/Bldg	4
				Construction Modifier		Units/Parcel	53

Land Information LAND DETAILS

Land	340	DOR	340	Sewer	Municipal	Neighborhood	MMMM
Use		Code					MM Neighborhood Map
Size	165,266.64 SqFt	Size	3.794 Acres	Street	Paved	Zoning Code	MF30
				Water	Muni		

1 of 2 5/31/2022, 1:51 PM

Sales and Transfer Records

RECORDER SEARCH

Grantor	Grantee	Doc #	Doc Type	Doc Date	DOR	Value/Sale	Sale	Note
					Code	Price	Code	
	HOUSING AUTHORITY CITY OF RENO	887441		10-25-1983		0		



Valuation Information A The 2022/2023 values are preliminary values and subject to change.


	Taxable	New	Taxable	овѕо	Тах Сар	Taxable	Land	Imps	Total	Exemption
	Land	Value	Imps		Value	Total	Assessed	Assessed	Assessed	Value
2022/23 NR	780,000	0	1,580,508	0		2,360,508	273,000	553,177	826,178	826,178
2022/23 VN	780,000	0	1,580,508	0		2,360,508	273,000	553,177	826,178	826,178
2021/22 FV	624,000	0	1,646,793	0	2,270,795	2,270,793	218,400	576,377	794,778	794,778




All parcel data on this page is for use by the Washoe County Assessor for assessment purposes only. The summary data on this page may not be a complete representation of the parcel or of the improvements thereon. Building information, including unit counts and number of permitted units, should be verified with the appropriate building and planning agencies. Zoning information should be verified with the appropriate planning agency. All parcels are reappraised each year. This is a true and accurate copy of the records of the Washoe County Assessor's Office as of 05-30-2022

If you have questions or corrections about our property data you can call us at 775-328-2277 or email us at exemptions@washoecounty.gov

2 of 2 5/31/2022, 1:51 PM



McElhaney Structural Engineers, LLC





November 24, 2020

Matthew Robinson City of Reno Housing Authority Email: mrobinson@renoha.org

Re: Interior Foundation Stabilization

Hawk View Apartments 1524 Steelwood Ln, Reno, NV 89512

Matthew,

McElhaney Structural engineers have performed the structural reconnaissance for the interior foundation at aforementioned address for building at the aforementioned address. The buildings are a 2-two story wood structure with a concrete perimeter continuous footing and interior cripple wall over a concrete continuous footing. It appears that the interior concrete footings are settling, causing cracks to form on the ceiling and walls of the apartment units. It appears that the structure rest on clay soil and to our best engineering judgement this appears to be the primary contributing factor for the interior footing settlement. The interior footing appears to show significantly more settlement than the exterior due to more tributary load and less soil embedment.

We have performed the structural analysis to stabilize the interior footing and found that push piers are the recommended solution. This push pier system would avoid having to drill from the first-floor apartments, therefore allowing the apartments to remain occupied during construction. Refer to the drawings for the push pier locations.

Below is the Material cost and labor for each building. This quote is provided the Madole Construction based on the information provided by us.

- 1) (10) 288 Push pile 15 LF with bracket \$6,278.50
- 2) Install Labor 3-man crew allow 60 hours each Excavate access pit, set push frame, push pipe to depth, set bracket, backfill access pit \$18,000.00
- 3) Equipment allowance \$3,000.00
- 4) (10) Smart jacks \$4,000.00
- 5) LVL Beams \$4.25 per foot \$701.25
- 6) Carpentry labor to remove existing pony wall, install smart jacks, and LVL \$3,600.00
- 7) Overhead 6,803.34 **Total \$42.383.09**

Sincerely,

McElhaney Structural Engineers, LLC Brett A. McElhaney, MBA, MS, PE, SE Sai Enugala, PE U.S. Seismic Design Maps






Hawk View Apartments

1548 Steelwood Ln, Reno, NV 89512, USA

Latitude, Longitude: 39.5542233, -119.7934475



Туре	Description	Value
Hazard Level		BSE-2N
S _S	spectral response (0.2 s)	1.5
S ₁	spectral response (1.0 s)	0.515
S _{XS}	site-modified spectral response (0.2 s)	1.2
S _{X1}	site-modified spectral response (1.0 s)	0.412
Fa	site amplification factor (0.2 s)	0.8
F _v	site amplification factor (1.0 s)	0.8
ssuh	max direction uniform hazard (0.2 s)	1.61
crs	coefficient of risk (0.2 s)	0.951
ssrt	risk-targeted hazard (0.2 s)	1.531
ssd	deterministic hazard (0.2 s)	1.5
s1uh	max direction uniform hazard (1.0 s)	0.544
cr1	coefficient of risk (1.0 s)	0.945
s1rt	risk-targeted hazard (1.0 s)	0.515
s1d	deterministic hazard (1.0 s)	0.6

Type Description	1	Value
Hazard Level		BSE-1N
S _{XS} site-modifie	ed spectral response (0.2 s)	0.8
S _{X1} site-modifie	ed spectral response (1.0 s)	0.275

1 of 2 6/1/2022, 9:34 AM

Description	Value
	BSE-2E
spectral response (0.2 s)	1.133
spectral response (1.0 s)	0.375
site-modified spectral response (0.2 s)	0.907
site-modified spectral response (1.0 s)	0.3
site amplification factor (0.2 s)	0.8
site amplification factor (1.0 s)	0.8
	spectral response (0.2 s) spectral response (1.0 s) site-modified spectral response (0.2 s) site-modified spectral response (1.0 s) site amplification factor (0.2 s)

Туре	Description	Value
Hazard Level		BSE-1E
S _S	spectral response (0.2 s)	0.553
S ₁	spectral response (1.0 s)	0.179
S _{XS}	site-modified spectral response (0.2 s)	0.442
S _{X1}	site-modified spectral response (1.0 s)	0.143
Fa	site amplification factor (0.2 s)	0.8
F _v	site amplification factor (1.0 s)	0.8

Туре	Description	Value
Hazard Level		TL Data
T-Sub-L	Long-period transition period in seconds	6

DISCLAIMER

While the information presented on this website is believed to be correct, SEAOC /OSHPD and its sponsors and contributors assume no responsibility or liability for its accuracy. The material presented in this web application should not be used or relied upon for any specific application without competent examination and verification of its accuracy, suitability and applicability by engineers or other licensed professionals. SEAOC / OSHPD do not intend that the use of this information replace the sound judgment of such competent professionals, having experience and knowledge in the field of practice, nor to substitute for the standard of care required of such professionals in interpreting and applying the results of the seismic data provided by this website. Users of the information from this website assume all liability arising from such use. Use of the output of this website does not imply approval by the governing building code bodies responsible for building code approval and interpretation for the building site described by latitude/longitude location in the search results of this website.

2 of 2 6/1/2022, 9:34 AM

National Flood Hazard Layer FIRMette


250

500

1,000

1.500






2.000

Basemap: USGS National Map: Orthoimagery: Data refreshed October, 2020

Legend

SEE FIS REPORT FOR DETAILED LEGEND AND INDEX MAP FOR FIRM PANEL LAYOUT



This map complies with FEMA's standards for the use of digital flood maps if it is not void as described below. The basemap shown complies with FEMA's basemap

an authoritative property location.

The pin displayed on the map is an approximate point selected by the user and does not represent

accuracy standards The flood hazard information is derived directly from the authoritative NFHL web services provided by FEMA. This map was exported on 6/3/2022 at 4:08 PM and does not reflect changes or amendments subsequent to this date and time. The NFHL and effective information may change or become superseded by new data over time.

This map image is void if the one or more of the following map elements do not appear: basemap imagery, flood zone labels, legend, scale bar, map creation date, community identifiers, FIRM panel number, and FIRM effective date. Map images for unmapped and unmodernized areas cannot be used for regulatory purposes.

From: <u>Public Records Center (Reno NV)</u>

To: <u>Maggie Castelli</u>

 Subject:
 Public Records :: G076118-032122

 Date:
 Monday, March 21, 2022 3:26:13 PM



Dear Maggie:

Thank you for your interest in public records of the City of Reno.

Your request was received in this office on March 21, 2022 and given the reference number:

#G076118-032122 for tracking purposes.

Request Details: AEI Consultants has been commissioned to complete a Project Capital Needs Assessment and/or Phase I Environmental Site Assessment for the following properties and addresses: Mineral Manor, 1633 Andesite Avenue Tom Sawyer Village, 2565 Tom Sawyer Drive Silverada Manor, 1402 Silverada Boulevard Stead Manor, 5062 Bravo Avenue Haw View Apartments, 1548 Steelwood Lane Essex Manor, 7760 Carlyle Drive Myra Birch Manor, 3500 Mazzone Avenue Are these properties within your jurisdiction? As part of this assessment, and due diligence, we are required to request the following information, including, but not limited to the following: Building Department for any copies of Certificates of Occupancy and building permits from the last 10 years (year, type of permit, and owner/applicant), as well as the following information regarding building codes: 1. Building code enforced at the time the property was constructed. 2. Additional building codes enforced at the property since construction. 3. Current building code enforced by the municipality. 4. Copies of any outstanding building code violations. Planning and Zoning the current zoning classification of the property; AND copies of any outstanding zoning code violations. Who would be the appropriate contacts to provide all necessary information and documents? Please notify me in advance if there are fees with this request.

Your request will be forwarded to the appropriate City department(s) to locate the information requested. Pursuant to NRS 239.0107 we will notify you within five (5) business days of receipt of the anticipated date your records will be available, and any estimated cost to produce them. Please note any confidential, proprietary, or protected information will be redacted prior to the release of your records.

You can monitor the progress of your request at the link below and you'll receive an email when your request has been completed.

Again, thank you for using the City of Reno Public Records Center.



To monitor the progress or update this request please log into the <u>City of Reno Public Records</u> Center.

From: Public Records Center (Reno NV)

To: <u>Maggie Castelli</u>

Subject: Fire Department Public Records :: F076116-032122

Date: Monday, March 21, 2022 3:24:08 PM



Dear Maggie:

Thank you for your interest in public records of the City of Reno Fire Department.

Your request was received in this office on March 21, 2022 and given the reference number: **#F076116-032122** for tracking purposes.

Type of Record Requested:

Your request will be forwarded to the appropriate City department(s) to locate the information requested. Pursuant to NRS 239.0107 we will notify you within five (5) business days of receipt of the anticipated date your records will be available, and any estimated cost to produce them. Please note any confidential, proprietary, or protected information will be redacted prior to the release of your records.

You can monitor the progress of your request at the link below and you'll receive an email when your request has been completed.

Again, thank you for using the City of Reno Public Records Center.



To monitor the progress or update this request please log into the <u>City of Reno Public Records Center</u>.



Public Records Center

MENU

Public Records Menu

FAQs

See All FAQs Q

What types of records are

Question:

How can I obtain a zoning verification letter?

Answer:

The City of Reno does not prepare formal zoning verification letters, however, the following information is available online:



license from the City of Reno?

Can I get a copy of a divorce Decree from the City of Reno?

Can I get a copy of a birth or death certificate from the City of Reno?

What is the City Clerk's Office?

How can I obtain a zoning verification letter?

Can I obtain information on the City of Reno's Sphere of Influence?

You can also download a full pdf of the code here www.reno.gov

Reno Master Plan

Adopted PUD and SPD Handbooks

The City of Reno offers an online GIS Mapserver with information on zoning, sewers, parcels, aerial photography and more. The Virtual Permit Place allows citizen access to City data on parcels, planning case information and building permit information.

The Reno Planning Department cannot provide confirmation that all development, structures and uses on a site are conforming. All inquiries regarding existing or closed violations go through the City's Code Enforcement division.




Management Rate Sheet?

What is the Mission Statement of the City Clerk's Office



Single-Family Residential (6 units/ acre) SF-6

(See "Details" for instructions. Clear browser cache if layers don't



Mixed-Use Downtown Powning Dist. MD-PD

MU-RES

Large Lot Residential (1 acre) LLR-1

From: Public Records Center (Reno NV)

To: <u>Maggie Castelli</u>

 Subject:
 Public Records :: G076118-032122

 Date:
 Monday, March 21, 2022 8:20:38 PM

--- Please respond above this line ---



Dear Maggie,

RE: Public Records Request Reference # G076118-032122.

The City of Reno received a public records request from you on March 21, 2022. Your request mentioned:

AEI Consultants has been commissioned to complete a Project Capital Needs Assessment and/or Phase I Environmental Site Assessment for the following properties and addresses:

Mineral Manor, 1633 Andesite Avenue Tom Sawyer Village, 2565 Tom Sawyer Drive Silverada Manor, 1402 Silverada Boulevard Stead Manor, 5062 Bravo Avenue Haw View Apartments, 1548 Steelwood Lane Essex Manor, 7760 Carlyle Drive Myra Birch Manor, 3500 Mazzone Avenue

Are these properties within your jurisdiction?

As part of this assessment, and due diligence, we are required to request the following information, including, but not limited to the following:

Building Department for any copies of Certificates of Occupancy and building permits from the last 10 years (year, type of permit, and owner/applicant), as well as the following information regarding building codes:

- 1. Building code enforced at the time the property was constructed.
- 2. Additional building codes enforced at the property since construction.
- 3. Current building code enforced by the municipality.
- 4. Copies of any outstanding building code violations.

Planning and Zoning the current zoning classification of the property; AND copies of any outstanding zoning code violations.

Who would be the appropriate contacts to provide all necessary information and documents? Please notify me in advance if there are fees with this request.

Our office has reviewed its files and determined there are no open or outstanding code

enforcement violations associated with these properties at this time.

If you have any additional questions, please feel free to contact the City Clerk's Office Public Records Division at 775-348-3932.

Thank you for contacting the City of Reno.

Sincerely,

City of Reno Code Enforcement Division

To monitor the progress or update this request please log into the <u>City of Reno Public Records</u> <u>Center</u>.



Total Feet Due: \$171.49

Total VMTs:

Address: 1500 STEELWOOD LN

Job Type: Building/Commercial/Rockery & Retaining Walls/NA

Parcel No: 004-292-17

Zordag: MF-30

Type:

Dwelling Units: 0

Height:

Area(Sa.Fu):

Subdivision: PJ KELLY'S

Lot: 10, 11

Valuation: 5 12,000.00

Occupancy:

Опощо:

Fire Serinklers:

Fire Alarm:

Stories:

Tenant Information:

Owner Mometion:

HOUSING AUTHORITY CITY OF RENO.

HOUSING AUTHORITY CITY OF RENO

Permit Number: BLD20-08982

1525 E 9TH ST RENO, NV 89612

1525 E 9TH ST .

RENO, NV 89512

Description of Work to Be Done RETAINING WALL.

REPAIR EXISTING RETAINING WALL

Builder / General Contractor:

BLACK DEVELOPMENT GROUP INC.

360 DAWSON JACOB LN

RENO, NV 89503 775-322-4341

NV No.: 0075874

NOTICE

- The Building Permit and a full set of City of Reno APPROVED plans must be kept on the work site until completion of the project. Building permits issued shall become invalid unless the work authorized by such permit is commenced within 180 days after its issuance.
- Work permitted under this permit is only valid upon completion of all required inspections.
- All work being performed neest comply with all provisions of Building Codes and Ordinances as adopted by the City of Reno whether specified on plans or not.
- Approval of construction plans as submitted and granting of a permit shall not be construed. as approval of any pre-existing conditions which may be in violation of current codes.

1500 STEELWOOD LN LOT: 10, 11

inspection Record *Additional inspections may be required

Inspector Signature

Date

Final Inspections

9800 Retaining Wat First

8887 1704 Specinsp Fine Rep

PERMIT NUMBER: BLD20-88982

POST THIS PERMIT IN A CONSPICUOUS PLACE

Permit Inspection Record
City of Reno Building Permit

GENERAL NOTES:

II le unitavitul lo remove this record from the job sits until ell final inspections have been made

After Permit Issuance, you may schedule inspections 24 hours a day using a computer online at https://onenv.us. or with our mobile app. Text portification will be sent between 7:00 s.m. and 7:30 s.m. to the mobile phose number provided during scheduling. Your inspector will indicate an estimated time of armal If a lext was not possible your inspector will arrive as the job site between 7:30 s.m. and 3:00 p.m. For help or assistance call (775) 334-2063.

Health Inspections (Washos County Health District - WCHD):
ONLY accepts inspection requests BY PHONE
Please call (775) 328-2434 (option #8) to solvedute all required
Health Inspections which begin with the letter "H."

Fire Department Inspections:

Fire Department inspections should be requested for the "Next Burshwas Day" regardless of the date required. A Fire Inspection will call the next business day to schedule the actual date and time of the Inspection many the telephone number provided either ording or on the mobilecopy inspection request appro-

Scan QR code for your device



or search your
App Store









Total Feet Due: \$205.81.

Total VMTs:

Address: 1500 STEELWOOD LN

Owner Information: HOUSING AUTHORITY CITY OF REND

Permit Number: BLD19-06424

Job Type: Building/Commercial/Remodel & Accidion/NA

Valuation: \$ 15,000.00

Parcel No: 004-292-17 Zoning: Public Facility Type:

Occupancy: Group:

Deathing Units: 0

Fire Sprinklers: No

Height

Fire Alarm: No

Area(Sq.Ft.):

Subdivision:

Stones:

Lat:

HOUSING AUTHORITY CITY OF RENO

1525 E 9TH \$T REMO, NV 89512

1525 E 9TH ST. REVO, NV 89512

Description of Work to Be Done

CMU WALL..

CMU WALL REPAIR 24'L X8'H AS PER PLANS

Builder / General Contractor:

Tenant Information:

BLACK DEVELOPMENT GROUP INC

380 DAWSON JACOB LN RENO, NV 89503

775-322-4341

NV LR.: 0075874

The unequagres hereby agrees to defend undernsty and hold harmfest the City of Rand, its officers employees and egents from and against at demands. escara de Garcillairo must una assumad againos des Ciny of Remo unsung from des undersigned's construction activities performed pursuant to the restrance of this payminit directly string that have largered as the unadersegreed is freeking to perform it econologica with the approved prehat and plants), some and events such decrease, existing on Section, that area from the City of Reno's soft negligerors of within missoncues.

The sendencepted agrees to obtain maintain commercial Babbity Insurance covering a covering the serim of the construction authorized by this permit in enemount no legal that the solid construction cost of the work to be performed, and warrants that such isolary policy shall include completed operations obvious its well as an addressed insulad andorsement naming the Cey of Rena as an andicates insuled with respect to operations certainted by at for the undersigned tor which the City of Reno has asked a building permit, without exclusion to bodily injury or preparty damage within the completed operations of hezdro.

Sudder/General Confractor of the Authorized Agent

Building Permit

Permission is hereby gramed to execute the work described in this. application in accordance with the Flates. Regulations, and Ordinances of the Cky of Reno.

Duilding and Safety Division | TY OF RENO

BUILDING DIVISION

PERMIT EXPIRATION:

In accordance with the IBC. (Na permit shall expline if work is not commenced within 180 days from the ideas. date or if work is auspended or abandoned et any lime efter the work is commenced for a period of 120 days.

1500 STEELWOOD UN LOT:

Inspection Record

Inspector Signature

Dage

Building Inspections 8424 Groot

Reigh Reserved May bloom aum mathecodes

Pinal Inspections

PERMIT NUMBER: BLD19-08424

POST THIS PERMIT IN A CONSPICUOUS PLACE

Permit Inspection Record
City of Reno Building Permit

GENERAL NOTES:

It is underviol to receive thes record from the job sale until all final intertwient have been made.

After Permit tsauance, you may schoolide inspections 24 hours a day using a computer online at <u>happer/onent.gg</u> or with our mobile app. Test molification will be \$\$\text{sph}\$ between 7 00 s.m. and 7:30 a.m., to the mobile ahous number prodoed along scheduling. Your inspection will include an estimated time of armat. If a text was not possible, your inspector will arme at the job site between 7.30 a.m., and 3:00 p.m. For help or assistance call (775) 334-2063.

Health Inspections (Washoe County Health District - WCFD):

- ONLY accopts Inspection requests BY PHONE
'Phone cell (775) 328-2434 joption #4) to schedule all required Health Inspections which begin with the letter =#."

Fire Department Inspections:

Fire Department inspections should be requested for the "Next Business Day" regardless of the date required. A Fire inspected will call the next business day to schedule the actual date and lane of the respection using the talephone number provided either antine or on the mobile app.

NOTICE:

This Form shall be a permanent part of approved plans acached herato. Approved plans must be on the job site at all times and the inebection card poeted for inspection purposes. Plans are approved in accordance the IBC except that noted structural ristable shall be provided before construction is initiated in noted areas. The Renc Building Division shall receive a copy of all teating and field reports. Any changes in the approved drawings shall be submitted in writing for opproved. Provide or regain, as required, sidewalks, curbs and pureus in accordance with RMC. Excavation, iii, compaction and dramage shall comply with the IBC 90% minimum compaction under all concrete states.

Corrections and modifications as noted on plans and provisions of building codes and endingness as adopted by the City of Renoinfestion specified on plans or not, shall be complied with.

PREE inspection request app.

Scan QR code for your device



or search your
App Store
for
"Reno Building
Inspections"





Total Fees Dun: \$41.25

Total YMTs:

Address: 1508 STEELWOOD LN 3

Owner Information:

HOUSING AUTHORITY CITY OF RENO

Permit Number: BLD19-05862

1525 F 9TH ST RENO, NV 89512

Tenant Internation

Job Type: Building/Commercial/Plumbing/NA

Parcel No: 004-282-17

Valuation: \$ 1,976.00

Zoning: Public Facility

Occupancy: Group:

Type:

Fire Sprinklers:

Dwalling Units: 0

Fire Alarm:

Height:

Area(Sq.Ft.):

Stories:

Subdivision:

Lot:

Description of Work to 84 Dane

WATER HEATER.

CHANGE OUT 30 GAL GAS WATER HEATER WITH 40 GAL

GAS WATER HEATER.

Builder / General Contractor:

MICHAELS PLUMBING & DRAIN SERVICE

673 KRESGE LN SPARKS, NV 69431 775-355-1611

NV Lie.: 50226

The uncertigined besety agrees to defend, externally and bold harmhell the City of Read, as oncers amproyees and agents from and epants of comends. essions on baselikes shall are deterred against the City of Remo anising from the undersigned's consecution acception partormed pursuant to the research of Trisparmin (including but not firmed to the vinderskywed's lietore to perform in accordance will the approved permy and stone), they and staged auch demands, exercis ou liability that arise from the City of Fleno's acts regigente of with marconoucl.

The undersigned agrees to observationum commorpie) hybrid insurance covering it camp the serm of the construction authorized by this petitial, in as amount no less that the strat construction cost of the work to be performed, and valuations that south leability policy shall include completed operations coverage at well as an applicated insured endomerroni naming the City of Ramo as an acclinated insured with respect to operations performed by at lot the uncersioned to which the City of Reno has issued a building permit without exclusion to poddy wyrry ar property darwege within the competed coefficient of necessity

BuildestGeneral Contractor of the Authorized Avens

Beriding Permit

Permission is heceby granted to execute the work described in this application in accordance with the Rules, Regulations and Ordenances. at the City of Reno.

Building and Salaby

CITY OF REN BUILDING DEPT PERMIT EXPIRATION.

In accordance with the IBC, this permit shall expire if work is not commenced within 180 days from the leave. date or if work is susponded or abandened at any time. after the work is commenced for a period of 180 days.

1508 STEELWOOD LN 3 LOT: Inspection Record

Inspector Signature

Date

Plambing Inspections 8529 Vanomater

Final Impections 8573 Pluncing Final PERMIT NUMBER BLD19-85662

POST THIS PERMIT IN A CONSPICUOUS PLACE

Permi Inspection Record City of Rena Bullding Permit

GENERAL NOTES:

It is unlawful to remove this second from the job site until all final inspections have been made.

After Permit Issuance, you may achedule inepections 24 hours a day using a computer online at https://gnepy.us or with our mobile sop. Text notification will be sent between 7:00 a.m. and 7:30 a.m. to the mobile phonononumber provided during scheduling, Your inspector will indicate an estimated time of armys. If a text was not possible, your inspector will armye at the job site between 2:30 a.m. and 3:00 p.m. For help or assistance call (775) 334-2063.

Health Inspections (Washoo County Health District - WCHD):

ONLY accepts inspection requests BY PHONE.

Please call (776) 328-2434 (option #4) to schedule all required Health inspections which begin with the letter "H."

Ptre Doportmont Inepactions:

Fire Department Inspections, should be sequested for the "Next Business Day" regardless of the date required. A Fire Inspector will call the next business day to schedule the actual date and time of the inspection using the telephone number provided althor online or on the mobile app.

NOTICE.

The Form shall be a permanent part of approved plans asserted hereig. Approved plans must be on the job site at all times and the inspection card posted for inspection purposes. Plans are approved in accordance the IEC except that noted structural details shall be provided before construction is initiated in noted areas. The Reng Burketing Division shall receive a copy of all leguing and field reports. Any changes in the approved drawings shall be submitted in writing for approval. Provide or sepair, as required sidewalks, curbs and guiters in eccardance with PMC. Excevation, fill, compaction and drawings shall comply with the IBC 90% minimum compaction under all concrete stable.

Corrections and modifications as noted on plans and provisions of building codes and ordinances as adopted by the City of Penowhether specified on plans or not shall be complied with.

FREE inspection request app.

Scan QR code for your device

or search your



 $a \cos g h p$

App Store
for,
"Reno Building
Inspections"





EZ BUILDING PERMIT APPLICATION

City of Reno Building & Safety Division Commonity Development Department \ F. First St., 2rd floor, PO Box 1900, Reno, NV 89505 permits@reno gov (775)334-2063 Commercial & Residential

Perind #<u>BLD/9-0586</u>2

Recid by. DCA

This application is for min- below only. INCOMPLETE	or electrical, mechanical Espolications will not be	l and plumbing (without plans) and other processed, amail completed application	over-the-counter projects listed to to participate of the counter projects listed
Parcel Number: ()()2 Description of Work Replace 30 agr natur	:	Address: 1508 Steelwood leater with new 40 gal	_
neater	J	341	THE PROPERTY OF THE PARTY OF TH
Owner Information: Owner Name: Address: <u>।ನ25 E</u>		um) <u>Peuro Hiausing Martu</u> Phone NV 89512	mty 775 329 3650
Contractor Information Contractor: <u>Mitchael's F</u> Address: <u>676 ⊁-62-96</u> Email address: <u>seauci</u> Nevada Contractor Lic t	Jumbring Heating In Spayes Niv Emiclosels Plumba	<u>ng. ne#</u> Phone#: 779	1.dy Loipe 2 5-353-1611 15 License No.:
Project Information:			
Contract Amount \$	976.90	(Cost of materials and labor/\(\)	/a vation per ISC 108.3)
Furnace Installations	Water Heater _ 나이 yalons	Electrical & Plumbing	ReRoof (same meterial)
o Gas Change out 6TU s	(Gas	o Elec Service Change # of Amps	o Téar off
o Oil Change out	a Electric	u Water Line Replacement	o Composition
n New Furnace BTUrs ft of gas line	o Gas to Electric o Electric to Gas	 Sewer line Replacement (Private Property only) 	o Recover-MAX 2 layers
e Oil Io Gas BTU's	o Relocate	o Gas line Add/Replace	o Add sheathing
		o NV Energy hazard	b Indicate other:
E A/C		o Lawn Sprinklers (Residential)	
**Imp o Pick up permit at B		Charles	Other o Window Replacement o Sking o Slocco
V 24		Deal.	

Choose one: Commercial o OR Residential x

I understand that this application does not guarantee pennil issuance nor allow work to commence

I certify that i have the authority and authorization of the property owner to obtain this permit and, that this permit application is accurate and does not violate applicable ordinances, rules or regulations of the City of Reno.

I assume full responsibility for compliance with the adopted Budding Codes (1 B.C.) and all other applicable City of Reno Ordinances.

I agree to abide by all conditions on the Permit and understand that my signature below is being accepted by the City of Renoin lieu of my signature on the permit.

Sandy Lopez Int 19/19
Print Name: Date:



Total Feet Due: \$40.30

ABRICA 1500 STIRLWOOD LN 4

AND Exper Building/Commercial/ParalyngP10

Part of Nov

Upopular EARORO

Zormig, underhed

Occupancy. Groups Groups

Type Daniel gradus ()

Fere Sprinklers:

HeleM.

For Alberta

енниза Ец.

Sierlas:

lol:

Careerono's of Mars to the Come WATER HEATEN.

CAS TO GAS AD GALL ON YOUTH MINTER CHANGE OUT

Die unterlagene seinen agenen ist dem ist, eingeneh und reicht befordigen der Die de Marin, aus stäteren, erspätzungt und aggesen. Mit mit bijdebei all abstähelt. mara of hishest the me topical papers for Coy of Spin physic had the appropriate consistency against published for make his for clinical in Feb. array conductor was many broady or the general property thanks to detect to recovering much the department departs and attack) these tool except, there search, dema er bretty der jest men de Coy di Mirch i ville designiste d


The purpose against the communities contracted before district culture of figure the series of the specification business to the factor of the recognising type the tiple distilluiable does of the color to percently the and the latter and the second كالكلاث كالمتخاط المطاولية مؤرسات ويوميه ويوبيه والمراوي والمراوي

Ċœн

Bakka/Garand Compations the Systembolis Age N

Belleting Patrick

Paradicare a haraby promote specule Provert described in Still professor a property of the Bules Republican and Children's pi pag Cayler Reno



BUILDING DIVISION

Permit Number: BLD19-04165

Value VIII for

Owner Milder alles.

ATTROHITUS SHISKOH GARSA

MAS E STHIST

eging M.

Female Information:

RENO HOUSING AUTHORITY.

1535 F 9TILAT PENG NY

Builder | Demarcal Contractor MICHAELS PLUMENAG & DRAIN SERVICE.

MAKAEARE 74 SPAPKS, NV 49434 135.355 [643

MV Lieu: QUBULAS

PERMIT EXPERATIONS

in accordance million with the process shall evering the page (parige parameters) and an 186 days from the labor. app or despite a purported to alternitrated in my way. ather the work to comment that for a port of 140 days.

1500 STEELWOOD LN 4 LOT.

Inépédién Record

Інасиски Баневин

Physician Suppositions MY Green fa me watulear just in Francisco d'Arab

PERMIT PRINCES: BLD19-DLIGS

POST THIS PERMIT IN A CONSPICUOUS PLACE

Permaticspection Record Cury of Florid Building Partiti

GÉHERAL HOTÉS:

dictional to remove this record from the picture are and all their Karama Mariamana

Aller Partier i vizzanca per traspici herende de peralega de perensis The works to the street seems at page 1999 and the street mabble and Transmittendon will be norm spreamen? If was una P 50 и.м. чете товых рязне потбогрионах даміну таковыну. Your property will end cate an adversed time of server. A a temperaer poules per adjects with the man on the person like s v. and 340 em. Ferheis et authlands call (7% 334-296).

Hastiniane: Ikwa Mastos Covely Holds Midski - Alfaldz - ONLY acreso inspection requires BY PHONE -Magra call 1754 bith into logitors when schedule all respects THE SEC POLICE COME WHICH SECURE WERE THE PART OF THE

Par Copperation les partiers

For Department supermore meals to require he for the West Continue trop regulation and an energy A Francisco eral feer restriction of whiteher or will constitute and line elika hapa, por gregika injegropa semper gerdand simpe selfer as conductive mebber ago.

HOTICE

let fain year to a become out of mount along shaded miliano. Papramio prena silvillo de on dia pa am el de ares electros ma Aprilian and paths for expected majority. Also we approved I RESTRUCT ON the Except that name tradition of the top top meeted before communication in record profess before The Meno parang Chamar gara appear a regy of an arming can devo repose. Any casegue is the appreciate arrange proof as promining in waiting to approve Premise in resemble to beginning the court and guesta de proposera com Plato - Francisco de encombra par dening the property with the RC STV property procedure under March 1980

Corrections and medifications at tiosed at areas was predicted as building codes and anonamous as appeared by the Charlet Ramo evenno appearant on signa or ser until de despusa veus

PREE inspector request sup-

Scan QR code for your device



or search your App Store

"Reno Building Inspections"





Description of Work.

EZ BUILDING PERMIT APPLICATION

City of Remo Building & Safety Division Computery Devisionment Department 1 B. Fars (\$7 25th Remo PG) Box 1980 Remo No 69505 partmiss@eno.cov-175(1934-2063)

Commercial & Resistant	-
	í
Recia by	_

Choose one: Commercial o	ÓŘ	Residential par	
--------------------------	----	-----------------	--

That application when many electrical mechanical and plumbing matrical growth and other over-than course property tested before any electric projections with the processor C. and completely consistent accomplications with Parcel Hymber: 004 (292.11) Address: 1500 Sheet Legary List #4 Rene 815|Z

Oleset thereo cut of 40 ejection. Nethrol gas mater neuter which all code opganish Owner Information Business Name (Com) HOUSING Portharity CITO OF RELIA Owner Name: Phone 775- 32% 34450 ያትንተረ Address: は5.2 づ KENJa Contractor Milormation: Continuos Microscia Plumbino, Hisanno, i Airi Contact Name: K Address to 10 Viveter to Shares aw \$4512 Email address: Secure & michaelsplanting met Phone 7 775 - 344 - 14-11 Nevada Contractor Ltd No and Classification 💆 City Business License No. 60274 Project Informacion. 4-00 **0**0 Contract Amount 5. (Cost of materials and labor/Valuation, pay 180, 198 b). Furnéce lestallations Water Heater Electrical & Plumbing Reflect town named 4*D* gallers in Gan Change out p Dec Service Change o Tear oil **STU**s For Ambs

DOT Charge out a Electric c Water Line Replacement

Differ Female c Get to Deptic c Sever line Replacement

Biffur I of des line of Electric to Class

Differ Get to Case of Relocate c Gos line Ade/Replace

Biffur I of des line of Relocate c Gos line Ade/Replace

Biffur I des line of Relocate c Gos line Ade/Replace

Biffur I des line of Relocate c Gos line Ade/Replace

n Add sheateny a Maiassa atten

O PRECIONAL MAIN 2 Moreon

& Composition

5**4**(0

lune

p/Pay and grain online

""important""

a FK# up permit at Building Permit counter.

CLEAN SOURCE CHENNED

c MAY Energy hessert

MOV 0 6 200 0 0W

o Window Peplacomeco

ı

Спу от нево Станува Останува Оста

- is Server to Servero
- I syntérotero Revitts application does not guarantes pensió naustres not allow work jo grammage.
- Locality Pea, I have the politically and authorisation of the property owner to obtain mis permit and, that the permit settlements exclude and does not viotate applicable ordinances, talks or reputational the flag of Report
- Legiture (utilización-billy for compliance with the accipied Building Codes (LB C) and attraction city of Pero Orderance.
- I Agrice to doing by all conditions on the Permit and understand that my signature below is being accepted by the City
 of Hero in real of my segnature on the payms.

Katheren Sayrah	datt 1	19/4/2018
Provi et autor 1 3 3	. 1825 25	\$ ***



Valuation: \$ 1,657.00

Total Face Due: \$40.00

Occupancy:

Fire Alarm:

Stories:

Fire Sprinklers:

Group:

Total VMTs:

Address: 1504 STEELWOOD LN 4

HOUSING AUTHORITY CITY OF RENO.

Permit Number: BLD18-08801

Owner information:

Tanuat Information:

Job Type: Building/Commercial/Plumbing/NA

Parcel No: 004-292-17

1525 E STHIST. RENO, NV 89512

Zoning: Public Facility

Type:

Dwelling Units: 0 Height.

HOUSING AUTHORITY CITY OF RENO. 1525 E DTH ST

Area(Sq.FL):

Subdivision:

Lab

RÉNO. NV 83512

Description of Work to Be Done

Builder / Gaserel Contractor: JET PLUMBING & ORAIN SERVICES.

WATER HEATER.

1553 HYMER AVE SPARKS, NV 89431

775-331-3933

REPLACE40 GAL GAS WATER HEATER

MV Lie : 0024184

The undersigned hereby agrees to defend, internally and bold harmless be-City of Ratio, at officers, equilibrium and agents from and agents all comands. Claims of liabilities that are executed against the City of April arising from the undersigned's continuous accurate performed pursuant to the incurance of the permit (including our not kineed to the undersigned's failure to perform in accordance was the accreved payme and plane), eave and except such definancia, diament or Mathity than prope known the Carry of Raiso's edie negligence or with a street or the

The undersigned agrees to optamination commercial Material visualine covering it during the term of the construction authorized by this permit in an amount no lives that the total construction cost of the work to be performed, and warrance that such lightery policy shall include completed operations construct as web as an accessful insured endoscreek naming me City of Reco as an additional insured with respect to operational performed by all for the continuous for which the City of Reso has lessed a building germs, without exclusion for boddy injury of property damage within the completies operations of hezard.

Building Permit

Permission is hereby granted to execute the work described in this

application in accordance with the Rules, Regulations, and Ordinances.

Suider General Contractor or the Austromaga Agent

PERMIT EXPIRATION:

In accordance with the IBC, this person shall expire if work is not commanced within 180 days from the Issue date or if work is suspended or abandoned at any time. efter the work is commenced for a period of 180 days.

Building and Safety Division

of the City of Rang.

1504 STEELWOOD LN 4 LOT:

Inspection Record

Inspector Signature

Durie

Plumbing inspections E-928 Manufactors Fringl Inspections E-9579 Physbing Post

PERMIT NUMBER: 8LC48-08901

POST THIS PERMIT IN A CONSPICUOUS PLACE

Permit Inspection Record City of Reno Building Permit.

GENERAL NOTES:

It is unlawful to remove this record from the job size until all final inspections have been trade.

After Permit Issuance, you may streetile respections online 24 hours per day. Please provide a mobile phone surviver. You will receive a polification by text from your inspection the day of your inspection between 7:06 a.m. and 7:36 a.m., indepting the estimated time of arrival. If a text was not possible, the inspector will arrive at the job site between 7:30 a.m., and 3:00 p.m., for help of assistance cell (775) 334-2053.

Fire Department #1506ctions:

Fire Department inspections should be called in for the "Next Business Day" regardless of the date received. A Fire inspector will can the next business day using the relaphone number provided either craine or the on automated temphone line, and schedule the georgi date and time of the inspection.

Please refer to the Fire Department comments posted on the back of the front page of the appreved plans for additional information and requirements.

NOTICE:

This Form shall be a permanent part of approved plants attached hereto. Approved plane must be on the job bits at all times and the inspection card posted for inspection perposes. Plants are exproved in accordance the 18C except that invest shoulded details shall be provided before construction is inlighted in noted areas. The Rano-Building Rivision shall receive a copy of all testing and fast reports. Any changes in the approved drawings that be submitted in writing for approval. Provide or vapar, as required, sidewiffs, curbs and guriers in accordance with RMC. Excavation, till, compaction and drawings shall comply with the IDC 50% minimum compaction under all conceres slabs.

Corrections and modifications as noted on plans and provisions of quirking codes and ordinances as adomes by the City of Renowhether specified on plans or wat, shall be compiled with.



Service Service

Easy scheduling... Free mobile appl





On-line inspection scheduling now available on the City of Rano website: www.reno.gov > Services menu > Licensing and Permits. Use an account to best mange inspection acheduling and tracking or check plan etable. (eta address: http://onenv.us.)



BUILDING PERMIT APPLICATION

City of Rono Community Devolopment Department 1 E., First Street – P.O. Box 1900, Rano, NV 89505 (775) 334-2083



Speedy Commercial	& Residential
-------------------	---------------

Pomit # 18-0880 (

Recidiby: \(\square\squ

Speedy: Commercial X OR Residential &

This application is to be used for minor electrical, mechanical and plumbing, and roofing demits only. INCOMPLETE applications cannot be processed. Fax completed application to (775) 334-2043 or email to permits@reno.gov

Parcel Number:	004-292-17	Address:	1504 SteelwoodL	ane #4	Crot.
Description of W		• • • • • • • • • • • • • • • • • • • •			- Pr
prescription of ve	OIR-	 	-	- 7 / 2	7. F-
: .					CEIVED
Replace 40 gal g	as water heater with:	same			<u> </u>
				4	PR 2017
Owner Information	on: Business Name.			C) T	T OF RENO
Owner Name:	R⊣A		Phor	ne Nøsk	OF REND
Address:					WIFE ACE
A001000	_				
Contractor Inform	ation:				
Contractor Jel	Plumbing		Contact Name:	Drew	Rolley
Address 15	43 Humer Ave Snort	e NV ROARI			
Obona No : 77	ation; Plumbing 53 Hymer Ave, Spark 5-331-3933	B, 147 00-101	Fax No.:	775.331.	5584
PHONE NO.	34404		City License		
Nevada License No			City Excense	140 <u> </u>	(3244W
Email address. —	Dispatch@JetPluml	ying.com			
Project Informatio	ric				
Contract Amount \$	1657	(value	ilon per (BC 108.3)		i
HVAC Installation				В.	Roof
		CHCLING	al & Plumbing	r.	ROOT
8TU's	40 gakonsi				
change out	8 Gas	o Elec S	агиксе Спапев	D.	Tear ciff
-		# o			
o New	n Electric	⊔ Water	tine Replacement	0.	Composition
			-		
a Electric unit to gas	⊕ Gas to Electric		ine Replacement	e l	Recover - MAX 2
•		(Private I	Property only)	la	yers
n Oil to Gas	e Electric to Gas		e Add/Replace	C)	Add sheathing
			l ae i		
o Furnace only	⊯ Relocate	Q LEWN S	prinklers (Residentier)	10	micate other:
,			•		
u A/C add H/P				Ō	ther
(tons)				e l	Window Replacement
		_			
Lunderstand that th	is application does not	quarantee cent	it saconce nor allow	work to d	commence. I certify
that I have the auth	erity and authorization	of the depondity of	week to obtain this p	ermit.	·
DIGITATION OF 1140 CONT.	2111) -10 -10 -10 -10 -10 -10 -10 -10 -10 -10				
Crew Rolley		120	(A)		4/30/18
		-Addresoni Signaturi	<u> </u>		Os4e:
Prim Applicant Name:		— Аррисані а фони	. /		OBAC.
	****	nds Oarrolf ALD	HORIZATION """		
				Permito	
ATES, DEBSE USE CIE	dil card payment authoriz	ation on tile. FAX	eman company		
I meneby certify that W	ns permit application is a	counte and oces	non viciale applicable o	Cadas (1.5	Care and all arthur
Ine City of Rene. 1 24	sume full responsibility to	or compession valu	Title excepted pullpling t	codes (I M	na jeren za terrar odkodkovi ilika se se s
applicable City of Ref	no Ordinances. I agree to	ankin ny alijamin'i	HIGH SOUTH ON UNG PE	III BNO J	unaugiano mei my
aignature balow is be	ing accepted by the City	M TROUBLE LIBER DAY	mysopperure on the per	11175	
0 0-11-	/	14 767	War (San Care)		4/30/18
Drew Rolley			- 4		
Print Name	Spina	100 P	PR 5 0 2913		Date. Rev. July 7014
		A	Ltr 10 tann		May. 301

CITY OF K (C) Community Decem on a



Valuation: \$ 1,400 00

Total Fees Due: \$40.00

Occupancy:

Fire Alerm:

Fire Sprinklere:

Group:

Stories:

Addmiss: 1512 STEELWOOD LN UNIT 2

Job Type: Building/Residential/Plumbing/I4A

Parcel No: 004-292-17

Zon≀ng: PF

Тура:

Dwelling Units: 0

Height:

Area(Sq.FL):

Subdivision: PJ KELLY'S

Lot

Description of Work to Be Done WATER MEATER. 40 GAL GAS Dire: \$40.00 Total VMTo:

Owner Information:

HOUSING AUTHORITY CITY OF RENO.

Permit Number: BLD18-01525

1525 E 9TH ST . RENO, NV 89512

Towart Information:

Builder / General Contractor:

JET PLUMBING & DRAIN SERVICES

1553 HYMER AVE SPARKS, NV 89431 775-331-3933

NV Lic.: 0024184

The undersigned hereby agrees to detend, indomnity and hold hormtess the City of Reno, its orticers, employees and agents from and agents at demands, charts or facilities that are asserted against the City of Reno analog from the undersigned's construction activities performed pursuant to the issuance of this permit, (including but not invited to the intertigned's tollare to perform in accordance with the approved permit and plants), save and except audit demands, claims or liability that arise from the City of Reno's sole aegligence or written insconduct.

The undersigned agrees to obtain/important commercial hybrids industricts covering at during the norm of the construction authorized by this period, in an amount no less that the total construction ods! of the work to be performed, and warrants that such subtry policy shall include completed operations obvertige during as an addenoral insured encomment naming the City of Remo as we acchinent insured with respect to operations performed by or for the underspectable which the City of Remo has assume the contribution performed by or for the underspectable which the City of Remo has assume the contribution operations of hazard.

PAID AUS 2 1 2017 SEXANT FERNS

ĝγ

Date

Budder/General Contractor or the Authorized Agent

Building Permit

Permission is hereby granted to execute the work described in this appacation in accordance with the Rules, Regulations, and Ordinances.

OMBRANDAMENTO

PLANNING DIVISION

1512 STEELWOOD LN UNIT 2 LOT:

Inspection Record

Inspector Signature

Dese

Plumbing inspections 0528 Management

Final Inspections

8573 Plumbing Final

PERMIT NUMBER: BLD18-01528 POST THIS PERMIT IN A

POST THIS PERMIT IN A CONSPICUOUS PLACE * •

Permit Inspection Record City of Reno Building Permit

GENERAL NOTES:

It is unlawful to remove this record from the job site until all final inspections have been made.

After Permit Issuance, you may schedule inspections chiline or by belephone at (776) 334-2396 on our outlomated line 24 hours por day. Please provide a mobile phone number. You will receive a polification by text from your inspector the day of your inspection between 7:00 a.m. and 7:30 a.m., indicating the estimated time of printal. If a text was not possible, the inspector will army at the job site between 7:30 a.m. and 3:00 p.m.

Fire Department Inspections

Fire Department inspections should be called in lor the "Mext Business Day" regardless of the date required. A Fire Inspector will call the next business day, using the helicitione number provided either online or the on automated telephone line, and schedule the actual date and time of the inspection.

Ptease refer to the Fire Department comments posted on the back of the front page of the approved plans for additional information and requirements.

NOTICE:

This Form shall be a permanent part of approved plans, affached hereto. Approved plans must be on the job site at all times and the inspection card posted for inspection purposes. Plans are approved in accordance the IBC except that noted structural details shall be provided before construction is mission in noted areas. The Reno Building Dirision shall receive a copy of all testing and field reports. Any changes in the approved drawings shall be summitted in writing for approval. Provide or repair, as required, sidewalks, curbs and gutters in accordance with RMC. Excavation. Bit, compaction and drawings shall comply with the IBC 90% primiting opmostion under all concrete states.

Corrections and modifications as noted on plans and provisions of building codes and undinances as adopted by the City of Reno whether specified on plane or not, shall be complied with

PERMIT EXPIRATION:

In accordance with the IBC, this permit shall expire if work is not commenced within 180 days from the issue date or if work is suspended or abandoned at any time after the work is commenced for a period of 180 days.

On-line inspection scheduling now available on the City of Reno's wabsite wave.repo.gov > Online Services menu > Virtual Permit Place/Citizen Access. Contractors may create an account and schedule inspections or check plan status.

(site address: http://onenv.us)

BUILDING PERMIT APPLICATION

City of Reno Community Development Department 1 E., First Street – P.O. Box 1900, Reno, NV 89505 (775) 334-2063



S	POCY	Commercia	18	Resident	<u> </u>
---	-------------	-----------	----	----------	----------

Permit #: 18-01525

Rec'd	by:	
	_	

Speedy: Commercial of Residential of

Phone No: Phone No:
Phone No: ntact Name: Drew Rolley Fax No.: 775-331-5584
Phone No: ntact Name: Drew Rolley Fax No.: 775-331-5584
ntact Name: Drew Rolley Fax No.: 775-331-5584
Fax No.: 775-331-5584
Fax No.: 775-331-5584
Fax No.: 775-331-5584
City License No.: 5244

er IBC 108.3)
fumbing ReRoof
Change o Tear off
s episcement a Composition
eplacement a Recover = MAX 2 by only) layers
Replace a Add sheathing
ers (Residential) a Indicate other:
Other
u Window Replaceme
ance nor allow work to commence. I certif
to etitain this permit.
8/18/17

AUG 18 20%



Total Fees Due: \$40.00

Total VMTs:

Address: 1516 STEELWOOD LN UNIT 1

Owner Information:

Permit Number: BLD18-01111

Job Type: Building/Residentiel/Plumbing/NA

HOUSING AUTHORITY CITY OF RENO.

Percel No: 004-292-17

1525 E 9TH ST. **RENO, NV 89512**

Zoning: PF

Valuation: \$ 1,350.00 Occupancy:

Type: Owelling Units: 0

Group: Fire Sprinklers:

Height

Fire Alarma

Area(Sq.Ft.):

Subdivision: PJ KELLY'S

Stories:

Lota

Tenant Information:

Description of Work to Be Done

WATER HEATER..

INSTALL 40 GAL GAS WATER HEATER

Builder / General Contractor:

JET PLUMBING & ORAIN SERVICES.

1553 HYMER AVE SPARKS, NV 89431 775-331-3033

NV Lic.: 0024184

The undersigned hereby agrees to defend, indemnify and hold harmless the Oby of Read, its officers, employees and agents from and against all demands, claims or Natiffies that are assessed against the City of Rano arising from the undersigned's construction activities performed pursuant to the issuance of this penal (including but not limited to the undersigned's failure to perform in accordance with the approved power and plane), save and emospi such demande, claims or liability that drive from the City of Rano's sole insolvenou or and first missesseduct

The undersigned agrees to obtain/mentern commercial legality enqueunce covering is during the serm of the communities sufferiored by this permit, in an emount no less that the total construction cost of the work to be performed, and warrants that such liability policy shall archide completed operations coverage as well as an additional insured endomerrant naming the City of Riero as an additional enseed with respect to operations conformed by or for the undersigned for which the City of Remo trac resuled a building permit, without exclusion for boddy vigury at property demage multim the completed operations of historic.

Date

ontractor or the Authorized Agent

Building Permit

Permission is hereby granted to execute the work described in this application in accordance with the Rules, Regulations, and Ordinances

of the City of Reno

Building and Sales Division

1516 STEELWOOD LN UNIT 1 LOT:

Inspection Record

Inspector Signature

Data

Plumbing Inspections B528 Manameter Final inspections

8573 Plumbing Final

POST THIS PERMIT IN A CONSPICUOUS PLACE

PERMIT NUMBER: 8LD18-01111

Permit Inspection Record City of Reno Suilding Permit

GENERAL NOTES:

It is unbawful to remove this record from the job alle until all final Inspections have been made.

After Permit Insurance you many achiedule inspections online or by telephone at (776) 334-2396 on our automated line 24 nours per day. Please provide a mobile phone number. You will receive a notification by text from your inspector the day of your inspection between 7:00 a.m. and 7:36 a.m. indicating the estimated time of arrival. If a fext was not possible, the inspector will arrive at the job site between 7:30 a.m. and 3:00 p.m.

Fire Department Inspections.

Fire Department empections should be called in for the "Next Business Day' regardless of the date required. A Fire Inspector wall call the next business day, using the telephone number provided either online or the on automated telephone line, and schedule the actual date and time of the impection.

Please refer to the Fire Department comments posted on the back of the front page of the approved plans for additional information prid reguments.

NOTICE:

This Form shall be a permanent part of approved plans attached hereto. Approved plans must be on the job site at all times and the respection card posted for respection purposes. Plans are approved in accordance the IBC except that noted structural details shall be provided before construction is withated in noted areas. The Reno Building Divition shall receive a copy of all testing and field reports. Any changes in the approved drawings shall be submitted in writing for approval. Provide or repair, as required saderwalks, curbs and guillers in accordance with PMC. Excavation, Fill, compaction and drainage shall compty with the IBC 90% minimum compaction under all concrete stabs

Corrections and modifications as noted on plans and provisions of building codes and cromances as adopted by the City of Reno whether specified on plans or not, shall be complied with.

PERMIT EXPIRATION:

in accordance with the IBC, this parmit shall expire work is not commenced within 120 days from the issue date or if work is suppended or abandoned at any time after the work is commenced for a period of 180 days.

On-line inspection scheduling now available on the City of Rano's website www.reno.gov > Online Services menu > Virtual Permit Placa/Citizen Access. Contractors may presse an account and schedule inspections or check plan status.

(site address: http://onenv.us)



BUILDING PERMIT APPLICATION

City of Reno Community Development Department 1 E. First Street – P.O. Box 1900, Reno, NV 89505 (775) 334-2063 FAX (775) 384-2043

EZ permit	^
Permit# KL1	$\times 10^{\circ}\Delta MD$
Rec'o By	}18-0// //
1,000 0 0,000	Rev 06/2012

This application is to be used for minor electrical, mechanical and plumbing (without plans), and rooking permits only. INCOMPLETE applications cannot be processed. Completed applications may be faxed to (775) 334-2843 or emailed to permits@reno.gov.

Choose one :	Commercial 🗆	Residential 🗓	
Parcel Number:	Address	: 1516 STEELW	00 <u>0</u>
Description of Work:	install 40 gal.	gas water heat	
Name: <u>Rino Lleua</u> Address: <u>1525 E</u> Contractor information	e diff (Line)	Phone No: 775	
Address:Phone No.:	MBING & DRAIN SERVICE 1553 Hyme: Avenue - Sparks, NV-89131 131-3038 • (775) 331-5564 c. 24164 • Exce # 57904	Fex No.:	· · · · · · · · · · · · · · · · · · ·
Project Information: Contract Amount \$ 3	50 eg w	raturation per IBC 109.3)	··-
HVAC Installations	Water Healer	Electrical & Plumbing	ReRoof
a Change out	<u>40</u> gallons \$Gas	□ Elec Service Change# of Amps o Water Line Replacement	c Tear off
a Electric unit to gas	a Blectric a Gas to Blectric	□ Sewer ine Replacement (Private Property only)	c Recover – MAX 2 layers attowed
∋ Oil to Gas	⇒ Electric to Gas	Gas line Add/Replace	: Add sheathing
o Furnace ofity	⇒ Relocale	⇒ Lawn Sprinklers (Residential)	c Indicate other:
I understand that this ap	pilication does not guarantee and authorization of the properties	permit issuance nor allow work to entry owner and above listed confra	commence. I certify sector to obtain this sector to be se



Total Pers Due: \$39.65

Address: 1548 STEBUNGOD LIN UNIT COMMI OFCE.

July Type: dummather-commit/Plembrights.

Page 18to: 004-252-17

Valuation, 6 5 297,00

Zoska M lypt:

Occupancy: ****

Owner, when o Herialic.

Flee Saulablers. Cler About

anadate:

Stöden:

Behildreice PUNELLY'S

Description of West, to Co Done

WATER MEATER. COMMUNITY SUDC OFFICE PEPLACE TANKWATCH HEATER WITH NEW RIMMORK SEEN TANKLESS WATER

HEATER

Permit Number: BLD17-45755

Total VMTs:

Dwine Information.

HOUSENI AU: HORSEY CITY OF FINNO.

1525 E ATH ST. RENO MY 69612

Party of Information:

Builder | General Coming aller

MICHAELS PLUMBAIG & CRAM SERVICE

STOKE SCELN SPARKS MV89421 119-355-1611

MY Lik = 3000226

The architecture match against to special expension and mild hypothesis for the collection of property property that the collection and against an expension. The second of the provided second for Car of Republishing State of Republishing State State State of Republishing State State State of Republishing State of Republishing State State State of Republishing State of Republishing State are or betains the ore experied assert the Car of East below that the

ты чанурые щим и ченические сименты можу измент and I have be seen to be described by the state of the section of ---ah ya ya ajibana aranda sahanarat sama dar Lap ot biba bi bi gayang anang ah sajapa in gapabaha palabaha ka di in da dibibagan THE PARK OF A PARK BAR WALL IS BEEN AND ARREST AND A COURSE OF

halder Parent of the Area of the Paris Agend

Building Permit

Desc

Commission for the property is a commission for the first first first on the The second by the second older Clay of Person

CITY OF SENIO

<u>nakang and Salah Dunas (B) ||| (B</u>HAS 11)**(EPT**.

PAID PARRITE

1548 STEELWOOD LINURAT COMM. OF CE LOT:

Integration Record

Planting respections
512 Georges
4 Colonia (Colonia Colonia Co

PERSON NUMBER: BLOOP-MISS

POST THIS PERMIT IN A CONSPICUOUS PLACE

Permit Impurates Record

City of Parts Substry April

GENERAL MOTER

in its collected to relative that handred their than both rise until all best despendence than the collected than the collected

Plate Petter Rejusions you make prompts improvious prince or by the plane of 1775 134-2565 on our automorph was 30 house yet day. Planes provide a modific groom number 1951 with inclusive of profitation by make from your flaquette that day of your organization between 1994 on, and 1985 a.m., indicating the symmetry of prince. If it fail was 444 detailed. The indipatite will arrive all the year the between 700 or an of 1986 a.m.

Fire Coccario era la aprobara -

Day.

From Conjuminant Immericans streets he costed to far one blood Business Conjumigenties of the data seasons! It file Immerica and cost the season business day using the seasons overhead provided where desire in the for automated territories and and activities the season data complete only impressed.

Person ander to the Box Coppositions controping passes, on the Copp of the Inter-page of the approved phase has additional information pair representation.

MO (NOTE:

Their Feath (and the is interfeation than of appropriate softers relaction from a figure and process report on the job judy of all prints, and from the delication purposes. Flam are depletioned in a superior purposes. Flam are depletioned in a record process the first design of the process of colors constrainty in addition in against depletion from the process of colors constrainty in addition in against depletion and field the processing flaments which increases a compact of the large participation of the processing of the large participation of the processing of the large participation of the processing of the large participation of

Contributes and Analistations at Author on plans and previous of Building codes and enforcement as sampling by the Cay of Repowhiten transfer on plans or not shall be consided with.

PERMIT EXPERAMENT.

in accommence with the MRC, this permit small explice if want is not commenced within 100 days from the leave falls or it worth to suggestion or physicians of all any time. The will be continued at permitted of 100 days.

On-three Mandelliers activities press available on the City of Meno's archeolog awar (everyor > Colline Servenes revers > Vehicle Servenes Record Mandelliers Accepts - Consequence Meno Accepts - Meno of Meno Accepts - Meno Accepts

Calle ad Press: Attack/oversous h

÷	
60 C. V.	١

•

BUILDING PERMIT APPLICATION

City of Rana Community Development Beginnered # 3 , First Street - P.C. Box 1930; Rana et 23255 (75) 194-1962 Ŕ

Permis ALDED (* Reciperate)

Reciple (* 7)

	Rang art 89505 17(5) 134-2063	~ NZ ~	·
Talk apply above	Spécity: Con	rimineisi : OR Residental) Stransa en janima, en redecin	Partitions into case (Esq. 1997)
	and an endough him transferries.	approcessor in 1775) 334, 2003 or morning Charles (Charles Charles Cha	Demis Blancou
Pescingilion	OT PTOIK:	ስታያያ ነው ነው ነው። የሚያያ ለ ነው ነው	∞ة محمدات ده
		an Papinee with N	iso Rinová.
Characte Myline	Melion Bushlesa Nume: 1%	and a Marian and Ass	3850F1 150
Address 19	have thanking the	A Prond	No <u>,3379-24,300</u>
Contractor to Conventor	iomailea; Marinoskia (1844)	Contact Name Yes	on Real se.
2004 to: <u>L1</u> }	Difference Leading Section 5.	Arks No Range	
Phone Mo	te ho ferance is	Pavillo2(5)Coy Leanse No	
E-mad address	ЦА		
Subject judgite	nejlon:		
Coffeet Amou		(valuation per 49C 108.3)	_
HVAC Malaßi BTU s		Emerican & Paratimp	Refeof
O Charge out	d Gen	s Eint Geryse Change Pipi Ampe	ы Гер он
4 New	& Electric	C Water & the Replacement	осетројани
C garden has so	per o Gaste Geeting	с Sower вое Редоссиясы. (Римана Беорьету стау)	o Recover – Majo, 2 Myeta
D ON M CAR	to Charge to Gas	GM des Addresses	D ADM shepping
n Fuestice orey	o Rélocule	n i dre fi Spenie and i Parte See as fi	D Mécale any
O AND BOTH MIP	A PARTONE WHILE	***** 5.7 Kd7	Olhai
(lorse)	Trippy Land Converse		ф РИМОРИ Колистепц
I understand Pa main have the a	e var 1902/53000 Oblid Noi due o	Club switch per mail issuance not below woo property dwiter to detect (http://perm	k lo rommenyo 4 ceney A
Trude C	aprileta 📅	<u> Aberlanda (</u>	<u>3 ಀೣ</u> ೣլ¬
	Soundy P	amin AUTHORIZATION	
The bed was in the mix	04:14 сана рауктему функция воду. В 1441 обића (франска) и посумен	on des FAX Population — Engle Agri La set close postibionale accessorable access	
	i Allemé iut respondibilit io 3000. Reno Outenance, i eterado estado	U WALE MULLINITED COMMOND COMP	54 OC yard all pres

explants City of Paris Olymentes. I streets exists by about consumptions or the Paris and undinaturalize my agreed to provide a contract country of Reports on the parish.

**The City Office 1.10 Act of City Olymentes and City Olymentes are contract of the parish.

**The City Office 1.10 Act of City Olymentes are contract of the City Olymentes and City Olymentes are contract of the City Olymentes and City Olymentes are contract of the City Olymentes and City Olymentes are contract of the City Olymentes and City Olymentes are contract on the City Olymentes and City Olymentes are contract on the City Olymentes and City Olymentes are contract on the City Olymentes and City Olymentes and City Olymentes are contract on the City Olymentes and City Olymentes are contract on the City Olymentes and City Olymentes are contract on the City Olymentes and City Olymentes are contract on the City Olymentes and City Olymentes are contract on the City Olymentes and City Olymentes are contract on the City Olymentes and City Olymentes are contract on the City Olymentes and City Olymentes and City Olymentes are contract on the City Olymentes and City Olymentes are contract on the City Olymentes and City Olymentes and City Olymentes are contract on the City Olymentes and City Olymentes are contract on the City Olymentes and City Olymentes are contract on the City Olymentes and City Olymentes are contract on the City Olymentes and City Olymentes are contract on the City Olymentes and City Olymentes are contract on the City Olymentes and City Olymentes are contract on the City Olymentes and City Olymentes are contract on the City Olymentes and City Olymentes are contract on the City Olymentes and City Olymentes and City Olymentes are contract on the City Olymentes and City Olymentes and City Olymentes and City Olymentes and City Olymentes are contract on the City Olymentes and City Oly

#11.

TO MAY PORT



Total Fees Due: 339 65

Permit Number: BLD17-03174

Owner Information:

Tenant laformation:

Total VMTs:

Address: 1512 STEELWOOD IN UNIT 1

Job Type: Building/Residential/Plumbing/NA

Parcel No: Zoning: PF Valuation: \$ 600 00. Occupancy:

zoning: Pr Type:

Group:

Dwelling Units: 0

Fire Sprinklers:

Height:

Fire Alarm:

Area(Sq.Ft.):

Stories:

Subdivision: PJ KELLY'S

Lot

Description of Work to Be Cone WATER HEATER...

CHANGE OUT NATURAL GAS 40 GALLON WATER HEATER

Builder / General Contractor: MICHAELS PLUMBING & DRAIN SERVICE

670 KRESGE LN SPARKS, NV 89431

NV Lic.: 0060226

The undersigned horeby agrees to defend, indemnify and hold transless the City of Reno, its officers, employees and agents from and against all demands, objects or individues that are asserted agrees the City of Reno among from the undersigned's construction activities performed pursuant to the issuance of this permit enduring but not imited to the undersigned's tailure to perform in accordance with the approved permit and plans), save and except such committee, claims or leabery that area from the City of Reno's one negligories or with mesonagues.

The undersigned agrees to obtain/maintein commercial liability inturance covering a during the lemi of the coestaction extraction by this perform, in an amount no leas that the total coestaction cost of the work to be performed, and warrants that such liability policy shall include completed operations coverage at well as an additional insured endorsement aurining the City of Preno as an additional insured with respect to operations performed by or for the undersigned for which the City of Preno has sessed a building power, without evaluation for booking rejudy to property damage within the completed operations of hazard.

By Fayers

DM011[2[16

Builder/General Contractor or the Authorized Agent.

Building Permit

Permission is hereby granted to execute the work described in this application in accordance with the Rules, Regulations, and Ordinances of the Oth of Reno

Building and Salety Division

CITY OF HENC FOLDING DIV A TO

1612 STEELWOOD LN UNIT 1 LOT:

Inspection Record

Inspector Signature

Date

Plumbing inspectors 8528 Manameter

Final Inspections

B573 Plumbing Final

PERMIT NUMBER: BLD17-03174

POST THIS PERMIT IN A CONSPICUOUS PLACE >

Permit Inspection Record Cdv of Reno Building Permit

GENERAL NOTES:

N is unleased to remove this record from the job site until all final Inspersions have been made.

After Permit leavance, you may schedule inspections online or by selephone at (775) 33#-2998 on our automated line 24 hours per day. Please provide a mobile placed number. You will receive a modification by text from your inspector the day of your inspection between 7:00 a.m. and 7:36 a.m., indicating the estimated time of errival. If a text was not possible, the inspector will arrive at the job sile between 7:30 a.m. and 3:00 p.m.

Fire Department Inspections:

Fire Department inspections should be called in for the "Next Business Day" regardless of the date required. A Fire inspector wall call the next business day, using the telephone number provided either online or the on automated reliaphone line, and schedule the actual date and time of the wapection.

Please refer to the Fire Department comments posted on the back of the front page of the approved plant for additional information pand requirements.

NOTICE:

This Form shall be a permanent part of approved plans attached hereto. Approved plans must be on the job elle at all times and the inspection card posted for inspection purposes Plans are approved in accordance the IBC except that noted structural detects shall be provided before construction is withhed in noted areas. The Reno Building Division shall receive a copy of all realing and field reports. Any changes in the approved drawings shall be submitted in writing for approval. Provide or repair as required, salevalles, curbs and guiters in accordance with RMC. Excavation, fill, comparation and dirainage shall comply with the IBC 90% minimum compaction under all concrete stabs.

Corrections and modifications as noted on plant and provisions of building codes and codinances as adopted by the Caty of Reno whether specified on plans or not, shall be complied with

PERMIT EXPIRATION:

in accordance with the IBC, this permit shall expire work is not commenced within 180 days from the issue date or if work is auspended or abandoned at any time after the work is commenced for a period of 180 days.

On-line inspection scheduling powervaltable on the City. of Reno's website www.reno.gov > Online Services menu > Virtual Permit Place/Citizen Access. Contractors may create an account and schedum inspections or check plan status.

(aite address. http://onenv.as)

BUILDING PERMIT APPLICATION

City of Reno



Speedy Commercial & Resigential

17-03/74 Permit #:

ŘĚKÔ	Community Development C 1 E., First Street ~ P O Bo: Reno, NV 89505 (775) 334-2063	1900, 1 9 Z	Recidity DPP.
This application applications ca	B IS 10 be used for minor electric	Commercial in OR Resider 8t, mechanical and plumbing, and r ted application to (775) 334-2043 o	polino permite colo esiconeco e vo
Parcel Num Description	ben (MA-2013) [7] of Work:	Address: 1512 Steelin	sod Linus 14 mosts
Direct	change out of	Pinatural gas	When hearen
Owner infor	mation: Business Name.	Housing Asstrantal	Culai of Reno
Owner Name Address: <u>I</u> <	P'	eno. NJ 8 3512	Phone No. <u>강려역- 장대장</u> 스
Contractor in		KIIK 120 BH 21 W	
Contractor:	r karis flumbing 14	<u>eathriath Ath</u> Coglad N a m	e tea.
Address: 😘 🕧	ZKresak Ln 🤻 🤻	00 MRS 10/00 894131	
Phone No 3 Nevada Licen	39 No. (6 CARL		<u> </u>
Email address	<u>Service@michaels</u>	Aurilang net	
Project Infor	mation:		
Contract Amp	unt \$ <u>600 • 60</u>	(valuation per IBC 108	31 11 42
HVAC Install; BTU:		Electrical & Plumbing	ReRoal 5 8
o Charge oul	or Gas	o Elec Service Change	a Tearoff 111 🥰
o New	o Cłestric	c Water Line Replacement	o Composition பத்
e Electric unit to	gas o Gas to Electric	o Sewer line Replacement	o Recover - MAX 2 0C
c Oi to Gas	o Electric to Gas	(Private Property only) a Gas line Add/Replace feet	o Add sheathing
o Furnace only	o Relocate	a Lawn Sprinklers (Raside)	ntial) o indicale (ther
o A/C add H/P (10ns)			Other a Window Replacement
I understand (h that I have the	at this application does not g authority and authorization o	puereptée pergni resuance nor a of the property owner to obtain d	Bow work to commence, I cently us permit
I pa tol	MMK5	LAULINV)	$at \Rightarrow tda$
Print Applicate News	; 1144	Scherne Schrede	
	***\$nee	dy Permit AUTHORIZATION "	
gVes, please us	e credii card payment authoriza	tion on file FAX Permit # 6	так Регия о
the Cay of Reno	ial Tus perm il application is so c I a ssume hill resconsibility to:	turate and does not violete applica compliance with the adopted Bulk	ble ordinances, rules or requistons or
applicable City o	Reno Ordinances I agree to e	buye by Ali conditions printed on I'l	e Permit and understand that my

signature below is being accepted by the City of Rangin lieg of my signature on the permit

Rev July 2014



City of Reno Community Development Permit Receipt

Receipt #: 17REC-03393

Date: 11/03/2016

Line Items:

Case No	invoice No	Description	Revenue Account No	Amount Paid
1612 STEELM BLD17-03174	100 D LN 1 10 5800	Wajer Haafer - RES - Flat Fee	40040 0000 5363 0000	39.65
			Line from Total:	539.66

Payments:

Date	Method	Payer	Check Number	Confern No	Amount Pald
11/03/2016	Credit Card	MICHAELS PLUMBING & DRAM SERVICE		0776 8 G	39.65
		INCOME STREET		Payment Total:	\$39,48

THE PERMET MALE

RENO, NY 8950E

11/03/2016

12,7525

CHECK CURD

VISA SALE

Card #	XXXXXXXXXXXXXXXXX
\$6 \$	14
Batch 6:	407
BYOICE	H
Approval Code:	077 68 G
Ortry Method:	Manual
Node:	Online
Tax Amount	\$9.10
Ans Code:	YYY

SALE AMOUNT

\$39.65

CUSTOMEN COPY





Total Fees Day: \$39.65

Permit Number: BLD15-01517

Total VMTs:

Address: 1544 STEELWOOD LN UNIT 4

Job Type: Building/Residential/Plumbing/NA.

Parcel No: 004-292-17

Valuation: \$881.00

Zonetg: MF-30

Occupancy:

Type:

Ground

Dwelling Units: 0

Fire Sprinkders:

Height

Fire Alama:

Area(Sq.Ft.):

Stories:

Subdivision: CLEAR ACRE CONDOMINIUMS

Lot

Description of Work to Be Done

WATER HEATER .

REPLACE 40 GALLON NATURAL GGAS WATER HEATER.

WITH CODE UPGRADES.

Owner Information:

HOUSING AUTHORITY CITY OF RENO

1525 E 9TH ST RENO, NV 89512

Tenant information:

Builder / General Contractor:

MICHAELS PLUMBING & DRAIN SERVICE

670 KRESGE LN SPARKS, NV 89431

775-385-1811 NV Lic.: 0060226

The wholestigned helicity agrees to delevel, indivindly and hold harmless the City of Rano, its officers, employees and agents from and agence oil demands, chaires or imbalant than are asserted against the City of Rumo answing from the undersigned's construction activities performed pursuant to the issuance of this permit (including but not himsed to the undersigned a failure to perform in accordance will the approved permit and plants, save and except such dividends, claims or Babbley that arise from the Cely of Reno's sole necligence or willed enjaconduct

The underlighed agrees to obtain/mention commercial legisley insurance covering it during the serm of the construction authorized by this permit in an amount no less that the total construction cost of the work to be performed, and exempts that such liability policy shall include completed operations coverage as refl at an additional material endomement persons the DAy of Reno as an sociaonal releated with releject to operations performed by or for the undersigned or which the City of Reno has assued a building permit, without exclusion for odby items of people's demage which the completed operations of healerd.

PAID

SEP 02 2014

CITY OF RENO PERMIT PLACE

Date Builder/General Confractor or the Authorized Agent

Building Permit

Permission is hereby granted to execute the work described in this application in accordance with the Rules, Regulations, and Ontinances

of the City of Reno.

Building and Safety Dwis@ATY OF RENO

BUILDING DIV

1544 STEELWOOD LN UNIT 4 LOT:

Inspection Record

Inspector Signatule

Dage

Plumbing Inspections
8528 Manorman

Final Inspections 8573 Flumbing Final PERMIT NUMBER: BLD15-01517

POST THIS PERMIT IN A CONSPICUOUS PLACE

Permit Inspection Record
City of Reno Building Permit

GENERAL NOTES:

(i. is unlawful to remove this record from the job swe unto all final impactions have been made

For inspections, please call the Building Div. automated phone line at (775) 334-2396 at any time. 24 hours a day. Contractors may also schedule inspections on-line at anytime once a registered account its established at the Virtual Permit Place at hits //applications emportees com/accolar. Maspections may be set until 5.00 am of the day the inspection is to be performed. On the day of the inspection, you may call the Building Inspection directly or through an operator at (775) 334-2060 from 7.30 a.m. to 5.00 a.m. to request an inspection whe.

Fire Department Inspections:

Affer the Fire Department inspections are scheduled, the Fire Inspector will telephone the contact number provided on the automated inspection dispatch within 48 hours to schedule in inspection time.

Please refer to the Fire Department comments posted on the back front page of the approved plans for additional information and requirements

NOTICE

This Form shall be a permanent part of approved plans attached hereso. Approved plans must be on the job site at all times and the imprection card posted for inspection purposes. Plans are opproved in accordance the IBC except that noted shuckural details shall be provided before construction is witisted in noted areas. The Reno Building Division shall receive a copy of all feeting and field reports. Any changes in the approved drawings shall be submitted in wrang for approval. Provide or repair as required, ordinately in wrang for approval. Provide or repair as required, ordinately, curbs and guillars in accordance with RMC. Excevation. St., compaction, and drainage shall comply with the IBC 90% minimum compaction under all concrete states.

Corrections and modifications as noted on plans and provisions of building codes and ordinances as adopted by the City of Reno whether specified on plans or not, shall be complied with.

PERMIT EXPIRATION:

in accordance with the IBC, this permit shall expire if work is not commenced within 190 days from the lesue thate or if work is adepended or abandoned at any time after the work is commenced for a period of 160 days.

On-line inspection acheduling now available on the City of Reno's website www.mno.gov > Online Services Menu > Community Development Permits > Virtual Permit Place. Contractors may create an account and schedule inspections or check plan status.

BUILDING PERMIT APPLICATION

City of Reno Community Development Department 1 E. First Street - P.O. Box 1900, Reno, NV 89505 (775) 334-2063



Speedy Commercial & Residential

Permit BUD 15-015

Rec'd By:

Speedy: Commerciat o OR Residential of This application is to be used for minor electrical, mechanical and plumbing, and roofing permits only, INCOMPLETE applications cannot be processed. Fax completed application to (775) 334-2043 or email to permits the permits form.

		application to (7.75) 334-2043 or email to peri	militario,gov	
Parcel Muraber: 004-393-17 Address: 1544 Stephano #4				
Description of Work:				
Replace Anons	A marchala male		518	
gir abor Atical	com Motorial	gos mosa Horser (proving)	
	~ ~~~~~~		Povided /	
Owner Information: B	usiness Name: 🏋	ana Housiaa Au	theritin	
Owner Name: System	<u>ره</u>	Phone No:	20X1-21-120	
Address: 15.25 F		et Kuno ny 8951	<u> </u>	
C			N 135-36 5	
Contractor Information:			-4. —1	
Contractor: The Charles	<u> </u>		<u> 4•</u> .	
Address: 1.76 K/3 Phone No.: 256-1		~ ~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~		
Nevada License No∴ 1	AN	Fax No.: 25<_	<u> </u>	
Email address:	oc x-scali ti	City License No.:		
CINES BUSINESS . 1 11	·			
Project Information:			• —	
· · · · · · · · · · · · · · · · · · ·	·			
Contract Amount \$ 8	101.18	Australian new IDO 400 M		
HVAC Installations		(valuation per IBC 108.3)		
	Water Heater	Electrical & Plumbing	ReRoof	
BTU's	<u>40 gallons</u>			
g Change out	Louges	Proposition also		
Committee Calif	₩Gae	o Eleo Service Change # of Amps	o Tear off	
o New	o Electric	o Water Line Replacement	о Сотровійол	
p Electric unit to gas	a Ges to Electric	a Sever the Replacement	o Recover - MAX 2	
-		(Private Property only)	lavers	
o Oi to Gas	n Electric to Gas	,	o Add sheething	
-5				
o Europece confy	n Reloçate	o Gas line Add/Replace	o indicate other:	
o A/C add H/P	•	o Lawn Sprinklers (Residential)		
(tons)		o rami olumnas (cosmolita)		
I understand that this app	dication does not gua	raniee permit italiance nor allow work to	Convinence, I certify	
that I have the authority and authorization of the property owner to obtain this permit.				
_ , ^		1 . 1	~	
Trucky Horbert	15 ates	Att all all a start	વ્યક્તિન	
Print Applicant Harns:	- Ap	plicant Chicheure	Delu.	
	trent Connection	O		
oYes, please use credi(card		Permit AUTHORIZATION **** For the FAX Permit of Email Permit	_	
I hereby certify that that part	nit sonication is accura	the and does not violate applicable ordinance		
the City of Reno. Fassume:	full responsibility for co-	mpliance with the adopted Building Codes (I	I.B.C.) and all other	
applicable City of Reno Ordi	mances. I agree to ebid	le by all conditions printed on the Permit and	I understand that my	
signature below is being acc	septed by the City of Re	uno in lieu of my signature on the permit.		
	C stal	1 0 1 1.10	Alabel	
TANCO PARTITION	THE LATER	CAN TO MORE OF THE SAME	1 0 1 1 1	
· // · — —	Administration.	0	Raw June 2012	



Total Page (San: 2012) 61 🛍

Permit Number: 8) D14-81621

Court White

ADDRESS TO THE THE PART OF THE PART OF

Job Topo, Burana/Render/WPI-moinsvik.

Parcel 44: 004:282-17

W-Aveten: \$ 771.00

Lerung: NF-3C

Оссидением: O-coc

Type Ower land Liable: O

Ни Зотине:

HAMMANA.

Fin Anna

Artesta FUI:

Loh

SABARAMA CLEAR ACRE COMPONENTIAS

Department of West to the Dame MATTER HEATTER GAS TO GAS 40 GAL WATER HEATER WITH CODE UP-GALADES

Owner Information:

HOUSEAG AUTHORNTY CITY OF REMO

1635 F RTH ST RENO INVIRMO

fation interestor:

Bullio I Gearmh Centractor.

MCMAILS PLINNING LORUM SERVICE

620 RESGE 166 SMARKS HV 60434 775-365-KH1

664 LBc.: 00000266

The professional nature agreem to deliver endowedy and make harmoging type of Parks. In delivers, well-field and agents from non agents as demands on an endowed agents for the of Parks asking now may be included an endowed by the control of the c Printed by an inches to be entropered taken to particular the state of the property from any provide two and recent man the states of thinky fall title two the Ch of Ferry was accurate as

The contraction against to terrestration continued byogh employed part is but providing a contract to the property of the contraction of the contr NAME OF THE TAX DE TAX OF HOMES THE PER PER LIFE OF THE PROPERTY. the the that them, both the mean compared (op-files) compare to d -- At HOSEAU FALST STEPANE, 1940, PA CAP of Fram -- gr rector beared was assessed to operations perfection by as an pre-supplying PRINT TO SEE OF PART THE COURT & BROWN, COMM. LEGAL AND ADDRESS AND higher a process where affect the process governor a record

eral Commission (n<u>. B</u>of feet collect Agent

Belished Panels

Provinces was stylightful to a recent the west clean that in the Company position of the flow, Espenier and Command

THE PERSON OF TH

PAID SEP 1 0 20:3 PERMIT PLACE

1504 BYERLWOOD LINUME PER LOT:

Inspection Record

Projector Systems

Photological parties . منزات بههما اي per hand has

POTENT MUSICLE DEGLEMENT

POST THIS PERMIT IN A COMMPICUOUS PLACE

Pamis trucedon Record Christ Reso Balding Porme

OBSTRAL HORES:

the colorest to review this record from the jub with until all the Personal area case much

For inspections, plumpe sail the faulting Day againsing phone use s (77% 30-2300 of any bern, Tallegury a day. Compactors may and whether medication andre at anythe parts a represent ecount & establishment as the ribbert from a Place of expolatopica constitution conventional measurement casy be see with 500 and at the Oby the majorithm is to be performed. On the the of the processes yet may can be Surces respective mades of Brough as opinion in (775) 304-2000 Port 7-38-bar. In 6 DC arms C lebels I produce the Mile.

or Decomposed Pagestone

When the Day Department respections are actualized, the Funame of inches to make make product on the adorsom lagadke dajaka relim 41 haja sa adam weeker land

Place with a Mic the Department varieties projet on the bad teri page of the appropriate them to principal minimisco part symmetric.

MOTICE:

This form that he is improved part of approved more asserted have. Appeared plans mad be no the jab was at at larger and the hazacean case second for inspection purposes. Para an apperated in accommon the INC energy May make another action the prompt today correspond to remain in round make The fact Julian Children court receive a page of an exercic and feet names. Any charges on the approved descript and be errebel in writing the expression. From an appear in magazine, Charles, carbo and gallett is accordance with Rick. Economics BL companies and drawage and comply year on DC 30% THE RESERVE AND ADDRESS OF THE PARTY AND ADDRESS OF THE PARTY.

Committees and ringfiltations as voted on place and accurate a talking codes, and prefrences as adequal by the Chy of Read raffer specification when or not shall be completed with

HORATEUR THERES

a appropriate with the 190, this passed what exists if with its and commissional military 100 days desire the langual bes at it work is enspecially or abordance at any usual diar dan werk is communication a proved all (it) days.

Or the inspection researches new Massach calling City of Paracia variation was according to Colonia Services, Prince Community Development Products in Virtual Permit Place. Collisions may coming an account and BOTH BUT Intel® Commence of the states.

	Ε.	10.13	1.71PM	W. ef val'e	Planking/Ope	B	B CIC
76.8	•	2015	1:3//[Milest 5	7 8 4 88 · 82 / UP 4	Mag I	paps,

_	-	_
4		
٠		

BUILDING PRIMIT APPLICATION

City of Reso Community Development Department 450 Shelair Street - P.O. Bon 1900. Rume, NV 30505

BZ parmit Parmit A	
B	

G75) \$54-2063 FAX (778) 334-2040 Сотятенноміції 🗓

lo 6163 | 1 | 1

This spelluration is to be used for minor electrical, mechanical and prantiting (military plane), and molting-portrate only. InsCORPLETE applications cannot be precessed. Completed applications may be fused to (775) 304-2043 or employ to DATE OF THE PARTY OF THE PARTY

<u>Gegoription of Work</u>			
para nano n	chiatement in a	ene upgrada.	
Dermar Enformacións James (AZYLO ELENS) A.	a Andronisty	Photo No: 연호수	-3430
Valdresex: <u>1785</u> 55	NOWING REN	D NOV 89512	
Contractor Informação Contractor: (N1) Chale (S Vadresa: (N10) PO⊋ão	nt 1 Allumbring Heating 18 Janes - Sancks	4 And Common Name: # TRUC	<u> अभवर</u> ु
Чине М ак <u>, 3636 - У</u>	0/1	Par No 3/45 - 10	-34 <u> </u>
upvada License Ho.:	60 206	City License No.	
mel estres :	 - ·		
roject beformation:	:		
· · · · · · · · · · · · · · · · · · ·	<i>171.3</i> 5	(relaying per ISC 160.2)	
	Water Header	Exercises & Phonoling	Ruttool
(VAC Installations		SALVANIA A LAMBANA	
•	40 mm		
BĪVs	4D gastons	a files Service Change	n. Tape OH
BTUN Charge out	<u>40</u> gadom)c6an	a Bloc Service Charge	1
BTUN Change out)cii e	a files Service Change	o Tapa oH o Composition
ETUS Charge our)ciida o Nacino	o files Service Charge F of Amps c Weier Line Regimenterial g Space in p Applacement	e Composition
FAC Installations ETUs ENergy our Here Electric wall begats)cii e	a files Service Charge of Ampe o Weier Line Replicoetets	a Composition
BTUN Charge out Here Blectric wall to gas)cGen o Necho o Gento Necho	o files Service Charge F of Amps c Weier Line Regimenterial g Space in p Applacement	e Composition
BTUN Change out Here Bleethic wall to gate)ciida o Nacino	o filet Service Charge # of Amps # Weier Lies Replacement # Spare in a Aspiscement [Presse Replacement	o Composition o Recover - MAX : layere allowed
ETUN Change our) (See o Blacks o See to Blacks o See to Blacks	o files Service Charge # of Amps g Weier Lies Replacement g Spare Ing Replacement (Presse Peoplety 019) to Gos Ing Astriceptors	o Composition o Recover - MAX : layere allowed
BTUN Change our Here Blectric wall to gate Directors)cGen o Necho o Gento Necho	o filed Service Charge of Of Amps o Weler Lise Replacement o Speer in Aspiscement (Provide Repeaty only) or God into Astaritophace liter	is Composition o Recover – MAX : Expere allowed is And sheeking

DO THE

TRICIA	STAATS



City of Rano Building Permit

Total Food Bas: \$61 Di-

Permit Number: BLD14-01822

Andreas, 1900 STEELINGOOD IN LIGHT of

Temb William

TENTO I CEST

PENO MYRIGIZ

Јан Туре Дейбарбіца працебеленадтік,

Part of Ma: 000-298-17

Volumber, 1 001/00

Printer: NF -50

OCCUPACE:

Trace.

Describe Units: 0

Fire Controllers

مخما وار

Fire Alberta

WHATER FL)

استاست

CANADASIA : CLEAR ACRE DOMOCHIMA NA

Lot

Total last mades

Comer printers and

Description of Work to By Cone

WATER PEATER.

SAS TO GAS 40 GAL WATER HEATER WITH CODE

UPGRACES

Builder J General Contraction

HECHARI A FRURIENCO A DESANGACIÓNICA.

HOUSENS AUTHOR TO CITY OF REHID-

AND ARRESTME LIN SPARKS, MY \$6431

775-255-1811 MV Ltc.: 0004716

कुर्ज केल्क कुरू र सक्ते संस्थान के या प्राप्त कराय of Core. It effort, resistant and spars has not square at entering. ---perspects observative eductor authored paramer to the bearing of the ten personnel had be before it the production of the tenth to perform to the state and the survived served and others some and manage more taken, comm or assess, the state had be the property with designation or

The addresses of the contraction and the property of the party of the y err met boday erro, ann revous ampetes quantum mettigs to to an existence between contentions coming the City of Auro of the regioner 🗝 region of acceptant participal as a los site acceptant. with the Chr. of Pear has brief a suffing power amount authors for the card is \$10000 statute with the challed complete to beyond

WHI CONTROL OF THE APPROXIMAT ASSAULT

Statistical Payment

ind to doubt. In your processed in the ordin accordance emitada Rados, Regulanças, ana Organisas

ALL INSPECTIONS MUST BE COMPLETED

PAID SEP : 0 2013

CITY OF HENCE PERMIT PLACE

1900 STEELWOOD LM WHIT JZ LOT:

Impection Record

MARKON SAMELING

^-

Printering the purpose. 1994 mail Mannet US 86/3 Perside: Fear

PERSON MANAGER: (LINEARIES)

A M. TRESP CAST TROOP CONSPICUOUS PLACE

Person wasersten Record Cats of Paint Bullion Farms

OCCUPAL NOTES:

t a unimet is necess the mass time to got our was at that MARKETON STATE PARK PROPER

for inspections, please our was thanking that parameters proces who er (TTS 104-2046 as any time debters in the Comments may and streets represent course is approximate a registered or an expension of the Artist Forms France or FOR . . MP/MANAGE CRYSTOCOMESTOCK Medicine may be ad rid 500 are all try any top regulation is in the performing. On the this of the remedien you may call the Building beneater dentity on through an apparator on (77% 114-)060 kpcs 7-16 pro- to tribburs - Warrall an Irapychies Itra.

Pro Construent in questions After than Park Copperation, association, and secondary, the Pirch reservir -0 hispitane like comment mercen provided an the commend agreement allowers within allowers in comments as क्रमान्त्र के स

Perior into la tra fen Organisaria comunità postes de Via esco. tion page of the against plant for appearable becoming and

The Policy of the a processing seem of approved place electric baraka inggeriwaa peragi mangi aa aa maa job uma ar aa peragi aan ma NAMES AND POST OF THE PROPERTY OF THE PARTY MOTERNO IN MOCKETAGE MA MIC MICHIEF UNIX ANGLE ANALYSIS CALANA Add to provided before constitution is intented in solid series. Тти Язин башинд Силуар ушар насране и сору об да науваа вич had reports. Any changes in the expressed aboverage about beможения из между их дварија. Втрафа их прози, до прадица, Witwells, cutin and gallers in exemptions with MAC Researchers opposition and district their comply with the MG 90% mary compaction water at concrete date

Compilers and medicenses so need so plans and providers of widing ecopy and prominent as account by the Cay of Agend folion appoind an place or risk shall be prograind with

PERMIT COPPRANCE

n percendance with the ESC, this permit would explin aark in aan camaqagad addin 180 dug bara da baay diffs on all most to supposed on Management of your to after the work in commerced for manned of 100 days.

On the state of the SC bed billion SC Western on the Ger of Stance wagers were read and a Calife Services Many o Companyably Determinational Processing of Virtual Permit Place Confractors may country an account and national designations of check along thing.

4.	4	2013	1 1/64	Moderal	ş	Floorbong/One	Hope	BY#C
----	---	------	--------	---------	---	---------------	------	------



BUILDING PERMIT APPLICATION

City of Reso Community Development Department 450 Smelai Street - P.O. Ben 1900, Reno, 4V 88506

Permit #

(775) 224-2063 FAX (176) 334-2043 Commercial [

This application is to selected for misor electrical, mechanical and plantising featured planting, and meaning permits only. BECOMPLETE applications desired by processed. Complished explications may be travel to (715) 314-3041 or synthe-

mjater tabater <u>poeculation</u> o <u>t mour</u>	replacement with	th code upgrades.	<u></u>
Namer leformanium: leme: <u>MCRO HOL</u> Barres: 12:45 6	king Acthoraty E. Winter ST K	Prome No: 329	-3130
enementor (nicomordo capación (MICA) (davet: (ICA) (1774) hone He: (S) (S) evada License He: (mai address:	ls élumbing Head tge Lane . Sa La U	Hong Consect Name: TV (6) Fig. No.: 355 City Ucense Ho.:	
rojest intermation:			
	CMI DE		
	904,85	(ужиро д рег вВС 100.3)	
	Windor Phrates	Electrical & Fluetbing	Refront
VAG kustalis Perse BTU's		Electrical & Fluenthing p Say, Sayrier Classes	Reflect o Tourest
PAG Installerione STUTE Charge pul	Windor Pleaters <u>40</u> paleons jacthor	Electrical & Flumbing	
pagenci Amoyadi S	Water Heater 40 palant	Electrical & Fluenbing p Say, Sayrica Classips 2 of Amps	o Tsaroff
VAG Installations STUR Change sul	Windor Heaters 40 palant active a Dischic	Electrical & Flumbing p Say, Service Change \$ of Amps p Weler Line Replacement p Source line Periocoment	o Toeroff o Composico o Recover - MAX

annote.



City of Reno Building Permit

Tabal Face Day 561 DT

Permit Number: BLD14-00633

HOUSING AUTHORITY CITY OF PEING

Table I VILITE

1975 B SEN ST

figure), why dath of

Address: 1520 STEELWOOD IN

Job Type BuildingResonatish Markington

Percel Inc. 604-282-47

VM-00-04-17:00

Taning MF-20 Trans

0140≠1*cy:

Period Cati: U

Georgia (

WAAT:

Para Spalmateur; Para Anglero

Janual Ing State

twelve:

Sund-leke: CLEAR ACRE CONDOMINUES

Let

Types brings and

Owner laboratelyes:

Subter / General Consistent. NECHARLS PLANSING & DRAIN SERVICE

P 0-00% A168 \$PARIS, MY \$6672 276-088-161 s

MV UA:: 0000022A

Sourception of Main to do Sont WATER HEATER .

REPLACE EXISTING WITH METWOR ON CAS MAILIN

HEATER

For contraling receivery agency to credital conjunctive and may receive judge.

Lay or From the deficient engagement and appears to properly of general to come or some or some or some and appears the Cay or reach sensing from the property of the property of the contract accordance parameter purposes of the engagement of the enterty parameter property of the enterty of the enterty parameter of

The probability depicts in Observations consumers coming assumed company of desiral first bear. In the expensions explosively by the property on a depicts are the SER to high probability upply of the explosive to be probable as the company of the explosive and the expensions of the explosive of the explosive constitution of the expension of the explosive operation of the explosive constitution of the explosive operation of the explosive of the explosive of the explosive constitution of the explosive operation of the explosive of the explo

B. Adar Carraca Contractor or the Agriculary Agency

لحداث وطنخت

Paradona mitanity grand to require the year describes in the implication or accordance with the Paties Regulations and Carlinances of the Anthropius.

Garage State of State of

وسطون فدارها

7/3/17

Salvey or at Parish Diggs.

ALL INSPECTIONS MUST BE COMPLETED

JUL 3 0 1013 CHY OF PLACE PERMIT PLACE

1629 STEELWOOD LINLOT:

Imperior Coost

Ingeres Signature

Physiology State Inspections

State Inspections

State Inspections

State Inspections

PORNIT MUNICIPAL CLUB 14-44633

POST THIS PERMIT IN A CONSPICUOUS PLACE

Permi Impedion Record On al Rene Building Permi

CONTACTOR

in a substanti de reputato della seconda fina disc (chi stati utti all' finali reggiorizza, result seggi mango

For empartment, picture call the designing the appropriate passes have or (270) UPS-2000-16 by lefts 20 februs 4 day. Combattois from any common in improcious common pl. Anymon many 2 requested 5000000 th estatement in this visitual former based of try programment or this day the improcious to be the preferred to the call of the improcious, you may ago you destately improve growing to the ory of the improcious, you may ago you destately improve growing to through our operation of UTS 304-2000 form 7.30 may be \$100 may a sequent subsequenced print.

Production and and desired

Contra

Mar in Fire Copenium expension are administrate the Fire impacts and plagmane may compel number provided on the properties immediate changes, while element to collabor an impaction date.

Property prior to the Fire Department company to people on the best from early of the market plant for ambitional frictionary and results below

* WOTCE.

The first case he is germaning pair of appearing page, another, the first often depressed paths hard to an interfer sets of all more and the expectation many posters for an appearing payment. April 200 percent of the expectation of the expec

Comparisons and magnifestorie as rests an olsee and president of building codes and entirences as adopted by the City of Pence energy specifies an paper many sharing comparisons.

PERMIT EXPERIMENTAL HOR:

he recordinate with the INO, this permit shall easies if work is not commenced when the days into the bessel date so it work is companied as alteratived at any large often the north is democrated for a permit of 420 days.

Que time temperation automitating more reception op the Copof the telephone temperature > On the Develope Eleman > Copperaturity Operature receipts > Network Personal Proof. Contract life why viscolar as non-receipts achieving temperature or chapt plan peaces.

1815 stod dot



BUILDING PERMIT APPLICATION

City of Reno Community Denetoporani Department 460 Sinctor Steph -- P.O. &ox 1800, Rano, NV 89505

<u>EZpennjalt</u> Pennali#	
Rec3t By	

(775) 334-2063 FAX (775) 334-2043 Сопиратија 🖸

Rosiden EM

This application is to be used for winor electrical mechanical sins planning (without plann), and croking pourses only. INCOMPLETE applications cannot be processed. Completed applications may be taxable (175) 334-2043 or ensured by pourseparts.

póunifo <u>tó</u> -enú-gov				
Percel Number: 🕥	- 393-17 Address	E1500 SAPELLINON	010	
Description of Work	: .	Reno nv 8951A		
161240114	an naugo	water Heater		
Address: <u>\^_</u> Contractor Informatio Contractor (\)\(\)\(\)\(\)	<u>E CH++ SHYAQ+, R</u> His Halin Distance in An	Contact Name: ML D		
Phone No . <u>05</u> 5-1 Nevada Linense No.: Email address . <u>N/A-</u> Project Information:		Fav No.: ASS.—1	- Plás	
Contract Amount \$	·	veluation per (BC 108.3)		
MVAC Installations	WaterHeater	Electrical & Physiolog	ReRoof	
BFL/s c Change out	40 pellons 10,500 Peptanamant	g Eins Service Change Fol Amps p Water Use Repincoment	o Tesa off o Composition	
a Blechic unit to gain	a Gas to Dactors	g Seams time Replacement (Provide Property only)	s Recover – MAX 2 layers a lower	
∉CN to Gan	o Clean to Gas	g Gas time Add Replace	o Add steathing	
a. Furnació enty	o Relocate	a Lawn Symmetric (Residential)	o inorcess other	
aAC (1014)			l	
I understand that this a	pplication does not guarante	e permit ippugnice nor allow work t	o commence, I certify	

that I have the authority and authorization of the property owner and above listed conflictor to obtain the



City of Rena Building Permit

fold from Don. 3014 . 5

Permit Number: BLD 72-04238

sana s formyskie.

ACCUMENT 1000 STEELWGODUN AND FIL

#obType: Eviding Readon ranks madel & Address NA

Parkentin 004-252-17

Yakuliya \$6,000 00

Zonna WF-A

Occusency

Free Designations, b Orono

Himphi.

fine Street art.

----pii. AMMSQTEK filip algent; 510-85.

Brandshipper Pragil (9

14

Certai Milandadon

HOLSENG AUTHORN I CITY OF HEHO

525 (984.5T., PENO No.8961)

Freedom (1997) and the first

Description of Work or the Done HereCollin.

UPARAGE VITÉMEN TO AGA ACCESSIBLE STANDARAS

ELECTRICAL, PLUMBING, MECH.

Publicar I General Concructor.

ЗЕЕРА (1906) ОБОБЬТ (230 € СРЕС 48 58440-5 NV 3043) 179-356-6800

MM Ltd., CORSTS9

The mathematics from the brown to deleted authorizing and saled constraint to the constraint of the co

The undertyped opens to utake blockers committee battery is undertoomly a control of their point of the control of undertoomly the control of the control of the control of their points and the control of their points and their points are their points and their points are their points are control of their points are their points are their points are their points are their points and their points are their points and their points are their points and their points are their points are their points and their points are their points

Subcordsclore.

(2004) (2004) 1280 (2004) (2004) 1280 (2004) 1286) (2004)

190 640 100 2790

COMPUSITE SUBCIPACION WAS DOUBLES & BOVE RENT, AN 69521 (726, 771-907)

HV CA : OBSIGNA

See Hard Samuel Con 192 14-15-12

Bartoran Gasessa Core Associate No. Austropried Agents

Permanental Telephone Sept Telephone the was represented to the permanent and continuents.

THE READ

a me sub al Fero

reach and Selections

ALL INSPECTIONS MUST BE COMPLETED

1904 21EEUW	UUU IPTUNII XTI	.01:
Inépe	cilion Record	
w.241	, 	Ç.ee
Fire in all trappy records With Declar Front		
Carriery reservoirs 500 Protecting Tag Sa		
CONTRACTOR OF THE PROPERTY OF		
ESSENCE FAR		
h XI Heaton and hardway and		

PERMIT HUMBAR: BAD12-14234

POSITINS PERMIT IN A CONSPICUOUS PLACE

Petra Impetion Record City of Record Database Process

COMPANIES HOTES

It to commend to compact the vegoes begin the job can can't be toned expected one have been above

Contrappenent persons on the Parking Decreases in account of 20 (27) (264-2006) in the same Salingues 5 days Conference was 20 (27) (264-2006) in account of grantees which is operated occasion in experienced on the Salind Review Shape as Bay Congress (Advisor) (Convertige) in agent from the big operaciant Salinda, or the salinda, or the salinday of the separation of the case Salinday or the salinday of the separation of the Convertige of the Salinday of the separation of the separation of the salinday of the Salinday of the Salinday Planck of Salinday Salinday of the Salinday of the Salinday of the Salinday Salinday of the Salinday of the Salinday of the Salinday Salinday of the Salinday of the Salinday of the Salinday Salinday of the Salinday of the Salinday Sa

^Сге Оволога ент ицреноват.

Other and Park Engineers instructions are named and that happens are recognized that couldn't promote promote as the manufactured properties and promote and promo

Piperg rate to the Comp Companion processor payons on the gapti none page on the against gapting to advanced anomalies and materials

HOTICO

Then Payer hand he is consequent pair to appearus purp asserted thereto Appearus prime mous les on the pair for 11 M lens; and the appearus purposes. Plans asserted in accordance to accordance purposes. Plans asserted in accordance to a SC accept managed to accordance to a SC accept managed to accept delicated delicated in accordance to accordance to accordance to accept delicated delicated to accept accept as accordance to accept t

Constitues and modification of ware on post and constitues of Deliving Colle 443 reflected de sépoles de 190 (47 of Évico Profile 400 àris de partir par republic compléte vals

PERMITE APPRAISE

of Accessions with the BC, the permit shall explice at which of not compensate within 180 days from the reserdate of 2 more is supporting to physicistic at any time 30% this work to compensate for a period of 180 days.

Ori-I'ms Impection acheckeing from EndPather on the Cely of Prace's equation area agong prace - Dealing Spensors Wenner - Community Deviception Fernance - Windows Permit Place - Co-Institute may trette an automatical secreticis impections or check plantistation.

BUILDING PERMIT APPLICATION

RESIDERATION

Case No.:

Cary of Reno.:
Community Development Department
450 Sinctor Silect – P.O. Box 1900, Reno. NV 89405

Rec'd By:_____

450 Sincler Silest - P.O. Box 1900, Reno. NV 89905 (775) 334-2063 - 444w. reno.gov Fax (775) 334-2043

)12-04238

	$\underline{\hspace{1cm}}$
Parcel Number: Ad-	wess: 1504 1 Steel wood
Osecripiton of Work:	<u> </u>
Remodel · vydate kite	DENS ADA
Electroick	
Plumbing	
אים ופחניון	
Owner (glormation: Owner/Bu	ider Permi? Yes <u>X</u> No
Name:	Phone No:
Address:	
Contractor Information:	
Steam Problymouth	of how
General Contractor: Elector Section Address	<u> Deuts amount (ac</u> Contact Marrie) <u>F677 After a Lave (ac</u>
Address 1216 Edges 1st Springer No	V #9H,81
Phone No.: 354-4860	Fax No.: 352-465 3
Nevada Lisense No.: 64 7.457	City License No.: 110.7.19
Person to contact regarding the permit:	
Name 23(7) Sandhan vi	Phone No.: <u>745-264년</u>
EMBI: All & All attended to the word (A	<u>и Бринот, сом</u> Рад №:: <u>784-4933</u>
Design Professional Information:	.
Architect's Name:	Phone No.:
Engineer's Name	
Email:	Fai No.:
Project Information:	
Valuation: \$ 6 order.	ZorángLol #
No. of Stones:	Project Sq. Footage:
140, 04 000458.	Building Height:
Fire Sprinkler System?" Yes a Noo	Current Living Area Sq. Footage:
Fire Alarm System? Yes u Nou	Proposed Living Area Sq. Foolage:
Septic Tank? Yas a No p	Current Garage Sq. Footage:
Water Wet? Yes o No ⊐	Proposed Garage Sq. Foolage:
Fire Demo Permit No.;	Proposed Living & Garage Sq. Footage:
Shed Sq. Footage:	·
Ti-10 04 / Congoi	•

17-4000 004-342-18 OVER -

Plumbing Comractor <u>Figure</u> #) Hevada License No.: <u>+7219 }</u>	Phone No:931~ 2 7 7
Mechanical Contractor:	Phono No.:
Electrical Contractor: <u>Zome Lib</u> Neveda License No.: <u>679 2 C</u>	Phono No Phono No P52 - 136 }
Building Code in formation:	
Edition of Code:	Building Code used.
Type of Construction: Wood Framing	p = - Steel Framing o Occupancy Use
Occupancy Group: Single Partity Home	a - Townhouse v - Duglisk o
Alfordishle Housing? Yes a h	60
Applicant (primi) <u>(قراب من د</u>	eren (sign) Bell Land Manager

٠.



City of Reno Bullding Permit

Iosa Fees Over \$104.35

Permit Number: BLD12-04239

Televilla

Address 1944 STEELWOOD (#1967 F)

you Type: #ustage?esgerand-emotes a AprillonniA Partial R6 (004 202-17)

Assessment 1.4 KM NO

Zanag (#-30

Occupancy:

Type:

Grand

Daviding Gride, 4

hay Syrmakes

ничем.

Free Alberta.

Grewan Hill

Stories.

Sabdheden Puketty 5

Lab

Owner le/ormanion 40USING AUTHORITY (JTY OF RIEND)

15.35 E-00H-51

FENO NV 89542

Teneri Inkovedion

быйва Уба**га ча** Соничног

freezingwen of whom to the Dree-REMUDEL

DECRMANDE TO FORM IT OF ADALASED STANDARDOS FLECTRICAL PROMOBILE MECH

SIERMA DE VELD**ING** HE 1200 E CPEC: #8 SAMARKS, NOV SQUEST 775-356-6600 HM 844.: 0008750

Subcontactors

Dig of Army 41 claims angligans to dynny tion to dynny if 400041 dame of Fabruary that are accepted against the King at Rains entiring term for CONTRACT CAMBRIDGE WHILE HAVE AN ARREST A THE CONTRACT OF THE the reading to the branch to the exchapter times to proper a electronic part has account overly and electric time and provide to a demands claims a larger, that sees have the Copy of Parcy vices replicated to ## 1410 ##P

The moving age timber above to debug warrant and tole tolerate Me.

District and the second second sections and the second THE PERSON OF AN ARCHITECTURE. BY IN CASE OF GRADE & product Make in this factor day controlled call to the local to be precised to a the same of the same and the party of the same of the same of the same of an an is anything allowed the party and an is the an easons where we repect to excessed continues by or fit we hadroged provided the contract of the contract of the contract of the provided by CONTRACTOR DISCOURT AND ADMINISTRATION OF THE PARTY OF TH

CHEMICAL POINTERING 1271 | GPS46 ST 5P4948, NV 39401 הדקונות פסיי.

NV Lac : CD43 "PT

CONTURTE ELECTRICALC 3424 DOUBLER BUYE REND, My 89521 .TT5-774 B420

end Life 400078096

CITY OF REMO PERMIT PLACE

ALL INSPECTIONS MUST BE COMPLETED

Builtin Kings of Commission on the Arthur and Agent

Continue Present Party and a harmy grant of grant and the state of the sta airte Carol Peno

g and Selay brease

1544 STEELWOOD UN UNIT AS LOT:	PERMIT MUMBER, BUD124(24)
Inépécion Record	POST THIS PERMIT IN A
	CONSPICUOUS PLACE
Maryanera September Calc	Perma Inspection Record
lectric at manage forms Sind Santau at Roma	13 by of Famor Po Adong Started
Serving Reproducts 550 Permany for Dan	ÇAHARAL MOTES
CANTAID-UP) 14 BILL Protection BILL State and France	The additional fit thereby, his appeal beyon the pit 144 and pit long promodican have been under
NVP Reserved P_brain_i abid	For adjustment process can see Dynamic that systematic contents a first Contract a service of 1775 1774-2705-11 are the Contract a first Contract a service of 2775 1774-2705-11 are the Contract a service of 2775 1774-2705-11 are the Contract a service of 2775-11 are the Contract a service of 2775-11 are the Contract a service of 2775-11 are the Contract and 2775

The Rance Stateing College phase species is easy to use spring and high imports. They consigns to use approved 100-ways shad to submittee to whence to paper and provide or import on the operation. According to the Companies and Self-College and the college and

hOWNE The Parts their he a principle (his or granded pant) paying Briefs - 2000047 0846 must be on Peripik this he at head had be

deproved a accordance on BC elega may speed anudaral delega did to (speeded being combined a soletal or equal page

Pipe de

ANDREA CERTAINS OF CHICA DISC COLLEGE

PERMIT EXPERTIGE

In accordingly with the IEC, tally general study expend of their, it not communicat without 100 days from the moundate on it make to distinct the appropriation of pay have also the mouth as communication appropriation (400 days).

On these temporals and extending more framinate on the Edg. of Renny and otherwise series gout a figure 5 country. Memory 6 Commercialy Development Planners 2 stituted framed Planner Committees may comite as arrectly and screening framed and screening series.

BUILDING PERMIT APPLICATION

City of Reno-

Community Development Department 450 Sinctair Street - P.O. Box 1800, Reno, NV 8950 (775) 334-2063 · www rene gov Fex (775) 334-2043

Cose No.:___

<u>ه</u> م	Rec'd Byr	
WIN.	. ~ *	11001
まりんし	12.0	4239
Z 5200	e l Joseph	

Parcel Number:		Ac	idress: /544 # 3	Stee	1 64004
Description of Work:					
Remodel V	p dnl	n per 3	shows 1904		
Electroick					
Plurabing					
7,55-27-7					
Owner Information:		Омпри/В	ulder Permit? Yes	<u> </u>	-
Name:			Phys	ne Mo:	
Address:			, 1100		
Contractor Information	ır				<u></u>
		خ ندر بسیمویاره	-4-		
General Contractor: 5/4	ata Car	etalleshibus	COT STATE COT	lad Nan	19: <i>#377 #60-25-</i>
Address: 1211 EA-	Acr 160		41 PANE		
Phone No.: 354-446	<i>a</i> ′		Fax	No.: <u>æ.</u>	SL-6413
Nevada Ukense No	427 9	5	Cliy	License	No.: 110799
Person to contact rega	rding th	e permit:			
Name: 23/11 5-40	ومحكام	الم	Pho	ne No.	745.2684
Email: <u> </u>		And American Land	Fax	No.:	356-6833
			•		
Design Professional In	ijermot	on:			
Architect's Name:			Pho	ne No.:_	
Engineer's Name: Phone			ne Mo:_		
Email:			Fax	No.:	
Project Information:					
Veluation:\$	••		Zoniren:		Lot#
No. of Storles:			Project Sc. Foota	OB:	
			Building Kelphi:		
Fire Sprinkler System?;	Yes a	Noo			ootage:
Fire Alarm System?	Yea o	Noo			. Foolege:
Septic Tank?	Yes o	Noo			age:
Septic Tank? Water Well?	Yes o	Non	Proposed Garage	\$q. Fo	otage
Fire Demo Perms No			Proposed Living 8	t Garag	e Sq. Foolege
Shed S q. Footage:			_		-
_					

Plumbing Contractor_Ergs.as_Plumbin/9_Phone No: _33) - 12 7 7	
Nevada License No.: 11201 (August City License No.:	
Mechanical Contractor:Phone No:	
Nevada License No.:(Required City License No.:	
Electrical Contractor: Complete Startesic. Phone No.: 882 - 136	
Mevada License No.: 67824	
Belitting Code Information:	
Edition of Code: Building Code used:	
Fype of Construction: Wood Preming 6 - Steel Framing 6 - Occupancy Use	
Occupancy Group: Single Ferrity Home: n - Townhouse a - Duplex a	
Affordable Housing? Yes No to	
Applicant (print) Bill Sandone (sign) Bull Sand Margare	'n

٠.,

Nev. 0425/10



City of Reno **Building Permit**

Total Beet Dam St La M.

Permit Number: Bt D12-04240

fatel Walls.

Address: 1548 STEELWOODLINGSTON

gog Pypy () raping/heyabassarRemoder 8.7-adron*44.

Percal No. 004-295-17

Valuation \$ 6 (90) (9) Фосиралон:

Zonana: ME (Y) Type

terre.

Complete State 0

H40-001

Pre Sonnélara For JUIN

areacSq 441:

Herm.

Supplied and Pull CLL 11S.

CØ.

Center Informations HOUSING AUTHORITY OUTNIES PEND.

6525 B 2TH 5T

PEHO NV 99512

Former Merconations

Date of the Control of the Control RUMDOLL

LIPARADE HITCHEN TO JOY ACCESSIN EISTANDARDS:

BLESTA CAL PLUMBING WECH

Bullder I Cheery Compactor

SIERRATE VELOPIARET 1020 E QPE3 #8 SPARKS NV ENGT 79,356,6800

MAILE -: 0006559

The improperty operation as a second materials and field for that the to a Paris to private prophersy and power how and popular of the above. gang as hipsays out on species agains do not of Price away for Fr erencyclis commicco economic performed pumpers in the informati 2 this and pulpose to any common or the secondary based or confere to experience and the expension particle but store your and rever both quarter, give, or expensions are seen for it from a rate replication of A PROPERTY.

The workington process to experience community before community ar provide at the provided to areas at many and a part of the appropriate and a part of the many of the particular and to agreem temporal became phops may their the their states wis at the appropriate section to distributions coming the Call of Final decides at brancher on all a planeterment production of the entire and the contract of by plack the Cap of Reno an expent a booking private matter exchange to gape ago, organistic receipt amends amends arrested beautiful.

Sebogranecases:

EXPRESS PLUMBING 1220 E /3KEG 84 SPARKS INVERSE r7750314277

WALLE GUALISM

COMPLETE BLECTRIC LLC. MIS DOUBLE R BLVG PEH), NV 85621 775 771 9420

VV Lie. DOSTAZA

CITY OF RENO PERMIT PLACE

Oak No.181-12 (General Contractor or the Robords #A)th 4

Винамирения

Participants bright granted by maketh for with Olympian with the ol no Chicago page 1-65 ONED

DERRESH SHIP SHIP SHIP

ALL INSPECTIONS MUST BE COMPLETED

1541 STEELWOOD UNUNIT PLLOT:		PERMIT MUMBER: BUD 12 (424)
Inspection tecord		POST THIS PERMIT IN A
		CONSPICUOUS PLAGE
M. 886-2 (7) 4007	ÇM;	Perna Impedion ReCOV
Florate was concerned. 6752 Stephend Bloods		Cay to Rose Reading Ported
Planting of product Prof. Planting Tax Gar		GEHERAL MORES
Fore Bright on the Control of the Co		n is utbinds to history the head south file for history to history the head had been been be
#100 for head Pack #100 Messace can feet to year		For interesting, news on the Dealest December 11th 11th 11th 11th 11th 20th 20th 11th 11th 11th 11th 11th 11th 11th 1
		Fig Department interaces. Adm the Fire Communication imperious are ask tripace and editorine the company amount action and a projection of the company of the company action and the company action action and the company action acti

A MA CORES MACON MANAGEMENT COLORS

PK 294 POIN PA 1949

wroniend beam we ly - Communitation and c CHECK P. MIGHINGS American Page # and 1507 Met and e seulenteen. On we 2 4606701 MeCh 0 Julia in 600am

erhaldert for for ii pitrakad se ibe re to schooling ex-

Same rater to the Pas Coombood compaints cather an the back kani page ai ma approves paus na sédennei -tarmiten eref ***********

-01120

ing here that he is assumed and of account may started marks. Accorded plant must be an the MD (44 of 48 Min), and the пурески, камі решей фи мерионая регрозка. Мата жа chard in account on the second flavouries because in because SAME DE ANTIGORA GROCE CONSTIGNOS AS ANTIGORA AL MANUEL MARIE The Core Briance Common was proper a near of 4 willing page ett været i New changes en har approved (klamag); stråt litt Lawrence in making the Apparents. Provide at open his required edinantes culto une guillers in persedince and RMC. Encarenari 1905 كى دى دىرى بىلى ئىلىنى ئىلىنى بىلىنى بىلىن панами сопротива смонгий ссиднау одов

Carrentens, and repréditions et l'intern en partie and production de building coder deed confermaces on adopted to the Chip of Rebb. with the by-exploration and place of the body and the company of the

PERMIT EXPERATION

in accordance with the UC, this person shall expert th werk in the communicativities (60 vays from the neus) case or 8 with a suspense of abordoned at any time. prior the work it commenced for a period of 160 days.

Conding images on someousing now available on the City. of Pierra's methodo manazano por "Otrone Sorricos Муна - филоному Францирияни филов - Уйлын Permit Place - Consectors may consider account and schedule impeditors in their day (CRU)

BUILDING PERMIT APPLICATION

Oily of Rono -Community Development Department 450 Sinctair Street - P.O. Box 1900, Seno, NV 89505 Case No :_____

Reo'd By:

RESIDENTIAL

12-04240	,	м мини. дол		(775) 334-2 Feer (775) S
wood	ddress: /5	. A		arcel Number:
				secription of Work:
	CheNS	e Kir	V dat	Remodel V
				Electrical
				Photoping
				, , , , , , , , , , , , , , , , , , , ,
ła	luider Perm	Owner/E		wner (adornation:
				ame:
<u> </u>				didress:
			c	ontractor information
	-	e Sagarangar d	-	Ser
me: <u>Bill Manchema</u>	<u>e Grand</u>	<u> </u>	, <u>e - 65 e</u>	énéral Contractor: <u>#746</u>
54-6833	100 794 B	Marks 1	- 144-159 -	ddress: <u>1218 P.b</u> hone No. <u>; 766-484</u>
a No.: 110799				evada License No
4.42	_			
	:	e permit:	rding th	eraon to contact rega
<u>. 745-2634</u>		رم	ويساران	6me: <i>15/77 _бъ</i> р
354-4833	Control Special Control	சீஸ் சு நக ர்.		Mali Audi P. Stebons
			Lavannik	ecign Professional In
		Architect's Name: Engineer's Name:		
				mail.
_				
				roject Information:
Łol #	Zoning			ekiellon: \$
	Project			o of Stones:
	Bulde			
Foctage	Curren	Non	Y#\$ 0	ite Sprinkler System?:
q. Foolage:		Noo	Yes o	ire Alarm System?
lago:	Currer	_	Yes o	eptic Tank?
oolage	Рюро	—	Yeso	later Well?
ge Sa Foolage:	_ Pιορα			ire Demo Permit No 👝
	_			hed Sq. Foolage:
	_			hed Sq. Foolage:

Plumbing Contractor <u>Figure</u> <u>Plum</u> Nevada Ucense No.: <u>412/9</u> /	obile/5 Phone No.: 931-1277
Machanical Contractor:	Phone No.:
Electrical Commercion Lorn plate Elec	Phone No.: 952 ± 13 ()
Nevade License No.: 67824	
Suitiding Code Information:	
Edition of Code:	Building Code ((sed):
Type of Construction: Wood Framing D	- Steel Framing to Occupancy Use
Occupancy Group. Single Family Home o	- Townhouse a - Duplace .
Ahoudakie Housing? Yes D No :	
, <u>;</u> ·	•
Applicant (print) Bi') Francisco	an join Bell Land Manager
* # *	
Ļ	

APPENDIX J Property Evaluator Qualifications





Scott Moyer

Construction Cost Estimator/HUD Cost Analyst

EDUCATION

• BS, Civil and Building Design Engineering - Old Dominion University

CERTIFICATIONS

HUD MAP Certified

SUMMARY OF PROFESSIONAL EXPERIENCE

Mr. Moyer brings over 20 years' experience and has extensive experience as a Senior Estimator/Cost Analyst working with General Contractors primarily in the multi-family, commercial and industrial construction.

As a Construction Cost Estimator and a Senior HUD Cost Analyst, Mr. Moyers responsibilities consist of developing Independent Cost Estimates for project economic cost comparison analysis and risk identification, then authoring Conceptual Budget Reviews (CBR), Construction Risk Analysis (CRA), and Cost to Complete (CTC) reports for the Construction Risk Management (CRM) division of AEI Consultants. Responsible for coordination, planning, and oversight efforts for assigned FHA Cost Reviews in accordance with directives as set forth in the HUD MAP Guide. Duties include review of project documents for completeness and coordination, and to determine discrepancies or conflicts in the documents which may lead to adverse cost impacts to the project, advising the MAP Team members in proper resolution of issues and HUD MAP cost reporting procedures, and final approval to FHA of proposed project costs submitted by the project General Contractor. Cost Review involves a fully independent project cost estimate to be developed for comparison analysis, schedules to be reviewed for adequate duration and monthly draw amounts, addendum letters for updates to projects at firm application, and any required resolution of HUD/FHA review produced comments.

All produced cost review estimates assembled into an in-house database for future work cost approvals. Non-HUD roles taken on involved production of Cost to Complete Reports, Insurable Replacement Valuations, and cross-training for Construction Loam Monitoring (CLM). Additional responsibilities include cost reviews for HUD financed projects utilizing either the FHA 223(f), 221(d)(4) or 232 Lean Loan Program.

PROJECT EXPERIENCE

Project experience for Mr. Moyer includes:

- Cedar Grove Portfolio 4 -property multifamily dwelling with 1,125 unit for veterans. Mr. Moyer developed an Independent Cost Estimate, for this project economic cost comparison analysis and risk identification, then authorized Conceptual Budget Review.
- Frontenac, MO Is a Hospitality building with 253 rooms. Mr. Moyer prepared a
 Conceptual Budget Review on this property. Costing was based on R.S. Means
 building construction cost data and R.S. Means Square Foot Cost Reports along
 with internal data to provide a cost comparison of the proposed budget with
 typical industry costs.

A list of HUD compliant cost estimating project Mr. Moyer completed are summarized below:

HUD MAP 221 (d)(4) Multifamily New Construction (NC) & Sub-Rehabilitation (SR) Program

- The Station at Gardner Mill, West Jordan City, Utah
- Cedar Court Apts. and Site Ren, Norwalk, Ct.
- Meadow Cliff Apartments, Oklahoma City, Oklahoma
- Walker Court North & South, Jonesboro, Arkansas
- Cameron Creek Apartments, Tempe., Arizona
- Elevate as Southwest Station, Eden Prairie, MN
- The Elliot, Little Rock, Arkansas
- The Commodore Place Apartments, Cleveland, Ohio
- River Run Apartments, North Bend, Washington
- RAD Lofts, Asheville, NC
- Midlothian Town Center Apartments, Midlothian, Virginia
- Gateway at Carolina Forest, Myrtle Beach, SC
- Midtown Pointe, Royal Oak, Michigan
- Lakehouse Commons,
- Buffalo Sunset Apartments, Las Vegas, NV
- Gateway at Carolina Forest, Myrtle Beach, SC
- Dwell @ 2nd, Philadelphia, PA
- Brennan Point Apartments, Newport News, VA

HUD MAP 232 Lean, Healthcare, Assisted Living, and Skilled Nursing Facilities

- The Guilford House, Guilford, Connecticut
- Congress Oaks, Palm Springs, Florida
- Abbington Crossing of Wilson, Wilson, North Carolina
- Grand View Place, Grand Rapids, Michigan
- The Highland Club, Baton Rouge, Louisiana
- The Park at Sydney Drive, Birmingham, Alabama
- Hinds County Nursing and Rehabilitation Center, Byram, Mississippi
- Brandermill Assisted Living, Chesterfield, Virginia

Resume Page 2

- Jasper Senior Living, Jasper, Indiana
- Nevins Nursing and Rehab Center, Methuen, MA
- Parkhaven Retirement & Assisted Living, Manhattan, Montana

HUD MAP 223 Heavy-f, Multifamily Refinance with Heavy Renovation

- Pecan Place
- Euclid Hills Villa

Resume Page 3



Jeb Bonnett

Director of Building Assessments - HUD

EDUCATION

- B.B.A Finance, James Madison University
- Principles of Real Estate Program, James Madison University

CERTIFICATIONS

- HUD Multi-Family Accelerated Processing (MAP) Cost/A&E Seminar New York City
- HUD Multi-Family Accelerated Processing (MAP) PCNA Workshop Columbus
- Virginia Housing Development Authority Universal Design Training
- Fair Housing Act Accessibility Training Course- Phillip Zook
- Fair Housing Act Accessibility Training Seminar- Fair Housing Act First
- Elevator Training Courses Sanjay Kamani, QEI, KP Property Advisors LLC
- Building Performance Institute Training Services
- Building Specs Training Institute, Building/Design Inspection Courses

SUMMARY OF PROFESSIONAL EXPERIENCE

Mr. Bonnett has worked exclusively in the niche HUD real estate due diligence consulting industry since 2005. He has performed and directed thousands of building assessment projects for HUD MAP, HUD LEAN, and Public Housing Authority clients. He has expert knowledge of HUD's Capital Needs Assessment guidelines and software reporting requirements. In addition, he has extensive experience and training on numerous accessibility standards, including, UFAS, ADA, ANSI, and the Fair Housing Act Guidelines.

As Director of Building Assessments - HUD, Mr. Bonnett is responsible for providing direction for the development of HUD Building Assessment services throughout AEI. Day to day responsibilities include, creating organizational process assets, training internal and external stakeholders, identifying and understanding industry guidelines for HUD Building Assessment services, senior reviewing, project oversight, business development and client management.

PROJECT EXPERIENCE

Project experience for Mr. Bonnett includes:

- Performing and directing the successful completion of over 3,000 HUD MAP and HUD LEAN compliant Capital Needs Assessments.
- Performing and directing the successful completion of RAD and GPNA projects for over 100 HUD Public Housing Authority AMPs.
- Leading the creation of software reporting platforms to efficiently populate HUD's CNA E-Tool, RAD Tool, and GPNA Tool software systems.
- More than 5 years' experience in multifamily assessments including numerous assignments for Freddie Mac, Fannie Mae and HUD execution.
- Creating and performing HUD E-Tool training seminars for HUD MAP lenders and internal staff.



Matthew Youngblood

Senior Project Manager

B.S. - Environmental Science, Colorado Mesa University, Grand Junction, CO

AAS - Forest Technology, University of NH, Durham, NH

Colorado Certified Asbestos Inspector Certification #14697 US HUD LP Visual Assessment Course OSHA 40-Hour Hazardous Waste Operations and Emergency Response Training

Mr. Youngblood has performed Due Diligence services in 45 of the 50 states on in excess of 2,000 properties. To ASTM compliance and satisfaction of client requirement. Mr. Youngblood's management and technical experience has allowed AEI's projects to be performed in a cost effective and timely manner to the satisfaction of AEI's clients and regulatory agencies. On projects including: Phase I Environmental Site Assessments, Property Condition Assessments, Environmental Transaction Screens, Spill Reports and Investigations, Subsurface Remediation System Installation and Monitoring as well as Phase II soil and groundwater investigations since 2003.

Project experience for Mr. Youngblood includes:

Phase I Environmental Site Assessments, Environmental Transaction Screens and Property Condition Assessments on a wide range of properties, including multi-tenant residential, commercial office, retail strip centers and mall properties as well as industrial and warehousing facilities

More than 5 years' experience in multifamily assessments including numerous assignments for Freddie Mac, HUD, and Fannie Mae execution.

The design and implementation of Phase II soil sampling investigations for a variety of suspected contaminants for UST removal, hazardous material spills and due diligence purposes.

Asbestos Inspections and Lead Based Paint sampling.

www.aeiconsultants.com



Roy Anderson

PE - Seismic Services Manager, Building Assessments

EDUCATION

• University of California, San Diego; BS Structural Engineering 1990

CERTIFICATIONS

- Professional Engineer, California, Civil 82059
- California Licensed General Contractor, B641049, Inactive
- ATC First Responder Training, California OES Volunteer
- Redwood Empire Remodelers Association, Board Member, Past President
- Appointed to the City of Santa Rosa Board of Building Regulations Appeals, Chairman
- Committee Member ASTM WK55885 Seismic Risk Assessment of Real Estate Portfolios
- American Society of Civil Engineers (ASCE)
- Structural Engineers Association of Northern California (SEAONC)
- Earthquake Engineering Research Institute (EERI)

SUMMARY OF PROFESSIONAL EXPERIENCE

Mr. Anderson has over 39 years of construction, construction management, structural design, seismic retrofit, structural assessment, and commercial due diligence experience. He owned and operated a successful structural design consulting firm for over 14 years.

His project experience includes public infrastructure, public works, and private developments including both residential and commercial projects. He has acted as a regional manager for a national consulting services firm overseeing property and casualty and seismic risk assessment operations in the western states, performing over 2000 Seismic Risk Assessment (Probable Maximum Loss) assessments and reports in the seismically active United States, Europe, and Mexico, over 100 Property Condition Assessments, and over 400 Property Damage Assessments for the insurance industry in 38 states. He has investigated and assessed damage in the 2014 Napa 6.0, Virginia 5.8, Oklahoma 5.7, and Northridge 6.7 earthquakes.

Mr. Anderson currently oversees and manages the Seismic Services Division of AEI's Building Assessments Department. Responsibilities include Senior Assessment of Seismic Risk Assessment Reports, Conducting Peer Reviews, scheduling, Seismic Retrofit Design, interfacing with Clients, providing outreach and education to Clients and Building Owners.

Some of his specific areas of expertise include forensic analysis of architectural and structural damage, seismic assessments of buildings, structural remediation and

rehabilitation of properties (URM, Historic, seismic, tornado, hurricane, flood, and fire), and structural design of swimming pools, wood and timber framed structures, structural steel structures, reinforced concrete structures, reinforced masonry structures, and pre-manufactured light gage steel structures.

PROJECT EXPERIENCE

Project experience for Mr. Anderson includes:

- Structural Design since 1991
- Seismic Retrofit Design since 1991
- Seismic Risk Assessments since 1994
- Forensic Assessments since 2007

Publications: 2016 ASTM Seismic Standards Update, California Mortgage Finance News, Fall 2016.

Resume Page 2



Staige Miller

Director of Environmental Services, HUD

EDUCATION

- MPA Master of Public Administration, Virginia Commonwealth University
- B.S. Environmental Policy & Planning and Political Science, Virginia Polytechnic Institute & State University

CERTIFICATIONS

- HUD Environmental Review Training
- HUD Multifamily Accelerated Processing (MAP)/LEAN Section 232 Underwriter Training
- AHERA Accredited and Virginia Licensed Asbestos Inspector #3303-002751
- ITRC Vapor Intrusion Pathway: A Practical Guideline (2-day Training)
- ASTM E 2600 Vapor Encroachment Online Course commonground University
- Building Performance Institute Training Services

SUMMARY OF PROFESSIONAL EXPERIENCE

Ms. Miller has worked exclusively in the niche HUD real estate due diligence consulting industry since 2000 coinciding with the original publication of the HUD MAP Guide. She specializes in providing HUD environmental deliverables and has performed and directed thousands of Phase I and II Environmental Site Assessments, Asbestos, Lead-Based Paint and Radon assessments, noise assessments, 8-Step Decision-Making Processes, and Environmental Review Records for the Related Federal Laws and Authorities for HUD MAP, HUD LEAN, and Public Housing Authority clients. Ms. Miller has expert knowledge of HUD's MAP and LEAN Guidelines and reporting platforms. In addition, she has extensive experience documenting National Environmental Policy Act (NEPA) compliance for various federal, state and local agencies.

As Director of Environmental Services - HUD, Ms. Miller is responsible for providing direction for the development of HUD Environmental Services throughout AEI. Day to day responsibilities include, creating organizational process assets, training internal and external stakeholders, identifying and understanding industry guidelines for HUD Environmental Services, senior reviewing, project oversight, business development and client management.

PROJECT EXPERIENCE

Project experience for Ms. Miller includes:

- Client/Agency liaison to provide technical guidance on regulations and to ensure the successful completion of the Environmental Review process.
- Client training and speaking engagements to inform and educate clients regarding HUD
 environmental due diligence and emerging topics. Ms. Miller's speaking engagements
 have included presentations to the various HUD lender associations and client-specific
 training sessions. Ms. Miller is also the Environmental Instructor for the Mortgage
 Bankers Association (MBA) FHA Multifamily Underwriter Training Program.